

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP/0036/2018/CCS
Date : 30-Aug-18

Vehicle in workshop . Kindly arrange for survey.

Your insured vehicle number: SFY 651 T

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Motor Claims Dept

Tel: 6841 0055 - Fax 6256 4315

Owner's Name : Mr. Lee Ching Haur
Address : 26 Bukit Batok Street 52
#02-02
Singapore 659247
Telephone : (HP) 91789803
Type of Claim : Third Party Claims
Policy No. : P10065214R00
Vehicle No : **SKH 959 L**
Model Code : TOYOTA HARRIER PREMIUM 2.0 A
Model / Year : Jun-17
Engine No : 3ZRB681564
Chassis No : ZSU60064879
Mileage :
Date In : 29-Aug-18
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 28-Aug-18
Place of Accident : Clementi Ave 6 slip rd to Commonwealth Ave W

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.
Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SKH 959 L.

S/n	Nature of Jobs	Estimated Charges	Remarks
1	To remove and transfer wiring harness for rear bumper and rear lid.	S/N \$ 200.00 ✓	
2	To remove and reinstall rear upholstery, seats, garnishes, trimming etc. To facilitate repair.	S/N \$ 150.00 ✓	
3	To place vehicle on car-o-liner bench and rectify chassis to recommended specification.	S/N \$ 400.00 ? photo.	
4	To dismantle rear bumper and rear lid. Repair rear chassis structure to origin specification. Cut out and weld rear cross panel. Repair rear wheel housing, both rear fenders and tail lamp panels. Renew all damaged panels. Reinstall all parts removed.	350/day. \$ 2,500.00 1750.	
5	To respray rear bumper, rear lid, rear lid trim, rear end panel, rear wheel housing, both rear fenders and rear tail lamp panels.	1/2 250/panel 1375 \$ 2,400.00	
6	To renew rear windscreen.	S/N \$ 250.00 ✓	
7	To carry out diagnostic check.	S/N \$ 192.00 ✓	
8	To re-apply rear windscreen solar film.	S/N Price TBA ?	
TOTAL LABOUR CHARGES		: \$ 6,092.00	

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SKH 959 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 1,000.00	de ✓
2	REAR BUMPER LOWER SPOILER	\$ 300.00	de ✓
3	REAR BUMPER LIGHT REFLECTOR - LH/RH	2 \$ 100.00	X
4	REAR BUMPER RETAINER - LH/RH	2 \$ 100.00	new ✓
5	REAR BUMPER GUIDE - LH/RH	2 PRICE TBA	new ✓
6	REAR BUMPER CLIP	15 \$ 55.00	new ✓
7	REAR BUMPER INNER SPONGE	\$ 140.00	new ✓
8	REAR LID	\$ 1,500.00	bt ✓
9	REAR LID SEAL - OUTER	PRICE TBA	?
10	REAR LID SEAL - INNER	PRICE TBA	9 m ✓
11	REAR LID SIDE INNER TRIM - LH/RH (metal)	2 \$ 160.00	?
12	REAR LID INNER BOARD - LOWER	\$ 440.00	?
13	REAR LID LOCK	\$ 600.00	?
14	REAR LID LOCK COVER	\$ 50.00	new ✓
15	REAR LID PUSH BUTTON	\$ 140.00	X
16	REAR LID LOCK STRIKER	\$ 90.00	bt ✓
17	REAR WINDSCREEN MOULDING - LH/RH	\$ 150.00	new ✓
18	REAR WINDSCREEN MOULDING - LOWER	\$ 100.00	new ✓
19	REAR LID 'HARRIER' EMBLEM	\$ 100.00	new ✓
20	REAR LID 'TOYOTA' LOGO	\$ 90.00	new ✓
SUB-TOTAL SPARE PARTS CHARGES		\$ 5,115.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SKH 959 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	REAR LID GANISH - OUTER	\$ 860.00	?
22	REAR LID TAIL LIGHT - LH/RH	2 \$ 800.00	?
23	REAR FENDER TAIL LIGHT - LH/RH	2 \$ 800.00	?
24	REAR END PANEL	\$ 600.00	bt -
25	REAR END PANEL UPPER TRIM	\$ 360.00	de -
26	REAR LUGGAGE COMP. TRIM - LH UPPER	\$ 560.00	?
27	REAR LUGGAGE COMP. TRIM - LH LOWER	\$ 540.00	de -
28	REAR LUGGAGE COMP. TRIM - RH UPPER	\$ 560.00	?
29	REAR LUGGAGE COMP. TRIM - RH LOWER	\$ 540.00	de -
30	REAR WINDSCREEN	\$ 1,300.00	?
31	GLASS PRIMER	\$ 20.00	ne -
32	REAR WINDSCREEN SEALANT	S/N \$ 200.00	ne -
33	ACRYLIC SEALER	S/N \$ 180.00	ne -
34	CAVITY WAX	S/N \$ 140.00	ne -
35	STONE CHIP	S/N \$ 180.00	ne -
36	REAR NO. PLATE W/ HOLDER	S/N \$ 35.00	st -
37	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 13,090.00
TOTAL LABOUR CHARGES		:	\$ 6,092.00
GRAND TOTAL		:	\$ 19,182.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Name : Tanjun 97495749.
Surveyed Date : 3/9/18.
Authorised Date : 'WP'
Excess Cost :
Liability :
Remarks : sur@khanto.com 10 days
Resunny before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6474 3323 for appointment.

Yours faithfully,
Premium Autocare Centre

Allan Wu
Body Shop Manager