Soon Bee Vehicle & Bodywork Maintenance

10 Anson Road #33-17 International Plaza Singapore 079903.
GST Registration No: 53076555A Email: paul@soonbee-vbm.com.sg

Quotation No.:

SB-GA-TCC18014

AIG Asia Pacific Insurance Pte. Ltd.

Date: 30-Aug-18

gapore 079120			
3-1			_
ar Sir/Mdm,	LKK Auto Consul	tants hence notify	
timated Cost of Penair Joh for: SBS380	" Demoiror of II	10 TOHOWHILLS	
timated Cost of Repair Job for: SBS330 cident on 23/08/2018, along HOUGANG AVE 10 involving SBS3308U and \$1	MA 139 Aurvey before	after spray painting	
sidefit off 20/00/2010, diolig 110 00/110/112 10 intolining 02/00/2010	 To display damage 	d part(s) during resurvey	
are pleased to submit the below estimated quotation for your consideration	Parts prices are su	is on a "Without Prejudic	e" ba
Vehicle No: SBS3308U			
Model : B9TL-9.4 D (A)	No illegal mounce No illegal mounce	m(s) must be resurveyed	and
	is subjects) linal	m(s) must be resurveyed approved to tall Price ance (S\$)	Com
List Item: Lower deck front dome with sealant	00.400.04		
Lower deck front dome with sealant Off side front light bezel	Acknowledges by	Repairer	
Off side front deflector	Signal\$#62.09		
Off side front corner bumper	Date: \$340.94		_
O/S Sumper bottom attachment bracket	\$37.30 \$33.46		
O/S Compression corner fixing bracket Main beam headlamp assy	\$173.62		
Dipped beam headlamp assy	\$187.16		
Front indicator	\$221.90		
Front centre bumper	\$558.14		
Front bumper mech	\$1,011.21 \$47.00		
Front f/glass corn fix bracket Crash pivot ground	\$2,531.01		
Compress front mid bumper fix bracket	\$36.84		
Stainless steel hinge assembly	\$33.46	2	
Paint (Green/ White/ Grey/ Black)	\$870.00	100	
Underseal anti rust tuff coating Parts Total	\$136.56	\$9,057.82	1
Labour: Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front v	wiper \$5.290.00	3500	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front vassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cen		3500	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front vassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cen bumper and bkt holders, main beam, dipped beam, indicator and support plate,	ntre	3500	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front vassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cen bumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring		3500	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front vassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cen bumper and bkt holders, main beam, dipped beam, indicator and support plate,	\$129.00 \$1,390.00	80	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front v assy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cen bumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Labour Total	\$120.00 \$1,300.00	80 (005 \$6,620.00	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front v assy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cen bumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Labour Total Parts and Labour Total	\$120:00 \$1,300.00 I Sum:	\$6,620.00 \$15,677.82	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front v assy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cen bumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Parts and Labour Total GST (\$120.00 \$1,300.00 I Sum: Cost: (7%):	\$6,620.00 \$15,677.82 \$1,097.45	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front vassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cenbumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Parts and Labour Total GST (T	\$120:00 \$1,300.00 I Sum:	\$6,620.00 \$15,677.82	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front vassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cenbumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Parts and Labour Total GST (T	\$120.00 \$1,300.00 I Sum: Cost: (7%): Total:	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front vassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cenbumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Parts and Labour Total GST (T	\$120.00 \$1,300.00 I Sum: Cost: (7%): Total:	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26 Working Day	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front vassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cenbumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Parts and Labour Total GST (T	\$120.00 \$1,300.00 I Sum: Cost: (7%): Total:	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26 Working Day	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front vassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cen bumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Parts and Labour Total GST (T Repair Dur Term of Payr	\$120.00 \$1,300.00 I Sum: I Cost: (7%): Fotal: ration: 10 ment: 30 Days U	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26 Working Day pon Invoice	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front wassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cenbumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Parts and Labour Total GST (T Repair Dur Term of Payr	\$120.00 \$1,300.00 I Sum: I Cost: (7%): Fotal: ration: 10 ment: 30 Days U	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26 Working Day	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front wassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cenbumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Parts and Labour Total GST (T Repair Dur Term of Payr	\$120.00 \$1,300.00 I Sum: I Cost: (7%): Fotal: ration: 10 ment: 30 Days U	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26 Working Day pon Invoice	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front wassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cenbumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Parts and Labour Total GST (T Repair Dur Term of Payr	\$120.00 \$1300.00	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26 Working Day pon Invoice	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front wassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cenbumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Parts and Labour Total GST (T Repair Dur Term of Payr	\$120.00 \$1,300	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26 Working Day pon Invoice	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front wassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cenbumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Parts and Labour Total GST (T Repair Dur Term of Payr	\$120.00 \$1300.00	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26 Working Day pon Invoice	
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front wassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cen bumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Parts and Labour Total GST (T Repair Dur Term of Payr Appoint Surveyor Name: Regards, Surveyor NRIC: 1st Signature /Date :	\$120.00 \$1,300	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26 Working Day pon Invoice irmation & agreed:	-
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front wassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cen bumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Labour Total Parts and Labour Total GST (Repair Dur Term of Payr Appoint Surveyor Name: 1st Signature / Date:	s120.00 \$1,300.00 I Sum: I Cost: (7%): Total: ration: ment: 10 30 Days U	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26 Working Day pon Invoice irmation & agreed:	basis
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front wassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cen bumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Labour Total Parts and Labour Total GST (Repair Dur Term of Payr Appoint Surveyor Name: 1st Signature / Date:	\$120.00 \$1,300	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26 Working Day pon Invoice irmation & agreed:	basis
Labour charges to remove and refit lower deck front dome, chrome plated ABS Labour charges to remove and refit front quarter glass, windscreen Labour charges to remove and refit near side front parts and lighting fitting, front wassy, wiper arms & blade, crash pivot ground, stainless steel hinge assy Labour charges to refit both side deflectors, light bezel, corner bumpers, front cen bumper and bkt holders, main beam, dipped beam, indicator and support plate, Labour charges to check and recitfy wiring Labour charges to re-spray and polishing affected area Labour Total Parts and Labour Total GST (T Repair Dur Term of Payr Appoint Surveyor Name: Surveyor NRIC: 1st Signature /Date:	s120.00 \$1,300.00 I Sum: I Cost: (7%): Total: ration: ment: 10 30 Days U	\$6,620.00 \$15,677.82 \$1,097.45 \$16,775.26 Working Day pon Invoice irmation & agreed:	basis