

ASS. REC. BY:

REF CS/SMO18015882/AtD3n2

Survivor

Adrian

ASSIGNMENT (Office)

From (Person)

Ngo sau wei

of SMO

Date/Time: 29/8/18 @ 5:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SGT161E

Insured:

GBC2099M

at Workshop n/s

United SG

Tel:

6747 4454

of

53 ubi Ave 1 #01-56

Policy No:

D18MTPCVC002696

Claim No:

EMTD1803699

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/8/18

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

12:48pm 30/8/18

Person Contacted:

Chris

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SGT161E - NA/MSG18015473/k4

D.O.A: 24/8/18

GBC2099M - NA/MSG18015473/k4

D.O.A: 24/8/18

5/9@1742 revert menmen pending estimate.

Finalize. lump sum \$43001- (Red: 10437.88; 70%.)

(00/1/13) wel  
ASS. REC. BY:

REF: SMO

### ASSIGNMENT

From: Date: 30/8/18

Estimated Cost:

OR ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGT 161E

at Workshop m/s

of 53 Ubi Ave 1 # 01-56

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

hup

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGT 161E Yr Regn: 2017, Jue

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 c.c. 1496.

Colour: 88 Grey A/C: Insured / Std / NI / NA

Sp. Reading: 14213 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6BN224840158694

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 30/08/18

Survey held at United SG.

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sumpo.

RECEIVED 25 APR 2019

Date/Time, File Pass to?

1) JH Typast

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 4300/-

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ )

☐ : Interview (\$ )

☐ : Tech. Invs (\$ )

☐ : Weekend (\$ )

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

350  
10

360



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18015882/Atd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 31-08-2018



Code : SMO

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 2099M	Veh. Inspected	SGT 161E
Policy No.	D18MTPCVE002696	Coverage (\$)	0.00
Claim No.	CMTD1803699	Excess (\$)	0.00
Assign From	MERIMEN (NGO SAU WEI)	Assign Date	31/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	24/08/2018	Inspection Date	30/08/2018
Survey held at	UNITED SG AUTOMOBILE PTE LTD 53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	27 Aug 2018		29 Aug 2018 17:15 <a href="#">Assign</a>			
						<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS**
[Created by insurer]

Insured:	VENUS TECHNOLOGY (FE) PTE LTD, Co. Reg. No.: 199803679R		
Main Claimant:	TOH WEE SIONG, ID: S8013831H		
Vehicle Reg. No.:	SGT161E	Date of Loss:	24/08/2018 17:00 - :59
Claim Type:	TP / CMTD1803699	Policy/Cover Note No.:	D18MTPCVE002696 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC2099M	Policy No. (Claimant):	
		Excess:	
Repairer:	United SG Automobile Pte Ltd (HQ) 53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park, 408934 Ubi - Tel: 9007 7556		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/09/2018]		
Driver/Custodian (Insured):	CHONG YONG KEONG (), NRIC: S9211743Z, Tel: +6590213391		

**ASSOCIATED MAIL RECEIVED**
View All
Compose Case Mail

- SOMPO\_SG (29/08/2018): TP SURVEY

**ALL ASSOCIATED TASKS**
View All
Search Tasks
Create New Task
Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

12:48pm  
6747 4454  
Chris  
veh. ✓

## View Sent Message

This mail is associated with :

**\*SGT161E (CMTD1803699)**  
**[GBC2099M]**

TP  
TOH WEE SIONG  
Aug 24 2018 5:00PM  
[VENUS TECHNOLOGY (FE) PTE LTD]  
United SG Automobile Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 05/09/2018 17:42 PM.  
**To** Shawn.Ngo@sompo.com.sg  
**CC** sur@lkkauto.com  
**Subject** \*SGT161E (CMTD1803699) [GBC2099M]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGT 161E on 30/8/2017  
We are pending estimate from repairer.

Regards,  
Denise  
LKK Auto

### DOCUMENTS SUMMARY

There are no documents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/08/2018 16:09
Date Of Accident	24/08/2018 17:20
Exact Location Of Accident	BALESTIER ROAD BEFORE MOULMEIN ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGT161E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TOH WEE SIONG
NRIC No	S8013831H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92995046
Alternative Phone No	OTHERS-92995046

### Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3 SEDAN 1.5 AT EU6
Exact Purpose for which vehicle was being used at time of accident	ON THE WAY TO WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80459147 QMX
Cover Note Number	

### Driver

Name of Driver	TOH WEE SIONG
NRIC No	S8013831H
Date Of Birth	13/05/1980
Occupation	OUTDOOR
Date Of Driving Pass	23/04/2004
Driving Experience	14 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92995046
Fax Number	
Contact Number	OTHERS-92995046
Email Address	NOEMAIL

Address	BLK 538 SERANGOON NORTH AVENUE 4 #05-83
Postcode	550538
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REVERT
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2099M
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHONG YONG KEONG
NRIC/Passport Number	S9211743Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	TOH WEE SIONG
Approximate Age	
Injuries Sustain	HEAD AND NECK
Injured person in which vehicle?	SGT161E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I was driving from home to a shop for the afternoon to  
 collect at the Zebra crossing, I felt a <sup>small</sup> impact from the front  
 and realised that a van (GBC 2099M) collided with my  
 vehicle (SGT 161E)

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

- 25/8/2018

# United

## SG Automobile Pte Ltd

"We are always in your journey"....

53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934

Tel : 6747 4454 | Fax : 6747 7752 | Email: claims@unitedsg.com.sg

UEN No. 201729521C | GST Registered No: 2017259521C

### ESTIMATION QUOTE

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE

#05-01/06 SINGAPORE LAND TOWER

SINGAPORE 048623

ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SGT161E

MAKE MODEL : MAZDA 3

REFERENCE : USG-201808-16

DOA : 24-Aug-18

CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
*REAR BOOT <i>dent</i>	1	\$ <del>1,985.20</del>	758
*REAR BOOT LOCK <i>2nd</i>	1	\$ 485.20	x
*REAR BOOT LOCK CATCH <i>1st</i>	1	\$ 89.50	x
*REAR BOOT RUBBER <i>1st</i>	1	\$ <del>365.90</del>	130
*REAR BOOT HINGE @ 62.50 <i>2nd</i>	2	\$ 125.00	x
*REAR BOOT ABSORBER @ 195.10 <i>1st</i>	2	\$ 390.20	x
*REAR BOOT CENTRE LOGO <i>2nd</i>	1	\$ 45.50	✓
*REAR BOOT EMBLEM 3 <i>1st</i>	1	\$ 35.20	✓
*REAR BOOT EMBLEM MAZDA <i>1st</i>	1	\$ 35.20	✓
*REAR BOOT EMBLEM SKYACTIVE <i>1st</i>	1	\$ 42.50	✓
*REAR BOOT INNER BOARD <i>1st</i>	1	\$ 596.30	x
*REAR BOOT LAMP @ 795.30 <i>1st</i>	2	\$ <del>1,590.60</del>	265
*REAR BOOT CENTRE GARNISH <i>1st</i>	1	\$ 548.20	x
*REAR TAIL LAMP RH <i>1st</i>	1	\$ <del>1,025.30</del>	766
*REAR TAIL LAMP PANEL RH <i>1st</i>	1	\$ 389.40	x
*REAR END PANEL <i>1st</i>	1	\$ <del>945.10</del>	506
*REAR END PANEL TOP GARNISH <i>1st</i>	1	\$ 315.60	x
*REAR BUMPER <i>1st</i>	1	\$ 1,425.20	1075
*REAR BUMPER SIDE RETAINER @ 31.70 <i>1st</i>	2	\$ 63.40	✓
*REAR BUMPER REINFORCEMENT <i>1st</i>	1	\$ <del>652.20</del>	538
*REAR BUMPER LAMP @ 105.00 <i>1st</i>	2	\$ 210.00	105
*REAR BUMPER TOW COVER @ 41.70 <i>1st</i>	2	\$ 83.40	4170
*REAR EXHAUST SILENCER <i>2nd</i>	1	\$ 1,425.30	x
*REAR EXHAUST HEAT SHIELD <i>1st</i>	1	\$ 165.20	x
*REAR EXHAUST RUBBER @ 39.50 <i>1st</i>	2	\$ 79.00	x
*REAR BUMPER SPOILER <i>1st</i>	1	\$ 1,500.00	x
*REAR END PANEL SEALANT <i>1st</i>	1	\$ 100.00	60(EN)
*REAR SPARE TYRE PANEL TOP INSULATOR <i>1st</i>	1	\$ 250.00	x

\$ 14,963.60

LESS 20% \$ 2,992.72

SUBTOTAL \$ 11,970.88

BALANCE C/F \$ 11,970.88

4543.10

3634.48

14W:60

6697.40  
5357.92

## ESTIMATION QUOTE

**SOMPO INSURANCE SINGAPORE PTE LTD**  
 50 RAFFLES PLACE  
 #05-01/06 SINGAPORE LAND TOWER  
 SINGAPORE 048623  
 ATTN: MOTOR CLAIMS DEPARTMENT

**VEHICLE NO** : SGT161E  
**MAKE MODEL** : MAZDA 3  
**REFERENCE** : USG-201808-16  
**DOA** : 24-Aug-18  
**CLAIM TYPE** : TP CLAIM

PAGE 2 OF 2

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F \$ 11,970.88			
REAR BUMPER CLIPS <i>New</i>	1	\$ <del>107.00</del>	30
REVERSE SENSOR <i>Damaged</i>	1	\$ <del>400.00</del>	200
REAR END PANEL SEALANT <i>Replaced</i>	1	\$ 100.00	X
SUBTOTAL \$ 607.00			
BALANCE C/F \$ 12,577.88 <i>230</i>			

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F \$ 12,577.88			
CHECK REAR WIRING AND LIGHTNING SYSTEM	1	\$ <del>80.00</del>	30
REMOVE AND RENEW REAR REVERSE SENSOR	2	\$ <del>200.00</del>	50
PANEL BEATING ON AFFECTED AREAS	3	\$ <del>800.00</del>	700
SPRAY PAINTING ON AFFECTED AREAS	4	\$ <del>1,000.00</del>	600
APPLY ANTI RUST ON AFFECTED AREAS	5	\$ <del>80.00</del>	30
SUBTOTAL \$ 2,160.00 <i>1440</i>			
GRAND TOTAL \$ 14,737.88 <i>1280</i>			

*total: 5364.48*  
*1/2: 4.3K ✓*

*Adrian Ling.*  
*1/s 30/08/18*  
*06 Aug*

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*6967.92*  
*5574.33*  
*25550*

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18015882/ATD3N2

Date: 08/05/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE002696
Claimant Vehicle No :	SGT161E	Insured Vehicle No :	GBC2099M
Date of Loss:	24/08/2018	Nature of Claim:	TP
		Claim No:	CMTD1803699

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SGT161E	Engine No:	P520451327
Make & Model:	MAZDA 3, 1.5 SEDAN EU6 (A)	Chassis No:	JM6BN22A8H0158694
Reg. Date:	07/06/2017 (Man. Year: 2017)	Odometer:	14213 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,577.88	3,975.20	8,602.68	68.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,440.00	720.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>14,737.88</b>	<b>5,415.20</b>	<b>9,322.68</b>	<b>63.26</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,300.00</b>		
<b>(\$\$)</b>	<b>14,737.88</b>	<b>4,300.00</b>	<b>10,437.88</b>	<b>70.82</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,031.65</b>	<b>301.00</b>	<b>730.65</b>	<b>70.82</b>
<b>Nett Amount (\$\$)</b>	<b>15,769.53</b>	<b>4,601.00</b>	<b>11,168.53</b>	<b>70.82</b>

## INSPECTION

Date of Assignment:	29/08/2018	
Date Inspected:	30/08/2018	Inspected At:
		United SG Automobile Pte Ltd (HQ)
		53 Ubi Avenue 1, #01-56 Paya Ubi
		Industrial Park
		Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2019)
Parts:	143	MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT161E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	1,985.20 FL	*958.00 FL
2	1		*REAR BOOT LOCK	Not Necessary	485.20 FL	*- FL
3	1		*REAR BOOT LOCK CATCH	Not Necessary	89.50 FL	*- FL
4	1		*REAR BOOT RUBBER	Cut	365.90 FL	*130.00 FL
5	2		*REAR BOOT HINGE	Not Necessary	125.00 FL	*- FL
6	2		*REAR BOOT ABSORBER	Not Necessary	390.20 FL	*- FL
7	1		*REAR BOOT CENTRE LOGO	Necessary	45.50 FL	*45.50 FL
8	1		*REAR BOOT EMBLEM 3	Necessary	35.20 FL	*35.20 FL
9	1		*REAR BOOT EMBLEM MAZDA	Necessary	35.20 FL	*35.20 FL
10	1		*REAR BOOT EMBLEM SKYACTIVE	Necessary	42.50 FL	*42.50 FL
11	1		*REAR BOOT INNER BOARD	Not Necessary	596.30 FL	*- FL
12	1		*REAR BOOT LAMP	N/s Cracked	1,590.60 FL	*265.00 FL
13	1		*REAR BOOT CENTRE GARNISH	Not Necessary	548.20 FL	*- FL
14	1		*REAR TAIL LAMP RH	Cracked	1,025.30 FL	*766.00 FL
15	1		*REAR TAIL LAMP PANEL RH	Repair	389.40 FL	*- FL
16	1		*REAR END PANEL	Dented	945.10 FL	*506.00 FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	315.60 FL	*- FL
18	1		*REAR BUMPER	Deformed	1,425.20 FL	*1,075.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	63.40 FL	*63.40 FL
20	1		*REAR BUMPER REINFORCEMENT	Bent	652.20 FL	*538.00 FL
21	1		*REAR BUMPER LAMP	N/s Cracked	210.00 FL	*105.00 FL
22	1		*REAR BUMPER TOW COVER	Missing	83.40 FL	*41.70 FL
			(2 Pcs)			
23	1		*REAR EXHAUST SILENCER	Not Necessary	1,425.30 FL	*- FL
24	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	165.20 FL	*- FL
25	2		*REAR EXHAUST RUBBER	Not Necessary	79.00 FL	*- FL
26	1		*REAR BUMPER SPOILER	Not Necessary	1,500.00 FL	*- FL
27	1		*REAR SPARE TYRE PANEL TOP INSULATOR	Not Necessary	250.00 FL	*- FL
28	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
29	1		*REAR BUMPER CLIPS	Necessary	107.00 FS	*30.00 FS
30	1		*REVERSE SENSOR	Damaged	400.00 FS	*200.00 FS
31	1		*REAR END PANEL SEALANT	Repeated	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,550.60	4,896.50
- List Item Discount on L Items 20.00/20.00% (S\$)	2,972.72	921.30
<b>Total Parts (S\$)</b>	<b>12,577.88</b>	<b>3,975.20</b>

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	80.00	30.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	200.00	50.00
3	PANEL BEATING ON AFFECTED AREAS	New	800.00	700.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
5	APPLY ANTI RUST ON AFFECTED AREAS	New	80.00	60.00
Gross Labour Cost (\$\$)			2,160.00	1,440.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;