



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SKJ4499K\*RA

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

### Vehicle & Document Information

WIP No **26383**  
Reg No/Reg Date **SKJ4499K\*RA / 24/07/2014**  
Date In/Mileage **02/10/2018/ 46001**  
Chassis No **WDD2050422F021949**  
Engine No **27492030176835**  
Make/Model **MB/MB C 200 SEDAN (W205) "AMG LINE"**  
Colour/Trim **027 792 Palladium S/ 042 267 Aubergine/B**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	17/10/2018/ 16:36	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : DMPCSN1823071800 // 23.08.18 DRIVE IN/EXCESS : 24.08.18 // \$500 DATE IN/DATE SURVEY: 02.10.18 // 30.08.18 TAUFIKH=LKK 12NOON BY/AUTHORIZED ON : VERON CHEN-LKK // 31.08.18				
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB REMOVE & REFIT LUGGAGE COMPARTMENT,TRIM, GARNISH- CARPET FOR NECESSARY REPAIR.				480.00
A BPILAB DISASSEMBLE AND REPLACE ON REAR BUMPER,LEFT REAR FENDER,END PANEL				1920.00
A BPIRES RESPRAY ON REAR BUMPER, LEFT REAR FENDER,END PANEL				1800.00
X BPNEXC INSURANCE EXCESS				-500.00
X AMG REAR BUMPER	1.00	1894.66	00.00	1894.66
X LEFT BASIC MOUNTING FOR BUMPER	1.00	51.97	00.00	51.97
X LEFT REAR LAMP COMBINATION	1.00	679.52	00.00	679.52

Finalization

7 Days

Confirmed & accepted by

7% GST on **Nett 6,706.15**  
**6706.15 469.43**

Authorized signatory and company stamp

**Total Payable 7,175.58**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg