



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJA9898T

Tanoto Shipyard Pte Ltd

No. 1 Jalan Samulun
Singapore 629119

Work: 62647300

Vehicle & Document Information

WIP No **26421**
Reg No/Reg Date **SJA9898T / 16/06/2011**
Date In/Mileage **/ 0**
Chassis No **WDD2120482A390599**
Engine No **27186030191377**
Make/Model **MB/E 200 CGI SEDAN (W212)**
Colour/Trim **023 359 Tansanite B/ 042 201 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	27/08/2018/ 17:04	K0	301 / Kerlyn Ong

Description of Goods / Services

Qty

Unit Price

Disc%

Amount

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : VA1/GA042912 // 25/08/2018

DRIVE IN/EXCESS : 27/08/2018 // \$500

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY RH/ REAR DOOR, RH/ REAR FENDER & REAR BUMPER

A BPILAB

USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

M RH/ REAR DOOR

1.00

2125.25 00.00

2125.25

M RH/ REAR DOOR WEATHERSTRIP

1.00

280.72 00.00

280.72

M RH/ REAR DOOR SIDE WINDOW FIXED

1.00

120.85 00.00

120.85

M GLAZING REPAIR KIT

1.00

154.72 00.00

154.72

M RH/ REAR DOOR WINDOW GUIDE RAIL

1.00

164.19 00.00

164.19

M RH/ REAR DOOR ORNAMENTAL COVER

1.00

85.80 00.00

85.80

M RH/ REAR DOOR SEALING RAIL

1.00

135.77 00.00

135.77

M RH/ REAR DOOR CHROME MOULDING

1.00

91.20 00.00

91.20

M LH/ REAR BUMPER CHROME MOULDING

1.00

128.17 00.00

128.17

M RH/ REAR BUMPER CHROME MOULDING

1.00

128.17 00.00

128.17

M CTR/ REAR BUMPER CHROME MOULDING

1.00

172.55 00.00

172.55

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Kerlyn Ong Kai Li

Confirmed & accepted by

DID: 6771 4420 HP: 9186 5113

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Acknowledged by Repairer

Authorized signatory and company stamp

Total Payable

9,381.11

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg