

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0982/2018/PH
Date : 27-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Glenn Koh Si Jie
Address : 329 River Valley Road
#02-02
Singapore 238361
Telephone : HP +65 97561296
Type of Claim : Own Damage Claims
Policy No. : 2100491595-01
Vehicle No : **SLJ 2668 R**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : 28/011/2016
Engine No : CVN 023992
Chassis No : WAUZZZF40HA067048
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Aug-18
Place of Accident : Carpark Exit of 6 Shenton Way OUE Downtown 2

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLJ 2668 R .

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1000 ✓	1350
3	To respray front bumper, rhs front fender.	\$ 1,500.00 1100 ✓	✓
6	To carry out diagnostic check	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 4,152.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 2668 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>del</i>	\$ 1,849.00	✓ 1479.20
2	FIXING PARTS FOR FRONT BUMPER	\$ 245.00	+
3	SECURING STRIP	2 \$ 60.00	+
4	AIR GUIDE -RH	\$ 73.00	+
5	AIR GUIDE GRILLE - RH	\$ 118.00	+
6	GUIDE SECTION - RH	\$ 32.00	x
7	FRONT FENDER - RH <i>Brekked</i>	\$ 665.00	✓ 532
8	ATTACHMENT PARTS FOR FENDER <i>Not nec</i>	\$ 45.00	? X
9	CLOSING ELEMENT - RH <i>nec.</i>	\$ 44.00	? 34.56
10	BRACKET FOR FENDER - RH <i>Not nec</i>	\$ 31.00	? X
11	BRACKET FOR DEFORMATION ELEMENT <i>nec</i>	\$ 43.00	✓ 34.16
12	POP RIVERT <i>Not nec</i>	6 \$ 18.00	- X
13	BRACKET FOR FENDER <i>Not nec</i>	\$ 27.00	? X
14	BRACKET <i>Not nec</i>	\$ 15.00	? X
15	FENDER BRACE <i>Not nec Bent</i>	\$ 103.00	✓ 82.40
16	WHEEL HOUSING LINER - RH <i>Not nec Deformed</i>	\$ 209.00	167.20
17	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>Not nec</i>	\$ 78.00	62
18	WHEEL SPOILER - RH <i>Not nec</i>	\$ 63.00	x
19	STONE CHIP GUARD - STAIN BLACK <i>nec</i>	\$ 44.00	✓
20	SPOILER - RH <i>Not nec</i>	\$ 31.00	34.56
SUB TOTAL SPARE PARTS CHARGES		\$ 3,793.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 2668 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	COVER <i>Renew</i>	\$ 27.00	? X
22	COVER - RH <i>Renew</i>	\$ 20.00	? X
23	LED HEADLIGHT - RH <i>Renew cracked</i>	\$ 6,973.00	5578.40
24	LIFT CYLINDER - RH <i>Renew damaged</i>	\$ 184.00	147.00
25	SUNDRIES <i>New</i>	\$ 300.00	? 33.36
TOTAL SPARE PARTS CHARGES		:	\$ 11,297.00
TOTAL LABOUR CHARGES		:	\$ 4,152.00
GRAND TOTAL		:	\$ 15,449.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

23,172.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Adrian Ling
30/08/18

~~Not~~ Authorised Repairs, 04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant