

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7623G

MAKE :

MODEL : HYUNDAI i40

EQ/LKK
ReAR

DATE 29/8/2018 16:44

Fz
Fauzy

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X Repair</i>			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips <i>X</i>			\$ 22.00
	Rear Bumper Sponge <i>X</i>			\$ 143.40
	Rear Bumper Under Cover <i>X</i>			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70 Nett
	Rear Bumper Rubber Mat <i>X</i>			\$ 50.00 Nett
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 350.00 ¹⁰⁰
	Spray Painting Charge			\$ 250.00 ²⁰⁰
	Wiring Charge			\$ 50.00 <i>X</i>
	R/Refix Reverse Sensor			\$ 120.00 <i>X</i>
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 2,481.58

Ka Wilky
30/8/18 1106hrs.
2 hrs.
4/
After Repair p/b

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.