CWS Adna	ASSIGNMEN	I (Office)	
From (Person) Sovere	fet of F	CÍ Date/	30/8/18@3.42
Estimated Cost OD TP WS/TP RES/	B	ill to	
To Inspect Vehicle No:	SIQ 473 21	Transcription	0110 CA2115
at Workshop m/s	Force Motor		3HC 8439E
	1.01 4.1	01-27	1820548
Policy No	11100 7		1171145011
Sum Insured		Claim No: _ D18006	4-11MF3H
Make of Veh	V	Excess: D.O.A	27/08/2018
	2		
	(DS)		
CA / REV / REP. / REV		Bourche on William). Endorsement
CA / REV / REP. / REV	31818 Person Contacted: 8	no.	O. Endorsement
CA / REV / REP. / REV	31818 Person Contacted: 8	new Cheng Vehicle	2
CA / REV / REP. / REV	31818 Person Contacted: 8	no.i new cheng Vehicle	2
CA / REV / REP. / REV	31818 Person Contacted: 8	iewcherg Vehicle	2
CA / REV / REP. / REV	318/18 Person Contacted: 8 ction () Estimate 17321-x 8439.E-05/FCC170	21388/Krbn 2	2
CA / REV / REP. / REV	318/18 Person Contacted: 8 ction () Estimate 17321-x 8439.E-05/FCC170	21388 Krbn 2 use are pending	2

ASSI	G	N	V	П	ij	N	I
	ī						_

From: Date:	Veh No: 33041321 - Yr Regn: 2809 / May.
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Itanda Jazz cc 1497
at Workshop m/s	Colour Yellow A/C: Insured / Std / NI / NA
of	Sp.Reading 149280 . T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: THMGE. 88 SO9S 28661
Claims No.	Gen. Cond Good Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim STD A/Rim or
	Tyre Size: F: 55 215
(Policy Condition)	R: 25 65 615
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. Ob mm R/Bal. Qb mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est Repairs: 6 days Res.: Yes or No	D.O.A. D.O.I. 30 08 18 "
Lum Sum: % 3 Val.: Yes or No	Survey held at Fong Molos.
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
11 /5. 64 /	ED 2 3 OCT 2018
RECEIV	EU C 3 CO. L
MV: WE16.51C	
Nett 300 .A.11c.	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
173 10 MMAY : Final Report	Resurvey No. of Trip: Survey Fee: 150
Date/Time, File Return to?	Transportation: 50
Add Fee	e: Site Insp (\$)s+Rssi5()
	: Interview (\$) Photos 62
Report Format: 7P	Tech. Invs (\$) Others
Lump Sum / LB.E. (\$ 4(00)	:Weekend (\$
	TOTAL 312



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

FIRST CAPITAL II	NSURANCE LTD	ternationale Des Experts En Aut				
		Ref : CS/FCI1801	5914/Aqd3			
36 ROBINSON RO #16-01 CITY HOU	OAD SESINGAPORE 068877	Date: 31-08-2018				
1.	Policy Post	Code: FCI2				
Insured Veh	. SHC 8439E	ulars :- THIRD PARTY CL	AIM			
Policy No.	. 0110 0409E	Veh. Inspected	SJQ 4732L			
Claim No.	D18006471MFSH	Coverage (\$)	0.00			
Assign From		Excess (\$)	0.00			
2.		Assign Date	31/08/2018			
	Vehicle I	Particulars & Condition				
Make & Mod		c.c	0			
Engine No.	HIDDEN	Year of Reg.				
Chassis No.						
Odometer	•	Steering				
Brakes		Modification				
General						
	Cor	nditions of Tyres	had a see a see a see			
	Size	Make	Palana			
R/H Front Tyr			Balance mm			
L/H Front Tyre						
R/H Rear Tyre			mm			
L/H Rear Tyre			mm			
	Descri	ption of Damages	mm			
	3,000	phonor bailinges				
Engine No.	Gene	eral Information				
Accident Date	Oelli					
Survey held at		Inspection Date	30/08/2018			
	1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883					
and the series with	and the surprise Conc	Remarks				
A)THE INSPECTI	ON WAS CONDUCTED ON A"W					
DIN ACCORDAN	CE TO YOUR INSTRUCTIONS,	WE HAVE NOT AUTHORISE	D REDAIDS			



MS First Capital Insurance Limited co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

29-08-2018

Our Ref No. D18006471MFSH

Accident Date

27-08-2018

Claim Type. Third Party

Insured Vehicle

SHC8439E

Third Party Vehicle. SJQ4732L

Survey Location

(AUTOBAY@KAKI BUKIT) 1 KAKI BUKIT AVE 6BLK C #01-27/#01-45

Contact Person.

SIEW CHENG

Contact No.

67485648/81820548

Fax No. 0

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED (NO

EST. COR)

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

FONG MOTORS

Attention. NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SERENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Tuesday, 23 October 2018 11:29 AM

To:

'Claim Workflow System'; assignments SERENELER@MSFIRSTCAPITAL.COM.SG; SUR

Cc: Subject:

RE: SURVEY ASSESSMENT - D18006471MFSH/1

Attachments:

CSFCI18015914Aqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SJQ 4732L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)

Sent: Friday, 31 August 2018 3:08 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18006471MFSH/1

Dear Serene,

Please be informed that we have inspected the vehicle SJQ 4732L on 30/08/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 30 August 2018 3:56 PM

To: 'Claim Workflow System' < cwsmotorclaims@msfirstcapital.com.sg; assignments < assignments@lkkauto.com

Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR < sur@lkkauto.com >

Subject: RE: SURVEY ASSESSMENT - D18006471MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18006471MFSH

Date: 23 October 2018

Our Ref: CS/FCI18015914/Aqd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJQ 4732L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/08/2018 at the premises of M/s FONG MOTOR. and have the following to report:-

 Workshop Estimate Amount
 : \$\frac{\\$S\\$}{7,840.90}\$.

 Revised Estimate Amount
 : \$\frac{\\$S\\$}{4,100.00}\$ (Lump Sum) .

 "Check" Items Amount
 : \$\frac{\\$S\\$}{2}\$.


 Market Value
 : \$\frac{\\$S\\$}{2}\$.

 LTA Reimbursement Value
 : \$\frac{\\$S\\$}{2}\$.

 Nett Value
 : \$\frac{\\$S\\$}{2}\$.

Description of Damage:

<u>The vehicle sustained damages</u>
at the rear portion.



Yours faithfully

ADRIAN LING WAI PING

B. Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 31 August 2018 3:08 PM

To:

'Claim Workflow System'; assignments

Cc:

SERENELER@MSFIRSTCAPITAL.COM.SG; SUR

Subject:

RE: SURVEY ASSESSMENT - D18006471MFSH/1

Dear Serene,

Please be informed that we have inspected the vehicle SJQ 4732L on 30/08/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 30 August 2018 3:56 PM

To: 'Claim Workflow System' < cwsmotorclaims@msfirstcapital.com.sg>; assignments < assignments@lkkauto.com>

Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18006471MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 30 August 2018 3:42 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18006471MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards, Admin Team

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:		(1)///
Owner ID:	Singapore NRIC	
Vehicle Details	7411Z	
Vehicle No.:	SIO47221	THE RE
Vehicle to be Exported:	SJQ4732L Yes	
Intended De-registration Date:		
Vehicle Make:	30 Aug 2018 HONDA	
Vehicle Model:		
Primary Colour:	HONDA JAZZ 1.5L A	
Manufacturing Year:	Yellow	
Engine No.:	2008	
Chassis No.:	L15A71004535	
Maximum Power Output:	JHMGE88509S203661	
Open Market Value:	88.0 kW (118 bhp)	
Original Registration Date:	\$23,654.00	
First Registration Date:	13 May 2009	
Transfer Count:	13 May 2009	
Actual ARF Paid:	0	
Intended PARE Rebate Details	\$23,654.00	
PARF Eligibility:	以10.00mm (1.10mm) (1	Action
PARF Eligibility Expiry Date:	Yes	
PARF Rebate Amount:	12 May 2019	
ntended COERebate Details	\$11,827,00	
COE Expiry Date:	THE RESERVE OF THE PROPERTY OF	
COE Category:	12 May 2019	
COE Period(Years):	A - Car (1600cc & below)	
QP Paid:	10	
COE Rebate Amount:	\$8,489.00	
Total Rebate Amount:	\$593.00	
information contained herein is correct as at 30 Aug 2	\$12,420.00	



ONE RAFFLES PLACE ROADSHOW SPECIAL, 29 - 31 August 2018










> Low prices guaranteed > Specialist in Japanese cars > Easy loan approval > All terms are negotiable



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT	The Paris of the Paris of
Date Of Report	28/08/2018 13:59	
Date Of Accident	27/08/2018 18:10	
Exact Location Of Accident	BEDOK NORTH RD	
Country/State of Loss	SINGAPORE	

THE RESERVE AND ADDRESS OF THE PERSON OF THE	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJQ4732L	
Insured/Policyholder		
Name Of Registered Owner	LIM EK HENG	
NRIC No	S0187411Z	

NRIC No	S0187411Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-929

Mobile Phone No (LOCAL) +65-92967322
Alternative Phone No OFFICE-92967322

Vehicle Particulars

Manufacturer HONDA Model JAZZ

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company LONPAC INSURANCE BHD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number Z18VP05018445

Cover Note Number

Driver

Name of Driver SALLY LIM CHOON LENG

 NRIC No
 \$1651079C

 Date Of Birth
 01/10/1964

 Occupation
 INDOOR

 Date Of Driving Pass
 21/08/1991

Driving Experience 27 YEARS AND 0 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-91069166

Fax Number

Contact Number

EMail Address EHLIMNSALLY@GMAIL.COM

Address BLK 61 TAMPINES AVE 1 #13-01

Postcode 529776

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

NO

NO

NO

YES

NO

1

Circumstances of Accident

MY VEHICLE WAS STATIONARY DUE TO HEAVY TRAFFIC. SUDDENLY, I FELT AN IMPACT AND REALISED THAT VEHICLE B HAD KNOCKED AGAINST MY REAR PORTION.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC8439E

Vehicle Make/Model/Colour

Details Of Properties VEHICLE B

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

·

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Oriver's Signature

(If driver is not the policyholder)

Date & Time:

28-08.18

Reporting Centre Personnel's Signature

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

. 6	1.0		
The state of the s		1-4-1-1	
	विक्रमुचळा		*
100	WUNDE		
		HERENTIA	
	RIBE CIRCUMSTANCES OF THE ACCIDI	ENT to h	reavy traffic.
DESC	RIBE CIRCUIVISTANCE	ationary due to	lized that vehicle
	My venice felt au	impact any reas	portion.
-	B had knocked	against	lized that vehicle
	THOM .	in overy respect.	
	DECLARATION I/We declare the foregoing particulars	are true in every form	il. Constituté
	4	Sample	Reporting Centre Personnel's Signature Name:
	Policyholder's Signature	Oriver's Signature (if driver is not the policyholder) Date & Time:	NRIC/FIN NO.:
	Date & Time:	Water and the same of the same	

THE PAY STANDARD MANUAL AS

Fong Motors

1, Kaki Bukit Ave 6, #01-45/27, Autobay, Singapore 417883

Vehicle No.

SJQ4732L

Make/Model

HONDA JAZZ

Year

Chassis No.

TP 15 Gay20

DATE:

6/9/2018

xino Chen.

JHMGE885095203661

-	-			-
PA	КI	5	LI	ST
		_	_	_

		Distorted	U	Init Price	221:40
1	1 pc	REAR BOOT LID Pistorted	\$	981.90	\$ 981.90 736-60
2	1 pc	REAR BOOT LID LOCK Dernjed	\$	218.00	\$ 218.00 186:20
3	1 pc	REAR EMBLEM-JAZZ ML	\$	56.50	\$ 56.50
4	1 pc	REAR EMBLEM-HONDA WE ME	\$	47.80	\$ 47.80 ×
5	1 pc	REAR WEATHERSTRIP CT	\$	102.30	\$
6	1 pc	REAR END PANEL Deuted	\$	639.00	\$ 639.00 276.50
7	1 pc	REAR END PANEL GARNISH	\$	229.50	\$ 229,505 86.90
8	6 рс	REAR END PANEL CLIP	\$	4.50	\$ 27.00 / 0
9	1 pc	REAR SPARE TYRE GARNISH	\$	192.50	\$ CONTRACTOR OF THE PARTY OF THE
		REAR TAIL LAMP LH/RH coulted	\$	398.00	\$ 705-005 674
		REAR BUMPER Distarded	\$	698.00	\$ 598.00 460 30
		REAR BUMPER BRACKET NEW	\$	36.50	\$ 36.50+
		REAR BUMPER SIDE RETAINER	\$	57.50 28.75	\$ 57.50
		REAR BUMPER CLIP rec	\$	4.50	\$ 27.00
		REAR BUMPER LOWER GARNISH	\$	393.40	\$ 393.40
		REAR WINDSCREEN GLASS MOULDING	\$	69.50	\$ 69.50
		Res Boot Lid Lover Take Color 225			\$ 4,572.40
		Tool Box Sporge and 245			
		LABOUR CHARGE			
		1SET REVERSE SENSOR			\$ 300.00 10 0
		TO REMOVE AND REPLACE REVERSE SENSOR			\$ 80:00-50
		TO KNOCK AND CHANGE PARTS			\$ 900.00
		TO SPRAY PAINT THE AFFECTED AREAR			\$ 1,000.00
		TO REMOVE AND REFIX INNER TRIM BOARD			\$ 120.00-80
		TO CHECK WIRING			\$ 100.00 3
		TUFF KOTE and			\$ 120:00
		TO REMOVE REFIX REAR WINDSCREEN GLASS			\$ 150.00 120
					\$ 7,342.40

IPI tonly cover Missing

28.50

LKK Auto Consultants hence notify

the Repairer of the following:

- . To resurvey before/after spray painting
- MOTORS To display damaged page ONG
 Parts prices are subject Ong of the page of the page
- . Third party ... ey is on a "Without Preju
- . No illegal monification(s) is allowed.
- Supplementary item(s) is subject to final approval from Insurance ompany

Acknowledged by Repairer

Signature:

Date:

hist 3635-60 undoj. 29084P

SN: 200

tolel: \$13848 4/5: A.1 K.

7840.90





5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inter	rnationale Des Experts En Autor	mobile
FIR	ST CAPITAL INSU	RANCE LTD	Ref : CS/FCI180159	914/Aqd3e2
	ROBINSON ROAD -01 CITY HOUSES	SINGAPORE 068877	Date: 29-10-2018 Code: FCI2	
1.		Policy Particul	lars :- THIRD PARTY CLA	.IM
	Insured Veh.	SHC 8439E	Veh. Inspected	SJQ 4732L
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18006471MFSH	Excess (\$)	0.00
	Assign From	SERENE LER	Assign Date	30/08/2018
2.		Vehicle P	Particulars & Condition	
	Make & Model	HANDA JAZZ	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JHMGE88509S203661	Colour	YELLOW
	Odometer	149280	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Cor	nditions of Tyres	THE PERSON NAMED AND ADDRESS OF THE PERSON NAMED AND ADDRESS O
		Size	Make	Balance
	R/H Front Tyre	185/55 R15	YOKOHAMA	6 mm
	L/H Front Tyre	185/55 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	185/55 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	185/55 R15	YOKOHAMA	6 mm
4.		Descr	ription of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE ETAILS.	REAR PORTION.	
5.		Ger	neral Information	
	Accident Date	27/08/2018	Inspection Date	30/08/2018
	Survey held at	FONG MOTORS		
		1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883		
5a.			Remarks	
	B)THE INSPECTIO		PORT. "WITHOUT PREJUDICE" BAS IS, WE HAVE NOT AUTHORIS	

Estimate Days of Repair

6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 4732L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID	DISTORTED	981.90	736.60
1	REAR BOOT LID LOCK	DAMAGED	218.00	186.20
1	REAR EMBLEM - JAZZ	NECESSARY	56.50	56.50
1	REAR EMBLEM - HONDA	NOT NECESSARY	47.80	
1	REAR WEATHERSTRIP	CUT	102.30	102.30
1	REAR END PANEL	DENTED	639.00	276.50
1	REAR END PANEL GARNISH	DEFORMED	229.50	86.90
6	REAR END PANEL CLIP @\$4.50	NECESSARY	27.00	10.00
1	REAR SPARE TYRE GARNISH	NOT NECESSARY	192.50	-
2	REAR TAIL LAMP LH/RH @\$398.00	CRACKED	796.00	674.40
1	REAR BUMPER	DISTORTED	698.00	460.30
1	REAR BUMPER BRACKET	NOT NECESSARY	36.50	,
2	REAR BUMPER SIDE RETAINER @\$28.75	NECESSARY	57.50	57.50
6	REAR BUMPER CLIP @\$4.50	NECESSARY	27.00	27.00
1	REAR BUMPER LOWER GARNISH	DEFORMED	393.40	393.40
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	69.50	69.50
1	REAR BOOT LID INNER TRIM	CRACKED	225.00	225.00
1	TOOL BOX SPONGE	CRACKED	245.00	245.00
1	TOWING COVER	MISSING	28.50	28.50
	LESS 20% DISCOUNT		-	-727.12
			5,070.90	2,908.48
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN)	DAMAGED	300.00	200.00
			300.00	200.00
	LABOUR			
	TO REMOVE AND REPLACE REVERSE SENSOR.		80.00	50.00
	TO KNOCK AND CHANGE PARTS.		900.00	900.00
	TO SPRAY PAINT THE AFFECTED AREA.		1,000.00	800.00
	TO REMOVE AND REFIX INNER TRIM BOARD.		120.00	80.00
	TO CHECK WIRING.		100.00	30.00

Report Ref No. CS/FCI18015914/Aqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TUFF KOTE.		120.00	50.00
	TO REMOVE AND REFIX REAR WINDSCREEN GLASS.		150.00	120.00
			2,470.00	2,030.00
	GRAND TOTAL		7,840.90	5,138.48

RECOMMENDED COST OF LUMP SUM REPAIRS	4,100.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI18015914/Aqd3e2

MARKET VALUE: \$16,500.00(EST)-PAPER VALUE: \$12,400.00=NETT VALUE: \$4,100.00



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.