

SALES/RENT

From (Person)

Adrian
Monica Chung

ASSIGNMENT (OFFICE)

MSG

Date/Time: 30/8/18 @ 3:04pm

Estimated Cost

Bill to

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SLQ 7203D

Insured

SL8 8746L

at Workshop to/

Hwei Meng

Tel

67478064

of

1 Kaki Bkt Ave 6 #01-61

Policy No

A29 035052 Avw

Claim No

568716

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

28/08/2018

CA / REV / REP. / REV 24 HRS

hwp

H.O.D. Endorsement

Date/Time

Person Contacted

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLQ 7203D - x

SL8 8746L - x

31/08/18

@ 15:45 p.m. revert pending estimate from repairer to Monica Chung via messenger.

REF:

ASS. REQ. BY Adrian Ling

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLQ7203D- Yr Regn: 2009 / Feb.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Estima cc 2862

Colour:

Blue - A/C: Insured / Std / NI / NA

Sp. Reading

103554 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ACR500080809:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/35R20

R: 245/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

30/08/18

Survey held at

Hua Meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP MS(6).

18/10/18 Continued HS \$ 6,800/- @ 7 days with Adrian.

(\$ 8,123.72 Red-54%)

MV 127K

PV 120.1K

Nett 6.9K

RECEIVED 18 OCT 2018

Date/Time, File Pass to?

18/10/18

1)

Typ 21

Date/Time, File Return to?

2)

☐

Preli. Report

☒

Final Report

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee:

200

Transportation:

S-RS \$

Photo:

Other:

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format:

Lump Sum / L.B.L (\$ 6,800/- HS)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018		30 Aug 2018 15:04 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	YEO AI LING (YANG AILING) , ID: S7315833H, Tel: +6581215816								
Main Claimant:	CHIAM ISAAC SHER-WEN , ID: S8032296H								
Vehicle Reg. No.:	SLQ7203D	Date of Loss:	28/08/2018 15:00 - :59 [114 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 568716	Policy/Cover Note No.:	A29035052AVW (Comprehensive) Coverage: 10/10/2017 - 09/10/2018						
Vehicle Reg. No. (Insured):	SL58746L	Policy No. (Claimant):							
		Excess:	S\$3,500.00						
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/08/2018]								
Driver/Custodian (Insured):	THOMAS JEREMY GOH KUO LIANG (), NRIC: S7132784A, Tel: +6597965319								
Adj Asg. Remarks:	LIABILITY 100%. TP AGREE WITH SJE - ASSIGN LKK AUTO CONSULTANTS PTE LTD.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18015915/Gsd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 31-08-2018



Code : MSG

1.

Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 8746L	Veh. Inspected	SLQ 7203D
Policy No.	A29035052AVW	Coverage (\$)	0.00
Claim No.	568716	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	31/08/2018

2.

Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

5.

General Information

Accident Date	28/08/2018	Inspection Date	30/08/2018
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a.

Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2296H
Vehicle Details	
Vehicle No.:	SLQ7203D
Vehicle to be Exported:	Yes
Intended De-registration Date:	30 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	2AZC494821
Chassis No.:	ACR500080809
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$40,189.00
Original Registration Date:	11 Feb 2009
First Registration Date:	11 Feb 2009
Transfer Count:	2
Actual ARF Paid:	\$40,189.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Feb 2019
PARF Rebate Amount:	\$20,094.00
Intended COE Details	
COE Expiry Date:	10 Feb 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$689.00
COE Rebate Amount:	\$30.00
Total Rebate Amount:	\$20,124.00

The information contained herein is correct as at 30 Aug 2018

OK

CHEAPEST CAR INSURANCE RENEWAL

Choice of
\$0 excessOption of any
workshop

GET A CHEAPER QUOTE NOW!

SEARCH Price Range Depreciation 2009 Vehicle Type [Advanced Search](#)

Used Car Comparison

— Comparing 4 Vehicles —

Toyota Estima 2.4A Aeras Premium Moonroof



Clear All

[Back to search result](#)

Toyota Estima 2.4A Aeras



Toyota Estima 2.4A Aeras Premium Moonroof



Toyota Estima 3.5A Aeras



CAR DETAILS

	Toyota Estima 2.4A Aeras Premium Moonroof	Toyota Estima 2.4A Aeras	Toyota Estima 2.4A Aeras Premium Moonroof	Toyota Estima 3.5A Aeras
Price	\$35,800	\$35,888	\$38,500	\$38,700
Instalment	\$2,151	\$2,156	\$2,313	\$2,151
Registration Date	31-Aug-2009	11-Sep-2009	16-Sep-2009	27-Oct-2009
Manufactured	2009	2009	2008	2009
Mileage	133,000 km	185,000 km	168,616 km	125,000 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	2,362 cc	2,362 cc	2,362 cc	3,456 cc
Road Tax	\$1,638 /yr	\$1,638 /yr	\$1,638 /yr	\$3,100 /yr
Power	125.0 kW (167 bhp)	125.0 kW (167 bhp)	125.0 kW (167 bhp)	206.0 kW (276 bhp)
Curb Weight	1,770 kg	1,730 kg	1,770 kg	1,880 kg
Features	Comes With Sunroof And 2 Power Doors.	8 Seater, Powerful 2.4L VVT-i Engine, CVT Transmission, SRS Airbags, ABS, Push Start, Keyless Entry, Dual Zone Climatic Aircon.	Moonroof, Pioneer Head Unit, Overhead 12" Screen Monitors.	Power By 3.5L V6 DOH Control, 6 Speed Auto Dual SRS Airbags, Xen Keyless Entry, Dual Zo Control.
Accessories	17" Sport Rim.	Leather Seats, Year Old Original Factory Rim, HID Headlights, DVD Player.	In View Car Camera (Front), Rear View Camera, Parking Sensor.	7 Seater, Dual Power ! Reverse Camera, Retri Mirrors With Signal In
Description	Option To Purchase With 5 Years COE At \$52,300 Or 10 Years COE At \$69,000	High Parf Rebate, Regularly Serviced (Last Done In Jun 2018) New OEM Aircon Compressor Replaced In Jun 2018, Well Maintained. Interested, Please Conta Ct For Viewing And Test Drive.	Detailed Monthly With ZYMOL At Autoinc Detailing. Car Services Every 6 Months By Optima Werkz. Contact Via SMS/CALL Only. No Whatsapp.	1 Owner, Very Well Ma ARF Of \$48174, Power Consumption On Par V White On Black Interic Maintain, Ideal For Sh Call Now To Appreciab House Loan Available. Plus Body. Call To Vie
COE	\$18,890	\$4,889	\$19,289	\$16,290
OMV	\$35,633	\$35,636	\$35,558	\$48,174
ARF	\$35,633	\$35,636	\$35,558	\$48,174
Depreciation	\$17,980 /yr	\$17,540 /yr	\$19,850 /yr	\$12,640 /yr
No. of Owners	2	3	1	1
Type of Vehicle	MPV	MPV	MPV	MPV
Category	PARF Car	PARF Car, Direct Owner Sale	PARF Car, Direct Owner Sale	PARF Car
Availability	Available	Available	Available	Available

SELLER INFORMATION

Seller	Euro-Asia Motor	Direct Owner	Direct Owner	Hua Hong Motoring
--------	-----------------	--------------	--------------	-------------------

View Sent Message

This mail is associated with :

***SLQ7203D (568716)
[SLS8746L]**

TP
CHIAM ISAAC SHER-WEN
Aug 28 2018 3:00PM
[YEO AI LING (YANG AILING)]
Hua Meng Spray Painting Workshop

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **31/08/2018 15:45 PM**.
To monica_chung@sg.msig-asia.com
CC sur@lkkauto.com
Subject **SLQ7203D (568716) [SLS8746L] TP**

Dear Monica,

Please be informed that we have inspected the vehicle SLQ 7203D on 30/08/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2018 12:19
Date Of Accident	28/08/2018 14:45
Exact Location Of Accident	YIO CHU KANG ROAD TOWARDS SERANGOON (LP:185)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ7203D
Insured/Policyholder	
Name Of Registered Owner	CHIAM ISAAC SHER-WEN
NRIC No	S8032296H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90693123
Alternative Phone No	OFFICE-90693123

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103398988
Cover Note Number	

Driver

Name of Driver	CHIAM ISAAC SHER-WEN
NRIC No	S8032296H
Date Of Birth	15/10/1980
Occupation	INDOOR
Date Of Driving Pass	07/04/2000
Driving Experience	18 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90693123
Fax Number	
Contact Number	OFFICE-90693123
Email Address	NOEMAIL

Address	34 MIMOSA DRIVE
Postcode	S805441
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG LANE 1 OF YIO CHU KANG ROAD TOWARDS SERANGOON ON 28.08.2018@ 1445HRS. SUDDENLY I HEARD A BANG SOUND AND FELT AN IMPACT FROM MY REAR. VEHICLE B WAS COLLIDED ONTO REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS8746L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary along lane 1 of Yio Chu Kang Road towards Serangoon on 28.08.2018 @ 1445hrs. Suddenly, I heard a bang sound and felt an impact from my rear. Vehicle B was collided onto rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

CHIAM ISSAC SHER-WEN
34 MIMOSA DRIVE
S 805441

TP MS16
Shirley

Date :14.09.2018
Vehicle no :SLQ 7203 D
Make/Model :TOYOTA ESTIMA
Accident date :28.08.2018

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>new</i>	1	\$ 100.2 ✓
2	Rear tailgate <i>Distorted</i>	1	\$ 1590.3 ✓
3	Rear tailgate hinges @ \$60.80 <i>not new</i>	2	\$ 121.6 x
4	Rear tailgate shock absorber @ \$277.20 <i>not new</i>	2	\$ 554.4 x
5	Rear tailgate upper lock <i>Damaged</i>	1	\$ 397.8 ✓
6	Rear tailgate lower lock <i>not new</i>	1	\$ 38.8 x
7	Rear tailgate inner board <i>cracked</i>	1	\$ 524.6 ✓
8	Rear tailgate inner handle	1	\$ 19.9 x
9	Rear tailgate centre reflector	1	\$ 197.2 x
10	Rear tailgate side reflector @ \$197.20	1	\$ 394.4 x
11	Rear tailgate centre logo <i>new</i>	1	\$ 73.4 ✓
12	Rear tailgate handle <i>not new</i>	1	\$ 171.8 x
13	Rear tailgate ESTIMA emblem <i>new</i>	1	\$ 48.5 ✓
14	Rear tailgate AERAS emblem	1	\$ 56.7 ✓
15	Rear tailgate weather strip <i>not</i>	1	\$ 358.3 ✓
16	Rear end panel <i>Distorted</i>	1	\$ 688 ✓
17	Rear end panel inner top garnish <i>deformed</i>	1	\$ 286.6 ✓
18	Rear end panel inner lower trim	1	\$ 193.8 ✓
19	Rear bumper <i>Distorted</i>	1	\$ 595.9 ✓
20	Rear bumper side holder @ \$57.10 <i>new</i>	2	\$ 114.2 ✓
21	Rear bumper reflector @ \$57.50 <i>not new</i>	2	\$ 115 x
22	Rear bumper towing hook cover @ \$20.20 <i>not new</i>	1	\$ 40.4 x
23	Rear bumper clips (1set) <i>new</i>	1	\$ 60.30
24	Rear bumper sponge @ \$70.20 <i>cracked</i>	2	\$ 140.4 ✓
25	Rear tailgate centre lock sensor <i>cracked</i>	1	\$ 146.7 ✓
26	Rear spare tyre top board <i>deformed</i>	1	\$ 1082.8 <i>655.20</i>
27	Rear spare tyre well <i>Repair</i>	1	\$ 805.9 x
28	Rear spare tyre well insulation @ \$226.80 <i>not new</i>	3	\$ 680.4 x
29	Rear spare tyre well trim <i>not new</i>	1	\$ 404.9 x
30	Rear fender inner garnish @ \$707.70 <i>cracked</i>	2	\$ 1415.4 ✓
			\$ 11418.3
			\$ 2854.58
			\$ 8563.72

7416
5562

Less 25% Disc
Total

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

CHIAM ISSAC SHER-WEN
34 MIMOSA DRIVE
S 805441

Date :14.09.2018
Vehicle no :SLQ 7203 D
Make/Model :TOYOTA ESTIMA
Accident date :28.08.2018

No	Description	Qty	Amount (\$\$)
----	-------------	-----	---------------

Special Nett Items

1	Rear bumper reverse sensor <i>changed</i>	1	\$ 380 ²⁰⁰
2	Rear tailgate camera <i>new</i>	1	\$ 800 ^x
	Tailgate Sound Insulation Pad <i>new</i>		
		Total	\$ 1180

Labour Cost

1	To supply soundproof sticker	\$ 480 ²⁰⁰
2	To supply rear windscreen sealant	\$ 50 ✓
3	To supply rear end panel inner sealant	\$ 200 ⁶⁰
4	Remove & reinstall rear windscreen	\$ 200 ¹²⁰
5	Remove & reinstall reverse sensor	\$ 200 ⁵⁰
6	Remove & reinstall boot lid inner garnish	\$ 200 ⁸⁰
7	Remove, replace & repair consistent to the accident	\$ 2000 ¹⁰⁰⁰
8	Respray painting	\$ 1600 ⁷⁰⁰
9	Tuff kote	\$ 150 ⁵⁰
10	Remove & reinstall rear camera	\$ 100 ⁴⁰
	Total	\$ 5180

Grand Total \$ 14923.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 8612
x/s 6-812
07 days

6-812

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018		30 Aug 2018 15:04 Edit Adj Rpt	S\$6,800.00 Edit Estimates	S\$6,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	YEO AI LING (YANG AILING) , ID: S7315833H, Tel: +6581215816								
Main Claimant:	CHIAM ISAAC SHER-WEN , ID: S8032296H								
Vehicle Reg. No.:	SLQ7203D	Date of Loss:	28/08/2018 15:00 - :59 [114 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 568716	Policy/Cover Note No.:	A29035052AVW (Comprehensive) Coverage: 10/10/2017 - 09/10/2018						
Vehicle Reg. No. (Insured):	SLS8746L	Policy No. (Claimant):							
		Excess:	S\$3,500.00						
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 31/08/2018]								
Driver/Custodian (Insured):	THOMAS JEREMY GOH KUO LIANG (), NRIC: S7132784A, Tel: +6597965319								
Adj Asg. Remarks:	LIABILITY 100%. TP AGREE WITH SJE - ASSIGN LKK AUTO CONSULTANTS PTE LTD.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ7203D (568716)
[SLS8746L]
TP
CHIAM ISAAC SHER-WEN
Aug 28 2018 3:00PM
[YEO AI LING (YANG AILING)]
Hua Meng Spray Painting Workshop

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		☐	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	30/08/18 09:19	Accident Statement From: SC - Reg. No: SLS8746L, Claimant: YEO AI LING (YANG AILING)					Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	(Draft)	Adjuster Immediate Advice					(Protected)		
Photos/Images						3 per page		☐	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	17/10/18 15:13	General View					Load JPG	☒	
2	17/10/18 15:13	General View					Load JPG	☒	
3	17/10/18 15:13	General View					Load JPG	☒	
4	17/10/18 15:13	General View					Load JPG	☒	
5	17/10/18 15:13	General View					Load JPG	☒	
6	17/10/18 15:13	General View					Load JPG	☒	
7	17/10/18 15:13	General View					Load JPG	☒	
8	17/10/18 15:13	General View					Load JPG	☒	
9	17/10/18 15:13	General View					Load JPG	☒	
10	17/10/18 15:13	General View					Load JPG	☒	
11	17/10/18 15:13	General View					Load JPG	☒	
12	17/10/18 15:13	General View					Load JPG	☒	
13	17/10/18 15:13	General View					Load JPG	☒	
14	17/10/18 15:13	General View					Load JPG	☒	
15	17/10/18 15:13	General View					Load JPG	☒	
16	17/10/18 15:13	General View					Load JPG	☒	
17	17/10/18 15:13	General View					Load JPG	☒	
18	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
19	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
20	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
21	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
22	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
23	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
24	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
25	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
26	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
27	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
28	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
29	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
30	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
31	17/10/18 15:13	Reinspection Photo					Load JPG	☒	
32	17/10/18 15:13	Reinspection Photo					Load JPG		

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	17/10/18 15:13	Reinspection Photo		☒
34	17/10/18 15:13	Reinspection Photo		☒
35	17/10/18 15:13	Reinspection Photo		☒
36	17/10/18 15:13	Reinspection Photo		☒
37	17/10/18 15:13	Reinspection Photo		☒
38	17/10/18 15:13	Reinspection Photo		☒
39	17/10/18 15:13	Reinspection Photo		☒
40	17/10/18 15:13	Reinspection Photo		☒
41	17/10/18 15:13	Reinspection Photo		☒
42	17/10/18 15:13	Reinspection Photo		☒
43	17/10/18 15:13	Reinspection Photo		☒
44	17/10/18 15:13	Reinspection Photo		☒
45	17/10/18 15:13	Reinspection Photo		☒
46	17/10/18 15:13	Reinspection Photo		☒
47	17/10/18 15:13	Reinspection Photo		☒
48	17/10/18 15:13	Reinspection Photo		☒
49	17/10/18 15:13	Reinspection Photo		☒
50	17/10/18 15:13	Reinspection Photo		☒
51	17/10/18 15:13	Reinspection Photo		☒
52	17/10/18 15:13	Reinspection Photo		☒
53	17/10/18 15:13	Reinspection Photo		☒
54	17/10/18 15:13	Reinspection Photo		☒
55	17/10/18 15:13	Reinspection Photo		☒
56	17/10/18 15:13	Reinspection Photo		☒
57	17/10/18 15:13	Reinspection Photo		☒
58	17/10/18 15:13	Reinspection Photo		☒
59	17/10/18 15:13	Reinspection Photo		☒
60	17/10/18 15:13	Reinspection Photo		☒
61	17/10/18 15:13	Reinspection Photo		☒
62	17/10/18 15:13	Reinspection Photo		☒
63	17/10/18 15:13	Reinspection Photo		☒
64	17/10/18 15:13	Reinspection Photo		☒
65	17/10/18 15:13	Reinspection Photo		☒
66	17/10/18 15:13	Reinspection Photo		☒
67	17/10/18 15:13	Reinspection Photo		☒
68	17/10/18 15:13	Reinspection Photo		☒
69	17/10/18 15:13	Reinspection Photo		☒
70	17/10/18 15:13	Reinspection Photo		☒
71	17/10/18 15:13	Reinspection Photo		☒
72	17/10/18 15:13	Reinspection Photo		☒
73	17/10/18 15:13	Reinspection Photo		☒
74	17/10/18 15:13	Reinspection Photo		☒
75	17/10/18 15:13	Reinspection Photo		☒
76	17/10/18 15:13	Reinspection Photo		☒
77	17/10/18 15:13	Reinspection Photo		☒
78	17/10/18 15:13	Reinspection Photo		☒
79	17/10/18 15:13	Reinspection Photo		☒
80	17/10/18 15:13	Reinspection Photo		☒
81	17/10/18 15:13	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
82	17/10/18 15:13	Reinspection Photo		☒
83	17/10/18 15:13	Reinspection Photo		☒
84	17/10/18 15:13	Reinspection Photo		☒
85	17/10/18 15:13	Reinspection Photo		☒
86	17/10/18 15:13	Reinspection Photo		☒
87	17/10/18 15:13	Reinspection Photo		☒
88	17/10/18 15:13	Reinspection Photo		☒
89	17/10/18 15:13	Reinspection Photo		☒
90	17/10/18 15:13	Reinspection Photo		☒
91	17/10/18 15:13	Reinspection Photo		☒
92	17/10/18 15:13	Reinspection Photo		☒
93	17/10/18 15:13	Reinspection Photo		☒
94	17/10/18 15:13	Reinspection Photo		☒
95	17/10/18 15:13	Reinspection Photo		☒
96	17/10/18 15:13	Reinspection Photo		☒
97	17/10/18 15:13	Reinspection Photo		☒
98	17/10/18 15:13	Reinspection Photo		☒
99	17/10/18 15:13	Reinspection Photo		☒
100	17/10/18 15:13	Reinspection Photo		☒
101	17/10/18 15:13	Reinspection Photo		☒
102	17/10/18 15:13	Reinspection Photo		☒
103	17/10/18 15:13	Reinspection Photo		☒
104	17/10/18 15:13	Reinspection Photo		☒
105	17/10/18 15:13	Reinspection Photo		☒
106	17/10/18 15:13	Reinspection Photo		☒
107	17/10/18 15:13	Reinspection Photo		☒
108	17/10/18 15:13	Reinspection Photo		☒
109	17/10/18 15:13	Reinspection Photo		☒
110	17/10/18 15:13	Reinspection Photo		☒
111	17/10/18 15:13	Reinspection Photo		☒
112	17/10/18 15:13	Reinspection Photo		☒
113	17/10/18 15:13	Reinspection Photo		☒
114	17/10/18 15:13	Reinspection Photo		☒
115	17/10/18 15:13	Reinspection Photo		☒
116	17/10/18 15:13	Reinspection Photo		☒
117	17/10/18 15:13	Reinspection Photo		☒
118	17/10/18 15:13	Reinspection Photo		☒
119	17/10/18 15:13	Reinspection Photo		☒
120	17/10/18 15:14	Reinspection Photo		☒
121	17/10/18 15:14	Reinspection Photo		☒
122	17/10/18 15:14	Reinspection Photo		☒
123	17/10/18 15:14	Reinspection Photo		☒
124	17/10/18 15:14	Reinspection Photo		☒
125	17/10/18 15:14	Reinspection Photo		☒
126	17/10/18 15:14	Reinspection Photo		☒
127	17/10/18 15:14	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/08/18 09:19	TP PRI Notice		☐
2	30/08/18 09:20	SLQ7203D E-FILE REPORT		☐

Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
3	30/08/18 12:40	MSIG Insurance (Singapore) Pte. Ltd. (HQ) tp agree SJE - assign LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18015915/GSD3Q2

Date: 26/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29035052AVW

Claimant Vehicle No: SLQ7203D

Insured Vehicle No: SLS8746L

Date of Loss: 28/08/2018

Nature of Claim: TP

Claim No: 568716

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ7203D

Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A)

Engine No: 2AZC494821

Reg. Date: 11/02/2009 (Man. Year: 2008)

Chassis No: ACR500080809

Colour: Black

Odometer: 103554 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 R20

Rear Tyre Size: 245/35 R20

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,223.72	6,062.00	4,161.72	40.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,180.00	2,550.00	2,630.00	50.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,403.72	8,612.00	6,791.72	44.09
Approved Total (Overridden) (S\$)		6,800.00		
Nett Amount (S\$)	15,403.72	6,800.00	8,603.72	55.85

INSPECTION

Date of Assignment: 30/08/2018

Date Inspected: 30/08/2018 Inspected At:

Hua Meng Spray Painting Workshop (HQ)

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2018)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ7203D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN RUBBER	Necessary	100.20 FL	*100.20 FL
2	1		*REAR TAILGATE	Distorted	1,590.30 FL	*1,590.30 FL
3	2		*REAR TAILGATE HINGES	Not Necessary	121.60 FL	*- FL
4	2		*REAR TAILGATE SHOCK ABSORBER	Not Necessary	554.40 FL	*- FL
5	1		*REAR TAILGATE UPPER LOCK	Damaged	397.80 FL	*397.80 FL
6	1		*REAR TAILGATE LOWER LOCK	Not Necessary	38.80 FL	*- FL
7	1		*REAR TAILGATE INNER BOARD	Cracked	524.60 FL	*524.60 FL
8	1		*REAR TAILGATE INNER HANDLE	Not Necessary	19.90 FL	*- FL
9	1		*REAR TAILGATE CENTRE REFLECTOR	Not Necessary	197.20 FL	*- FL
10	1		*REAR TAILGATE SIDE REFLECTOR	Not Necessary	394.40 FL	*- FL
11	1		*REAR TAILGATE CENTRE LOGO	Necessary	73.40 FL	*73.40 FL
12	1		*REAR TAILGATE HANDLE	Not Necessary	171.80 FL	*- FL
13	1		*REAR TAILGATE ESTIMA EMBLEM	Necessary	48.50 FL	*48.50 FL
14	1		*REAR TAILGATE AREAS EMBLEM	Necessary	56.70 FL	*56.70 FL
15	1		*REAR TAILGATE WEATHER STRIP	Cut	358.30 FL	*358.30 FL
16	1		*REAR END PANEL	Distorted	688.00 FL	*688.00 FL
17	1		*REAR END PANEL INNER TOP GARNISH	Deformed	286.60 FL	*286.60 FL
18	1		*REAR END PANEL INNER LOWER TRIM	Deformed	193.80 FL	*193.80 FL
19	1		*REAR BUMPER	Distorted	595.90 FL	*595.90 FL
20	2		*REAR BUMPER SIDE HOLDER	Necessary	114.20 FL	*114.20 FL
21	2		*REAR BUMPER REFLECTOR	Not Necessary	115.00 FL	*- FL
22	1		*REAR BUMPER TOWNG HOOK COVER	Not Necessary	40.40 FL	*- FL
23	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
24	2		*REAR BUMPER SPONGE	Cracked	140.40 FL	*140.40 FL
25	1		*REAR TAILGATE CENTRE LOCK SENSOR	Cracked	146.70 FL	*146.70 FL
26	1		*REAR SPARE TYRE TOP BOARD	Deformed	1,082.80 FL	*655.20 FL
27	1		*REAR SPARE TYRE WELL	Repair	805.90 FL	*- FL
28	3		*REAR SPARE TYRE WELL INSULATION	Not Necessary	680.40 FL	*- FL
29	1		*REAR SPARE TYRE WELL TRIM	Not Necessary	404.90 FL	*- FL
30	2		*REAR FENDER INNER GARNISH	Cracked	1,415.40 FL	*1,415.40 FL
31	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
32	1		*REAR TAILGATE CAMERA	Not Necessary	800.00 FS	*- FS
33	1		*TAILGATE SOUND INSULATION PAD	Necessary	480.00 FS	*300.00 FS

F=Franchise part, S=SpchNett, L=ListItemDisc

Sub Total (S\$)	13,078.30	7,916.00
- List Item Discount on L Items 25.00/25.00% (S\$)	2,854.58	1,854.00
Total Parts (S\$)	10,223.72	6,062.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY SOUNDPROOF STICKER	New	480.00	200.00
2	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	50.00
3	TO SUPPLY REAR END PANEL INNER SEALANT	New	200.00	60.00
4	REMOVE & REINSTALL REAR WINDSCREEN	New	200.00	120.00
5	REMOVE & REINSTALL REVERSE SENSOR	New	200.00	50.00
6	REMOVE & REINSTALL BOOT LID INNER GARNISH	New	200.00	80.00
7	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	2,000.00	1,000.00
8	RESPRAY PAINTING	New	1,600.00	900.00
9	TUFF KOTE	New	150.00	50.00
10	REMOVE & REINSTALL REAR CAMERA	New	100.00	40.00
Gross Labour Cost (S\$)			5,180.00	2,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >