

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 31 Aug 2018

Preliminary Advice

Insured Vehicle No : SLN2741R

TP Vehicle No : SJP9295D

Make : TOYOTA CAMRY

Date of Inspection : 30/08/2018

Inspection At : Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Accident Date : 28/08/2018

Assignment Date : 31/08/2018

Est. Duration of Repair : 4 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,427.88
Revised Amount	:S\$	4,169.00
Check Items (Estimated)	:S\$	619.35
Total	:S\$	4,788.35

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.