

3/20/2002

ASS. REC. BY:

REF: CS/MSG18015917/Kod3er Special Instruction:

SURVEYOR

From (Person):

Kenneth
Irene Tan

ASSIGNMENT (Office)

of MSG

Date/Time: 3/18/18 @ 9:46am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIP 9295D

Insured:

SLN 2714R

at Workshop m/s

Alan's United

Tel:

6453 8686

of

Blk 7, Sin Ming Ind. Est #01-76

Policy No:

A28949243AVW

Claim No:

568760

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 28/08/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9:53am @ 3/18/18

Person Contacted:

Kenny

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SIP 9295D - x

SLN 2714R - x

3/18/18

@ 15:51 p.m. revised IA to Irene Tan via messenger.

ASS. REC. BY:

REF: *MSK/*

ASSIGNMENT

STP 92950

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *8 22k*

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *04* days

Res.: Yes or No

Lum Sum: *20* %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SKC 58742*Yr Regn: *04 09*Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Toy Camry*c.c. *2.362*Colour: *M. Green*

A/C: Insured / Std / NI / NA

Sp. Reading *192206*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *NR053BK 4007033487*Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: *215/60R16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. *5* mmR/Bal. *4* mmL/Bal. *5* mmL/Bal. *4* mmD.O.A. *28/4/18*D.O.I. *30/8/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S/B

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*31/8**File pass to Gathang MWP**05/09/18**Parts Price checked by Kenneth**Confirmed L/S \$3,300/- @ 4 days with Kenneth*
(\$3,127.88 Red - 49%)

RECEIVED 7 SEP 2018

Date/Time, File Pass to?

07/09/18☐ : Prel. ReportDays Of Repair: *4*Resurvey No. of Trip: *1*Survey Fee: *150*

Transportation: _____

S + RS. \$ _____

Photos *10*

Others _____

TOTAL *160*1) *Typist*

Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I: (\$ *3,300/-* L/S)Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Aug 2018		31 Aug 2018 09:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	DR LOW CHENG OOI, ID: S1184917B, Tel: +6596357315, Email: CHENGOOILOW@MSN.COM		
Main Claimant:	BOND M & E PTE LTD, Co. Reg. No.: 198100907H		
Vehicle Reg. No.:	SJP9295D	Date of Loss:	28/08/2018 16:00 - :59 [112 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568760	Policy/Cover Note No.:	A28948243AVW (Comprehensive) Coverage: 27/04/2018 - 26/04/2019
Vehicle Reg. No. (Insured):	SLN2741R	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76, 575642 Sin Ming - Tel: 6453 8686		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/09/2018]		
Driver/Custodian (Insured):	DR LOW CHENG OOI (62 / Male), NRIC: S1184917B, Tel: +6596357315		
Adj Asg. Remarks:	on WP, LIABILITY : 100% Please appoint MR KENNETH KONG from LKK AUTO to conduct the survey . Kindly contact MR KENNY @ 6453 8686 to arrange for survey .		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18015917/Ksd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 31-08-2018



Code : MSG

1.

Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLN 2714R	Veh. Inspected	SJP 9295D
Policy No.	A28948243AVW	Coverage (\$)	0.00
Claim No.	568760	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	31/08/2018

2.

Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

--

5.

General Information

Accident Date	28/08/2018	Inspection Date	30/08/2018
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a.

Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0907H
Vehicle Details	
Vehicle No.:	SJP9295D
Vehicle to be Exported:	No
Intended De-registration Date:	31 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.4 AUTO ABS AIRBAG
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	2AZE131625
Chassis No.:	MR053BK4007033487
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$27,844.00
Original Registration Date:	17 Apr 2009
First Registration Date:	17 Apr 2009
Transfer Count:	2
Actual ARF Paid:	\$27,844.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Apr 2019
PARF Rebate Amount:	\$13,922.00
Intended COE Rebate Details	
COE Expiry Date:	16 Apr 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$7,501.00
COE Rebate Amount:	\$470.00
Total Rebate Amount:	\$14,392.00
Message	

The information contained herein is correct as at 31 Aug 2018

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 31 Aug 2018

Preliminary Advice

Insured Vehicle No	: SLN2741R	Accident Date	: 28/08/2018
TP Vehicle No	: SJP9295D	Assignment Date	: 31/08/2018
Make	: TOYOTA CAMRY	Est. Duration of Repair	: 4 days
Date of Inspection	: 30/08/2018		
Inspection At	: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,427.88
Revised Amount	:S\$	4,169.00
Check Items (Estimated)	:S\$	619.35
Total	:S\$	4,788.35

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2018 18:05
Date Of Accident	28/08/2018 17:05
Exact Location Of Accident	MAPLETREE BUILDING CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJP9295D
Insured/Policyholder	
Name Of Registered Owner	BOND M & E PTE LTD
Co Reg No	198100907H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67411968

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1620051802
Cover Note Number	

Driver

Name of Driver	WONG YOKE SEONG
NRIC No	S2680065Z
Date Of Birth	14/08/1985
Occupation	OUTDOOR
Date Of Driving Pass	06/03/2000
Driving Experience	18 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97898828
Fax Number	
Contact Number	
Email Address	BEPL@BONDGRP.NET

Address	BLK 169A PUNGGOL FIELD #13-689
Postcode	821169
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN2741R
Vehicle Make/Model/Colour	VOLSWAGEN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LOW CHENG OOI
NRIC/Passport Number	S1184917B
Contact Number	96357315
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:
2-9 AUG 2018


Driver's Signature
(If driver is not the policyholder)
Date & Time:

2-9 AUG 2018

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.: **Jenny Lim
S6927273H**

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 18/8/2018 AT ABOUT 1700 HRS, I WAS DRIVING ALONG THE COMPOUND SERVICE RD GOING TO EXIT FROM THE COMPOUND. WHILE DRIVING, VEHICLE SLN 3241R SUDDENLY DASH OUT FROM PARKING LOT WITHOUT CHECKING TRAFFIC. HEAVY HIS VEHICLE FROM COLLIDING INTO MY VEHICLE. AFTER THE ACCIDENT WE EXCHANGE INFORMATION FOR INSURANCE CLAIM. NO ONE WAS INJURED.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

2-9 AUG 2018
GIARMC Sketch Plan Form V3

Driver's Signature
(If driver is not the policyholder)
Date & Time:

2-9 AUG 2018

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:

Jenny Lim
S6927273H



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Co Reg No. 200208384E

MX4F
R SN
AN0044A
Cov.Type: C

MOTOR PRIVATE CAR

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE No.	DMPCSN1620051802	Engine No :2AZE131625 ChaNo:MR053BK4007033487
1. Index Mark and Registration Number of Vehicle	SJP9295D	AUTOSAFE =====
2. Name of Policy Holder	M/S BOND M & E PTE LTD	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	17 April 2018	Named Drivers Ex Sect. I S\$1,500.00 Additional Ex Other than Named Drivers: Ex Sect. I - Age <= 25..... S\$3,000.00 Ex Sect. I - Age >= 26..... S\$500.00 * Age as at date of accident EX ON WINDSCREEN S\$100.00
4. Date of Expiry of Insurance	16 April 2019	
5. Persons or Classes of Persons entitled to drive*		

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use:*

Use for social, domestic and pleasure purposes and for the Policyholder's business.
The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled.

One time Waiver of Excess for the first S\$500 will apply to the Insured and Named Drivers in the event

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: TAN NGEE LING EILEEN
Authorised Officer

Authorised Signatory

Transaction ref 20140124121031644166

The owner and vehicle particulars for Vehicle No. SJP9295D as at 24 Jan 2014 are as follows:

1.	Name	: BOND M & E PTE LTD
2.	Identification No. Type	: Company
3.	Identification No.	: 198100907H
4.	Place Of Passport Issue	: -
5.	Vehicle No.	: SJP9295D
6.	Previous Vehicle No.	: -
7.	Effective Date of Ownership	: 24 Jan 2014
8.	Original Registration Date	: 17 Apr 2009
9.	First Registration Date	: 17 Apr 2009
10.	Vehicle Type	: N18 - Passenger (Co) Company Car (Single Rate)
11.	Vehicle Scheme	: Normal
12.	Attachment 1	: No Attachment
13.	Attachment 2	: -
14.	Attachment 3	: -
15.	Vehicle Make	: TOYOTA
16.	Vehicle Model	: CAMRY 2.4 AUTO ABS AIRBAG
17.	Year of Manufacture	: 2009
18.	Primary Colour	: Silver
19.	Secondary Colour	: -
20.	Passenger Capacity	: 4
21.	Chassis/Trailer Chassis No.	: MR053BK4007033487 / -
22.	Propellant	: Petrol
23.	Engine No./Motor No.	: 2AZE131625 / -
24.	Engine Capacity(cc)/Power Rating(kW)	: 2362 / -
25.	Maximum Power Output(kW/bhp)	: 123.0 / 164
26.	Unladen Weight(kg)	: 1540
27.	Maximum Laden Weight(kg)	: 1970
28.	Open Market Value	: \$27,844.00
29.	PARF Eligibility	: Yes
30.	PARF Eligibility Expiry Date	: 16 Apr 2019
31.	Minimum PARF Benefit	: \$13,922.00
32.	No. of Transfers	: 2
33.	IU Label No.	: 1122942146
34.	COE No.	: 2009050103000391D
35.	COE Expiry Date	: 16 Apr 2019
36.	COE Category	: B - Car (1601cc & above)
37.	Quota Premium/Prevailing Quota Premium	: \$7,501.00 / -
38.	Actual Quota Premium/PQP Paid	: \$7,501.00
39.	Actual ARF Paid	: \$27,844.00
40.	CO2 Emission(g/km)	: -
41.	Actual CEVS Rebate Utilised	: -
42.	CEVS Surcharge Paid	: -
43.	Actual Green Vehicle Rebate Utilised	: -
44.	Vehicle Lifespan Expiry Date	: -
45.	Road Tax Amount	: -
46.	Road Tax Start Date	: -
47.	Road Tax End Date	: -
48.	Remarks	: To renew the COE, the Prevailing Quota Premium payable is that of Category B. This vehicle is eligible for PARF.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05843

Date : 30-Aug-2018

PAGE : 1

Vehicle Insured : SLN2741R
Accident Date : 28-Aug-2018

Our Ref : 218149 (MSIG) / CHAN

BOND M & E PTE LTD
NO.35 KAKI BUKIT VIEW
KAKI BUKIT TECH PARK II
Singapore 415966

Not Withheld
1/1 Sy & ?
Resurvey After Point
4 days
31/8/18

ESTIMATED COST OF REPAIR FOR TOYOTA CAMRY 2.4 SJP9295D

1 pc	Front n/s fender	B	737.30	—
1 pc	Front n/s fender inner shield	CM	141.80	—
6 pcs	N/s fender inner shield clip @ S\$ 3.80	CM	22.80	—
1 pc	Front n/s fender inner panel	R	667.20	X
1 pc	N/s headlamp	CM	2,748.30	—
1 pc	Front bumper fascia	R	486.70	—
1 pc	Front n/s bumper side retainer	D	50.10	—
1 pc	Front n/s foglamp		266.90	X SVC
1 pc	Front n/s foglamp cover	D	43.10	—
1 pc	Front n/s bumper chrome	CM	101.90	—
1 pc	Front bumper reinforcement		421.70	? X R
1 pc	Front bumper sponge		97.20	? X SVC
1 pc	Radiator support panel	R	905.50	X
			6,690.50	
		Less 25% :	1,672.62	

1 pc Radiator coolant

5,017.88

CM X 30.00 sn

To rewire damaged parts and refocus headlamp beam.

80.00 201

To putty and spray replaced parts

600.00 5002

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

700.00 4001

Total : S\$ 6,427.88

Singapore Dollars Six Thousand Four Hundred and Twenty Seven and Cents Eighty Eight Only

LKK Auto Consultants hence notify the insurer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLN2741R
Accident Date : 28-Aug-2018

No. : 05843

Date : 30-Aug-2018

Our Ref : 218149 (MSIG) / CHAN

PAGE : 1

BOND M & E PTE LTD
NO.35 KAKI BUKIT VIEW
KAKI BUKIT TECH PARK II
Singapore 415966

*Not Withheld
1/1 Sy @ 3300
Reserve After Point 4000*

ESTIMATED COST OF REPAIR FOR TOYOTA CAMRY 2.4 SJP9295D

1 pc Front n/s fender					
1 pc Front n/s fender inner shield					
6 pcs N/s fender inner shield clip	@ S\$ 3.80				
1 pc Front n/s fender inner panel					
1 pc N/s headlamp					
1 pc Front bumper fascia					
1 pc Front n/s bumper side retainer					
1 pc Front n/s foglamp					
1 pc Front n/s foglamp cover					
1 pc Front n/s bumper chrome					
1 pc Front bumper reinforcement					
1 pc Front bumper sponge					
1 pc Radiator support panel					

R	737.30	—
CM	141.80	—
M	22.80	—
R	667.20	X
CM	2,748.30	—
R	486.70	—
D	50.10	—
J	266.90	X
D	43.10	—
N	101.90	—
R	421.70	X
R	97.20	X
R	905.50	X

Less 25% : 1,672.62

*4332.00
1083.00
3249.00*

1 pc Radiator coolant

To rewire damaged parts and refocus headlamp beam.

To putty and spray replaced parts

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

*5,017.88
30.00 sn
80.00 201
600.00 5002
700.00 4001*

Total : S\$ 6,427.88

Singapore Dollars Six Thousand Four Hundred and Twenty Seven and Cents Eighty Eight Only

*1/1 sum
3300.00 ✓ ok*

*3249.00
920.00
4169.00
833.80
3335.20*

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Aug 2018		31 Aug 2018 09:46 Edit Adj Rpt	S\$3,300.00 Edit Estimates	S\$3,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: DR LOW CHENG OOI , ID: S1184917B, Tel: +6596357315, Email: CHENGOOILOW@MSN.COM									
Main Claimant: BOND M & E PTE LTD , Co. Reg. No.: 198100907H									
Vehicle Reg. No.:	SJP9295D	Date of Loss:	28/08/2018 16:00 - :59 [112 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 568760	Policy/Cover Note No.:	A28948243AVW (Comprehensive) Coverage: 27/04/2018 - 26/04/2019						
Vehicle Reg. No. (Insured):	SLN2741R	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76, 575642 Sin Ming - Tel: 6453 8686								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/09/2018]								
Driver/Custodian (Insured):	DR LOW CHENG OOI (62 / Male), NRIC: S1184917B, Tel: +6596357315								
Adj Asg. Remarks:	on WP. LIABILITY : 100% Please appoint MR KENNETH KONG from LKK AUTO to conduct the survey . Kindly contact MR KENNY @ 6453 8686 to arrange for survey .								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJP9295D (568760)**
[SLN2741R]
TP
BOND M & E PTE LTD
Aug 28 2018 4:00PM
[DR LOW CHENG OOI]
Alan's United Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	30/08/18 15:29	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement From:OD - Reg. No: SLN2741R, Claimant: LOW CHENG OOI		Load HTM	
1	31/08/18 15:51	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
1	07/09/18 10:24	LKK Auto Consultants Pte Ltd (HQ) General View		Load JPG	<input checked="" type="checkbox"/>
2	07/09/18 10:24	General View		Load JPG	<input checked="" type="checkbox"/>
3	07/09/18 10:24	General View		Load JPG	<input checked="" type="checkbox"/>
4	07/09/18 10:24	General View		Load JPG	<input checked="" type="checkbox"/>
5	07/09/18 10:24	General View		Load JPG	<input checked="" type="checkbox"/>
6	07/09/18 10:24	General View		Load JPG	<input checked="" type="checkbox"/>
7	07/09/18 10:24	General View		Load JPG	<input checked="" type="checkbox"/>
8	07/09/18 10:24	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
9	07/09/18 10:24	General View		Load JPG	<input checked="" type="checkbox"/>
10	07/09/18 10:24	General View		Load JPG	<input checked="" type="checkbox"/>
11	07/09/18 10:24	General View		Load JPG	<input checked="" type="checkbox"/>
12	07/09/18 10:24	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
13	07/09/18 10:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
14	07/09/18 10:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	30/08/18 15:34	MSIG Insurance (Singapore) Pte. Ltd. (HQ) TPD SJP9295D GIA REPORT		Load PDF	
2	30/08/18 15:34	TPD SJP9295D - ESTIMATE REPAIR		Load PDF	
3	30/08/18 15:34	TPD SJP9295D - PRI		Load PDF	
4	30/08/18 15:50	Reply email to TP Workshop & appoint KENNETH KONG from LKK AUTO		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> <div></div> <div> </div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18015917/KSD3E2

Date: 07/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28948243AVW

Claimant Vehicle No : SJP9295D

Insured Vehicle No : SLN2741R

Date of Loss: 28/08/2018

Nature of Claim: TP

Claim No: 568760

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJP9295D

Make & Model: TOYOTA CAMRY, 2.4 ABS AIRBAG (A)

Engine No: 2AZE131625

Reg. Date: 17/04/2009 (Man. Year: 2009)

Chassis No: MR053BK4007033487

Colour: Metallic Green

Odometer: 192206 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size: 215/60R16

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,047.87	3,249.00	1,798.87	35.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	920.00	460.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,427.87	4,169.00	2,258.87	35.14
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	6,427.87	3,300.00	3,127.87	48.66
+ GST 7.00/7.00% (S\$)	449.95	231.00	218.95	48.66
Nett Amount (S\$)	6,877.82	3,531.00	3,346.82	48.66

INSPECTION

Date of Assignment: 31/08/2018

Date Inspected: 30/08/2018 Inspected At:

Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Sep 2018)
Parts: 143	TOYOTA CAMRY 2.4 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP9295D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S FENDER	Bent	737.30 FL	*737.30 FL
2	1		*FRONT N/S FENDER INNER SHIELD	Cracked	141.80 FL	*141.80 FL
3	6		*N/S FENDER INNER SHIELD CLIP	Necessary	22.80 FL	*22.80 FL
4	1		*FRONT N/S FENDER INNER PANEL	Repair	667.20 FL	*- FL
5	1		*N/S HEADLAMP	Cracked	2,748.30 FL	*2,748.30 FL
6	1		*FRONT BUMPER FASCIA	Bent	486.70 FL	*486.70 FL
7	1		*FRONT N/S BUMPER SIDE RETAINER	Distorted	50.10 FL	*50.10 FL
8	1		*FRONT N/S FOGLAMP	Serviceable	266.90 FL	*- FL
9	1		*FRONT N/S FOGLAMP COVER	Distorted	43.10 FL	*43.10 FL
10	1		*FRONT N/S BUMPER CHROME	Dented	101.90 FL	*101.90 FL
11	1		*FRONT BUMPER REINFORCEMENT	Repair	421.70 FL	*- FL
12	1		*FRONT BUMPER SPONGE	Serviceable	97.20 FL	*- FL
13	1		*RADIATOR SUPPORT PANEL	Repair	905.50 FL	*- FL
14	1		*RADIATOR COOLANT	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,720.50	4,332.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,672.63	1,083.00
Total Parts (\$\$)	5,047.87	3,249.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM	New	80.00	20.00
2	TO PUTTY AND SPRAY REPLACED PARTS	New	600.00	500.00
3	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	700.00	400.00
Gross Labour Cost (\$\$)			1,380.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >