



張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)

Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16

Singapore 079120

Tel: 64193000

Fax: 68357416

DATE: 28.08.2018

ABDUL ISMAIL BIN SIMIN

RE: FP500T YAMAHA TMAX530

ACCIDENT ON 20.07.2018 AT TUAS CHECKPOINT MALAYSIA

The damages are:

1 FRONT FORK ASSY RH		\$ 750.00	✓
2 FRONT FORK ASSY LH		\$ 750.00	✓
3 UNDERBRACKET COMP		\$ 375.00	✓
4 BOARD FOOTREST (1)	500	\$ 97.50	✓
5 PANEL CONSOLE (1)	cm	\$ 67.50	✓
6 BOARD FOOTREST (2)	cre	\$ 97.50	✓
7 DAMPER PLATE	ms	\$ 5.00	✓
8 DAMPER PLATE	ms	\$ 12.00	✓
9 PANEL CONSOLE (2)	cm	\$ 67.50	✓
10 MAT (3)	hand	\$ 18.00	✓
11 MAT (4)	11	\$ 18.00	X
12 DUCT AIR	cm	\$ 37.50	✓
13 FENDER INNER (2)		\$ 52.50	?
14 LEG SHIELD (1)	cm	\$ 120.00	✓
15 LID		\$ 15.00	✓
16 LID ASSY		\$ 75.00	✓
17 BOX ASSY		\$ 45.00	✓
18 MOLE (1)		\$ 72.00	✓
19 MOLE (2)		\$ 72.00	✓
20 PANEL (1)	cm	\$ 97.50	✓
21 EMBLEM	2 PCS	\$ 45.00	✓
22 PANEL (2)	cm	\$ 97.50	✓
23 COVER	ms	\$ 27.00	✓
24 PLATE PROTECTOR (2)	cm	\$ 45.00	✓
25 PROTECTOR MUFFLER (1)	cm	\$ 60.00	✓
26 PROTECTOR MUFFLER (3)	Dis	\$ 105.00	✓

Not Allowed
LKR
2/53
5 day.
31/8/18
The Mr. Affinity

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

27 STAY	(1)		\$	27.00	?
28 HEADLIGHT ASSY			\$	960.00	—
29 FENDER FRONT			\$	75.00	—
30 STAY FENDER	(1)		\$	22.50	—
31 STAY FENDER	(2)		\$	22.50	—
32 FENDER FRONT	(2)		\$	27.00	?
33 HANDLE COMP			\$	67.50	?
34 BALANCER			\$	22.50	✓
35 CAP HANDLEBAR COVER			\$	60.00	?
36 COVER HANDLE UPPER (2)			\$	15.00	?
37 COVER HANDLE UPPER (1)			\$	15.00	?
38 CAP COVER HANDLE (2)			\$	37.50	?
39 PANEL INNER	(1)		\$	42.00	?
40 BODY COWLING	LH		\$	180.00	—
41 BODY COWLING	RH		\$	195.00	—
42 PANEL INNER	(2)		\$	52.50	—
43 COVER FRONT			\$	112.50	—
44 SCREEN			\$	240.00	—
45 REAR VIEW MIRROR ASSY	LH		\$	75.00	—
46 REAR VIEW MIRROR ASSY	RH		\$	75.00	—
47 SIDE COVER	LH		\$	105.00	—
48 COVER SIDE	(3)		\$	120.00	—
49 MOLE SIDE COVER	(1)		\$	82.50	?
50 SIGNAL LIGHT FRONT			\$	90.00	?
51 MAINSTAND			\$	180.00	X
52 INNER SIDE COVER LH			\$	22.50	?

SUB TOTAL \$ 6,147.50
LESS 10% \$ 614.75
SUB TOTAL \$ 5,532.75

ADD NETT

1 LABOUR	\$	600.00	450
2 NUMBER PLATE	\$	30.00	10
3 SPRAY		KIV	?

Total

7 6162

PG 2
FP500T