

REPAIR ESTIMATE*

VEHICLE NO : SHC 8264S

DATE 30/8/2018 15:40

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (RH) <i>— Part</i>			\$ 619.00
	Front Fender Shield (RH) <i>X 500</i>			\$ 169.80
	Front Fender Retainer <i>X 200</i>			\$ 9.20
	Front Door (RH) <i>— Part</i>			\$ 2,256.40
	Front Door Mirror (RH) <i>X 450</i>			\$ 980.50
	SUB TOTAL			\$ 4,034.90
	LESS 20%			\$ 806.98
	DISCOUNTED TOTAL			\$ 3,227.92
	Front Door Comfort Logo (RH) <i>— 200</i>			\$ 75.00
	Labour Charge			
	Panel Beating			\$ 560.00 <i>400</i>
	Spray Painting Charge			\$ 650.00 <i>450</i>
	Wiring Charge			\$ 50.00 <i>X 77</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Transfer of Door			\$ 120.00 <i>50</i>
	TOTAL LABOUR			\$ 1,430.00
	ESTIMATE TOTAL			\$ 4,732.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalvin Ucky
30/8/18 1605hr
20/11
45
Alvin Rajapala

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.