

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 10 Sep 2018

## **Preliminary Advice**

Insured Vehicle No : XD575C  
TP Vehicle No : SHC795D  
Make : Hyundai I40  
Date of Inspection : 01/09/2018  
Inspection At : Soon Hock Motor Pte Ltd (HQ)  
Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint  
Singapore 568047

Accident Date : 28/08/2018  
Assignment Date : 30/08/2018  
Est. Duration of Repair : 10 days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,283.38
Revised Amount	:S\$	15,117.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,117.88

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Survey Report - TP - WP