

21/02/2002

ASS. REC. BY:

REF:

CS/AIG18015961/Ksd3et

Special Instruction:

Survivor:

Mehmen

Kenneth

ASSIGNMENT (Office)

From (Person):

Mithoo Singh

of

AIG

Date/Time:

31/8/18 @ 3:39pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 6333H

Insured:

SLF 2835X

at Workshop m/s

TKB Motor Repairs

Tel:

6458 0296

of

Blk 160 Sin Ming Drive # 08-03

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/8/18

CA / REV / REP. / REV 24 HRS

(up)

3/9/18

H.O.D. Endorsement:

Date/Time:

4:28pm @ 31/8/18

Person Contacted:

Judy

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SKZ 6333H - X

SLF 2835X - X

28/10 61Ln 817k email

1/11 Mr Tay don't open on 61Ln offer, will pass case to lawyer
61Ln 817k email re: Mr. Tay

ASS. REC. BY:

REF:

A/G /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

T&B

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

834k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

26

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1'22

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

4/9

File pass to Catherine, est not ready

19/11

M Toy asking for UIC & 20k

20/11/18

Confirmed HS \$17,800 @ 26 days.

MV - \$34k

LTA - \$17,751.00

Nett - \$17,249.00

Veh No:

SKZ633314

Yr Regn:

01, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A) MPV

Make:

Toy Etamp

c.c

2362

Colour:

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

135260

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

ACR50

0006805

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modl:

Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/8/18

D.O.I.

3/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 20 NOV 2018

file pass back to handler

RECEIVED 14 DEC 2018

receive file from handler

Date/Time, File Pass to?

20/11/18

☐ : Prell. Report

1)

Typist

☒ : Final Report

Date/Time, File Return to?

Days Of Repair:

26

Resurvey No. of Trlp:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

250

Transportation:

S + RS, SI

Photos

Others

20

TOTAL

270

Report Format:

Lump Sum / I.B.I: (\$

17,800/- HS

-- Pre repair inspection request - SKZ6333H VS SLF2835X (OI) DOA: 30/08/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Azlan, Syazairdina, Chan, Yoke Shi
Sent: 31/8/2018 3:39:46 PM
Attachments: 80780 (Notice of Accident).pdf

Hi,

Please refer to the enclosed request from **Cheonghoh Law Corporation**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Cheong Hoh Lee [mailto:mail@cheonghoh.sg]

Sent: Friday, August 31, 2018 3:34 PM

To: Mithoosingh, Aashweenjeetkaur

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi

Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF2835X AND SKZ6333H ON 30/08/2018 - LCH.my/SMTB-80780.18

Dear Sir/ Madam,

We refer to your email of even date.

Our client hereby nominate Mr Kenneth Kong of LKK Auto Consultants Pte Ltd to conduct the pre-repair survey of the damages to our client's vehicle SKZ 6333 H arising out of the above mentioned accident.

Kindly inform Mr Kenneth Kong of LKK Auto Consultants Pte Ltd to contact Mr Tay at 6458 0296 from T & B Motor Repairs Services Pte Ltd, Blk 160 Sin Ming Drive #08-03 Sin Ming Auto City Singapore 575722 for the said arrangement on an urgent basis.

Regards,
Melody
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

On Aug 31, 2018, at 9:19 AM, Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com> wrote:

<logo.jpeg>

<lock.gif>

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยกับข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-09-07 09:19 +08 to read your message. After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

<SecureMessageAtt.html>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Aashweenjeetkaur.Mithoosingh@aig.com

To: mail@cheonghoh.sg

Cc: Lily.Tan@aig.com, Andy.SY.Fong@aig.com, Baljit.Kaur@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Syazairdina.Azian@aig.com, yokeshi.chan@aig.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF2835X AND SKZ6333H ON 30/08/2018 - LCH.my/SMTB-80780.18

Date: Fri, 31 Aug 2018 01:19:43 +0000

Without Prejudice

Your Reference : LCH.my/SMTB-80780.18
Our Reference : SLF2835X

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Cheong Hoh Lee [mailto:mail@cheonghoh.sg]

Sent: Thursday, August 30, 2018 6:58 PM

To: Abu Kassim, Noor Mariesa

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene

Subject: Notice of Accident- Traffic accident involving PRS on vehicle SKZ 6333 H and SLF 2835 X (AIG) on 30 August 2018 at/along yellow box of junction Eng Neo Avenue- Our ref: LCH.my/SMTB-80780.18

Dear Sir/ Madam,

Please see attached Notice of Accident for your attention and reply.

Regards,

Melody

Cheonghoh Law Corporation

Blk 53 Chin Swee Road #03-05

Singapore 160053

Tel: 6337 8700

Fax: 6337 3700

On May 4, 2018, at 2:51 PM, Cheong Hoh Lee <mail@cheonghoh.sg> wrote:

Dear Sir/ Madam,

Please see attached Notice of Accident for your attention and reply.

Regards,

Melody

Cheonghoh Law Corporation

Blk 53 Chin Swee Road #03-05

Singapore 160053

Tel: 6337 8700

Fax: 6337 3700

<80386 (Notice of Accident).pdf>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18015961/Ksd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 31-08-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 2835X	Veh. Inspected	SKZ 6333H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MITHOOSINGH	Assign Date	31/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	30/08/2018	Inspection Date	03/09/2018
Survey held at	T & B MOTOR REPAIRS SERVICES PTE LTD BLK 20 SIN MING ROAD #01-28 SINGAPORE 575678		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6715J
Vehicle Details	
Vehicle No.:	SKZ6333H
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	2AZC063320
Chassis No.:	ACR500006805
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$31,114.00
Original Registration Date:	19 Jan 2007
First Registration Date:	19 Jan 2007
Transfer Count:	2
Actual ARF Paid:	\$34,226.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$26,330.00
COE Rebate Amount:	\$17,751.00
Total Rebate Amount:	\$17,751.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Sep 2018

OK


WIDE RANGE OF PRE-OWNED TOYOTA AND OTHER MAKES AVAILABLE


LEARN MORE

VISIT OUR NEW SHOWROOM FOR A PREMIUM PRE-OWNED EXPERIENCE @ 2 PANDAN CRESCENT INCHCAPE CENTRE

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year COE Renewal Honda Stream 1.8A X



\$2800 Downpayment! Monthly
\$588 Onwards! Lowest 3.68%
P.a. @ GV Cars Financing!
GV Credit Pte Ltd StarAd


Lake View Credit Pte Ltd

view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category ▼

« Back (1 2 3) Next »

Sort by Date Posted ▼

20 results/page ▼

58 vehicles

toyota estima

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota estima		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Toyota Estima 2.4A Aeras (COE till 12/2026)	\$63,800	\$7,660 /yr	27-Jan-2007	2,362 cc	-	MPV	Available	
7 Seaters. Sporty White Estima, Excellent Condition, Serviced Regularly, Very Well Kept And Clean Interior. GST Included. Call Us For Viewing.									
Posted: 03-Sep-2018 Tags: 2007 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota									
	Toyota Estima 2.4A Aeras (COE till 08/2028)	\$71,700	\$7,200 /yr	20-Aug-2008	2,362 cc	130,000 km	MPV	Available	
Low Mileage, Best Value Toyota 7 Seater MPV! Immaculate Condition, Genuinely Well Maintained Unit. High Trade-in, Minimum Down Payment And Attractive Financing Available. Call Now To Arrange For Viewi...									
Pang's Motor Trading Pte Ltd									
Posted: 03-Sep-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota									
	Toyota Estima 2.4A (New 5-yr COE)	\$55,800	\$11,150 /yr	28-Jul-2008	2,362 cc	-	MPV	Available	
Down Payment \$5800, Lowest Monthly \$938 Onwards. Low Interest At 3.68% Per Annum By GV Cars Financing. 100% Loan Approval. 2 Years Warranty/Servicing By GV In House Workshop. New Fully Pure Leather Se...									
GV Credit Pte Ltd									
Posted: 02-Sep-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota									
	Toyota Estima 2.4A Aeras (COE till 11/2027)	\$72,800	\$7,930 /yr	09-Nov-2007	2,362 cc	132,000 km	MPV	Available	
2017 New Facelift! Drive Away From \$8000 Onwards! 2017 Facelift, "TWO YEARS IN-HOUSE WARRANTY!" Purchase With Official Warranty Certificate With A Peace Of Mind, Fully Refurbished, Accident Free, Wea...									
Carway									
Posted: 02-Sep-2018 Tags: 2007 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota									
Car Buying	Car Selling	Car Ownership							
Car Aftermarket	On The Move	Lifestyle							
Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation									
	Toyota Estima Hybrid 2.4A (COE till 07/2028)	\$72,777	\$7,390 /yr	10-Jul-2008	2,362 cc	-	MPV	Available	
Fuel Type: Petrol-Electric									
Beautiful Estima Hybrid! Moonroof. 1st Owner. New 10 Years COE. Low Mileage. Regularly Serviced And Well Maintained. 80% To 90% Loan. Affordable Depreciation. Most Popular, Reliable, Spacious And Comf...									
Posted: 01-Sep-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota									
	Toyota Estima 2.4A Aeras G (New 10-yr COE)	\$77,800	\$7,770 /yr	10-Jul-2008	2,362 cc	113,300 km	MPV	Available	
(COE Cars Specialist). New 2015 Facelift. 8 Seater. New Paintwork And New Leather Seats. Twin Power Door. DVD With Reverse Camera. Genuine Low Mileage. Comfortable Drive For Big Family. Flexible Bank/...									
Posted: 01-Sep-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota									
	yota Estima 2.4A Aeras (OE till 11/2027)	\$73,800	\$7,980 /yr	18-Jan-2008	2,362 cc	160,000 km	MPV	Available	
wn Payment Of \$7k For 7 Seaters With Moonroof Unit, Superb Well Maintained, Low Mileage Done, Excellent Condition, Worn Out Parts									

Compare



Replaced, Trade In Welcome, Spacious And Problem Free, Hassle Fr...

Tay Motor & Credit Pte Ltd

Posted: 01-Sep-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



Toyota Estima 2.4A X (New 10-yr COE)

\$71,800

\$7,170 /yr

31-Jul-2008

2,362 cc

95,000 km

MPV

Available

One Year In House Warranty!" STA/Vicom Evaluation Are Welcome, From \$8k Onwards Drive Away, Comes With Official Warranty Certificate For A Peace Of Mind, Company Renew COE Cars Based On Car Condition ...

Carway

Posted: 01-Sep-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



Toyota Estima 2.4A G (COE till 08/2022)

\$39,880

\$9,990 /yr

06-Sep-2007

2,362 cc

-

MPV

Available

G Model Moonroof Unit With Power Tailgate, Owner Relocated. Light Brown Walnut Interior. Front Driver Electric Seat. Regularly Serviced, Bank/In Hse Loan Avail. With Fast Approval. Call Us To View It.

Posted: 31-Aug-2018 Tags: 2007 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



Toyota Estima 2.4A Aeras (COE till 07/2028)

\$68,988

\$6,980 /yr

21-Jul-2008

2,362 cc

-

MPV

Available

Excellent Condition, Comes With 0.5 Year Engine And Gearbox Protection Shield. View To Appreciate. Loan Up To 90%. High Approval Rate. High Trade In. Please Call Or SMS Now For Enquiries And Viewing A...

Posted: 31-Aug-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota

PREMIUM AD



Compare your car insurance quotations!

Save 25% on your car insurance, compare your quote from 10 insurers! Make your choice on zero excess and own workshop! Get your cheaper quote now!

Find out more!



Toyota Estima 2.4A Aeras Premium Moonroof (COE till 06/2022)

\$36,800

\$9,750 /yr

13-Jun-2007

2,362 cc

153,000 km

MPV

Available

Price Adjusted, Close To Dealers/Export Price. Well Maintained Family Car Looking For New Home! This Is Our 2nd Car Mainly Used For Fetching Kids And Weekends Family Gathering. Confident Of Condition ...

Posted: 31-Aug-2018 Tags: 2007 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota

DIRECT OWNER



Toyota Estima 2.4A Aeras Premium Moonroof (New 10-yr COE)

\$72,800

\$7,270 /yr

24-Jul-2008

2,362 cc

113,000 km

MPV

Available

"One Year In House Warranty!" Test Drive To Convince, Sta/Vicom Are Welcome, From \$8000 Onwards Drive Away, Comes With Official Warranty Certificate For A Peace Of Mind, Fully Refurbished, New Paintwo...

Carway

Posted: 31-Aug-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



Toyota Estima 2.4A Aeras Premium Moonroof (COE till 08/2028)

\$72,000

\$7,210 /yr

28-Aug-2008

2,362 cc

167,000 km

MPV

Available

Well Taken Care Of By Owner, Fresh 10 Years COE, Genuine Mileage, New Paintwork, Full New Set Of Engine Mountings, 6 Months Warranty On Engine And Gearbox, Extended Warranty Can Be Arranged, High Loan Wit...

Posted: 30-Aug-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota

PREMIUM AD



Toyota Estima Aeras Modellista 3.5A (New 10-yr COE)

\$68,800

\$6,870 /yr

07-Aug-2008

3,456 cc

90,000 km

MPV

Available

Beautiful White 7 Seater Estima, Powerful V6. Regular Serviced. Drive With Confidence With New COE! Loan Of Up To 90% Can Be Arranged. Call Us For Viewing!

Posted: 30-Aug-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota

PREMIUM AD



Toyota Estima 2.4A Aeras (COE till 03/2028)

\$79,000

\$8,280 /yr

18-Mar-2008

2,362 cc

-

MPV

Available

Please Call Or SMS Now For Enquiries And Viewing Appointment.

Posted: 29-Aug-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



Toyota Estima 2.4A X Moonroof (COE till 07/2023)

\$53,800

\$11,060 /yr

17-Jul-2008

2,362 cc

-

MPV

Available

Selling A Very Well Maintained 8 Seaters MPV. Regularly Serviced. No Repairs Needed. Consignment Vehicle. Great For Family With Kids. Please Call To Schedule For Viewing. High Trade In Welcome, Low Do...

isted: 28-Aug-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota

[Compare](#)



Toyota Estima 2.4A Welcab **\$53,800** **\$10,880 /yr** **15-Aug-2008** **2,362 cc** **113,000 km** **MPV** **Available**
(COE till 08/2023)

1 And Only In The Market, Special Indent For Handicapp, Superb Well Maintained, Low Mileage Done, Excellent Condition, No Repairs Needed, Loan Available, Trade In Welcome, Spacious And Problem Free, E...

Creative Auto

Posted: 25-Aug-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



Toyota Estima 2.4A Aeras **\$70,800** **\$7,070 /yr** **29-Aug-2008** **2,362 cc** **95,227 km** **MPV** **Available**
(New 10-yr COE)

Affordable Depreciation Of Less Than \$7000.RARE! 7 Seaters MPV,Comfortable Drive For Big Family, \$0 Down Payment,Bank And In House Loan Available, Fast And Easy Approval, Excellent Condition, Buy From Pe...

Posted: 25-Aug-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



Toyota Estima 2.4A X (COE till **\$53,800** **\$11,110 /yr** **08-Jul-2008** **2,362 cc** **92,000 km** **MPV** **Available**
07/2023)

2015 Face-lift. Excellent Condition. STA/VICOM/Own Workshop Pre Purchase Evaluation Welcomed! We Are The Cheapest In The Market. Loan Available. Call Us Now For More Enquiry. We Provide Test Drive Pri...

Posted: 25-Aug-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota

PREMIUM AD



Toyota Estima 3.5A Aeras **\$62,800** **\$6,500 /yr** **30-Apr-2008** **3,456 cc** **133,638 km** **MPV** **Available**
(COE till 04/2028)

COE Till 29 April 2028. Lowest Depreciation In The Market. Car In Tip Top Condition. No Repair Needed. Most Popular And Reliable 7 Seaters MPV. High Trade In And In House Loan Available.

Posted: 25-Aug-2018 Tags: 2008 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

« Back (1 2 3) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota estima, toyota estima Singapore, used toyota estima Singapore, used vehicles Singapore or even buy used toyota estima Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)
©2004-2018 sgCarMart. All rights reserved.

(Draft)

MLHM18112684 / Lai Huat (Meng Kee) Motor Pte Ltd - Sin Ming
 ENTRY DATE & TIME: 30/08/2018 16:58
 SUBMITTED BY: [To Be Confirmed]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/08/2018 16:58
 Date Of Accident 30/08/2018 06:50
 Exact Location Of Accident JUNCTION OF ENG NEO AVENUE TOWARDS BUKIT TIMAH
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKZ6333H
Insured/Policyholder
 Name Of Registered Owner TAI KWANG KIT (DAI GUANGJI)
 NRIC No S7526715J
 Email Address WEEAHI@GMAIL.COM
 Mobile Phone No (LOCAL) +65-93623250
 Alternative Phone No Others-97667190

Vehicle Particulars

Manufacturer TOYOTA
 Model ESTIMA 2.4 AERAS
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number DMPCSN3004501801
 Cover Note Number

Driver

Name of Driver IVY WEE AN-HWAY
 NRIC No S7611097B
 Date Of Birth 12/04/1976
 Occupation INDOOR
 Date Of Driving Pass 18/11/1995
 Driving Experience 22 YEARS AND 9 MONTHS
 Gender FEMALE
 Mobile Number (LOCAL) +65-97667190
 Fax Number
 Contact Number
 EMail Address WEEAHI@GMAIL.COM

s

40 VERDE GROVE
 VILLA VERDE

8/3Q/2018

E-FILE

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

40 VERDE GROVE
VILLE VERDE

Postcode

688572

2/1

SKETCH PLAN

Date: 30/8/18

TIME: 6:48 AM

(A) SKZ 6333H

(B) SLF 2835X

ENG NEO AVE

TOWARD BUKIT TIMAH

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30 August 2018 at about 6.48am, I exited to Eng Neo Avenue and I was driving straight in the right lane, heading towards Sixth Ave.

Nearing the yellow box junction at Eng Neo Ave (leading to Hse Nos 70-118, 100A, 102A), a red car appeared on my left and collided into my car on the left, causing my car to go to the opposite side of the road.

given

I was 2 days of medical leave from the doctor.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

North

Policyholder's Signature

Date & Time:

Am 8.

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: Poh Kwee Choo

NRIC/FIN No.: S6840583A

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 1 / 6

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

Estimate : ES003323

TAI KWANG KIT
40 VERDE GROVE VILLA VERDE
SINGAPORE 688572

Attention : Motor Claim Department

Date : 30/08/2018
Vehicle Num. : SKZ6333H
Make/Model : TOYOTA ESTIMA 2.4 AERAS
Chassis/Eng# :
Accident Date : 30/08/2018
Claim No. :
Reference :
Policy No. : DMPCSN3004501

Not Authorized
11 Lmp 816,000
Resurvey After Paint
Note 11 Lmp not more than 816k

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular
1.	1	FRONT WINDSCREEN GLASS
2.	1	FRONT WINDSCREEN GLASS SIDE GARNISH L/H
3.	1	FRONT WINDSCREEN GLASS SIDE GARNISH R/H
4.	1	FRONT WIPER GARNISH
5.	1	FRONT WIPER LINK ASSY
6.	1	FRONT BONNET
7.	1	FRONT BONNET LOCK
8.	1	FRONT BONNET LOCK CABLE
9.	1	FRONT BONNET INNER RUBBER
10.	1	FRONT BONNET INNER SHIELD
11.	4	FRONT BONNET INNER SHIELD CLIP
12.	1	FRONT BONNET HINGE LH
13.	1	FRONT BONNET HINGE RH
14.	1	FRONT FENDER LH
15.	1	FRONT FENDER INNER SHIELD LH
16.	10 (L/H)	FRONT FENDER INNER SHIELD CLIPS
17.	1	FRONT FENDER INNER GARNISH LH
18.	1	FRONT FENDER INNER COVER RH
19.	1	FRONT FENDER SIDE BRACKET LH
20.	1	FRONT FENDER SIDE TOP GARNISH LH
21.	1	FRONT FENDER SIDE LOWER PROTECTOR L/H
22.	2	FRONT WIPER GARNISH CLIP
23.	3	FRONT FENDER SIDE LOWER PROTECTOR CLIP
24.	1	FRONT BONNET LOCK SUPPORT PANEL
25.	1	FRONT BONNET STAY HOLDER CLIP
26.	1	FRONT SUPPORT PANEL TOP COVER
27.	5	FRONT SUPPORT PANEL TOP COVER CLIP
28.	1	FRONT GRILLE
29.	1	FRONT GRILLE LOWER LOGO

CR	1,952.36	✓
Sn	283.50	✓
R	283.50	✓
DT	584.98	✓
Sn	356.85	X
R	563.84	✓
DT	105.19	✓
Sn	59.63	X
R	35.74	X
Sn	226.57	X
5.50	22.00	✓
DT	59.10	✓
R	59.10	✓
CR	613.60	✓
5.50	246.68	✓
DT	55.00	✓
R	130.15	✓
Sn	246.68	X
R	80.43	X
DT	40.02	✓
5.50	393.49	✓
10.00	11.00	✓
R	30.00	✓
Sn	240.96	X
R	10.00	X
8.00	157.92	✓
DT	40.00	✓
CR	549.77	✓
R	103.96	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:

CONTINUE / ...

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 2 / 6

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

TAI KWANG KIT
40 VERDE GROVE VILLA VERDE
SINGAPORE 688572

Attention : Motor Claim Department

Estimate : ES003323

Date : 30/08/2018

Vehicle Num. : SKZ6333H

Make/Model : TOYOTA ESTIMA 2.4 AERAS

Chassis/Eng# :

Accident Date : 30/08/2018

Claim No. :

Reference :

Policy No. : DMPCSN3004501

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	4	FRONT GRILLE CLIPS		
31.	1	FRONT HEADLAMP (H.I.D) L/H	5.50	22.00 ✓
32.	1	FRONT HEADLAMP (H.I.D) R/H	Br	2,151.87 ✓
33.	1	FRONT BUMPER	mgc/m	2,151.87 ✓
34.	1	FRONT BUMPER TOP BEAN PANEL	TA	2,259.85 ✓
35.	1	FRONT BUMPER REINFORCEMENT PANEL	Br	121.45 ✓
36.	1	FRONT BUMPER SPONGE	CM	377.71 ✓
37.	1	FRONT BUMPER TOWING HOOK COVER	ni	95.59 ✓
38.	1	FRONT BUMPER SIDE RETAINER LH	CM	102.33 ✓
39.	1	FRONT BUMPER SIDE RETAINER RH	CM	80.43 ✓
40.	1	FRONT BUMPER SIDE SPORT LIGHT ASSY L/H	Br	80.43 ✓
41.	1	FRONT SUPPORT PANEL ASSY	Br	278.11 ✓
42.	1	FRONT HORN	Br	2,151.87 ✓
43.	1	FRONT AIRCON CONDENSER	Br	120.37 ✓
44.	1	FRONT AIRCON CONDENSER TOP BRACKET L/H	Br	1,248.20 ✓
45.	1	FRONT AIRCON CONDENSER TOP MOUNTING L/H	Br	155.67 ✓
46.	1	FRONT AIRCON CONDENSER TOP BRACKET R/H	Br	140.07 ✓
47.	1	FRONT AIRCON CONDENSER TOP MOUNTING R/H	Br	155.67 ✓
48.	1	FRONT AIRCON HIGHT PRESSURE PIPE	Br	140.07 ✓
49.	1	FRONT AIRCON LOW PRESSURE PIPE	Br	590.35 X
50.	1	FRONT AIRCON LIQUID PIPE	Br	587.45 X
51.	1	FRONT AIRCON RECEIVER DRYER	Br	487.11 X
52.	1	FRONT AIRCON FAN MOTOR	Br	458.77 X
53.	1	FRONT AIRCON FAN BLADE	Br	490.11 X
54.	1	FRONT AIRCON FAN COWLING	Br	170.38 X
55.	1	FRONT RADIATOR	Br	330.23 ✓
56.	1	FRONT RADIATOR TOP HOSE	Br / Br	1,947.93 ✓
57.	1	FRONT RADIATOR LOWER HOSE	Br	66.70 X
58.	1	FRONT RADIATOR FAN BLADE	Br	106.70 X
59.	1	FRONT RADIATOR FAN MOTOR	Br	170.38 X
60.	1	FRONT RADIATOR COWLING	Br	322.18 X
			Br	310.77 X

CONTINUE / ...

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 3 / 6

160, SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

Estimate : ES003323

Date : 30/08/2018

Vehicle Num. : SKZ6333H

Make/Model : TOYOTA ESTIMA 2.4 AERAS

Chassis/Eng# :

Accident Date : 30/08/2018

Claim No. :

Reference :

Policy No. : DMPCSN3004501

TAI KWANG KIT
40 VERDE GROVE VILLA VERDE
SINGAPORE 688572

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
61.	1	FRONT RADIATOR TOP MOUNTING L/H		
62.	1	FRONT RADIATOR LOWER MOUNTING R/H		
63.	1	FRONT RADIATOR OUTER SIDE GARNISH L/H		
64.	1	FRONT RADIATOR OUTER SIDE GARNISH R/H		
65.	1	FRONT AIR CLEANER BOX ASSY		
66.	1	FRONT AIR CLEANER DUCT GARNISH		
67.	1 (FRONT)	AIR FILTER		
68.	1	FRONT AIR CAMBER HOSE		
69.	1	FRONT GEAR BOX MOUNTING		
70.	1	FRONT ENGINE MOUNTING		
71.	1	FRONT ENGINE REAR MOUNTING		
72.	1	FRONT RIGHT ENGINE MOUNTING		
73.	1	BATTERY BRACKET		
74.	1	BATTERY TRAY		
75.	1	ENGINE E.C U BOX		
76.	1	ENGINE E.C U BOX BRACKET		
77.	1	FUSE BOX TOP COVER		
78.	1	FUSE BOX ASSY		
79.	1	FRONT ENGINE SIDE COVER L/H		
80.	1	FRONT SHOCK ABSORBER TOP MOUNTING LH		
81.	1	FRONT SHOCK ABSORBER TOP BEARING LH		
82.	1	FRONT SHOCK ABSORBER BUSH LH		
83.	1	FRONT SHOCK ABSORBER		
84.	1	FR SHOCK ABSORBER COOL SPRING WEATHERSTRIP LH		
85.	1	FRONT SHOCK ABSORBER TOP MOUNTING RH		
86.	1	FRONT SHOCK ABSORBER TOP BEARING RH		
87.	1	FRONT SHOCK ABSORBER BUSH RH		
88.	1	FRONT SHOCK ABSORBER RH		
89.	1	FR SHOCK ABSORBER COOL SPRING WEATHERSTRIP RH		
90.	1	FRONT KNUCKLE ARM LH		
91.	1	FRONT WHEEL BEARING HUB ASSY LH		

CONTINUE / ...

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 4 / 6

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

TAI KWANG KIT
40 VERDE GROVE VILLA VERDE
SINGAPORE 688572

Attention : Motor Claim Department

Estimate : ES003323

Date : 30/08/2018

Vehicle Num. : SKZ6333H

Make/Model : TOYOTA ESTIMA 2.4 AERAS

Chassis/Eng# :

Accident Date : 30/08/2018

Claim No. :

Reference :

Policy No. : DMPCSN3004501

S/N	Quantity	Particular	Unit Price	Amount S\$
92.	1	FRONT WHEEL A.B.S SENSOR WIRE LH	Sm	424.75 X
93.	1	FRONT LOWER ARM LH	By	532.55 T
94.	1	FRONT LOWER ARM BALL JOINT LH	By	205.52 T
95.	1	FRONT DRIVE SHAFT LH	R	1,485.09 X
96.	1	FRONT DRIVE SHAFT OIL SEAL LH	Sm	30.50 X
97.	1	FRONT WHEEL BRAKE DISCS L/H	Sm	428.53 X
98.	1	FRONT STEERING RACK TIE ROD END L/H	Sm	111.65 X
99.	1	FRONT N.T LOWER BAR STAY L/H	Sm	129.00 X
100.	1	FRONT N.T LOWER BAR STAY R/H	Sm	129.00 X
101.	1	FRONT RADIATOR LOWER CROSS MEMBER	R	238.20 X
102.	1	FRONT ENGINE CROSS MEMBER	Sm	3,860.12 X
103.	1	FRONT LOWER ARM RH	Sm	532.55 X
104.	1	FRONT LOWER ARM BALL JOINT RH	Sm	285.52 X
105.	2	FRONT STEERING RACK & PINION TIE ROD END L/R	117.65 Sm	235.30 X
106.	1	FRONT DOOR LH	By	1,273.41 X
107.	1	FRONT DOOR TOP HINGE LH	R	35.21 X
108.	1	FRONT DOOR LOWER HINGE LH	R	35.21 X
109.	1	FR RADIATOR LOWER CROSS MEMBER SIDE SUPPORT	R	292.50 X
110.	1	MEMBER L/H	R	292.50 X
111.	1	FR RADIATOR LOWER CROSS MEMBER SIDE SUPPORT	R	78.18 X
112.	1	MEMBER R/H	Sm	110.95 X
113.	1	FRONT DOOR GLASS OUTER MOULDING LH	Sm	196.90 X
114.	1	FRONT DOOR GLASS CHANNEL LH	Red	1,230.49 X
115.	1	FRONT DOOR WEATHERSTRIP LH	By	1,267.47 X
116.	1	FRONT DOOR LOWER PROTECTOR LH	Red / CM	1,250.59 X
117.	1	SLIDING DOOR LH	12.00 R	120.00 X
118.	1	SLIDING DOOR LOWER PROTECTOR L/H	12.00 R	120.00 X
119.	10	FRONT DOOR LOWER PROTECTOR CLIP LH	Sm	108.27 X
120.	10	SLIDING DOOR LOWER PROTECTOR CLIP LH	Sm	1,006.72 X
121.	1	SLIDING DOOR GLASS OUTER MOULDING L/H		
122.	1	SLIDING DOOR SENSOR RUBBER LH		

CONTINUE / ...

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 5 / 6

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

TAI KWANG KIT
40 VERDE GROVE VILLA VERDE
SINGAPORE 688572

Attention : Motor Claim Department

Estimate : ES003323

Date : 30/08/2018

Vehicle Num. : SKZ6333H

Make/Model : TOYOTA ESTIMA 2.4 AERAS

Chassis/Eng# :

Accident Date : 30/08/2018

Claim No. :

Reference :

Policy No. : DMPCSN3004501

S/N	Quantity	Particular	Unit Price	Amount S\$
123.	1	REAR FENDER SIDE PROTECTOR L/H		
124.	4	REAR FENDER SIDE PROTECTOR CLIP L/H		
125.	1	REAR BUMPER	10.00	393.49
126.	1	REAR BUMPER SIDE RETAINER LH		40.00
127.	1	REAR BUMPER SIDE RETAINER RH		1,503.57
				51.94
				51.94
		List Total S\$:		55,421.91
		25.00% Discount S\$:		13,855.48
				41,566.43
		NETT ITEMS :		
1.	1	FRONT WINDSCREEN GLASS IU BRACKET		
2.	1	FRONT BATTERY		25.00
3.	1	FRONT TYRE LH		280.00
4.	1	FRONT SPORT RIM		320.00
5.	1	FRONT NUMBER PLATE(EMBASSED)		550.00
				50.00
		Nett Total S\$:		1,225.00
		LABOUR :		
		1. TOWING FROM ACCIDENT PLACE TO WORKSHOP		60.00
		2. TOWING FROM WORKSHOP TO REPORTING CENTRE AND BACK TO WORKSHOP		100.00
		3. COMPUTER 4 WHEELS ALIGNMENT (BEFORE REPAIR)		120.00
		4. COMPUTER 4 WHEELS ALIGNMENT (AFTER REPAIR)		120.00
		5. REMOVE AND REFIX FRONT WINDSCREEN		250.00
		6. REMOVE AND REFIX AIRCON SYSTEM, VACCUM AIRCON SYSTEM AND CHECK FOR LEAK		250.00
		7. COMPUTER HIGH SPEED WHEEL BALANCING		180.00
		8. REMOVE & REFIX FRONT UNDERCARRIAGE, CROSS MEMBER &		

CONTINUE / ...

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 6 / 6

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

TAI KWANG KIT
40 VERDE GROVE VILLA VERDE
SINGAPORE 688572

Estimate : ES003323

Date : 30/08/2018

Vehicle Num. : SKZ6333H

Make/Model : TOYOTA ESTIMA 2.4 AERAS

Chassis/Eng# :

Accident Date : 30/08/2018

Claim No. :

Reference :

Policy No. : DMPCSN3004501

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
RELATED PARTS				
		9. REMOVE & REFIX ENGINE, GEAR BOX, CHECK ENGINE MOUNTING & WIRE HARENESS WIRE AND RADIATOR, CHECK COOLANT, TEMPERTURE AND GEAR BOX FLUID	nn 1,200.00	2
		10. CHECK WIRING & REPAIR, COMPUTER CHECK, SETTING, ERASE FAULT CODE AND PROGRAMMING	nn 1,500.00	1
		11. REMOVE & REFIX FRONT LEFT DOOR GLASS & POWER WINDOW SYSTEM	600.00	200
		12. REMOVE & REFIX FRONT LEFT SLIDING DOOR WINDOW, POWER WINDOW SYSTEM, SLIDING DOOR LOCK AND SLIDING DOOR SYSTEM	180.00	80
		13. REMOVE & REFIX DASHBOARD AND RADIO SYSTEM, AIRCON BLOWER, VENTILATION VENT, COOLING COIL AND HEATER SYSTEM	180.00	80
		14. SUPPLY & INSTALL SUN VISOR	nn 700.00	1
		15. SPRAY PAINT	480.00	180
		16. WASH CUSHION AND VACCUM	3,000.00	2200
		17. SPRAY PAINT ANTI-RUST COATING	nn 350.00	1
		18. LABOUR CHARGE FOR REPAIRING, ADJUSTING, KNOCKING, WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE, TESTING WATER LEAKING AND ON ROAD VEHICLE TESTING	350.00	150
		Labour Total S\$:	3,000.00	1400
				12,620.00

SingDollars : Fifty-Five Thousand Four Hundred Eleven & Cents Forty-Three Only

E. & O.E.

Total S\$: 55,411.43

=====

for T & B MOTOR REPAIRS SERVICES PTE LTD

57436.29

T & B MOTOR REPAIRS SERVICES PTE LTD

160 SIM MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

TAI KWANG KIT

40 VERDE GROVE VILLA VERDE

SINGAPORE 688572

Attention : Motor Claim Department

Supplementary Estimate : ES003327

Date : 30/08/2018

Vehicle Num. : SKZ6333H

Make/Model : TOYOTA ESTIMA 2.4 AERAS

Chassis/Eng# :

Accident Date : 30/08/2018

Claim No. :

Reference :

Policy No. : DMPCSN3004501

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|---|-----------------------------------|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | FRONT DOOR SIDE MIRROR ASSY LH | | |
| 3. | 1 | FRONT SHOCK ABSORBER COVER LH | | |
| 4. | 1 | FRONT SHOCK ABSORBER BUSH LH | | |
| 4. | 1 | FRONT STEERING RACK & PINION ASSY | | |

List Total S\$:

25.00% Discount S\$:

Ang P17	645.13	✓
EM	55.85	✓
m	34.91	✓
B712m	1,963.93	✓
	2,699.82	
	674.96	
	2,024.86	

ole
10/10/18

SingDollars : Two Thousand Twenty-Four & Cents Eighty-Six Only

E. & O.E.

Total S\$:

2,024.86

for T & B MOTOR REPAIRS SERVICES PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Aug 2018 Edit Reg		31 Aug 2018 00:00 Edit Adj Rpt	S\$17,800.00 Edit Estimates	S\$17,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: SOHANPAL INDER AMOL SINGH , ID: 514222107									
Main Claimant: IVY WEE AN-HWAY , ID: S7611097B									
Vehicle Reg. No.: SKZ6333H		Date of Loss: 30/08/2018 07:00 - :59 [139 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4344214169SG		Policy/Cover Note No.: 2100479713 (Comprehensive) Coverage: 19/08/2018 - 18/08/2019							
Vehicle Reg. No. (Insured): SLF2835X		Policy No. (Claimant):							
		Excess:							
Repairer: T & B Motor Repairs Services Pte Ltd (HQ) Blk 20, #01-28, Sin Ming Road, 575678 Sin Ming - Tel: 64546958/64580296									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/09/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (03/09/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKZ6333H (4344214169SG)
[SLF2835X]
TP
IVY WEE AN-HWAY
Aug 30 2018 7:00AM
[SOHANPAL INDER AMOL SINGH]
T & B Motor Repairs Services Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images												3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print
1	20/11/18 10:02	General View											Load JPG	☒
2	20/11/18 10:02	General View											Load JPG	☒
3	20/11/18 10:02	General View											Load JPG	☒
4	20/11/18 10:02	General View											Load JPG	☒
5	20/11/18 10:02	General View											Load JPG	☒
6	20/11/18 10:02	General View											Load JPG	☒
7	20/11/18 10:02	General View											Load JPG	☒
8	20/11/18 10:02	General View											Load JPG	☒
9	20/11/18 10:02	General View											Load JPG	☒
10	20/11/18 10:02	General View											Load JPG	☒
11	20/11/18 10:02	General View											Load JPG	☒
12	20/11/18 10:02	General View											Load JPG	☒
13	20/11/18 10:02	General View											Load JPG	☒
14	20/11/18 10:02	General View											Load JPG	☒
15	20/11/18 10:02	General View											Load JPG	☒
16	20/11/18 10:02	General View											Load JPG	☒
17	20/11/18 10:02	General View											Load JPG	☒
18	20/11/18 10:02	General View											Load JPG	☒
19	20/11/18 10:02	General View											Load JPG	☒
20	20/11/18 10:02	General View											Load JPG	☒
21	20/11/18 10:02	Odometer Reading											Load JPG	☒
22	20/11/18 10:02	General View											Load JPG	☒
23	20/11/18 10:02	General View											Load JPG	☒
24	20/11/18 10:02	General View											Load JPG	☒
25	20/11/18 10:02	General View											Load JPG	☒
26	20/11/18 10:02	General View											Load JPG	☒
27	20/11/18 10:02	General View											Load JPG	☒
28	20/11/18 10:02	General View											Load JPG	☒
29	20/11/18 10:02	General View											Load JPG	☒
30	20/11/18 10:02	General View											Load JPG	☒
31	20/11/18 10:02	General View											Load JPG	☒
32	20/11/18 10:02	General View											Load JPG	☒
33	20/11/18 10:02	General View											Load JPG	☒
34	20/11/18 10:02	General View											Load JPG	☒
35	20/11/18 10:02	General View											Load JPG	☒
36	20/11/18 10:02	General View											Load JPG	☒
37	20/11/18 10:02	General View											Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	20/11/18 10:02	General View	 Load JPG	☒
39	20/11/18 10:02	Chassis Number	 Load JPG	☒
40	20/11/18 10:02	General View	 Load JPG	☒
41	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
42	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
43	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
44	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
45	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
46	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
47	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
48	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
49	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
50	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
51	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
52	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
53	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
54	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
55	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
56	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
57	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
58	20/11/18 10:04	Reinspection Photo	 Load JPG	☒
59	20/11/18 10:06	Reinspection Photo	 Load JPG	☒
60	20/11/18 10:06	Reinspection Photo	 Load JPG	☒
61	20/11/18 10:06	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/18 12:16	Supplementary	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/09/18 13:53	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18015961/KSD3E2

Date: 28/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100479713
Claimant Vehicle No : SKZ6333H **Insured Vehicle No :** SLF2835X
 Date of Loss: 30/08/2018 Nature of Claim: TP Claim No: 4344214169SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ6333H**
 Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A) Engine No: 2AZC063320
 Reg. Date: 19/01/2007 (Man. Year: 2006) Chassis No: ACR500006805
 Colour: Metallic Black Odometer: 135260 km
 Engine Capacity: 2362 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,816.30	24,330.48	20,485.82	45.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,620.00	4,820.00	7,800.00	61.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	57,436.30	29,150.48	28,285.82	49.25
Approved Total (Overridden) (S\$)		17,800.00		
Nett Amount (S\$)	57,436.30	17,800.00	39,636.30	69.01

INSPECTION

Date of Assignment: 31/08/2018
 Date Inspected: 03/09/2018 Inspected At: 160 SIN MING DRIVE #08-03
 Repairer : T & B Motor Repairs Services Pte Ltd (HQ)
 Estimated Period of Repair: 26.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Cracked	1,952.36 FL	*1,952.36 FL
2	1		*FRONT WINDSCREEN GLASS SIDE GARNISH L/H	Serviceable	283.50 FL	*- FL
3	1		*FRONT WINDSCREEN GLASS SIDE GARNISH R/H	Serviceable	283.50 FL	*- FL
4	1		*FRONT WIPER GARNISH	Distorted	584.98 FL	*584.98 FL
5	1		*FRONT WIPER LINK ASSY	Serviceable	356.85 FL	*- FL
6	1		*FRONT BONNET	Bent	563.84 FL	*563.84 FL
7	1		*FRONT BONNET LOCK	Distorted	105.19 FL	*105.19 FL
8	1		*FRONT BONNET LOCK CABLE	Serviceable	59.63 FL	*- FL
9	1		*FRONT BONNET INNER RUBBER	Serviceable	35.74 FL	*- FL
10	1		*FRONT BONNET INNER SHIELD	Serviceable	226.57 FL	*- FL
11	4		*FRONT BONNET INNER SHIELD CLIP	Necessary	22.00 FL	*22.00 FL
12	1		*FRONT BONNET HINGE LH	Distorted	59.10 FL	*59.10 FL
13	1		*FRONT BONNET HINGE RH	Distorted	59.10 FL	*59.10 FL
14	1		*FRONT FENDER LH	Bent	613.60 FL	*613.60 FL
15	1		*FRONT FENDER INNER SHIELD LH	Cracked	246.68 FL	*246.68 FL
16	10		*(L/H) FRONT FENDER INNER SHIELD CLIPS	Necessary	55.00 FL	*55.00 FL
17	1		*FRONT FENDER INNER GARNISH LH	Distorted / Dented	130.15 FL	*130.15 FL
18	1		*FRONT FENDER INNER COVER RH	Serviceable	246.68 FL	*- FL
19	1		*FRONT FENDER SIDE BRACKET LH	Serviceable	80.43 FL	*- FL
20	1		*FRONT FENDER SIDE TOP GARNISH LH	Missing	40.02 FL	*40.02 FL
21	1		*FRONT FENDER SIDE LOWER PROTECTOR L/H	Dented / Bent	393.49 FL	*393.49 FL
22	2		*FRONT WIPER GARNISH CLIP	Necessary	11.00 FL	*11.00 FL
23	3		*FRONT FENDER SIDE LOWER PROTECTOR CLIP	Necessary	30.00 FL	*30.00 FL
24	1		*FRONT BONNET LOCK SUPPORT PANEL	Repair	240.96 FL	*- FL
25	1		*FRONT BONNET STAY HOLDER CLIP	Not Necessary	10.00 FL	*- FL
26	1		*FRONT SUPPORT PANEL TOP COVER	Dented	157.92 FL	*157.92 FL
27	5		*FRONT SUPPORT PANEL TOP COVER CLIP	Necessary	40.00 FL	*40.00 FL
28	1		*FRONT GRILLE	Distorted / Cracked	549.77 FL	*549.77 FL
29	1		*FRONT GRILLE LOWER LOGO	Necessary	103.96 FL	*103.96 FL
30	4		*FRONT GRILLE CLIPS	Necessary	22.00 FL	*22.00 FL
31	1		*FRONT HEADLAMP (H.I.D) L/H	Broken	2,151.87 FL	*2,151.87 FL
32	1		*FRONT HEADLAMP (H.I.D) R/H	Mtg Cracked	2,151.87 FL	*2,151.87 FL
33	1		*FRONT BUMPER	Torn	2,259.85 FL	*2,259.85 FL
34	1		*FRONT BUMPER TOP BEAN PANEL	Repar	121.45 FL	*- FL
35	1		*FRONT BUMPER REINFORCEMENT PANEL	Bent	377.71 FL	*377.71 FL
36	1		*FRONT BUMPER SPONGE	Cracked	95.59 FL	*95.59 FL
37	1		*FRONT BUMPER TOWING HOOK COVER	Missing	102.33 FL	*102.33 FL
38	1		*FRONT BUMPER SIDE RETAINER LH	Cracked	80.43 FL	*80.43 FL
39	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	80.43 FL	*80.43 FL
40	1		*FRONT BUMPER SIDE SPORT LIGHT ASSY L/H	Broken	278.11 FL	*278.11 FL
41	1		*FRONT SUPPORT PANEL ASSY	Bent	2,151.87 FL	*2,151.87 FL
42	1		*FRONT HORN	Serviceable	120.37 FL	*- FL
43	1		*FRONT AIRCON CONDENSER	Bent	1,248.20 FL	*1,248.20 FL
44	1		*FRONT AIRCON CONDENSER TOP BRACKET L/H	Repair	155.67 FL	*- FL
45	1		*FRONT AIRCON CONDENSER TOP MOUNTING L/H	Serviceable	140.07 FL	*- FL
46	1		*FRONT AIRCON CONDENSER TOP BRACKET R/H	Repair	155.67 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT AIRCON CONDENSER TOP MOUNTING R/H	Repair	140.07 FL	*- FL
48	1		*FRONT AIRCON HIGHT PRESSURE PIPE	Serviceable	590.35 FL	*- FL
49	1		*FRONT AIRCON LOW PRESSURE PIPE	Serviceable	587.45 FL	*- FL
50	1		*FRONT AIRCON LIQUID PIPE	Serviceable	487.11 FL	*- FL
51	1		*FRONT AIRCON RECEIVER DRYER	Serviceable	458.77 FL	*- FL
52	1		*FRONT AIRCON FAN MOTOR	Serviceable	490.11 FL	*- FL
53	1		*FRONT AIRCON FAN BLADE	Serviceable	170.38 FL	*- FL
54	1		*FRONT AIRCON FAN COWLING	Cracked	330.23 FL	*330.23 FL
55	1		*FRONT RADIATOR	Punctured / Bent	1,947.93 FL	*1,947.93 FL
56	1		*FRONT RADIATOR TOP HOSE	Serviceable	66.70 FL	*- FL
57	1		*FRONT RADIATOR LOWER HOSE	Serviceable	106.70 FL	*- FL
58	1		*FRONT RADIATOR FAN BLADE	Serviceable	170.38 FL	*- FL
59	1		*FRONT RADIATOR FAN MOTOR	Serviceable	322.18 FL	*- FL
60	1		*FRONT RADIATOR COWLING	Serviceable	310.77 FL	*- FL
61	1		*FRONT RADIATOR TOP MOUNTING L/H	Serviceable	25.61 FL	*- FL
62	1		*FRONT RADIATOR LOWER MOUNTING R/H	Serviceable	25.61 FL	*- FL
63	1		*FRONT RADIATOR OUTER SIDE GARNISH L/H	Serviceable	76.35 FL	*- FL
64	1		*FRONT RADIATOR OUTER SIDE GARNISH R/H	Serviceable	76.35 FL	*- FL
65	1		*FRONT AIR CLEANER BOX ASSY	Cracked	822.65 FL	*822.65 FL
66	1		*FRONT AIR CLEANER DUCT GARNISH	Dented	63.79 FL	*63.79 FL
67	1		*(FRONT) AIR FILTER	Serviceable	79.01 FL	*- FL
68	1		*FRONT AIR CAMBER HOSE	Dented	86.35 FL	*86.35 FL
69	1		*FRONT GEAR BOX MOUNTING	Serviceable	285.35 FL	*- FL
70	1		*FRONT ENGINE MOUNTING	Serviceable	142.72 FL	*- FL
71	1		*FRONT ENGINE REAR MOUNTING	Serviceable	190.35 FL	*- FL
72	1		*FRONT RIGHT ENGINE MOUNTING	Serviceable	282.83 FL	*- FL
73	1		*BATTERY BRACKET	Repair	31.60 FL	*- FL
74	1		*BATTERY TRAY	Serviceable	325.25 FL	*- FL
75	1		*ENGINE E.C.U BOX	Serviceable	4,543.33 FL	*- FL
76	1		*ENGINE E.C.U BOX BRACKET	Repair	150.77 FL	*- FL
77	1		*FUSE BOX TOP COVER	Serviceable	105.67 FL	*- FL
78	1		*FUSE BOX ASSY	Serviceable	251.68 FL	*- FL
79	1		*FRONT ENGINE SIDE COVER L/H	Serviceable	201.29 FL	*- FL
80	1		*FRONT SHOCK ABSORBER TOP MOUNTING LH	Bent	1,840.10 FL	*184.10 FL
81	1		*FRONT SHOCK ABSORBER TOP BEARING LH	Necessary	31.22 FL	*31.22 FL
82	1		*FRONT SHOCK ABSORBER BUSH LH	Necessary	24.15 FL	*24.15 FL
83	1		*FRONT SHOCK ABSORBER	Bent	436.41 FL	*436.41 FL
84	1		*FRONT SHOCK ABSORBER TOP MOUNTING RH	Bent	184.10 FL	*184.10 FL
85	1		*FRONT SHOCK ABSORBER TOP BEARING RH	Necessary	31.22 FL	*31.22 FL
86	1		*FRONT SHOCK ABSORBER BUSH RH	Serviceable	24.15 FL	*- FL
87	1		*FRONT SHOCK ABSORBER RH	Bent	436.41 FL	*436.41 FL
88	1		*FR SHOCK ABSORBER COOL SPRING WEATHERSTRIP RH	Serviceable	45.85 FL	*- FL
89	1		*FRONT KNUCKLE ARM LH	Bent	530.80 FL	*530.80 FL
90	1		*FRONT WHEEL BEARING HUB ASSY LH	Bent	523.03 FL	*523.03 FL
91	1		*FRONT WHEEL A.B.S SENSOR WIRE LH	Serviceable	424.75 FL	*- FL
92	1		*FRONT LOWER ARM LH	Bent	532.55 FL	*532.55 FL
93	1		*FRONT LOWER ARM BALL JOINT LH	Bent	205.52 FL	*205.52 FL
94	1		*FRONT DRIVE SHAFT LH	Repair	1,485.09 FL	*- FL
95	1		*FRONT DRIVE SHAFT OIL SEAL LH	Serviceable	30.50 FL	*- FL
96	1		*FRONT WHEEL BRAKE DISCS L/H	Serviceable	428.53 FL	*- FL
97	1		*FRONT STEERING RACK TIE ROD END L/H	Distorted	111.65 FL	*111.65 FL
98	1		*FRONT N.T LOWER BAR STAY L/H	Serviceable	129.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
99	1		*FRONT N.T LOWER BAR STAY R/H	Serviceable	129.00 FL	*- FL
100	1		*FRONT RADIATOR LOWER CROSS MEMBER	Repair	238.20 FL	*- FL
101	1		*FRONT ENGINE CROSS MEMBER	Serviceable	3,860.12 FL	*- FL
102	1		*FRONT LOWER ARM RH	Serviceable	532.55 FL	*- FL
103	1		*FRONT LOWER ARM BALL JOINT RH	Serviceable	285.52 FL	*- FL
104	2		*FRONT STEERING RACK & PINION TIE ROD END L/R	Serviceable	235.30 FL	*- FL
105	1		*FRONT DOOR LH	Bent	1,273.41 FL	*1,273.41 FL
106	1		*FRONT DOOR TOP HINGE LH	Repair	35.21 FL	*- FL
107	1		*FRONT DOOR LOWER HINGE LH	Repair	35.21 FL	*- FL
108	1		*FR RADIATOR LOWER CROSS MEMBER SIDE SUPPORT MEMBER L/H	Repair	292.50 FL	*- FL
109	1		*FRONT DOOR GLASS OUTER MOULDING LH	Necessary	78.18 FL	*78.18 FL
110	1		*FRONT DOOR GLASS CHANNEL LH	Serviceable	110.95 FL	*- FL
111	1		*FRONT DOOR WEATHERSTRIP LH	Serviceable	196.90 FL	*- FL
112	1		*FRONT DOOR LOWER PROTECTOR LH	Dented	1,230.49 FL	*1,230.49 FL
113	1		*SLIDING DOOR LH	Bent	1,267.47 FL	*1,267.47 FL
114	1		*SLIDING DOOR LOWER PROTECTOR L/H	Dented / Cracked	1,250.59 FL	*1,250.59 FL
115	10		*FRONT DOOR LOWER PROTECTOR CLIP LH	Necessary	120.00 FL	*120.00 FL
116	10		*SLIDING DOOR LOWER PROTECTOR CLIP LH	Necessary	120.00 FL	*120.00 FL
117	1		*SLIDING DOOR GLASS OUTER MOULDING L/H	Serviceable	108.27 FL	*- FL
118	1		*SLIDING DOOR SENSOR RUBBER LH	Serviceable	1,006.72 FL	*- FL
119	1		*REAR FENDER SIDE PROTECTOR L/H	Dented	393.49 FL	*393.49 FL
120	4		*REAR FENDER SIDE PROTECTOR CLIP L/H	Necessary	40.00 FL	*40.00 FL
121	1		*REAR BUMPER	Repair	1,503.57 FL	*- FL
122	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	51.94 FL	*- FL
123	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	51.94 FL	*- FL
124	1		*FRONT WINDSCREEN GLASS IU BRACKET	Necessary	25.00 FS	*25.00 FS
125	1		*FRONT BATTERY	Serviceable	280.00 FS	*- FS
126	1		*FRONT TYRE LH	Serviceable	320.00 FS	*- FS
127	1		*FRONT SPORT RIM	Dented	550.00 FS	*550.00 FS
128	1		*FRONT NUMBER PLATE (EMBASSED)	Serviceable	50.00 FS	*- FS
129	1		*FRONT DOOR SIDE MIRROR ASSY LH	Mtg Distorted	645.13 FL	*645.13 FL
130	1		*FRONT SHOCK ABSORBER COVER LH	Cracked	55.85 FL	*55.85 FL
131	1		*FRONT SHOCK ABSORBER BUSH LH	Necessary	34.91 FL	*34.91 FL
132	1		*FRONT STEERING RACK & PINION ASSY	Bent/ Jammed	1,963.93 FL	*1,963.93 FL
133	1		*FR SHOCK ABSORBER COOL SPRING WEATHERSTRIP LH	Serviceable	45.65 FL	*- FL
134	1		*FR RADIATOR LOWER CROSS MEMBER SIDE SUPPORT MEMBER R/H	Repair	292.50 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	59,346.73	32,248.98
- List Item Discount on L Items 25.00/25.00% (S\$)	14,530.43	7,918.50
Total Parts (S\$)	44,816.30	24,330.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FROM ACCIDENT PLACE TO WORKSHOP	New	60.00	60.00
2	TOWING FROM WORKSHOP TO REPORTING CENTRE AND BACK TO WORKSHOP	New	100.00	100.00
3	COMPUTER 4 WHEELS ALIGNMENT (BEFORE REPAIR) }	New	120.00	120.00
4	COMPUTER 4 WHEELS ALIGNMENT (AFTER REPAIR) }	New	120.00	-
5	REMOVE AND REFIX FRONT WINDSCREEN	New	250.00	120.00
6	REMOVE AND REFIX AIRCON SYSTEM, VACUUM AIRCON SYSTEM AND CHECK FOR LEAK	New	250.00	100.00
7	COMPUTER HIGH SPEED WHEEL BALANCING	New	180.00	30.00
8	REMOVE & REFIX FRONT UNDERCARRIAGE, CROSS MEMBER & RELATED PARTS	New	1,200.00	0.00
9	REMOVE & REFIX ENGINE, GEAR BOX, CHECK ENGINE MOUNTING & WIRE HARENESS WIRE AND RADIATOR, CHECK COOLANT, TEMPERATURE AND GEAR BOX FLUID	New	1,500.00	0.00
10	CHECK WIRING & REPAIR, COMPUTER CHECK, SETTING, ERASE FAULT CODE AND PROGRAMMING	New	600.00	200.00
11	REMOVE & REFIX FRONT LEFT DOOR GLASS & POWER WINDOW SYSTEM	New	180.00	80.00
12	REMOVE & REFIX FRONT LEFT SLIDING DOOR WINDOW, POWER WINDOW SYSTEM, SLIDING DOOR LOCK AND SLIDING DOOR SYSTEM	New	180.00	80.00
13	SUPPLY & INSTALL SUN VISOR	New	480.00	180.00
14	SPRAY PAINT	New	3,000.00	2,200.00
15	WASH CUSHION AND VACUUM	New	350.00	0.00
16	SPRAY PAINT ANTI-RUST COATING	New	350.00	150.00
17	LABOUR CHARGE FOR REPAIRING, ADJUSTING, KNOCKING, WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE, TESTING WATER LEAKING AND ON ROAD VEHICLE TESTING	New	3,000.00	1,400.00
18	REMOVE & REFIX DASHBOARD AND RADIO SYSTEM, AIRCON BLOWER, VENTILATION VENT, COOLING COIL AND HEATER SYSTEM	New	700.00	0.00
Gross Labour Cost (S\$)			12,620.00	4,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >