

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711

TEL: 63476100 FAX: 62244174
 ATTN: Motor Claim Department

Claim Type: Third Party
 Accident Date: 26/08/2018
 TP Veh Reg No: SHB4153K

Xiao Tony

Estimate No: EST1800277

Date: 30 Aug 2018

Veh Reg No: SJM819T

Make/Model: HONDA FIT

Chasis No: GE61130606

Reg. Date:

Your Ref No: SHB4153K

Estimate Repair Cost to Vehicle No :SJM819T

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC BOOT LID <i>Dented</i>	871.50 ✓	
2	1 PC BOOT LID LOGO <i>new</i>	35.00 ✓	
3	1 PC BOOT LID FIT EMBLEM <i>new</i>	35.00 ✓	
4	1 PC BOOT LID TRIM <i>new</i>	284.20 ✓	
5	1 PC BOOT LID LOCK <i>new</i>	189.00 ✓	
6	1 PC BOOT LID LOCK CHECKER <i>new</i>	28.40 ✓	
7	1 PC BOOT LID RUBBER <i>new</i>	182.40 ✓	
8	1 SET REAR WINDSCREEN RUBBER <i>new</i>	125.00 ✓	
9	1 PC TAIL LAMP - RH <i>new</i>	286.20 ✓	
10	1 PC REAR PANEL <i>Dented</i>	296.50 ✓	
11	1 PC REAR PANEL TRIM <i>crushed</i>	90.80 ✓	
12	2 PCS REAR BUMPER BRACKETS <i>new</i>	96.40 ✓	
13	2 PCS REAR BUMPER RETAINERS <i>new</i>	56.60 ✓	
14	1 PC REAR TOWING COVER <i>missing</i>	31.40 ✓	
15	2 PCS EXHAUST PIPE MOUNTINGS <i>new</i>	82.40 ✓	
		2,690.80	
	Less 20%	538.16	2,152.64
	Special Net		
16	1 SET BOOT LID TRIM CLIPS <i>new</i>	60.00 <i>30</i>	
17	1 TUBE REAR WINDSCREEN SEALANT <i>new</i>	60.00 <i>30</i>	
18	1 PC REAR WINDSCREEN SEAL <i>new</i>	60.00 <i>30</i>	
19	1 PC REVERSE CAMERA <i>new</i>	480.00 ✓	
20	1 PC RADIO AMPLIFIER <i>new</i>	1,000.00 ✓	
21	1 SET REAR PANEL TRIM CLIPS <i>new</i>	40.00 <i>10</i>	
22	1 PC REAR BUMPER <i>Dented</i>	1,200.00 <i>800</i>	
23	1 SET REAR BUMPER CLIPS <i>new</i>	50.00 <i>30</i>	
24	1 SET REVERSE SENSORS <i>new</i>	250.00 <i>200</i>	
25	1 PC REAR BUMPER GRILLE <i>new</i>	120.00 ✓	
26	1 PC EXHAUST PIPE <i>new</i>	1,400.00 ✓	

2164.40

1731.52

Less 20%

1130

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 26/08/2018
TP Veh Reg No: SHB4153K

Estimate No: EST1800277
Date: 30 Aug 2018

Veh Reg No: SJM819T
Make/Model: HONDA FIT
Chassis No: GE61130606
Reg. Date:
Your Ref No: SHB4153K

Estimate Repair Cost to Vehicle No :SJM819T

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
		4,720.00	4,720.00
	Labour		
27	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00 800	
28	1 TO REMOVE AND REFIT REAR WINDSCREEN GLASS	120.00 ✓	
29	1 TO REMOVE AND REFIT BOOT LID TRIM AND SPEAKER COVER	180.00 80	
30	1 TO REMOVE AND REPLACE REAR EXHAUST PIPE	200.00 80	
31	1 TO SPRAY UNDERSEAL	100.00 50	
32	1 TO SPRAY PAINTING	1,200.00 600	
33	1 TO REMOVE AND REPLACE REVERSE SENSOR	80.00 40	
34	1 TO REMOVE AND REPLACE REVERSE CAMERA	80.00 40	
35	1 TO CHECK WIRING	50.00 30	
		3,210.00	3,210.00
	Total		SS 10,082.64
	Add GST @ 7%		705.78
	Total Amount Payable		SS 10,788.42

TOTAL: SINGAPORE DOLLAR TEN THOUSAND SEVEN HUNDRED EIGHTY EIGHT AND CENTS FORTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour

LKK Auto Consumers may be required after work has begun.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
H/S 03/09/18
06 Ramp

total: 4701.52

H/S: 3750 ✓

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE