

RACUL

ASSIGNMENT

Enq:

4/9/2018

Case No:

03/09/2018

Pre-assign / CCU / FTE



Insured Vehicle No. : 68631237

Name of Insured : WA KUN WAN ENG.

Insured Tel No. : HP: 1918/2018

Excess Sec II : S\$ D.O.A. : 1918/2018

Is driver the owner? ☒ NO Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. : (V/L YES / NO)

SLE 4708Y

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / NO



INSRS:
WSP: Any others.
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

18/11

SLE 4708Y - X ; 68631237 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 25/11/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

Receive TP CCU.

5/11/18

Called car confirm accident details. Inform OI we receive TP CCU. Agree to settle later and out

RECEIVED 14 DEC 2018

PRELIMINARY ADVICE

Date/Time:

18/11

Sent By:

12/11

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

14/11/18

Confirm with: ERIC

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No. :

NIL

If NO or B 28, Ass. Lia

Repair Cost:

S\$

1200.00

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

150.00

(S 20 x 3

days)

Loss of Income (LOI):

S\$

(S

x

days)

LOR only ☐ LOU only ☐

LOR + LOU ☐

LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

1357.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

1357.45

[Signature]

Rong Sheng Auto Engineering Trading

Payee 2: (Strike if N.A.)

S\$

Payee 3: (Strike if N.A.)

S\$

[Signature]

RONG SHENG AUTO ENGINEERING TRADING

NO 42 TOH GUAN ROAD EAST

01-79 ENTERPRISE HUB

SINGAPORE 608583

TEL : 9239 9009

REG NO : 53181821K

QUOTATION/ESTIMATE

VEHICLE NO : SLE4708Y - Rm 1126 1732 / 2016

RE: REPAIR VEHICLE ON HONDA VEZEL

DATE : 31/08/2018

TO : EQ INSURANCE COMPANY LTD

REFER NO : RSA/2018/ TP08/ 0012

PARTS DESCRIPTION

QTY UNTIL PRICE AMOUNT

NETT ITEMS

1 FRONT BUMPER	1	\$801.70	\$801.70	DE-
2 FRONT BUMPER RETAINER LH	1	\$18.10	\$18.10	ME-
3 FRONT BUMPER REINFORCEMENT	1	\$290.80	\$290.80	? *1-
4 FRONT FOG LAMP OUTER GARNISH LH	1	\$45.50	\$45.50	? X W
5 FRONT FOG LAMP LH	1	\$327.20	\$327.70	X W
6 LH FRONT FENDER	1	\$435.40	\$435.40	repair X
7 FRONT BUMPER CLIPS	10	\$2.80	\$28.00	ME-
TOTAL :		\$1,921.50	\$1,947.20	1138.60
LESS 20 %		\$384.30	\$389.44	202
TOTAL :		\$1,537.20	\$1,557.76	910.88

TOTAL SPARE PARTS : \$1,537.20 \$1,557.76

LABOUR DESCRIPTION

AMOUNT

1 LABOUR FOR PANEL BEATING	\$600.00	300
2 LABOUR FOR SPRAYPAINTING	\$600.00	400 / 700
3 WIRING	\$50.00	X M
4 RUST PROOF ON ACCIDENT AREAS	\$100.00	X W

TOTAL LABOUR : \$1,350.00

TOTAL PARTS AND LABOUR : \$2,907.76



PREPARE BY : ERIC KEE

Rasul
Hp 90010068
3 days
L/S
04/09/18 @ 1535
Recd after repair

910.88
700.00
1610.88
202
1288.70
43-1200
3 days

RONG SHENG AUTO ENGINEERING TRADING

NO 42 TOH GUAN ROAD EAST

01-79 ENTERPRISE HUB

SINGAPORE 608583

TEL : 9239 9009

REG NO : 53181821K

QUOTATION/ESTIMATE

RE: REPAIR VEHICLE ON HONDA VEZEL

TO : EQ INSURANCE COMPANY LTD

PARTS DESCRIPTION

NETT ITEMS

1	FRONT BUMPER	1	\$801.70	\$801.70 <i>Re-</i>
2	FRONT BUMPER RETAINER LH	1	\$18.10	\$18.10 <i>Re-</i>
3	FRONT BUMPER REINFORCEMENT	1	\$290.80	\$290.80 <i>?</i>
4	FRONT FOG LAMP OUTER GARNISH LH	1	\$45.50	\$45.50 <i>?</i>
5	FRONT FOG LAMP LH	1	\$327.20	\$327.70 <i>X</i>
6	LH FRONT FENDER	1	\$435.40	\$435.40 <i>repair</i>
7	FRONT BUMPER CLIPS	10	\$2.80	\$28.00 <i>Re-</i>

TOTAL :	\$1,921.50	\$1,947.20
LESS 20 %	\$384.30	\$389.44
TOTAL :	\$1,537.20	\$1,557.76

TOTAL SPARE PARTS :	\$1,537.20	\$1,557.76
---------------------	------------	------------

LABOUR DESCRIPTION

AMOUNT

1	LABOUR FOR PANEL BEATING	\$600.00 <i>300</i>
2	LABOUR FOR SPRAYPAINTING	\$600.00 <i>400</i>
3	WIRING	\$50.00 <i>X</i>
4	RUST PROOF ON ACCIDENT AREAS	\$100.00 <i>X</i>

TOTAL LABOUR :	\$1,350.00
----------------	------------

TOTAL PARTS AND LABOUR :	\$2,907.76
--------------------------	------------



PREPARE BY : ERIC KEE

RASUL
Hp 90010068
3 days
L/S
04/09/18 @ 1535
Recd after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

VEHICLE NO: **SLE4708Y** must be resurveyed and is subject to final approval from Insurance Company

DATE: **31/08/2018**

Signature:

Date:

REFER NO: **RSA/2018/TP08/0012**

QTY UNTIL PRICE AMOUNT



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/EQ118015991/R1wa3

Date: 07.09.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SLE 4708Y


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04.09.2018 at the premises of M/s Rong Sheng Auto Engineering Trading have the following to report:-

Workshop Estimate Amount	: S\$	2,907.76
Revised Estimate Amount	: S\$	1,378.24
"Check" Items Amount	: S\$	269.04
Total (Including Check Items)	: S\$	1,647.28
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Mei Kwan (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Friday, 12 October, 2018 11:31 AM
To: Mei Kwan (LKKAUTO)
Cc: Thin Thin (LKKAUTO); Vivian Lau (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving GBG3123Z (OI : EQI - DM18HO02311-JG) AND SLE4708Y (TP : LKK REF - CC6/EQI18015991/R1wa3) on 19/08/2018
Attachments: GBG3123Z (19.08.18).pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Joel Goh
Sent: Thursday, September 27, 2018 3:01 PM
To: 'Mei Kwan (LKKAUTO)'
Cc: Thin Thin (LKKAUTO); Vivian Lau (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving GBG3123Z (OI : EQI - DM18HO02311-JG) AND SLE4708Y (TP : LKK REF - CC6/EQI18015991/R1wa3) on 19/08/2018

Dear Mei Kwan

Our insured has not reported this accident.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Mei Kwan (LKKAuto) [mailto:MeiKwan@lkkauto.com]

Sent: Monday, September 10, 2018 2:19 PM

To: Joel Goh

Cc: Thin Thin (LKKAuto); Vivian Lau (LKKAuto); Admin A

Subject: RE: Direct Settlement - Accident Involving GBG3123Z (OI : EQI - TBA) AND SLE4708Y (TP : LKK REF - CC6/EQI18015991/R1wa3) on 19/08/2018

WITHOUT PREJUDICE

EQI ref: TBA

LKK REF: CC6/EQI18015991/R1wa3

Dear Joel,

We refer to the above matter.

Enclosed revert of vehicle: SLE 4708Y

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Wednesday, 5 September, 2018 11:49 AM

To: Joel Goh <joel.goh@eqinsurance.com.sg>

Cc: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Dear Joel,

We refer to the above matter.

This is a TP direct settlement case from M/s Rong Sheng Auto Engineering Trading.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

RONG SHENG AUTO ENGINEERING TRADING

(Reg No : 53181821K)

No 42 TOH GUAN ROAS EAST #01-79

ENTERPRISE HUB

SINGAPORE 60858

TEL :82390099

Letter Of Demand

Dear Sir ,

We act on behalf of the owner of vehicle No : SLE4708Y
Ms AKY LEASING to claim against you insured vehicle no
GBG3123Z on accident date 19/08/2018

The below following is :

- 1)Cost Of Repair =\$1200.00
- 2)Loss Of Use(04days x \$60.00)=\$240.00
- 3)LTA Search fee = \$7.49

Total =\$ 1447.49

Regards

Eric Kee

8239 0099





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/EQ118015991/R1wa3

10 December 2018

Loh Kim Wan Engineering
2 Sixth Lok Yang Rd,
Singapore 628100

Dear Sir/Madam,

ACCIDENT INVOLVING GBG 3123Z AND SLE 4708Y ON 19/08/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. **EQ INSURANCE COMPANY LIMITED**
(Motor Claims Dept)

RONG SHENG AUTO ENGINEERING TRADING

NO 42 TOH GUAN ROAD EAST

#01-79 ENTERPRISE HUB

SINGAPORE 608583

LETTER OF AUTHORISATION

I, AKY Leasing ("the third-party claimant"), of
_____ (address)

of the owner of SLE 47084 (vehicle no), hereby
authorise **RONG SHENG AUTO ENGINEERING TRADING** ("the workshop")
to act for me with respect to my claim for repair costs and/or rental and/or loss
of use ("the claim") for my vehicle no. SLE 47084 that was damaged
involving in the accident which occurred on 19/08/2018 (date) along

Jurong West Street 42.
(location) involving vehicle/s no. ABG 3123Z ("the accident").

I further authorise the workshop to settle my above mentioned claim in a manner that
they are deem fit and the workshop is further authorised to receive payment to
settlement of my claim with payment cheque/s being made in favour to the
workshop.

I further acknowledge that any settlement the workshop may reach with your
company on my behalf is on a without prejudice and without admission of liability
basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this on 01 day of 09 (month) 20 15 (year).

AKY LEASING
Reg No : 53339339J

Signature

(the third-party claimant)



Signature with company's stamp

(Workshop)

荣昇汽车贸易

RONG SHENG AUTO ENGINEERING TRADING

Blk 42 Toh Guan Road East #01-79 Enterprise Hub Singapore 608583

H/P: 9239 9009 / 8239 0099

(Reg. No. 53181821K)

CASH / INVOICE

INVOICE NO: 04236

Name / Address: <i>BQ Insurance COMPANY LTD</i>	Date: <i>24/10/2018</i>
	Vehicle No: <i>SLE 47084</i>
	Make of Vehicle: <i>Honda</i>
	Model of Vehicle: <i>Vezel</i>
	Your ref: <i>-</i>
	My ref: <i>-</i>

S/N	Qty	Descriptions	Unit Price	Amount S\$
01	-	<i>Cost of Repair</i>	-	<i>\$1200.00</i>
Remarks:			Total S\$	<i>1200.00</i>



RONG SHENG AUTO ENGINEERING TRADING

Recipient Signature



[Handwritten Signature]

Specialist of Motor Vehicles Repair & Services, Spray Painting, Panel Beating,
Accident Insurance Claims & Others.

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 31 Aug 2018 / 14:20:28

Receipt Date/Time : 31 Aug 2018 / 14:20:28

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180831-001290

Previous Receipt No. :

S/N Item Description/

**Business Transaction Reference
No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - YN6486Y

As at 31 Aug 2018/07:00:00

Insurance Co: ALLIED WORLD ASSURANCE COMPANY, LTD
(SINGAPORE BRANCH)

1 Insurance Enquiry - YN6486Y
Enquiry Fee
20180831141912584351

7.00	0.49	7.49
------	------	------

Sub-Total

7.00	0.49	7.49
------	------	------

Result of Insurance Enquiry - GBG3123Z

As at 19 Aug 2018/12:50:00

Insurance Co: EQ INSURANCE COMPANY LTD

2 Insurance Enquiry - GBG3123Z
Enquiry Fee
20180831141912634295

7.00	0.49	7.49
------	------	------

Sub-Total

7.00	0.49	7.49
------	------	------

Total Before Rounding

14.00	0.98	14.98
-------	------	-------

Rounding Difference

0.03

Total Amount Payable

14.95

Paid By

20180831141946837 Direct Debit: eNETS Debit
(Internet Banking)

14.95

Total

14.95

Cash Change

0.00

Tendered Amount

14.95

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 20/12/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBG 3123Z	(Insd Veh)	Your Ref. No. : DM18HO02311-JG
	SLE 4708Y	(TP Veh)	Our Ref. No. : CC6/EQI18015991/R1wa3q2
Date of Accident	19/8/2018		

Liability	100%	
Final Repair Cost	: \$ 1,200.00	
Loss of Use	: \$ 150.00	3 days
Rental (If any)	: \$	days
Others:	: \$ 7.45	
	: \$	
	1,357.45	
Final Settlement Sum	: \$ 1,357.45	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	RONG SHENG AUTO ENGINEERING TRADING	: \$ 1,357.45
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQI18015991/R1wa3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 20-12-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 3123Z	Veh. Inspected	SLE 4708Y
Policy No.	DMCPHQ18-004442	Coverage (\$)	0.00
Claim No.	DM18HO02311-JG	Excess (\$)	0.00
Assign From		Assign Date	04/09/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11201932	Colour	WHITE
Odometer	061694	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/08/2018	Inspection Date	04/09/2018
Survey held at	RONG SHENG AUTO ENGINEERING TRADING 42 TOH GUAN ROAD EAST #01-79 ENTERPRISE HUB SINGAPORE 608583		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 4708Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	801.70	801.70
1	FRONT BUMPER RETAINER LH	NECESSARY	18.10	18.10
1	FRONT BUMPER REINFORCEMENT	BENT	290.80	290.80
1	FRONT FOG LAMP OUTER GARNISH LH	NOT NECESSARY	45.50	-
1	FRONT FOG LAMP LH	NOT NECESSARY	327.70	-
1	LH FRONT FENDER	TO REPAIR SEE LABOUR	435.40	-
10	FRONT BUMPER CLIPS @\$2.80	NECESSARY	28.00	28.00
	LESS 20% DISCOUNT		-389.44	-227.72
			1,557.76	910.88
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING INCLUSIVE OF THE REPAIR OF LH FRONT FENDER .		600.00	300.00
	LABOUR FOR SPRAY PAINTING.		600.00	400.00
	WIRING .	NOT NECESSARY	50.00	-
	RUST PROOF ON ACCIDENT AREAS.	NOT NECESSARY	100.00	-
			1,350.00	700.00
	GRAND TOTAL		2,907.76	1,610.88
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00

Report Ref No. CC6/EQ18015991/R1wa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.