

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

31-Aug-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6263 H

1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00
1 pc	Rear bumper n/s reflector @ \$46.00	\$	46.00
			<hr/>
			\$ 1,907.00
Less 10%			\$ 190.70
			<hr/>
			\$ 1,716.30

### S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	<del>280.00</del> 200
Sundry		\$	<del>50.00</del> X
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	<del>120.00</del> 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	<del>180.00</del> X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc		\$	<del>650.00</del> 200 180
To putty and spray painting on rear bumper, end panel		\$	<del>400.00</del> X
To apply rustproofing on the repaired and replaced panels.		\$	<del>120.00</del> X
			<hr/>
			\$ 3,564.30

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

Kahin 10/16

3-18/18 11x5hr  
2 hrs  
L/S  
After Rep-photos