

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

01/09/2018 13:52

JOB-NO: 50110925

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC7067B

TRANS: AUTO

CHASSIS: KMHLB41UMGU086822

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDFU606406

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	850.00	0.00	850.00		Y	200
2 RUST PROOFING	1.00	80.00	0.00	80.00		Y	X
3 SUNDRIES	1.00	50.00	0.00	50.00		Y	20
4 R&R SPARE TYRE BOARD/ CARPET/ TRIM	1.00	120.00	0.00	120.00		Y	40
5 R&R REAR EXHAUST PIPE & MUFFLER LH	1.00	120.00	0.00	120.00		Y	X
6 R&R REVERSE SENSOR	1.00	60.00	0.00	60.00		Y	30
7 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
8 RESPRAY REAR BUMPER DIFFUSER	1.00	250.00	0.00	250.00		Y	100
9 RESPRAY REVERSE SENSOR	1.00	60.00	0.00	60.00		Y	30
10 RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	X
TOTAL:		2,090.00	0.00	2,090.00			

MATERIALS

1 REAR BUMPER	1.00	599.68	0.00	599.68	L	Y	de
2 REAR BUMPER DIFFUSER	1.00	228.40	0.00	228.40	L	Y	cut
3 REAR BUMPER REFLECTOR LH	1.00	43.85	0.00	43.85	L	Y	int
4 REAR BUMPER RETAINER LH	1.00	42.63	0.00	42.63	L	Y	re
5 REAR BUMPER RETAINER RH	1.00	42.63	0.00	42.63	L	Y	X
6 REAR EXHAUST PIPE & MUFFLER LH	1.00	967.22	0.00	967.22	L	Y	X
7 REAR EXHAUST PIPE & MUFFLER GASKET LH	1.00	42.88	0.00	42.88	L	Y	X
8 REAR BUMPER REINFORCEMENT	1.00	484.40	0.00	484.40	L	Y	?
9 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	98.63	0.00	98.63	L	Y	?
10 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	98.63	0.00	98.63	L	Y	?
11 REAR BUMPER REINFORCEMENT SPONGE	1.00	89.62	0.00	89.62	L	Y	?
12 REAR END PANEL	1.00	629.95	0.00	629.95	L	Y	RX
13 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	re
14 REAR BUMPER ADS STICKER	1.00	120.00	0.00	120.00	S	Y	re
15 REAR BUMPER REVERSE SENSOR SET	1.00	230.00	0.00	230.00	S	Y	200?
16 REAR BUMPER RUBBER PROTECTOR PAD	1.00	150.00	0.00	150.00	S	Y	re
17 REAR FENDER ADS STICKER LH	1.00	180.00	0.00	180.00	S	Y	re
18 REAR FENDER ADS STICKER RH	1.00	180.00	0.00	180.00	S	Y	re
19 REAR END PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	X
TOTAL:		4,313.52	0.00	4,313.52			

TOTAL PARTS & LABOUR :

6,403.52

0.00

6,403.52

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

EXCESS/LOADING:\$ 0.00

No. Of Day: 02 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY: 03/09/18

SURVEYED BY: Tarfin

CONTACT NO: 92495749 FAX NO: _____

Resurvey before paint
surelkhands.com

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL: _____ FAX: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____