






✓






✓




✓














7
1

Power Quality Monitoring















9
e









PAR Automotive Consultancy

Regn. No. 12986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0326-18-TCA

25 June 2018

ACCIDENT VEHICLE SURVEY REPORT

System Technic Engineering Pte Ltd
c/o Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No.:	GU3426S	Odometer:	430582km
Make & Model:	Toyota Hiace	Colour:	Silver
Chassis number:	LH1721003298	Date of accident:	27/09/2017
Year of Regn.:	01/03/2001	Date inspected:	29/09/2017
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	20/10/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.



