

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0924/2018
DATE : 01-SEP-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : FABIAN CHEW PENG BOON
ADDRESS : APT BLK 11 PINE CLOSE
#05-101
S(391011)
TELEPHONE NO : 9111 5279

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 2100484074
VEHICLE NO : SFQ183U
MODEL CODE : SJ5DK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y416617
CHASSIS NO : JF1S5J5KC5GG077744
MILEAGE : 1 KM
DATE IN : 01/09/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 30/08/2018

Print Date : 01/09/2018
Print Time : 09:14:43

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SPQ183U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	OD/CLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM AIG LOCATION:KPE TO CHANGIAIRPORT DATE:30/08/2018 TIME:1631HRS		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER, FRT RHS FENDER, FRT HOOD AND PANEL	1500.00	625/
4	ZZ/003	RESPRAY FRONT BUMPER, FRT RHS FENDER, FRT HOOD AND PANEL	1200.00	800/
5	ZZ/004	FAULT DIAGNOSTIC CHECK AND RESET SYSTEM	235.00	?
6	ZZ/005	TO CONDUCT FRONT ANTI-RUST COATING	NI 290.00	K
7	ZZ/006	REMOVE & REFLEX FRONT HEADLAMP WASHER AND PIPING	125.00	?
8	ZZ/007	SUNDRIES	100.00	20/
TOTAL LABOUR CHARGES			3450.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFQ183U

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 FRAME SD FF CP RH	51620SG0219P			540.00	?
2 RAD PNL COMPL RFR	53029SG0019P			360.00	?
3 FRT FENDER RH	57120SG0209P			<i>Bu</i> 270.00	✓
4 EXT FENDER F CP RH	57160SG0009P			25.20	?
5 HOOD F CPL	57229SG0009P			<i>Bu</i> 882.00	✓
6 STAY ASSY F HOOD	57251SG001			<i>K</i> 93.60	X
7 COVER FENDER UPR RH	57256SG020			18.00	?
8 HINGE COMPL F HD RH	57260SG0009P			<i>D.Y</i> 43.20	✓
9 HINGE COMPL F HD LH	57260SG0109P			43.20	?
10 BUMPER FACE F STD	57704SG030			<i>Bu</i> 502.60	✓
11 BRKT CORNER F RH	57707SG000			<i>cm</i> 36.00	✓
12 BRKT SD F RH	57707SG020			12.60	?
13 MOLDING EMPR F	57708SG000			43.20	?
14 BUMPER FACE F NA	57709SG030			594.00	?
15 BACK BEAM CPL F	57711SG0009P			288.00	?
16 ENERGY ABSOR F	57722SG020			126.00	?
17 COVER HOOK F STD	57731SG220			<i>Sm</i> 4.30	X
18 MUD GUARD ASSY F RH	59110SG021			<i>D.Y</i> 86.40	✓
19 LAMP ASSY HEAD EOF RHS	84002SG220			<i>ngent</i> 2380.00	✓
20 FOG LAMP ASSY F LHS	84501AJ060			272.00	?
21 BRKT F FOG ASSY RH	84927SG020			19.80	?
22 NOZZLE H L WASHERRH	86636SG361			80.00	?
23 NOZZLE COVER ASSTRH	86636SG380TQ			<i>m,y</i> 54.00	✓
24 GRILLE ASSY F UPR	91121SG210			140.40	?
25 GRILLE ASSY F CT	91121SG240			180.00	?

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFQ183U

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
26 GRILLE ASSY F LWRHG	91121SG280			52	316.80 X
SUB TOTAL		0.00	0.00	0.00	7411.30
LESS DISCOUNT (S/LIST-30 %)		0.00	0.00	0.00	2223.39
GRAND TOTAL		0.00	0.00	0.00	5187.91
OVERALL TOTAL		5187.91			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255


SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFQ183U

TOTAL LABOUR CHARGES	3450.00
TOTAL SPARE PARTS CHARGES	5187.91
GRAND TOTAL	8637.91 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:



For d/s

6 days

Not Authorized
1-B-1
Resurvey B4 point

Kenneth

Ref: 62564315

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: