

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

31-Aug-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8674 Y

1 pc	Front bumper <i>X rep</i>	\$	531.00
1 pc	Front bumper emblem <i>re</i>	\$	44.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>X</i>	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 <i>X</i>	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00	\$	32.00
1 pc	n/s headlamp <i>X</i>	\$	1,028.00
1 pc	Front bumper n/s fog lamp cover <i>X</i>	\$	66.00
1 pc	Front bumper n/s protector <i>X</i>	\$	51.00
1 pc	Front n/s fender inner shield <i>X</i>	\$	120.00
1 pc	Front n/s wheel cover <i>✓</i>	\$	116.00
		\$	2,052.00

Less 10%

S/NETT

1 pc	Front bumper clips <i>X</i>	\$	48.00
1 pc	Front n/s head lamp lower clip <i>X</i>	\$	6.00
2 pcs	Front n/s head lamp side clip <i>X</i>	\$	3.00
1 set	Front n/s fender inner shield clips <i>X</i>	\$	28.00
1 pc	Front n/s fender sticker <i>re</i>	\$	30.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

To check for wiring and to focus head lamps

4/9/18 1315h \$ 80.00 *X*

To check wheel alignment

20p \$ 80.00 *X*

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

4/5
After Repair photo \$ 180.00 *X*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s fender, etc.

200
\$ ~~750.00~~

To putty and spray painting on front bumper, front n/s fender

360
\$ ~~500.00~~

To apply rustproofing on the repaired and replaced panels.

\$ ~~100.00~~ *X*
\$ 3,651.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.