

ASSIGNED BY:

REF:

CS/CT18016010/Kqbn2

Special Instruction:

SURVIVOR

Kenneth

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CR

Date/Time:

03/09/2018 11:05am

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

3LV 9892A

Insured:

GV 5567A

at Workshop m/s

Autowork House

Tel:

of

176 Sin Ming Drx #02-01

Policy No:

DMCVSN 3026161801

Claim No:

SNM18P042243 (U).

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31082018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

03/09/2018 - 11:00am

Person Contacted:

Yuki

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	3LV 9892A x
	GV 5567A - x
14/3	Call 810,000 email
9/5	Re-broker 810,000 email (Red to 7150.00, 40%)
17/11/19 @ 11.09am	confirmed with Ms Lee LS @ 10700 by email.

ASS. REC. BY:

REF: C721

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Wb max

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLV 9892A Yr Regn: 01, 18Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or AMake: Mazda 3 c.c. 1.8Colour: M. Blue A/C: Insured / Std / NI / NASp. Reading: 10344 T/Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C/No: JN 6BN 24A 8 J 0200573Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 3/18/18

Survey held at

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or& 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/19 File pass to Catherine, em not ready

RECEIVED 20 NOV 2019

Date/Time, File Pass to?

☐ : Prell. Report11/19/11 MM☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 9Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS - SI

Fixes

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

TOTAL

220

Report Format :

Lump Sum / I.B.T. (\$

MEK-TPLO 700

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Aug 2018		03 Sep 2018 11:05 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	SING SEE SOON FLORAL & LANDSCAPE, Co. Reg. No.: 200009355G								
Main Claimant:	WOO LIAH MENG								
Vehicle Reg. No.:	SLV9892A	Date of Loss:	31/08/2018 10:00 - :59						
Claim Type:	TP / SNM18D04243C02	Policy/Cover Note No.:	DMCVSN3028161801 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	GV5567A	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Autoworx House - Sin Ming (HQ) 176 SIN MING DRIVE #02-01, 575721 Sin Ming - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/09/2018]								
Adj Asg. Remarks:	NO EST, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All   Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All   Search Tasks   Create New Task   Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

03192018 @ 1147am

Yuki Vohin.

Kenneth

## Shiau Chan (LKKAuto)

---

**From:** claim.autoworxhouse@gmail.com  
**Sent:** Tuesday, 19 November 2019 11:09 AM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** RE: SLV 9892 A

Dear Shiau Chan,

We accept your offer of \$10,700.00/-- for the repair cost.  
Thank you.

Best regards,  
Ms. Lee  
Autoworx House  
No.176 Sin Ming Drive  
#02-01 Singapore 575721  
Tel: 96725547 / 87668115  
Fax: 64517423

-----Original Message-----

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
Sent: Tuesday, November 19, 2019 10:32 AM  
To: admin@supreme.sg; Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>  
Subject: RE: SLV 9892 A

Dear Winnie,

Can confirm the repair cost as the insurance company chase us for report.

Best Regards,  
Shiau Chan (Ms) | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,  
#02-25 | S(408933)

-----Original Message-----

From: Shiau Chan (LKKAuto)  
Sent: Tuesday, 5 November 2019 10:54 AM  
To: admin@supreme.sg; Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>  
Subject: RE: SLV 9892 A

Dear Winnie,

Please find the attached of our surveyor's marking.

About the supplementary list, we have already replaced the prices in original estimate.

Best Regards,  
Shiau Chan (Ms) | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,  
#02-25 | S(408933)

-----Original Message-----

From: admin@supreme.sg <admin@supreme.sg>  
Sent: Tuesday, 21 May 2019 10:19 AM  
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>  
Subject: RE: SLV 9892 A

Hi Kenneth,

Can I have a copy of the marked supplementary estimate?  
Thank you.

Best regards,  
Yuki Ho  
Supreme Auto Service Pte Ltd  
No.176 Sin Ming Drive  
#02-01 Singapore 575721  
Tel: 64528211  
Fax: 64517423

-----Original Message-----

From: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>  
Sent: Thursday, 9 May 2019 9:34 AM  
To: admin@supreme.sg  
Subject: RE: SLV 9892 A

Attach finalised for SLV 9892A.

-----Original Message-----

From: admin@supreme.sg [mailto:admin@supreme.sg]  
Sent: Monday, 25 February, 2019 12:22 PM  
To: Kenneth Kong (LKKAuto)  
Subject: RE: SLV 9892 A

Attached is the estimate.

Best regards,  
Yuki Ho  
Supreme Auto Service Pte Ltd  
No.176 Sin Ming Drive  
#02-01 Singapore 575721  
Tel: 64528211  
Fax: 64517423

-----Original Message-----

From: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>  
Sent: Friday, 22 February 2019 9:15 AM  
To: admin@supreme.sg  
Subject: RE: SLV 9892 A

Where is the estimate of this case??

-----Original Message-----

From: admin@supreme.sg [mailto:admin@supreme.sg]  
Sent: Thursday, 21 February, 2019 2:40 PM  
To: Kenneth Kong (LKKAuto)  
Subject: RE: SLV 9892 A

Hello Kenneth,

Are we able to finalise this case?  
Thank you so much.

Best regards,  
Yuki Ho  
Supreme Auto Service Pte Ltd  
No.176 Sin Ming Drive  
#02-01 Singapore 575721  
Tel: 64528211  
Fax: 64517423

-----Original Message-----

From: admin@supreme.sg <admin@supreme.sg>  
Sent: Tuesday, 29 January 2019 9:49 AM  
To: 'Kenneth Kong (LKKAuto)' <KennethKong@lkkauto.com>  
Subject: SLV 9892 A

Hello Kenneth,

Attached are the estimate and resurvey photos for your finalisation.  
Thank you.

Best regards,

Yuki Ho  
Supreme Auto Service Pte Ltd  
No.176 Sin Ming Drive  
#02-01 Singapore 575721  
Tel: 64528211  
Fax: 64517423

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	31/08/2018 16:34
Date Of Accident	31/08/2018 09:55
Exact Location Of Accident	KALLANG ROAD TOWARDS VICTORIA STREET
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV9892A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WOO LIAH MENG
NRIC No	S1121631E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96300671
Alternative Phone No	OTHERS-96300671

### Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800011708
Cover Note Number	

### Driver

Name of Driver	WOO LIAH MENG
NRIC No	S1121631E
Date Of Birth	12/03/1955
Occupation	INDOOR
Date Of Driving Pass	08/03/1977
Driving Experience	41 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96300671
Fax Number	
Contact Number	OTHERS-96300671
EMail Address	NOEMAIL

Address	133 PASIR RIS GROVE #01-26
Postcode	518131
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GV5567A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	VELAYOUTHAM AYYAPPAN
NRIC/Passport Number	G2198804P
Contact Number	82911360/63156578
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBH34L
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

96605120

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

31 AUG 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:


Jenny Lim

NRIC/FIN No.:

S8927273H

SKETCH PLAN

Vehicle A  
SLV9892A  
Vehicle B  
BVS167A  
Vehicle C  
GBH341



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was along Kallang Road towards Victoria Street. Vehicle C was in front of me, it stopped and I stopped too, as traffic condition was heavy. Suddenly, I felt a huge impact on the rear of my vehicle. Vehicle B pushed into the rear of my vehicle with an impact so big my vehicle moved ahead and bump into vehicle C slightly.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature

Date & Time:  
31 AUG 2018

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: Jenny Lim  
S6927273H



# CERTIFICATE OF INSURANCE

## MAZDA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Woo Liah Meng  
Period of Insurance : 25 Jan 2018 To 24 Jan 2020  
Engine No. : P520492045  
Chassis No. : JM6BN24A8J0200573

Vehicle No. : SLV9882A  
Policy No. : 1800011708  
Endorsement No. : 000000000183141  
Issued Date : 27 Feb 2018

### ABOUT THE COVER

Make/Model : MAZDA 3 1.5 SKYACTIV  
Engine Capacity/Tonnage : 1.496.00 CC  
Driver Restriction : NA  
Sum Insured : Market Value  
Off Peak Car : No  
First Year of Registration : 2018  
Insuring with COE/PAF : Yes

#### Person or Classes of Persons Entitled to Drive\*

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

\*You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDRE") if You are in Your Authorised Driver (named or unnamed) is under the age of 22 and/or has less than 3 years' driving experience.

Age Condition : All Age Condition

#### Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

#### Section 1

Fire - \$0, Own Damage - \$500, Theft - \$0, Flood Cover - \$0

#### Section 2

Property Damage - \$0

Windscreen - \$100

#### Named Driver and Excess (where applicable)

Woo Liah Meng - \$500 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Thong Eunkeng Pte Ltd Add: 5-126 Class, Singapore 400005 81988889

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1969 (Malaysia).)

0503599190

ARF (AP) PTE LTD - MAZDA  
7 MAXWELL ROAD #01-100 ANNEX B MNO COMPLEX  
SINGAPORE 069111

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.  
AUTHORISED REPRESENTATIVE

0503599190

# AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

WOO LIAH MENG  
c/o 46 Lenton Plain  
Singapore 786548

*Not Notified*  
*11 Bmp 810, 700h*  
*Resurvey After Paint*  
*9 days*

Date: 31/8/2018

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QUANTITY	PARTICULARS	AMOUNT (\$)
	<b>RE: MAZDA 3 /SLV 9892 A</b>	
1 pc	front bumper <i>825-w</i>	<i>RM</i> 774.50 ✓
1 pc	front bumper top pad	<i>RM</i> 296.70 ✓
1 pc	front bumper lower air grille	<i>RM</i> 275.80 X
1 pc	front bumper centre inner pad	<i>CM</i> 179.40 ✓
2 pcs	front bumper front centre pad bracket @ 43.70	<i>RM</i> 87.40 X
1 pc	front bumper top grille	<i>RM</i> 654.20 ✓
1 pc	front bumper top grille emblem	<i>RM</i> 66.70 ✓
2 pcs	front bumper top grille chrome moulding @ 276.30	<i>RM</i> 552.60 ✓
2 pcs	front bumper top grille chrome moulding pad @ 67.80	<i>RM</i> 135.60 X
2 pcs	front bumper side retainer @ 45.20	<i>RM</i> 90.40 X
1 pc	front bumper tow cover	<i>RM</i> 31.30 X
2 pcs	front head lamp assy <i>e 1019</i> <i>RM/mg</i> @ 796.70	<i>RM</i> 1,593.40 ✓
1 pc	front number plate support	<i>RM</i> 119.70 X
1 pc	rear bumper <i>949</i>	<i>RM</i> 673.40 ✓
2 pcs	rear bumper side retainer <i>N/S D/S</i> @ 65.30	<i>RM</i> 130.60 ✓
2 pcs	rear bumper reflector @ 196.20	<i>RM</i> 392.40 X
1 pc	rear bumper tow cover	<i>CM</i> 43.50 ✓
1 pc	rear bumper reinforcement	<i>RM</i> 376.50 ✓
1 pc	rear bumper exhaust cover	<i>RM</i> 97.10 X
1 pc	rear tail lamp moulding panel L/H	<i>RM</i> 975.60 X
2 pc	rear tail lamp <i>N/S CM</i> <i>01/mg</i> @ 574.10	<i>RM</i> 1,148.20 ✓
1 pc	rear tail gate <i>1268</i>	<i>RM</i> 975.80 ✓
1 pc	rear tail gate outer garnish	<i>RM</i> 576.30 ✓
1 pc	rear tail gate lock	<i>RM</i> 276.40 ✓
1 pc	rear tail gate lock catch	<i>RM</i> 56.10 X
1 pc	rear tail gate inner trim	<i>RM</i> 377.20 ✓
1 pc	rear tail gate lock switch	<i>RM</i> 117.50 ✓
2 pcs	rear tail gate number plate lamp 96.70	<i>RM</i> 193.40 X
1 pc	rear tail gate lamp <i>0459</i> 396.40	<i>CM</i> 792.80 ✓
1 pc	rear tail gate windscreen glass	<i>RM</i> 1,075.20 ✓
1 pc	rear tail gate windscreen glass moulding	<i>RM</i> 96.30 ✓
	sub-total	13,231.80

	balance brought forward				13,231.80
1 pc	rear tail gate windscreen wiper blade			Sm	79.20 X
1 pc	rear tail gate windscreen wiper arm			Sm	116.30 X
1 pc	rear tail gate windscreen wiper motor			Tm	396.70 ✓
1 pc	rear lock control remote sensor			CM	273.20 ✓
1 pc	rear exhaust silencer			R	956.70 X
1 pc	rear emblem logo			me	67.30 ✓
1 pc	rear emblem "SKYACTIV"			me	58.60 ✓
1 pc	rear emblem "MAZDA 3"			me	55.40 ✓
1 pc	rear end panel			R	575.10 ✓
1 pc	rear end panel weatherstrip			Distal	296.30 ✓
		sub-total			16,106.60
		less 15% 201			2,415.99
		sub-total			13,690.61
2 pcs	number plate	Sc R/CM	s.nett @	35.00	600 70.00
2 pcs	number plate casing		s.nett @	35.00	600 70.00
1 set	reverse sensor		s.nett		500 220.00
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.				2000 1,600.00
	To remove rear windscreen glass to enable repair.				120 140.00
	To check wiring system.				40 60.00
	To install reverse sensor.				50 80.00
	To remove carpet and trimming to enable repair.				60 80.00
	To carry out exhaust works.				60 120.00
	Towing charges.				50 60.00
	To apply putty and spray painting on affected areas.				1000 1,200.00
	To apply rust proofing on affected areas.				60 150.00
	To apply waterproof sealant on affected areas.				30 150.00
		Total			17,690.61
					18697.26
					17250.00

# AUTOWORX HOUSE

C/O.176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 64520715 FAX: 64529250

## ESTIMATE

WOO LIAH MENG  
c/o 46 Lenton Plain  
Singapore 786548

Date: 18/3/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE: SUPPLEMENTARY FOR MAZDA 3 / SLV 9892 A</u>	
1 pc	front bumper	825.00
2 pcs	front head lamp assy @ 1,019.00	2,038.00
1 pc	rear bumper	949.00
1 pc	rear tail gate	1,268.00
2 pcs	rear tail gate lamp @ 457.00	914.00
	sub-total	5,994.00
	less 20%	1,198.80
	sub-total	4,795.20
	Total	4,795.20

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118016010/KQBN2

Date: 21/11/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3028161801
Claimant Vehicle No :	SLV9892A	Insured Vehicle No :	GV5567A
Date of Loss:	31/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D04243C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLV9892A	Engine No:	P520492045
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BN24A8J0200573
Reg. Date:	25/01/2018 (Man. Year: 2017)	Odometer:	10344 km
Colour:	Metallic Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Toyo 9 mm	Rear Left Side:	Toyo 9 mm
Front Right Side:	Toyo 9 mm	Rear Right Side:	Toyo 9 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,057.26	10,789.28	4,267.98	28.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	2,670.00	970.00	26.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>18,697.26</b>	<b>13,459.28</b>	<b>5,237.98</b>	<b>28.01</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>10,700.00</b>		
<b>Nett Amount (\$\$)</b>	<b>18,697.26</b>	<b>10,700.00</b>	<b>7,997.26</b>	<b>42.77</b>

## INSPECTION

Date of Assignment:	03/09/2018	Inspected At:	Autoworx House - Sin Ming (HQ) 176 SIN MING DRIVE #02-01 Singapore 575721
Date Inspected:	03/09/2018		
Estimated Period of Repair:	9.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2019)
<b>Parts:</b>	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV9892A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	825.00 FL	*825.00 FL
2	1		*FRONT BUMPER TOP PAD	Bent	296.70 FL	*296.70 FL
3	1		*FRONT BUMPER LOWER AIR GRILLE	Serviceable	275.80 FL	*-FL
4	1		*FRONT BUMPER CENTRE INNER PAD	Cracked	179.40 FL	*179.40 FL
5	2		*FRONT BUMPER FRONT CENTRE PAD BRACKET	Repair	87.40 FL	*-FL
6	1		*FRONT BUMPER TOP GRILLE	Dented	654.20 FL	*654.20 FL
7	1		*FRONT BUMPER TOP GRILLE EMBLEM	Necessary	66.70 FL	*66.70 FL
8	2		*FRONT BUMPER TOP GRILLE CHROME MOULDING	Dented/Scratched	552.60 FL	*552.60 FL
9	2		*FRONT BUMPER TOP GRILLE CHROME MOULDING PAD	Serviceable	135.60 FL	*-FL
10	2		*FRONT BUMPER SIDE RETAINER	Serviceable	90.40 FL	*-FL
11	1		*FRONT BUMPER TOW COVER	Serviceable	31.30 FL	*-FL
12	2		*FRONT HEAD LAMP ASSY	Cut / Mtg Cracked	2,038.00 FL	*2,038.00 FL
13	1		*FRONT NUMBER PLATE SUPPORT	Serviceable	119.70 FL	*-FL
14	1		*REAR BUMPER	Bent	949.00 FL	*949.00 FL
15	1		*REAR BUMPER SIDE RETAINER	N/s Distorted	130.60 FL	*65.30 FL
16	2		*REAR BUMPER REFLECTOR	Serviceable	392.40 FL	*-FL
17	1		*REAR BUMPER TOW COVER	Cracked	43.50 FL	*43.50 FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	376.50 FL	*376.50 FL
19	1		*REAR BUMPER EXHAUST COVER	Serviceable	97.10 FL	*-FL
20	1		*REAR TAIL LAMP MOULDING PANEL L/H	Repair	975.60 FL	*-FL
21	2		*REAR TAIL LAMP	N/s Cracked/O/s Mtg Cracked	1,148.20 FL	*1,148.20 FL
22	1		*REAR TAIL GATE	Bent	1,268.00 FL	*1,268.00 FL
23	1		*REAR TAIL GATE OUTER GARNISH	Mtg Cracked	576.30 FL	*576.30 FL
24	1		*REAR TAIL GATE LOCK	Dented	276.40 FL	*276.40 FL
25	1		*REAR TAIL GATE LOCK CATCH	Repair	56.10 FL	*-FL
26	1		*REAR TAIL GATE INNER TRIM	Mtg Cracked	377.20 FL	*377.20 FL
27	1		*REAR TAIL GATE LOCK SWITCH	Dented	117.50 FL	*117.50 FL
28	2		*REAR TAIL GATE NUMBER PLATE LAMP	Serviceable	193.40 FL	*-FL
29	1		*REAR TAIL GATE LAMP	Cracked (1 Pc only)	914.00 FL	*457.00 FL
30	1		(2 Pcs) *REAR TAIL GATE WINDSCREEN GLASS	Cut	1,075.20 FL	*1,075.20 FL
31	1		*REAR TAIL GATE WINDSCREEN GLASS MOULDING	Necessary	96.30 FL	*96.30 FL
32	1		*REAR TAIL GATE WINDSCREEN WIPER BLADE	Serviceable	79.20 FL	*-FL
33	1		*REAR TAIL GATE WINDSCREEN WIPER ARM	Serviceable	116.30 FL	*-FL
34	1		*REAR TAIL GATE WINDSCREEN WIPER MOTOR	Jammed	396.70 FL	*396.70 FL
35	1		*REAR LOCK CONTROL REMOTE SENSOR	Cracked	273.20 FL	*273.20 FL
36	1		*REAR EXHAUST SILENCER	Repair	956.70 FL	*-FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*REAR EMBLEM LOGO	Necessary	67.30 FL	*67.30 FL
38	1		*REAR EMBLEM SKYACTIV	Necessary	58.60 FL	*58.60 FL
39	1		*REAR EMBLEM MAZDA 3	Necessary	55.40 FL	*55.40 FL
40	1		*REAR END PANEL	Bent	575.10 FL	*575.10 FL
41	1		*REAR END PANEL WEATHERSTRIP	Distorted/Dented	296.30 FL	*296.30 FL
42	2		*NUMBER PLATE }	Scratched/Cracked	70.00 FS	*60.00 FS
43	2		*NUMBER PLATE CASING }		70.00 FS	*- FS
44	1		*SET REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 17,650.90 13,421.60  
 - List Item Discount on L Items 15.00/20.00% (S\$) 2,593.64 2,632.32

Total Parts (S\$) 15,057.26 10,789.28

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	1,600.00	1,200.00
2	TO REMOVE REAR WINDSCREEN GLASS TO ENABLE REPAIR	New	140.00	120.00
3	TO CHECK WIRING SYSTEM	New	60.00	40.00
4	TO INSTALL REVERSE SENSOR	New	80.00	50.00
5	TO REMOVE CARPET AND TRIMMING TO ENABLE REPAIR	New	80.00	60.00
6	TO CARRY OUT EXHAUST WORKS	New	120.00	60.00
7	TOWING CHARGES	New	60.00	50.00
8	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	1,000.00
9	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	150.00	60.00
10	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	150.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>3,640.00</b>	<b>2,670.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >