



Name: LOW JIA YU
Address: Blk 409C #03-279 Choa Chu Kang Ave 5 Singapore 683490
Policy Number: 10105645

Quotation for Reinstste / Repairs for vehicle

Date : 31/8/18
Vehicle No : SJL5330H

Parts Replacement – Cost Price

Cost Price

1 Pc	Rear Tailgate	\$	395.00
1 Pc	Rear Bumper	\$	240.00
1 Pc	Rear R/H Fender	\$	380.00
1 Pc	Rear R/H Tail Lamp	\$	165.00
1 Pc	Rear End Panel	\$	240.00
1 Pc	Rear L/H Bumper Retainer	\$	28.00
1 Pc	Rear R/H Bumper Retainer	\$	28.00
1 Pc	Rear R/H Fender Shield	\$	30.00
1 Pc	Rear R/H Fender Trim	\$	185.00
1 Pc	Rear Bumper Tow Cover	\$	15.00
1 Pc	Rear End PanelTop Garnish	\$	68.00
1 Pc	Rear Tool Sponge	\$	180.00

\$ 1,954.00

MISC & Labour & Charges

1 job	remove & replace all the parts mentioned above knocking straighten up necessary affected	\$	1,500.00
1 job	spray painting on affected areas	\$	800.00

Labour's Total : \$ 2,300.00

Sub-Total : \$ 4,254.00

GST 7% : \$ 297.78

Grand Total : \$ 4,551.78

Thank You
Your Faithfully,



Michael Tee
Wah Hong Motors & Credit Pte Ltd
Tel : 6773 7377
Fax : 6896 6321
Email : michael@wahhong.sg