

ASS. REC. BY:

REF:

CS/MS/18016025 / R1769

Special Instructions:

Survivor:

Rasul

ASSIGNMENT (Office)

Melimen

From (Person):

Elaine Ng

of

mslh

Date/Time:

21081018 358pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKK 9330A

Insured:

SKD 9640S

at Workshop n/o:

SIN 11WU

Tel:

6745 5783

of

Blk 3023A Ubi Rd 1 #01-59

Policy No:

80452825 QMX

Claim No:

568889

Sum Insured:

Excess:

Make of Veh:

D.O.A

28082018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKK 9330A - CCL R1769 / Kp30W2
	SKD 9640S - A
10/9/08	Report via manne preli advise
	lump sum \$52007 (red: 2979.99, 36%)

REF: MSLH

12316

ASSIGNMENT

From: Date: 03092018

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKK 9330A

at Workshop m/s

Sin Hwee

of Blk 3023A Ubi Rd 1 #01-59

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKK 9330A Yr Regn: 2013 / SEP

Type: M.Co / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota MSH CUT C.C. 1798

Colour: GRAY A/C Insured / Std / NI / NA

Sp. Reading: 85014 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JT0G420W 005 00 3820

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 28/08/18 D.O.I. 03/09/18

Survey held at: SIN HWEI

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 25 OCT 2018

Signature
24/10/2018

Date/Time, File Pass to?

25/10 Typist

Date/Time, File Return to?

☐ : Preli. Report

☒ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + RS. \$

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ 5200/-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018		31 Aug 2018 15:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:		KUAN YEW CHEONG, ID: 50039023B							
Main Claimant:		TOH JIAN XIAN, ID: S8231231E							
Vehicle Reg. No.:		SKK9330A	Date of Loss:	28/08/2018 14:00 - :59 [59 Months and 11 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / 568889	Policy/Cover Note No.:	80452825QMX (Comprehensive) Coverage: 20/01/2018 - 19/01/2019					
Vehicle Reg. No. (Insured):		SKD9640S	Policy No. (Claimant):						
		Excess:							
Repairer:		Sin Hwee Motor Pte Ltd (HQ) Bk 3023A, Ubi Road 1, #01-59, 408717 Ubi - Tel: 67455783							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/09/2018]							
Driver/Custodian (Insured):		KUAN YEW CHEONG (65 / Male), NRIC: S0039023B							
Adj Asg. Remarks:		SIE AGREE LKK. Pls contact Khim Hp : 9766 6672.							
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Rasul

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 10 Sep 2018

Preliminary Advice

Insured Vehicle No	: SKD9640S	Accident Date	: 28/08/2018
TP Vehicle No	: SKK9330A	Assignment Date	: 31/08/2018
Make	: TOYOTA WISH	Est. Duration of Repair	: 6.00
Date of Inspection	: 03/09/2018		
Inspection At	: SIN HWEE MOTOR PTE LTD (HQ) BLK 3023A, UBI ROAD 1, #01-59 SINGAPORE 408717		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,179.99
Revised Amount	:S\$	6,192.38
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,192.38
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2018 12:11
Date Of Accident	28/08/2018 14:30
Exact Location Of Accident	ALONG TOA PAYOH CENTRAL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK9330A
Insured/Policyholder	
Name Of Registered Owner	TOH JIAN XIAN
NRIC No	S8231231E
Email Address	JOHNSONTOH@ME.COM
Mobile Phone No	(LOCAL) +65-94772401
Alternative Phone No	OFFICE-94772401

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01011985
Cover Note Number	

Driver

Name of Driver	TOH JIAN XIAN
NRIC No	S8231231E
Date Of Birth	19/09/1982
Occupation	INDOOR
Date Of Driving Pass	17/02/2003
Driving Experience	15 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94772401
Fax Number	
Contact Number	OFFICE-94772401
Email Address	JOHNSONTOH@ME.COM

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

ACCIDENT STATEMENT (2000 characters)

My vehicle was stopped along the said location, on the left lane of two lane road. While waiting for traffic ahead to move, I felt an impact from my rear. Vehicle b front portion came into contact onto the rear of my vehicle. No injuries.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMAD HELMY BIN ALEHAM

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

TOH JIAN XIAN

DATE	30/8/2018
VEHICLE NO:	SKK 9330 A
MAKE:	TOYOTA
MODEL:	WISH

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	REAR BOOTLID	1,601.55	1,601.55
1 PC	"VALVEMATIC" LOGO	58.33	58.33
1 PC	"ELEGANCE" LOGO	48.75	48.75
1 PC	CENTER LOGO	55.25	55.25
1 PC	BOOTLID LOCK	407.80	407.80
1 PC	END PANEL	678.40	678.40
1 PC	END PANEL TOP GARNISH	268.60	268.60
1 PC	WEATHER STRIP	388.65	388.65
2 PCS	REVERSE SENSOR	248.55	497.10
1 PC	LOCK SENSOR	259.05	259.05
2 PCS	RETAINER	87.00	174.00
2 PCS	SIDE RETAINER	55.25	110.50
10 PCS	BUMPER CLIP	3.50	35.00
1 PC	REAR BUMPER	649.70	649.70
1 SET	WINDSCREEN SEAL	120.59	120.59
1 PC	EXHAUST BOX	880.52	880.52
1 PC	REAR FENDER INNER TRIM R/H	472.87	472.87
	----- SUBTOTAL		6,706.66
LESS 25%	----- LESS 25%	-25.00%	-1,676.67

6035.56

253

4826.67

spu-200

1 SET	NUMBER PLATE AND HOLDER	120.00	120.00
-	TO INSTALL AND CALIBRATE REVERSE SENSORS.	80.00	80.00
-	TO REMOVE AND REFIX REAR WINDSCREEN	150.00	150.00
-	TO SUPPLY WINDSCREEN SEALANT	80.00	80.00
-	TO DISMOUNT AND MOUNT REAR TRIMS, BOARD AND SEATS TO FACILITATE REPAIR WORK	150.00	150.00
-	TO TRANSFER BOOTLID FITTINGS, TRIM AND MECHANISM TO NEW BOOTLID	150.00	150.00
-	TO SUPPLY FITTINGS AND INSTALL REVERSE CAMERA.	150.00	150.00
-	TO REPLACE END PANEL INCLUDE KNOCKING, CUTTING AND WEDLING TO REPLACE, INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC.	850.00	850.00

Tel: 6745 5783 Fax: 6744 9582

Email: sinhweemotor@gmail.com

Website: www.sinhweemotor.com

TOTAL

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

TOH JIAN XIAN

DATE	30/8/2018
VEHICLE NO:	SKK 9330 A
MAKE:	TOYOTA
MODEL:	WISH

QUANTITY	DESCRIPTION	UNIT	AMOUNT
-	TO SPRAY PAINT REAR BUMPER, BOOTLID AND END PANEL	1,000.00	600 1,000.00
-	TO REPLACE AND ALIGN REAR EXHAUST BOX	150.00	80 150.00
-	TO SUPPLY AND TUFF KOTE ON AFFECTED PARTS	150.00	280 150.00
-	TO CARRY OUT WIRE CHECKING ON AFFECTED PARTS	120.00	30 120.00

1860

Rene
Hp 90010068

6 days

4/3

03/09/18 @1440

4/9/18

Resurvey after repair

4526.67

200.00

1860.00

6586.67

20%

5,269.33

45-5,200

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Tel: 6745 5783 Fax: 6744 9582

Email: sinhweemotor@gmail.com

Website: www.sinhweemotor.com

TOTAL \$8,179.99

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Aug 2018		31 Aug 2018 15:58 Edit Adj Rpt	S\$5,200.00 Edit Estimates	S\$5,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	KUAN YEW CHEONG , ID: S0039023B								
Main Claimant:	TOH JIAN XIAN , ID: S8231231E								
Vehicle Reg. No.:	SKK9330A	Date of Loss:	28/08/2018 14:00 - :59 [59 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 568889	Policy/Cover Note No.:	80452825QMX (Comprehensive) Coverage: 20/01/2018 - 19/01/2019						
Vehicle Reg. No. (Insured):	SKD9640S	Policy No. (Claimant):							
		Excess:							
Repairer:	Sin Hwee Motor Pte Ltd (HQ) Bk 3023A, Ubi Road 1, #01-59, 408717 Ubi - Tel: 67455783								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/09/2018]								
Driver/Custodian (Insured):	KUAN YEW CHEONG (65 / Male), NRIC: S0039023B								
Adj Asg. Remarks:	SJE AGREE LKK. Pls contact Khim Hp : 9766 6672.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKK9330A (568889)

[SKD9640S]

TP

TOH JIAN XIAN

Aug 28 2018 2:00PM

[KUAN YEW CHEONG]

Sin Hwee Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	31/08/18 09:18	Accident Statement From: SC - Reg. No: SKD9640S, Claimant: KUAN YEW CHEONG		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/09/18 17:48	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/10/18 10:36	General View		Load JPG	☒
2	26/10/18 10:36	General View		Load JPG	☒
3	26/10/18 10:36	General View		Load JPG	☒
4	26/10/18 10:36	General View		Load JPG	☒
5	26/10/18 10:36	General View		Load JPG	☒
6	26/10/18 10:36	General View		Load JPG	☒
7	26/10/18 10:36	General View		Load JPG	☒
8	26/10/18 10:36	General View		Load JPG	☒
9	26/10/18 10:36	General View		Load JPG	☒
10	26/10/18 10:36	General View		Load JPG	☒
11	26/10/18 10:36	General View		Load JPG	☒
12	26/10/18 10:36	General View		Load JPG	☒
13	26/10/18 10:36	General View		Load JPG	☒
14	26/10/18 10:36	General View		Load JPG	☒
15	26/10/18 10:36	General View		Load JPG	☒
16	26/10/18 10:36	General View		Load JPG	☒
17	26/10/18 10:36	General View		Load JPG	☒
18	26/10/18 10:36	General View		Load JPG	☒
19	26/10/18 10:36	General View		Load JPG	☒
20	26/10/18 10:36	General View		Load JPG	☒
21	26/10/18 10:36	General View		Load JPG	☒
22	26/10/18 10:36	General View		Load JPG	☒
23	26/10/18 10:36	General View		Load JPG	☒
24	26/10/18 10:36	General View		Load JPG	☒
25	26/10/18 10:36	General View		Load JPG	☒
26	26/10/18 10:36	General View		Load JPG	☒
27	26/10/18 10:36	General View		Load JPG	☒
28	26/10/18 10:36	General View		Load JPG	☒
29	26/10/18 10:36	General View		Load JPG	☒
30	26/10/18 10:36	General View		Load JPG	☒
31	26/10/18 10:36	General View		Load JPG	☒
32	26/10/18 10:36	General View		Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	26/10/18 10:36	General View	 Load JPG	☒
34	26/10/18 10:36	General View	 Load JPG	☒
35	26/10/18 10:36	General View	 Load JPG	☒
36	26/10/18 10:36	General View	 Load JPG	☒
37	26/10/18 10:36	General View	 Load JPG	☒
38	26/10/18 10:36	General View	 Load JPG	☒
39	26/10/18 10:36	General View	 Load JPG	☒
40	26/10/18 10:36	General View	 Load JPG	☒
41	26/10/18 10:36	General View	 Load JPG	☒
42	26/10/18 10:36	General View	 Load JPG	☒
43	26/10/18 10:36	General View	 Load JPG	☒
44	26/10/18 10:36	General View	 Load JPG	☒
45	26/10/18 10:36	General View	 Load JPG	☒
46	26/10/18 10:36	General View	 Load JPG	☒
47	26/10/18 10:36	General View	 Load JPG	☒
48	26/10/18 10:36	General View	 Load JPG	☒
49	26/10/18 10:36	General View	 Load JPG	☒
50	26/10/18 10:36	General View	 Load JPG	☒
51	26/10/18 10:36	General View	 Load JPG	☒
52	26/10/18 10:36	General View	 Load JPG	☒
53	26/10/18 10:36	General View	 Load JPG	☒
54	26/10/18 10:36	General View	 Load JPG	☒
55	26/10/18 10:36	General View	 Load JPG	☒
56	26/10/18 10:36	General View	 Load JPG	☒
57	26/10/18 10:36	General View	 Load JPG	☒
58	26/10/18 10:36	General View	 Load JPG	☒
59	26/10/18 10:36	General View	 Load JPG	☒
60	26/10/18 10:36	General View	 Load JPG	☒
61	26/10/18 10:36	General View	 Load JPG	☒
62	26/10/18 10:36	General View	 Load JPG	☒
63	26/10/18 10:36	General View	 Load JPG	☒
64	26/10/18 10:36	General View	 Load JPG	☒
65	26/10/18 10:36	General View	 Load JPG	☒
66	26/10/18 10:36	General View	 Load JPG	☒
67	26/10/18 10:36	General View	 Load JPG	☒
68	26/10/18 10:36	General View	 Load JPG	☒
69	26/10/18 10:36	General View	 Load JPG	☒
70	26/10/18 10:36	General View	 Load JPG	☒
71	26/10/18 10:36	General View	 Load JPG	☒
72	26/10/18 10:36	General View	 Load JPG	☒
73	26/10/18 10:36	General View	 Load JPG	☒
74	26/10/18 10:36	General View	 Load JPG	☒
75	26/10/18 10:36	General View	 Load JPG	☒
76	26/10/18 10:36	General View	 Load JPG	☒
77	26/10/18 10:36	General View	 Load JPG	☒
78	26/10/18 10:36	General View	 Load JPG	☒
79	26/10/18 10:36	General View	 Load JPG	☒
80	26/10/18 10:36	General View	 Load JPG	☒
81	26/10/18 10:36	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
82	26/10/18 10:36	General View	 Load JPG	☒
83	26/10/18 10:36	General View	 Load JPG	☒
84	26/10/18 10:36	General View	 Load JPG	☒
85	26/10/18 10:36	General View	 Load JPG	☒
86	26/10/18 10:36	General View	 Load JPG	☒
87	26/10/18 10:36	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/08/18 16:42	Third Party Accident Report	 Load PDF	
2	30/08/18 17:17	SJE AGREE LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016025/R1TBQ2

Date: 26/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80452825QMX

Claimant Vehicle No : SKK9330A

Insured Vehicle No : SKD9640S

Date of Loss: 28/08/2018

Nature of Claim: TP

Claim No: 568889

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKK9330A

Make & Model: TOYOTA WISH, 1.8 CVT (A)

Reg. Date: 17/09/2013 (Man. Year: 2013)

Colour: Grey

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 2ZR1271730

Chassis No: JTDGG20W005003820

Odometer: 85014 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,150.00	4,726.67	423.33	8.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	1,860.00	1,170.00	38.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,180.00	6,586.67	1,593.33	19.48
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	8,180.00	5,200.00	2,980.00	36.43

INSPECTION

Date of Assignment: 31/08/2018

Date Inspected: 03/09/2018 Inspected At:

Sin Hwee Motor Pte Ltd (HQ)
Blk 3023A, Ubi Road 1, #01-59
Singapore 408717

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK9330A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,601.55 FL	*1,601.55 FL
2	1		*VALVEMATIC LOGO	Necessary	58.33 FL	*58.33 FL
3	1		*ELEGANCE LOGO	Necessary	48.75 FL	*48.75 FL
4	1		*CENTER LOGO	Necessary	55.25 FL	*55.25 FL
5	1		*END PANEL	Bent	678.40 FL	*678.40 FL
6	1		*BOOTLID LOCK	Bent	407.80 FL	*407.80 FL
7	1		*END PANEL TOP GARNISH	Deformed	268.60 FL	*268.60 FL
8	1		*WEATHER STRIP	Necessary	388.65 FL	*388.65 FL
9	1		*REVERSE SENSOR	Not Working	372.83 FS	*200.00 FS
10	1		*LOCK SENSOR	Cracked	259.05 FL	*259.05 FL
11	2		*RETAINER	Not Necessary	174.00 FL	*- FL
12	2		*SIDE RETAINER	Necessary	110.50 FL	*110.50 FL
13	10		*BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
14	1		*REAR BUMPER	Deformed	649.70 FL	*649.70 FL
15	1		*SET WINDSCREEN SEAL	Necessary	120.59 FL	*120.59 FL
16	1		*EXHAUST BOX	Bent	880.52 FL	*880.52 FL
17	1		*REAR FENDER INNER TRIM R/H	Cracked	472.87 FL	*472.87 FL
18	1		*SET NUMBER PLATE AND HOLDER	Serviceable	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,702.39	6,235.56
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,552.39	1,508.89
Total Parts (\$\$)	5,150.00	4,726.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO INSTALL AND CALIBRATE REVERSE SENSORS	New	80.00	60.00
2	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
3	TO SUPPLY WINDSCREEN SEALANT	New	80.00	40.00
4	TO DISMOUNT AND MOUNT REAR TRIMS ,BOARD AND SEATS TO FACILITATE REPAIR WORK	New	150.00	60.00
5	TO TRANSFER BOOTLID FITTINGS ,TRIM AND MECHANISM TO NEW BOOTLID	New	150.00	80.00
6	TO SUPPLY FITTINGS AND INSTALL REVERSE CAMERA	New	150.00	60.00
7	TO REPLACE END PANEL INCLUDE KNOCKING ,CUTTING AND WELDING TO REPLACE ,INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC	New	850.00	650.00
8	TO SPRAY PAINT REAR BUMPER ,BOOTLID AND END PANEL	New	1,000.00	600.00
9	TO REPLACE AND ALIGN REAR EXHAUST BOX	New	150.00	80.00
10	TO SUPPLY AND TUFF KOTE ON AFFECTED PARTS	New	150.00	80.00
11	TO CARRY OUT WIRE CHECKING ON AFFECTED PARTS	New	120.00	30.00
Gross Labour Cost (S\$)			3,030.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >