

ASS. SEC. BY:

REF: CS/FCU8016027/Arbn2

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): CWS Lukern Jaw of FCL

Date/Time: 31082018 734pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJK 4677U

Insured: SHC 7127L

at Workshop m/s RICO 60 Auto

Tel: 62866060

of 8 Kaki Bukit Ave 4 *03-24

Policy No: Claim No: D18006454 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 78082018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 03092018 1143am

Person Contacted: Cass

Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate	
	SJK 4677U - NA / INC15014735 / h/v	DA: 280815
	SHC 7127L - NA / INC08025952 / r	DA: 210908
14/11/18	Refer 1A thru email.	
	Adnan confirmed L/s \$11K, 14 days (Red: \$19,921.04, 64%.)	

ASS. RMA BY: Adrian Ling

REF:

ASSIGNMENT

22/10/08

2008, Oct

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SJK4677U

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Latio

c.c.

1498

Colour:

Gold

A/C:

Insured / Std / NI / NA

Sp. Reading:

248393

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1BAAC11Z0020396

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

03/09/18

Survey held at

Rico 60

Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.

Pending COE Renewal.

MV: \$20K, LTA: \$15,774.00, NV: \$12,226.00

MV: 281K

3V: 161K

Nett: 12K

RECEIVED 14 NOV 2018

Date/Time, File Pass to?



Preli. Report

1) Final

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

7P

Lump Sum / FR (\$) 11,000.00

Survey Fee:

Transportation:

S + Rg. St

Photos

Other:

20x15=300

170+300

50

50

119

558

058

14/11/18

689



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006454MFSH

Date: 14 November 2018

Our Ref: CS/FCI18016027/Arb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJK 4677U

Please be informed that we had conducted the inspection of the above mentioned vehicle on 03/09/2018 at the premises of M/s RICO 60 AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>30,921.04</u>
Revised Estimate Amount	: S\$ <u>15,053.86</u>
"Check" Items Amount	: S\$ <u> </u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the front and rear portion.



Yours faithfully

ADRIAN LING
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	29-08-2018	Our Ref No. D18006454MFSH
Accident Date	28-08-2018	Claim Type. Third Party
Insured Vehicle	SHC7127L	Third Party Vehicle. SJK4677U
Survey Location	8 Kaki Bukit Avenue 4 #02-24 Premier @ Kaki Bukit	
Contact Person.	CASS CHUA	
Contact No.	62866060/ 0	Fax No. 62867060
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

05092018 @ 11:43am

Cass veh in

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	RICO 60 AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Wednesday, November 14, 2018 10:51 AM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: RE: SURVEY ASSESSMENT - D18006454MFSH/1
Attachments: SJK 4677U.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for SJK 4677U.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, September 03, 2018 11:44 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006454MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 31 August, 2018 7:34 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006454MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Inchcape
Pre-Owned

WIDE RANGE OF PRE-OWNED TOYOTA AND OTHER MAKES AVAILABLE

VISIT OUR NEW SHOWROOM FOR A PREMIUM PRE-OWNED EXPERIENCE @ 2 PANDAN CRESCENT INCHCAPE CENTRE



LEARN MORE



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2010 VW Jetta Sports Only 7k+ Depre! Monthly \$700!

Only 1 Owner! Immaculate Condition! Hurry Come Down To Our Showroom To View Now!

AutoPrestige Gallery StarAd

HIN LUNG AUTO
HoBee Group

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years of car sale

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

6 vehicles		Search		Latio		Advanced Search		Search		View All							
Make		Model		Price		Depreciation		Reg Date		Eng Cap		Mileage		Veh Type		Status	
Search Selection		Latio		Any		Any		2008		Any		Any		Any		Available	



☐ Nissan Latio 1.5A Sports Premium (COE till 11/2027)

\$46,188

\$5,000 /yr

04-Apr-2008

1,498 cc

177,000 km

Hatchback

Available

\$5k Drive Away With Only \$4k Low Depreciation! New Road Tax Till April 2019. Comes With Certified Warranty. Look No Further With Signature Nissan Latio Premium, Most Fuel Efficient And Economical Seda...

Euro Performance Asia Pte Ltd

Posted: 29-Aug-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan



☐ Nissan Latio 1.5A Premium

\$12,000

N.A

11-Nov-2008

1,498 cc

145,000 km

Sedan

Available

Posted: 01-Jul-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan

DIRECT OWNER



☐ Nissan Latio 1.5A Sports (New 5-yr COE)

\$31,388

\$6,270 /yr

14-Nov-2008

1,498 cc

104,500 km

Hatchback

Available

Sporty Outlook, Low Mileage Done, Clean And Neat Interior. All Our Cars Have Gone Through Complete Checks And All Necessary Repairs Done & Comes With Glossy New Paint! Backed By Our Own In-house Works...

Posted: 31-Aug-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan

PREMIUM AD



☐ Nissan Latio 1.5A (New 5-yr COE)

\$27,800

\$5,560 /yr

17-Dec-2008

1,498 cc

-

Sedan

Available

Drive With Peace Of Mind! High Trade In And Flexible High Loan Available, Please Call/SMS Our Sales Consultant For Viewing Appointment.

Net Link Partners Pte Ltd

Posted: 01-Sep-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan

PREMIUM AD

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

TYREPAC

Buy Tyres Online!
Latest Special Offers from Tyrepac!



☐ Nissan Latio 1.5A (OPC) (New 5-yr COE)

\$26,800

\$5,360 /yr

17-Dec-2008

1,498 cc

62,000 km

Sedan

Available

Great For COE Renewal, One Owner, Super Low Mileage Of 60,000 Km, Almost Immaculate Condition, Very Well-maintained By Careful Owner, Clean Interior And Exterior, Viewing Strictly By Appointment At Ca...

Posted: 30-Aug-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan



☐ Nissan Latio 1.5A (New 5-yr COE)

\$33,800

\$6,760 /yr

30-Dec-2008

1,498 cc

155,048 km

Sedan

Available

Drive With Peace Of Mind! High Trade In And Flexible High Loan Available, Please Call/SMS Our Sales Consultant For Viewing Appointment.

Accendore Autolukation Pte Ltd

Posted: 17-Aug-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan

Save this search criteria, to get email alerts whenever a match is found.

Save Search

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0485C

Vehicle Details

Vehicle No.: SJK4677U
Vehicle to be Exported: No
Intended Deregistration Date: 13 Oct 2018
Vehicle Make: NISSAN
Vehicle Model: LATIO 1.5L AT ABS D/AIRBAG 2WD 4DR
Primary Colour: Beige
Manufacturing Year: 2008
Engine No.: HR15036355B
Chassis No.: JN1BAAC11Z0020396
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$15,863.00
Original Registration Date: 22 Oct 2008
First Registration Date: 22 Oct 2008
Transfer Count: 1
Actual ARF Paid: \$15,863.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 21 Oct 2018
PARF Rebate Amount: \$7,931.00

Intended COE Rebate Details

COE Expiry Date: 30 Sep 2023
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$16,170.00
COE Rebate Amount: \$16,053.00
Total Rebate Amount: \$23,984.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Oct 2018

OK


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0485C
Vehicle Details	
Vehicle No.:	SJK4677U
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Nov 2018
Vehicle Make:	NISSAN
Vehicle Model:	LATIO 1.5L AT ABS D/AIRBAG 2WD 4DR
Primary Colour:	Beige
Manufacturing Year:	2008
Engine No.:	HR15036355B
Chassis No.:	JN1BAAC11Z0020396
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$15,863.00
Original Registration Date:	22 Oct 2008
First Registration Date:	22 Oct 2008
Transfer Count:	1
Actual ARF Paid:	\$15,863.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,170.00
COE Rebate Amount:	\$15,774.00
Total Rebate Amount:	\$15,774.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Nov 2018

OK



ATTN:		TP 1st Cap Janice	
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR BOOTLID <i>Buckled</i>	1	\$ 845.40
2	REAR BOOTLID CHROME HANDLE <i>3 new</i>	1	\$ 295.30
3	REAR BOOTLID INSULATOR <i>1 new</i>	1	\$ 187.40
4	REAR BOOTLID EMBLEM 'LATI0' <i>3 new</i>	1	\$ 76.20
5	REAR BOOTLID LOGO 'NISSAN' <i>3 new</i>	1	\$ 65.60
6	REAR BOOTLID LOCK <i>Damaged</i>	1	\$ 197.90
7	REAR BOOTLID WEATHERSTRIP <i>1 new</i>	1	\$ 166.00
8	REAR BOOTLID HINGE <i>new</i>	2	\$ 264.40
9	TAILLAMP L+R <i>cracked</i>	2	\$ 638.80
10	TAILLAMP PANEL L+R <i>Dented</i>	2	\$ 387.00
11	REAR BUMPER <i>Distorted</i>	1	\$ 751.20
12	REAR BUMPER SPONGE <i>cracked Repeated</i>	1	\$ 175.50
13	REAR BUMPER RETAINER L+R <i>new</i>	2	\$ 86.00
14	REAR BUMPER BRACKET L+R <i>Dented</i>	2	\$ 94.00
15	REAR BUMPER SPONGE <i>cracked</i>	1	\$ 85.00
16	REAR FENDER L+R <i>Repair</i>	2	\$ 1,908.00
17	REAR END PANEL <i>Dented</i>	1	\$ 542.60
18	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 173.70
19	REAR FLOOR PANEL <i>Repair</i>	1	\$ 845.00
20	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 495.00
21	REAR FENDER INNER TRIM L+R <i>1 new</i>	2	\$ 770.00
22	REAR FENDER AIR VENT L+R <i>new</i>	2	\$ 168.00
23	REAR FENDER COWLING L+R <i>new</i>	2	\$ 196.00
24	REAR EXHAUST PIPE <i>3 new</i>	1	\$ 794.60
25	REAR EXHAUST MOUNTING	2	\$ 42.80
26	BONNET <i>Distorted</i>	1	\$ 891.20
27	BONNET LOCK <i>Damaged</i>	1	\$ 96.20
28	BONNET LOCK BRACE PANEL <i>Bent</i>	1	\$ 78.30
29	BONNET INSULATOR <i>new</i>	1	\$ 94.90
30	BONNET HINGE L+R <i>Bent</i>	2	\$ 85.60
31	HEADLAMP L+R <i>cracked</i>	2	\$ 799.20
32	FRONT GRILLE <i>cracked</i>	2	\$ 273.60
33	FRONT BUMPER <i>Distorted</i>	1	\$ 595.10
34	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 58.40
35	FRONT BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 494.40
36	FRONT BUMPER SPONGE <i>cracked</i>	1	\$ 237.20
37	FRONT BUMPER LOGO <i>new</i>	1	\$ 48.30
38	FRONT FENDER L+R <i>Rt Buckled</i>	2	\$ 1,294.00
39	FRONT FENDER LAMP L+R <i>3 new</i>	2	\$ 106.20
40	FRONT FENDER COWLING L+R	2	\$ 197.20

41	FRONT LOWER BRACE PANEL <i>new</i>	1	S	97.50	+
42	FRONT SUPPORT PANEL <i>Buckled</i>	1	S	495.00	2
43	FRONT SUPPORT PANEL TOP GARNISH <i>del</i>	1	S	199.70	-
44	AIR DUCT <i>new</i>	1	S	162.30	+
45	HORN <i>new</i>	2	S	130.00	+
46	RADIATOR <i>tested</i>	1	S	896.00	2
47	RADIATOR TOP BUSH <i>new</i>	2	S	39.40	2
48	RADIATOR BOTTOM BUSH <i>new</i>	2	S	39.40	2
49	AIR CON CONDENSER <i>tested</i>	1	S	897.40	2
50	AIR CON SIDE GARNISH <i>Not new</i>	1	S	87.70	2

10815.40
9733.86.

				SUBTOTAL	\$ 18,645.60
				LESS 10%	\$ 1,864.56
				PARTS TOTAL	\$ 16,781.04

	SPECIAL NETT	QTY	PRICE	
1	FRONT NUMBER PLATE <i>cracked</i>	1	S 120.00	50
2	REAR NUMBER PLATE <i>new</i>	1	S 120.00	+
3	REVERSE SENSOR <i>Damaged</i>	2	S 300.00	200
4	REAR END PANEL SEALANT <i>new</i>	1	S 120.00	60
5	SPARE WHEEL PANEL SEALANT <i>new</i>	1	S 120.00	+
6	FRONT BUMPER CLIPS <i>3 new</i>	10	S 100.00	30
7	REAR BUMPER CLIPS	10	S 100.00	30
8	END PANEL TOP GARNISH CLIPS <i>new</i>	10	S 100.00	10
9	REAR FENDER COWLING CLIPS <i>new</i>	20	S 200.00	+
10	FRONT FENDER COWLING CLIPS <i>new</i>	20	S 200.00	+
11	REAR FENDER SEALANT <i>new</i>	2	S 240.00	+
12	REAR WINDSCREEN SEALANT <i>new</i>	1	S 120.00	+

SPECIAL NETT TOTAL \$ 1,840.00

	LABOUR	QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	1	S 5,400.00	2200
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	S 3,500.00	2200
	TO RUST PROOF ACCIDENT AFFECTED AREA	1	S 1,200.00	100
	TO RNR REAR WINDSCREEN	1	S 400.00	+
	TO RNR REAR BOOT MECHANISM	1	S 120.00	60
	TO RNR REAR LUGGAGE COMPARTMENT	1	S 400.00	80
	TO RNR REVERSE SENSOR & CHECK FUNCTION.	1	S 120.00	80
	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	1	S 250.00	+
	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	1	S 120.00	60
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	1	S 120.00	+
	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	1	S 120.00	30
	TO CHECK WIRING AND FENDER SIGNAL LAMP FUNCTION	1	S 120.00	+
	TO RNR FUEL TANK	1	S 120.00	+
	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	1	S 300.00	+
	TO DO WATER LEAK TEST .	1	S 120.00	+
	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	1	S 120.00	60



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016027/Arbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7127L	Veh. Inspected	SJK 4677U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006454MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	31/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN LATIO	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JN1BAAC11Z0020396	Colour	GOLD	
Odometer	248393	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	TOYO	6 mm	
L/H Front Tyre	195/60 R15	TOYO	6 mm	
R/H Rear Tyre	195/60 R15	TOYO	6 mm	
L/H Rear Tyre	195/60 R15	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/08/2018	Inspection Date	03/09/2018	
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 4677U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID	BUCKLED	845.40	787.50
1	REAR BOOTLID CHROME HANDLE	NOT NECESSARY	295.30	-
1	REAR BOOTLID INSULATOR	NOT NECESSARY	187.40	-
1	REAR BOOTLID EMBLEM "LATI0"	NECESSARY	76.20	76.20
1	REAR BOOTLID LOGO "NISSAN"	NECESSARY	65.60	65.60
1	REAR BOOTLID LOCK	DAMAGED	197.90	124.00
1	REAR BOOTLID WEATHERSTRIP	CUT	166.00	166.00
2	REAR BOOTLID HINGE	NOT NECESSARY	264.40	-
2	TAILLAMP L+R	CRACKED	638.80	566.60
2	TAILLAMP PANEL L+R	DENTED	387.00	387.00
1	REAR BUMPER	DISTORTED	751.20	548.60
1	REAR BUMPER SPONGE	REPEATED	175.50	-
2	REAR BUMPER RETAINER L+R	NECESSARY	86.00	86.00
2	REAR BUMPER BRACKET L+R	DENTED	94.00	94.00
1	REAR BUMPER SPONGE	CRACKED	85.00	55.60
2	REAR FENDER L+R	TO REPAIR SEE LABOUR	1,908.00	-
1	REAR END PANEL	DENTED	542.60	442.60
1	REAR END PANEL TOP GARNISH	DEFORMED	173.70	73.10
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	845.00	-
1	REAR FLOOR PANEL TOP BOARD	DEFORMED	495.00	495.00
2	REAR FENDER INNER TRIM L+R	NOT NECESSARY	770.00	-
2	REAR FENDER AIR VENT L+R	NOT NECESSARY	168.00	-
2	REAR FENDER COWLING L+R	NOT NECESSARY	196.00	-
1	REAR EXHAUST PIPE	NOT NECESSARY	794.60	-
2	REAR EXHAUST MOUNTING	NOT NECESSARY	42.80	-
1	BONNET	DISTORTED	891.20	891.20
1	BONNET LOCK	DAMAGED	96.20	96.20
1	BONNET LOCK BRACE PANEL	BENT	78.30	78.30
1	BONNET INSULATOR	NOT NECESSARY	94.90	-

Report Ref No. CS/FC118016027/Arbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BONNET HINGE L+R	BENT	85.60	85.60
2	HEADLAMP L+R	CRACKED	799.20	799.20
2	FRONT GRILLE	CRACKED	273.60	273.60
1	FRONT BUMPER	DISTORTED	595.10	595.10
2	FRONT BUMPER SIDE RETAINER	NECESSARY	58.40	58.40
1	FRONT BUMPER REINFORCEMENT	BENT	494.40	494.40
1	FRONT BUMPER SPONGE	CRACKED	237.20	237.20
1	FRONT BUMPER LOGO	NECESSARY	48.30	48.30
2	FRONT FENDER L+R	O/S BUCKLED	1,294.00	623.20
2	FRONT FENDER LAMP L+R	NOT NECESSARY	106.20	-
2	FRONT FENDER COWLING L+R	NOT NECESSARY	197.20	-
1	FRONT LOWER BRACE PANEL	NOT NECESSARY	97.50	-
1	FRONT SUPPORT PANEL	BUCKLED	495.00	495.00
1	FRONT SUPPORT PANEL TOP GARNISH	DEFORMED	199.70	199.70
1	AIR DUCT	NOT NECESSARY	162.30	-
2	HORN	NOT NECESSARY	130.00	-
1	RADIATOR	DENTED	896.00	896.00
2	RADIATOR TOP BUSH	NECESSARY	39.40	39.40
2	RADIATOR BOTTOM BUSH	NECESSARY	39.40	39.40
1	AIR CON CONDENSER	DENTED	897.40	897.40
1	AIR CON SIDE GARNISH	NOT NECESSARY	87.70	-
	LESS 10% DISCOUNT		-1,864.56	-1,081.54
			16,781.04	9,733.86
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	CRACKED	120.00	50.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	120.00	-
2	REVERSE SENSOR (SN)	DAMAGED	300.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	120.00	60.00
1	SPARE WHEEL PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
10	FRONT BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
10	REAR BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
10	END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	100.00	10.00
20	REAR FENDER COWLING CLIPS (SN)	NOT NECESSARY	200.00	-

Report Ref No. CS/FCI18016027/Arbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
20	FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	200.00	-
2	REAR FENDER SEALANT (SN)	NOT NECESSARY	240.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	120.00	-
			1,840.00	380.00
	LABOUR			
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD,KNOCK & REALIGN.INCLUSIVE OF THE REPAIR OF REAR FENDER L+R AND REAR FLOOR PANEL.		5,100.00	2,200.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		3,500.00	2,200.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.		1,200.00	100.00
	TO RNR REAR WINDSCREEN.	NOT NECESSARY	400.00	-
	TO RNR REAR BOOT MECHANISM.		120.00	60.00
	TO RNR REAR LUGGAGE COMPARTMENT.		400.00	80.00
	TO RNR REVERSE SENSOR & CHECK FUNCTION.		120.00	80.00
	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS.	NOT NECESSARY	250.00	-
	TO RNR A/C CONDENSOR ASSY AND REFILL GAS.		120.00	60.00
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS.	NOT NECESSARY	120.00	-
	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION.		120.00	30.00
	TO CHECK WIRING AND FEDNER SIGNAL LAMP FUNCTION.	NOT NECESSARY	120.00	-
	TO RNR FUEL TANK.	NOT NECESSARY	120.00	-
	TO DO DIAGNOSIS AND RESET,REPROGRAM OR CODING FAULT CODE.	NOT NECESSARY	300.00	-
	TO DO WATER LEAK TEST.	NOT NECESSARY	120.00	-
	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD.		120.00	60.00
	TOWING FEE.		70.00	70.00
	-		-	-
	-		-	-
	-		-	-
			12,300.00	4,940.00
GRAND TOTAL			30,921.04	15,053.86
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00

Report Ref No. CS/FCI18016027/Arbn2



Report Ref No. CS/FCI18016027/Arbn2

MARKET VALUE: \$28,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$15,774.00=NETT VALUE: \$12,226.00

A handwritten signature in black ink, appearing to read 'A. Ling'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.