

ASS. REC. BY:

REF: CS/CT118016028/Rthbs2

Special Instruction:

Surveyor

Risu

ASSIGNMENT (Office)

Mehmen

From (Person):

Joueyn Tay

of

CPL

Date/Time:

03092018 10:43am

Estimated Cost:

Bill to:

☒ TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

S6H 1200H

Insured:

at Workshop m/s

Cycle x Carriage

Tel:

of

330 Vbi Rd 3

Policy No:

DMP CSN 3031761800

Claim No:

SNM18D 0477C01

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

D.O.A.

28082018

(Client's Record)

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

03092018 11:41 am

Person Contacted:

Mars

Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	S6H 1200H - NA (ETL 8015700) / 24
4/9-	Revert via meymen
4/9-	14:10pm - authorise repair.
4/9@	5:38pm - inform mars authorise repair excess \$500/-
	Finalised \$9165/- (Red: 2515; 21%)

DA: 280818

REF:

55396

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGH 1200H

at Workshop m/s

CYCLE

of

330, WHI RD 3

Insured:

CTI

Policy No.

Claims No.

Sum Insured:

Excess:


500

(Client's Record)

Make of Veh:

(Policy Condition)

MAPS

 Remark: The veh had commenced its
repair at the time of inspection.


Bal. or Market Value:

50k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGH 1200H

Yr Regn:

2016 / MMV

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MITSUBISHI ATTARAGE 1.2 c.c 1193

Colour:

GRGY

A/C:

Insured / Std / NI / NA

Sp. Reading

033884

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MMBSTA134H H000311

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

28/08/18

D.O.I.

03/09/18

Survey held at

C&C CUBI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 10 OCT 2018

Date/Time, File Pass to?



Preli. Report



Final Report

1) 1010 Typist

Date/Time, File Return to?

2)

Days Of Repair:

8

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS: \$ SI

) Photos:

) Others:

TOTAL

Report Format :

OD

Lump Sum / I.B.I. (\$)

9165/-

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2018		03 Sep 2018 10:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:		MR LIM KIAN HUA, ID: S7405539G		[Created by insurer]
Vehicle Reg. No.:	SGH1200H	Date of Loss:	28/08/2018 06:00 - :59	
Claim Type:	OD / SNM18D04179C01	Policy/Cover Note No.:	DMPCSN3031761800 (Comprehensive) Coverage: 19/05/2018 - 18/05/2019	
		Excess:	\$500.00	
Repairer:	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3, 408650 Ubi - Tel: 67461000			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/09/2018]			
Driver/Custodian:	LIM KIAN HUA (LIN JIANHUA) (44 / Male), NRIC: S7405539G, Tel: +6597901402			
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY & REVERT. EXCESS OF \$500.00 APPLIES.			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

03091018 @ 11:41am
mars veh in.
Asail

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 4 September 2018 5:38 PM
To: 'mars.ler@ccfulco.com.sg'
Cc: SUR
Subject: SGH 1200H / OD / CHINA TAI PING

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGH 1200H (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 10 October 2018 10:38 AM
To: Mars Ler; Rasul (LKKAUTO)
Cc: SUR; Chris Bulaclac
Subject: RE: SGH 1200H / OD / CHINA TAI PING Before Paint & Finalization

Dear Mars,

Confirm final figure at \$9165 (before GST and excess), 8 working days repair

Please submit all relevant documents to China Taiping directly.

Thanks.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mars Ler <mars.ler@ccfulco.com.sg>
Sent: Friday, 21 September 2018 9:56 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; Chris Bulaclac <chris.bulaclac@ccfulco.com.sg>
Subject: RE: SGH 1200H / OD / CHINA TAI PING Before Paint & Finalization

Dear Rasul ,

As per attach for your reference , please help to finalize . (8 working days repair)

Thank You,

Best regards

Mars Ler
B & P Service Advisor
Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3 Singapore 408650
D/D 65949163 H/P 91792566

From: Denise Tay (LKKAUTO) [<mailto:denisetay@lkkauto.com>]
Sent: Tuesday, 4 September, 2018 5:38 PM
To: Mars Ler
Cc: SUR
Subject: SGH 1200H / OD / CHINA TAI PING

Dear Sir,

View Received Message

This mail is associated with :

***SGH1200H (SNM18D04179C01)**

OD

Aug 28 2018 6:00AM

[MR LIM KIAN HUA]

Cycle & Carriage Fulco Motor Dealer Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 04/09/2018 14:10 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$8556.00) - SGH1200H - Claim Handler: Jowyn Tay

Approved:8556.00:PLEASE PROCEED TO AUTHORIZE REPAIRS UP TO \$8,556.00 BEFORE EXCESS OF \$500.00

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay

Date: 04 Sep 2018

Preliminary Advice

Vehicle No	: SGH1200H	Accident Date	: 28/08/2018
Make	: MITSUBISHI ATTRAGE	Policy No.	: DMPCSN3031761800
Assignment Date	: 03/09/2018	Excess	: S\$500.00
Date of Inspection	: 03/09/2018	Est. Duration of Repair	: 7.00
Inspection At	: CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD (HQ) 330 UBI ROAD 3 SINGAPORE 408650		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,780.00
Revised Amount	:S\$	7,725.00
Check Items (Estimated)	:S\$	831.00
Total	:S\$	8,556.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	39,209.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,791.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/08/2018 09:00
Date Of Accident	28/08/2018 06:40
Exact Location Of Accident	SLIP RD SENGKANG EAST RD TWDS TPE (SLE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGH1200H
Insured/Policyholder	
Name Of Registered Owner	MR LIM KIAN HUA
NRIC No	S7405539G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97901402
Alternative Phone No	OFFICE-97901402

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE 1.2 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3031761800
Cover Note Number	

Driver

Name of Driver	LIM KIAN HUA (LIN JIANHUA)
NRIC No	S7405539G
Date Of Birth	23/02/1974
Occupation	INDOOR
Date Of Driving Pass	08/03/2006
Driving Experience	12 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97901402
Fax Number	
Contact Number	OFFICE-97901402
EMail Address	NOEMAIL

Address	BLK 310B ANCHORVALE ROAD #09-19
Postcode	542310
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED BEFORE THE STOPPING LINE OF SLIP RD SENGKANG EAST RD TO CHECK INCOMING VEHICLE BEFORE I CAN PROCEED. SUDDENLY I FELT AN IMPACT OF MY VEHICLE, I ALIGHT FROM MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM2539M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD NOOR NIZAM BIN SUKIMAN
NRIC/Passport Number	S7538614A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3

Passenger 1

NAME: :

GENDER: :

Passenger 2

NAME: :

GENDER: :

Accident Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

B: 5m2539m



refer to statement

refer to statement.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5539G
Vehicle Details	
Vehicle No.:	SGH1200H
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	3A92UDB6473
Chassis No.:	MMBSTA13AHH000311
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$13,519.00
Original Registration Date:	20 May 2016
First Registration Date:	20 May 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 May 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	19 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,009.00
COE Rebate Amount:	\$35,459.00
Total Rebate Amount:	\$39,209.00

The information contained herein is correct as at 04 Sep 2018

OK

50,000
39,209

10,791

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DMPCSN3031761800	Engine No : 3A92UDB6473 Chassis No: MMBSTA13AH000311
1. Index Mark and Registration Number of Vehicle	SGH1200H	
2. Name of Policy Holder	MR LIM KIAN HUA	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	19 MAY 2018	NAMED DRIVERS EX SECT. I.....S\$500.00 IN ADDITION TO NAMED DRIVERS EX: EX SECT. I - AGE <= 25.....S\$3,000.00 EX SECT. I - AGE >= 26.....S\$500.00 * AGE AS AT DATE OF ACCIDENT
4. Date of Expiry of Insurance	18 MAY 2019	EX ON WINDSCREEN.....S\$100.00
5. Persons or Classes of Persons entitled to drive *		

(A) THE POLICYHOLDER.

(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use: *

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.
THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS / THEFT) WILL BE DOUBLED.

ONE TIME WAIVER OF EXCESS FOR THE FIRST S\$500 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT OF OWN DAMAGE CLAIM AT OUR AUTHORISED WORKSHOPS FOR EACH POLICY YEAR.

HIRE PURCHASE CO. : MAYBANK AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia). Please see reverse
For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.



Countersigned By:

Authorised Officer

Authorised Signatory

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7405539G



LIM KIAN HUA
(LIN JIANHUA)

林建华

Race

CHINESE

Date of Birth

23-02-1974

Sex

M

Country of Birth

SINGAPORE



FOR C&C USE ONLY

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7405539G

Holder

LIM KIAN HUA
(LIN JIANHUA)



Birth Date 23 Feb 1974

Valid Date 08 Mar 2006

1001404988G



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

PASS DATE

08 Mar 2006

Class 3A Motor cars without clutch pedals (Auto) < 3000 cc
with < 7 passengers, exclusive of the driver; or
other motor vehicles without clutch pedals < 2500 cc




Licence No: S7405539G

UP 426A

FOR C&C USE ONLY

Agencies



S7405539G



Valid Date 27-02-2006



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name /Mr Lim Kian Hua (lin Jianhua) Reg No/Reg Date SGH1200H / 20/05/2016 Date In/Mileage / 0 Chassis No MMBSTA13AHH000311 Engine No 3A92UDB6473 Make/Model MIT/17MY ATTRAGE 1.2 CVT Colour/Trim A06 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	31/08/2018/ 11:39		218 / MarsLer	63902
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M SUNDRY					50.00
MIVEC PLATE EMBLEM					50.00
M SUNDRY					280.00
C & C LOGO					300 600.00
S MIPNT88088					60 80.00
REVERSE SENSOR					250.00
S MIPNT88088					2700 2100 3000.00
TO REMOVE & RE-INSTALL ALL CARPETS & TRIMMINGS TO GIVE WAY ACCESS FOR REPAIR					100 300.00
S MIPNT88088					300 600.00
TO CHECK REAR LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AREAS					2520 1680 2520.00
S MIPNT88088					DE 740.00
TO CONDUCT COMPUTER SCANNING, PROGRAMMING & RESETTING					20.00
S MIPNT88088					30.00
TO REPLACE REAR BUMPER, REAR BOOT, ETC -CUT & RE-WELD REAR END PANEL STRAIGHTEN, REFORM, ALIGN REAR ACCIDENT AFFECTED AREAS					27.00
S MIPNT88088					421.00
TO APPLY SEALANT ON NEW PANELS & REPAIRED AREAS					155.00
S MIPNT88088					216.00
TO TRANSFER ALL BOOT MECHANISM & COMPONENTS					
S MIPNT98088					
SPRAY PAINTING BOOT, REAR BUMPER, REAR END PANEL, RR FLOOR PAN & BOTH REAR FENDER ETC					
M JJ6410C750	FACE, RR BUMPER	1.00	740.00	0.00	740.00
M JJMU488006	CLIP, RR BPR COVER	10.00	2.00	0.00	20.00
P JJMR200300	CLIP, BUMPER	15.00	2.00	0.00	30.00
P JJ6410C433	LH BRACKET, RR BUMPER	1.00	27.00	0.00	27.00
M JJ5281A631	PANEL, RR END	1.00	421.00	0.00	421.00
M JJ5921A017	WEATHERSTRIP, TRUNK	1.00	155.00	0.00	155.00
M JJ5927A042	LATCH, TRUNK LID	1.00	216.00	0.00	216.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	<table> <tr> <td>Cust No/Name</td><td>/Mr Lim Kian Hua (lin Jianhua)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SGH1200H / 20/05/2016</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AHH000311</td></tr> <tr> <td>Engine No</td><td>3A92UDB6473</td></tr> <tr> <td>Make/Model</td><td>MIT/17MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>A06 / BK</td></tr> </table>	Cust No/Name	/Mr Lim Kian Hua (lin Jianhua)	Reg No/Reg Date	SGH1200H / 20/05/2016	Date In/Mileage	/ 0	Chassis No	MMBSTA13AHH000311	Engine No	3A92UDB6473	Make/Model	MIT/17MY ATTRAGE 1.2 CVT	Colour/Trim	A06 / BK
Cust No/Name	/Mr Lim Kian Hua (lin Jianhua)														
Reg No/Reg Date	SGH1200H / 20/05/2016														
Date In/Mileage	/ 0														
Chassis No	MMBSTA13AHH000311														
Engine No	3A92UDB6473														
Make/Model	MIT/17MY ATTRAGE 1.2 CVT														
Colour/Trim	A06 / BK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	31/08/2018/ 11:39		218 / MarsLer	63902

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
P JJ8341A200 GARNISH, RR END PANE	1.00	332.00	0.00	332.00
M JJ7415A438 MARK, ATTRAGE	1.00	21.00	0.00	21.00
P JJ7415A389 MARK, THREE-DIA	1.00	45.00	0.00	45.00
M JJ7240A172XA TRIM, RR END	1.00	65.00	0.00	65.00
M JJ7646A265 BOARD, TRUNK ROOM FL	1.00	193.00	0.00	193.00
M JJ8355A081 LH REFLECTOR	1.00	22.00	0.00	22.00
M JJ8355A082 RH REFLECTOR	1.00	22.00	0.00	22.00
M JJ8330A852 RH LAMP ASSY, COMBIN	1.00	332.00	0.00	332.00
M JJ8330A851 LH LAMP ASSY, COMBIN	1.00	332.00	0.00	332.00
M JJ8637A176 BUZZER, KEYLESS OPER	1.00	90.00	0.00	90.00
M JJ8637B115 ANTENNA, KEYLESS OPE	1.00	95.00	0.00	95.00
P JJ6410C434 RH BRACKET, RR BUMPE	1.00	27.00	0.00	27.00
M JJ5920A203 PANEL, TRUNK LID	1.00	865.00	0.00	865.00

Z NOTES

ACCIDENT ON 28/08/2018 ALONG SLIP RD SENGKANG EAST RD TWDS TPE(SLE)

TP # SJM2539M TP INS : NTUC

OWNER CLAIMING OWN POLICY (THIRD PARTY RECOVERY)

EXCESS ADVISE BY INSURANCE COMPANY : CHINA TAIPING

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Confirm & accepted by

Authorized signatory and company stamp

Parts	4,050.00
Labour	0.00
Standard Menu	0.00
Specialist Job	7,630.00
Others(Lub,etc)	0.00
Sundry	100.00
Total(w/o GST)	11,780.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Mr Lim Kian Hua (lin Jianhua)
	Reg No/Reg Date	SGH1200H / 20/05/2016
	Date In/Mileage	05/09/2018/ 30912
	Chassis No	MMBSTA13AHH000311
	Engine No	3A92UDB6473
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	21/09/2018/ 09:38		218 / MarsLer	63902

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 ADDITIONAL LABOUR ON REPAIR BOTH REAR OUTER FENDER				600.00
S MIPNT98088 SPRAY PAINTING ON BOTH REAR OUTER FENDER				840.00
Z NOTES SUPPLEMENTARY LABOUR & SPRAY PAINTING				

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Parts	0.00
Labour	0.00
Standard Menu	0.00
Specialist Job	1,440.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	1,440.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Mr Lim Kian Hua (lin Jianhua)
	Reg No/Reg Date	SGH1200H / 20/05/2016
	Date In/Mileage	05/09/2018/ 30912
	Chassis No	MMBSTA13AHH000311
	Engine No	3A92UDB6473
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	21/09/2018/ 09:41		218 / MarsLer	63902

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X JJ5921A017 WEATHERSTRIP, TRUNK	1.00	155.00	0.00	155.00
X JJ7415A438 MARK, ATTRAGE	1.00	21.00	0.00	21.00
X JJ7415A389 MARK, THREE-DIA	1.00	45.00	0.00	45.00
X JJ7240A172XA TRIM, RR END	1.00	65.00	0.00	65.00
X JJ7646A265 BOARD, TRUNK ROOM FL	1.00	193.00	0.00	193.00
X JJ5920A203 PANEL, TRUNK LID	1.00	865.00	0.00	865.00

Z NOTES

ACCIDENT ON 28/08/2018 ALONG SLIP RD SENGKANG EAST RD TWDS TPE(SLE)
 TP # SJM2539M TP INS : NTUC
 OWNER CLAIMING OWN POLICY
 EXCESS ADVISE BY INSURANCE COMPANY : CHINA TAIPING

Estimate

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Parts	2,555.00
Labour	0.00
Standard Menu	0.00
Specialist Job	6,510.00
Others(Lub,etc)	-500.00
Sundry	100.00
Total(w/o GST)	8,665.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2018		03 Sep 2018 10:43 Edit Adj Rpt	S\$9,165.00 Edit Estimates	S\$9,165.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																		
CLAIM SUBFOLDER DETAILS [Created by insurer]																						
<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Insured: MR LIM KIAN HUA, ID: S7405539G</td> <td style="width: 50%;"></td> </tr> <tr> <td>Vehicle Reg. No.: SGH1200H</td> <td>Date of Loss: 28/08/2018 06:00 - :59 [27 Months and 8 Days From LTA Reg Date (Man Yr)]</td> </tr> <tr> <td>Claim Type: OD / SNM18D04179C01</td> <td>Policy/Cover Note No.: DMPCSN3031761800 (Comprehensive) Coverage: 19/05/2018 - 18/05/2019</td> </tr> <tr> <td></td> <td>Excess: S\$500.00</td> </tr> <tr> <td colspan="2">Repairer: Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3, 408650 Ubi - Tel: 67461000</td> </tr> <tr> <td colspan="2">Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]</td> </tr> <tr> <td colspan="2">Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 12/09/2018]</td> </tr> <tr> <td colspan="2">Driver/Custodian: LIM KIAN HUA (LIN JIANHUA) (44 / Male), NRIC: S7405539G, Tel: +6597901402</td> </tr> <tr> <td colspan="2">Adj Asg. Remarks: PLEASE PROCEED TO SURVEY & REVERT. EXCESS OF \$500.00 APPLIES.</td> </tr> </table>					Insured: MR LIM KIAN HUA , ID: S7405539G		Vehicle Reg. No.: SGH1200H	Date of Loss: 28/08/2018 06:00 - :59 [27 Months and 8 Days From LTA Reg Date (Man Yr)]	Claim Type: OD / SNM18D04179C01	Policy/Cover Note No.: DMPCSN3031761800 (Comprehensive) Coverage: 19/05/2018 - 18/05/2019		Excess: S\$500.00	Repairer: Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3, 408650 Ubi - Tel: 67461000		Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 12/09/2018]		Driver/Custodian: LIM KIAN HUA (LIN JIANHUA) (44 / Male), NRIC: S7405539G, Tel: +6597901402		Adj Asg. Remarks: PLEASE PROCEED TO SURVEY & REVERT. EXCESS OF \$500.00 APPLIES.	
Insured: MR LIM KIAN HUA , ID: S7405539G																						
Vehicle Reg. No.: SGH1200H	Date of Loss: 28/08/2018 06:00 - :59 [27 Months and 8 Days From LTA Reg Date (Man Yr)]																					
Claim Type: OD / SNM18D04179C01	Policy/Cover Note No.: DMPCSN3031761800 (Comprehensive) Coverage: 19/05/2018 - 18/05/2019																					
	Excess: S\$500.00																					
Repairer: Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3, 408650 Ubi - Tel: 67461000																						
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]																						
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 12/09/2018]																						
Driver/Custodian: LIM KIAN HUA (LIN JIANHUA) (44 / Male), NRIC: S7405539G, Tel: +6597901402																						
Adj Asg. Remarks: PLEASE PROCEED TO SURVEY & REVERT. EXCESS OF \$500.00 APPLIES.																						
ASSOCIATED MAIL RECEIVED View All Compose Case Mail																						
<ul style="list-style-type: none"> CHINA_TAIPIING (18/10/2018): Alert - Adj Mandate Approved (S\$8556.00) - SGH1200H - Claim Handler: Jowyn Tay CHINA_TAIPIING (04/09/2018): Alert - Adj Mandate Approved (S\$8556.00) - SGH1200H - Claim Handler: Jowyn Tay 																						
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete																						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?													
No results.																						

Claim Documents

***SGH1200H (SNM18D04179C01)**
OD
Aug 28 2018 6:00AM
[MR LIM KIAN HUA]
Cycle & Carriage Fulco Motor Dealer Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▾









Assessment Reports


















1 per page ▾ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/18 13:07	Adjuster Immediate Advice	 Load HTM	<input checked="" type="checkbox"/>


















Photos/Images

3 per page ▾ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
32	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
33	04/09/18 11:51	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	04/09/18 11:51	General View	 Load JPG	<input checked="" type="checkbox"/>
35	04/09/18 11:51	General View	 Load JPG	<input checked="" type="checkbox"/>
36	04/09/18 11:51	General View	 Load JPG	<input checked="" type="checkbox"/>
37	04/09/18 11:51	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/10/18 10:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	10/10/18 10:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	10/10/18 10:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	10/10/18 10:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	10/10/18 10:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	10/10/18 10:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	10/10/18 10:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	10/10/18 10:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	10/10/18 10:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	10/10/18 10:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/10/18 10:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/09/18 10:30	Quotation/Replacement/Repair invoice	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/18 11:50	ESTIMATE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	28/08/18 09:14	Accident Statement	 Load HTM	
2	31/08/18 10:27	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
3	31/08/18 10:27	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	28/08/18 09:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print

Assessment Reports			1 per page ▾	✓
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	28/08/18 09:12	Accident Sketch Plan	 Load JPG	✓
2	28/08/18 09:12	Accident Sketch Plan	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18016028/R1TBS2

Date: 29/10/2018

REFERENCE

Insured/Claimant: MR LIM KIAN HUA Policy No: DMPCSN3031761800
Date of Loss: 28/08/2018 Nature of Claim: OD Claim No: SNM18D04179C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGH1200H**
Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UDB6473
Reg. Date: 20/05/2016 (Man. Year: 2016) Chassis No: MMBSTA13AHH000311
Colour: Grey Odometer: 33884 km
Engine Capacity: 1193 cc
Market Value/New Car Price: S\$50,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50R15 Rear Tyre Size: 195/50R15
Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,430.00	2,935.00	1,495.00	33.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,350.00	6,230.00	1,120.00	15.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,780.00	9,165.00	2,615.00	22.20
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	11,280.00	8,665.00	2,615.00	23.18
+ GST 7.00/7.00% (S\$)	789.60	606.55	183.05	23.18
Nett Amount (S\$)	12,069.60	9,271.55	2,798.05	23.18

INSPECTION

Date of Assignment: 03/09/2018
Date Inspected: 03/09/2018 Inspected At: Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)
330 Ubi Road 3
Singapore 408650
Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Oct 2018)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH1200H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE, RR BUMPER	Deformed	740.00 FS	*740.00 FS
2	10		*CLIP, RR BPR COVER	Necessary	20.00 FS	*20.00 FS
3	15		*CLIP, BUMPER	Necessary	30.00 FS	*30.00 FS
4	1		*LH BRACKET, RR BUMPE	Not Necessary	27.00 FS	*- FS
5	1		*PANEL, RR END	Bent	421.00 FS	*421.00 FS
6	1		*WEATHERSTRIP, TRUNK	Cut	155.00 FS	*155.00 FS
7	1		*LATCH, TRUNK LID	Serviceable	216.00 FS	*- FS
8	1		*GARNISH, RR END PANE	Serviceable	332.00 FS	*- FS
9	1		*MARK, ATTRAGE	Necessary	21.00 FS	*21.00 FS
10	1		*MARK, THREE-DIA	Necessary	45.00 FS	*45.00 FS
11	1		*TRIM, RR END	Deformed	65.00 FS	*65.00 FS
12	1		*BOARD, TRUNK ROOM FL	Cracked	193.00 FS	*193.00 FS
13	1		*LH REFLECTOR	Serviceable	22.00 FS	*- FS
14	1		*RH REFLECTOR	Serviceable	22.00 FS	*- FS
15	1		*RH LAMP ASSY, COMBIN	Serviceable	332.00 FS	*- FS
16	1		*LH LAMP ASSY, COMBIN	Serviceable	332.00 FS	*- FS
17	1		*BUZZER, KEYLESS OPER	Serviceable	90.00 FS	*- FS
18	1		*ANTENNA, KEYLESS OPE	Serviceable	95.00 FS	*- FS
19	1		*RH BRACKET, RR BUMPE	Serviceable	27.00 FS	*- FS
20	1		*PANEL, TRUNK LID	Bent	865.00 FS	*865.00 FS
21	1		*MIVEC PLATE EMBLEM	Necessary	50.00 FS	*50.00 FS
22	1		*C&C LOGO	Necessary	50.00 FS	*50.00 FS
23	1		*REVERSE SENSOR	Shorted	280.00 FS	*280.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	4,430.00	2,935.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RE-INSTALL ALL CARPETS & TRIMMINGS TO GIVE WAY ACCESS FOR REPAIR.	New	600.00	300.00
2	TO CHECK REAR LIGHTING & WIRING SYSTEM ON REAR ACCIDENT PARTS.	New	80.00	60.00
3	TO CONDUCT COMPUTER SCANNING, PROGRAMMING & RESETTNG.	New	250.00	250.00
4	TO REPLACE REAR BUMPER, REAR BOOT, ETC - CUT & RE-WELD REAR END PANEL. STRAIGHTEN, REFORM, ALIGN REAR ACCIDENT AFFECTED AREAS.	New	3,000.00	2,700.00
5	TO APPLY SEALANT ON NEW PANELS & REPAIRED AREAS.	New	300.00	100.00
6	TO TRANSFER ALL BOOT MECHANISM & COMPONENTS.	New	600.00	300.00
7	SPRAY PAINTING BOOT, REAR BUMPER, REAR END PANEL, RR FLOOR FAN & BOTH REAR FENDER ETC.	New	2,520.00	2,520.00
Gross Labour Cost (\$\$)			7,350.00	6,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Mr Lim Kian Hua (lin Jianhua)
	Reg No/Reg Date	SGH1200H / 20/05/2016
	Date In/Mileage	05/09/2018/ 30912
	Chassis No	MMBSTA13AHH000311
	Engine No	3A92UDB6473
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 / BK

Account No	Terms	Date/Time/Printed	CSE	Operator	WIP No			
F0000018	Credit	21/09/2018/ 09:41		218 / MarsLer	63902			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	SUNDRY							50.00
	MIVEC PLATE EMBLEM							50.00
M	SUNDRY							280.00
	C & C LOGO							300.00
S	MIPNT88088							60.00
	REVERSE SENSOR							250.00
S	MIPNT88088							2700.00
	TO REMOVE & RE-INSTALL ALL CARPETS & TRIMMINGS TO GIVE WAY ACCESS FOR REPAIR							100.00
S	MIPNT88088							300.00
	TO CHECK REAR LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AREAS							2520.00
S	MIPNT88088							-500.00
	TO CONDUCT COMPUTER SCANNING, PROGRAMMING & RESETTNG							740.00
S	MIPNT88088							20.00
	TO REPLACE REAR BUMPER,REAR BOOT,ETC							30.00
	-CUT & RE-WELD REAR END PANEL							421.00
	-REPAIR BOTH REAR OUTER FENDER							
	STRAIGHTEN,REFORM,ALIGN REAR ACCIDENT AFFECTED AREAS							
S	MIPNT88088							
	TO APPLY SEALANT ON NEW PANELS & REPAIRED AREAS							
S	MIPNT88088							
	TO TRANSFER ALL BOOT MECHANISM & COMPONENTS							
S	MIPNT98088							
	SPRAY PAINTING BOOT, REAR BUMPER,REAR END PANEL, FLOOR PAN,BOTH REAR FENDER ETC							
X	EXCESS							
	EXCESS							
X	JJ6410C750	FACE, RR BUMPER			1.00	740.00	0.00	740.00
X	JJMU488006	CLIP,RR BPR COVER			10.00	2.00	0.00	20.00
X	JJMR200300	CLIP, BUMPER			15.00	2.00	0.00	30.00
X	JJ5281A631	PANEL,RR END			1.00	421.00	0.00	421.00

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.