



AUTOBAY @ KAKI BUKIT
No. 1 KAKI BUKIT AVE 6 #01-04 SINGAPORE 11510
TELEPHONE: 6746 2795 FAX: 6746 2804
EMAIL: unimotor@unimotor.sg
Registration No.: 20092011W

PTE LTD

ITEM	ESTIMATE	FOR	QUANTITY	UNIT	PRICE	TOTAL
1 REAR TAILGATE WINDSCREEN MOULDING	X	nn	1		\$90.70	
1 REAR TAILGATE PANEL	/	buc	1		\$1,348.90	868.95
2 REAR TAILGATE HINGES	X	nn	2		\$192.40	
2 REAR TAILGATE ABSORBER UNIT	X	nn	2		\$571.60	
1 REAR TAILGATE LOCK ASSY	X	nn	1		\$215.30	
1 REAR TAILGATE LOCK STRIKER	X	nn	1		\$43.50	
1 REAR TAILGATE WEATHERSTRIP	X	nn	1		\$293.40	
1 REAR TAILGATE SUZUKI LOGO	/	al	1		\$63.30	55
1 REAR BUMPER ASSY	/	al	1		\$998.40	540.05
2 REAR BUMPER SIDE RETAINER	1 pc	al	2		\$124.60	20
2 REAR BUMPER BRACKET	X	nn	2		\$117.60	
1 REAR BUMPER REINFORCEMENT	X	nn	1		\$354.90	
1 REAR BUMPER R/H SIDE REFLECTOR	/	al	1		\$189.60	90
1 REAR FLOOR OUTER PANEL	/	buc	1		\$315.00	260.05
1 REAR FLOOR INNER PANEL	X	nn	1		\$424.00	
1 REAR R/H CORNER PANEL	X	nn	1		\$298.50	
1 REAR R/H FENDER ASSY	X	Repair	1		\$1356.30	442.9
1 REAR R/H FENDER INNER TRIM PANEL	X	3mm	1		\$987.60	
1 REAR R/H FENDER INNER TRIM BOARD	X		1		\$175.00	
1 REAR R/H FENDER INNER SHIELD	/	al	1		\$81.70	67
1 REAR R/H AIR DUCT	/	al	1		\$174.20	44.2
1 REAR FLOOR PANEL	X	Repair	1		\$823.70	
					\$9,240.20	1905.25
					\$1,386.03	
					\$7,854.17	1619.46

1 REAR 70KMH STICKET	\$	15.00
1 REAR 4 PAX STICKET	\$	15.00
1 REAR REVERSE SENSOR	\$	220.00
1 REAR WINDSCREEN DAM RUBBER	\$	60.00
1 REAR RH FENDER GLASS DAM RUBBER	\$	50.00

TO COMPLETE WHEEL ALIGNMENT	\$	120.00	X
TO SPRAY UNDERCOATING IN REPAIR	\$	180.00	60
TO DISM/REFIX REAR WINDSCREEN/R/H FENDER GLASS	\$	280.00	100
TO DISM/REWIRE DAMAGED PORTION	\$	200.00	30
TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	\$	1,800.00	800
TO PUTTY AND RESPRAY DAMAGED PORTION	\$	1,200.00	800
	\$	11,994.17	700

7 Days. 2479.46
20% 2800