

ASS. REC. BY:

REF:

CS / FCI 18016040 / Usbnz

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Lerrone jaw

of

FCI

Date/Time: 3/18/18 @ 12:01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBD105L

Insured: SHB 4766S

at Workshop m/s:

Erofi Motor

Tel: 6 7527740

of

1 Kelki Bkt Ave G # 02-62

Policy No:

Claim No: D18006085 MF&H

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11/08/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

1:30pm @ 3/18/18

Person Contacted:

Lee Lee

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	TBD 105L - X
	SHB 4766S - CCH 107416013404 / m1w342
06/09/18	@ 16:00 pm. revised PA to Lerrone jaw via email.

NA: 15073016

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBD105Lat Workshop m/s Enfu

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$800

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

16/9/2023

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBD105L Yr Regn: 17/9/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha T135 c.c. 135Colour: Mult. colour A/C: Insured / Std / NI / NASp. Reading: 4000 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 51P009222

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~In order~~ / Jammed / Leaked / Burnt or okBrake: ~~In order~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80/90-17 m.c.R: 90/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 11/8/18 D.O.I. 31/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Left, N/S side

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/9/1817/9/18 confirmed n/s #2700 with MR Teo.17/09/18 Confirmed HS \$2,700/- @ 5 days with Marcus
(\$2,359.10 Red - 47%)

RECEIVED 17 SEP 2018

Date/Time, File Pass to?

17/09/181) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, \$I

Photos

Others

1405050123363

Report Format :

Lump Sum / I.B.I: (\$ 2,700/- HS)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18016040/Usb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 03-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4766S	Veh. Inspected	FBD 105L
Policy No.		Coverage (\$)	0.00
Claim No.	D18006085MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	31/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/08/2018	Inspection Date	31/08/2018
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006085MFSH

Date: 06 September 2018

Our Ref: CS/FCI18016040/Usb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBD 105L

Please be informed that we had conducted the inspection of the abovementioned vehicle on 31/08/2018 at the premises of M/s Erofia Motor Trading Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,059.10</u>
Revised Estimate Amount	: S\$ <u>3,434.40</u>
"Check" Items Amount	: S\$ <u>574.20</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the front portion & n/s body.



Comments/ Present Status:

Damages Consistent.

Repair days: 5 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date 14-08-2018 Our Ref No. D18006085MFSH

Accident Date 11-08-2018 Claim Type. Third Party

Insured Vehicle SHB4766S Third Party Vehicle. FBD105L

Survey Location 1 KAKI BUKIT AVE 6 #02-62

Contact Person. MR TEO

Contact No. 67527740/ 90696165 Fax No. 67528669

Survey Type WITHOUT PREJUDICE: PENDING OUR ID'S VF TO DETERMINE EXACT LIABILITY

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA Fax No. 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop EROFIA MOTOR Attention. NIL
 TRADING PTE LTD

Cc : TP Solicitor NA TP Solicitor Fax No. NA

Officer Incharge LURENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 6 September 2018 4:00 PM
To: LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18006085MFSH/1
Attachments: FBD 105L - Preli Advise.pdf

Dear Lurene,

Enclosed herewith preliminary advice of FBD 105L.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 31 August 2018 1:41 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18006085MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 31 August 2018 12:00 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006085MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5585D
Vehicle Details	
Vehicle No.:	FBD105L
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2018
Vehicle Make:	YAMAHA
Vehicle Model:	T135
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	5YP009222
Chassis No.:	5YP009222
Maximum Power Output:	-
Open Market Value:	\$1,666.00
Original Registration Date:	17 Sep 2008
First Registration Date:	17 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$250.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Sep 2023
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$3,083.00
COE Rebate Amount:	\$3,082.00
Total Rebate Amount:	\$3,082.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Sep 2018

OK

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5050000877-07

Cover : Third Party

- | | |
|---|-------------------|
| 1. Index mark and Registration Number of Vehicle | : FBD105L |
| Chassis Number | : SYP0009222 |
| 2. Name of Policyholder | : CHONG KEE KEONG |
| 3. Effective Date of Insurance | : 17 Mar 2018 |
| 4. Expiry Date of Insurance | : 16 Mar 2019 |
| 5. Persons or Classes of Persons entitled to drive# | |

(a) Named Driver(s) Only.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
INSURE WITH COE	: N/A
NAMED DRIVER (1)	: CHONG KEE KEONG
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : THINK ONE AUTOMOBILE & TRADING PTE. LTD. (00000571089)

Date of Issue : 02 Mar 2018 10:58 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Authorised Officer



Chief Executive

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8185585D



CHONG KEE KEONG
張紀強

CHINESE
Date of Birth: 03 Nov 1981
Issued: 06 Feb 2013
Valid Until: 06 Feb 2018



REPUBLIC OF SINGAPORE DRIVING LICENCE


Licence Number: S8185585D

CHONG KEE KEONG

Birth Date: 03 Nov 1981
Issue Date: 06 Feb 2013



002149150F



No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417583

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Owner : Chong Kee Keong

Accident Date : 11 Aug 2018

Vehicle No : FBD 105 L

Vehicle Model : Yamaha T135

Estimated Repair Costs

Qty	Description	Amount S(\$)
1	Front cowling inner bracket	\$ 3.1 55.00
2	Front fork tubes assy	\$ 321.21 640.00
1	Front wheel rim	\$ 2700/- 280.00
1	Fork under bracket	\$ 3.1 185.00
1	Front rim shaft	\$ 3.1 45.00
1	Front rim bearing	\$ 2.9 38.00
1	Front brake disc	\$ 3.1 155.00
1	Handle bar	\$ 3.1 75.00
1	Handle bar end	\$ 1.2 28.00
1	Hand grip (1 set)	\$ 1.0 45.00
1	Handle bar inner bracket	\$ 1.2 68.00
1	Side mirror -L/H	\$ 1.0 55.00
1	Brake lever	\$ 1.0 32.00
2	Front signals	\$ 1.0 130.00
1	Headlamp	\$ 1.0 185.00
1	Fairing assy (1 set)	\$ 3.2 425.00
1	Side cowling inner garnish	\$ 1.0 90.00
1	Centre inner panel	\$ 1.0 145.00
1	Radiator	\$ 2.4 458.00
1	Radiator fan assy	\$ 1.1 90.00
1	Engine cover -L/H	\$ 1.1 145.00
1	Front footrest bracket	\$ 3.1 65.00
1	Front footrest rubber -L/H	\$ 1.0 35.00
1	Gear pedal	\$ 1.0 42.00
1	Rear footrest -L/H	\$ 1.0 40.00
1	Rear footrest bracket -L/H	\$ 1.1 78.00
1	Side stand	\$ 3.1 75.00
1	Main stand	\$ 2.2 95.00
1	Under seat panel	\$ 1.1 85.00
1	Rear taillamp	\$ 1.1 135.00
1	Rear fender	\$ 1.0 120.00
1	Side board	\$ 1.0 80.00
		\$ 4,219.00
		\$ 421.90
		\$ 3,797.10

PAGE 1 OF 2

c/f: \$ 3,797.10

<u>Special Nett Items</u>			
1	Number plate (1 set)	\$ 34	28.00 20
2	Fork oils	\$ 11	30.00 X
2	Fork oil seals	\$ 11	56.00 X
1	Steering cone (1 set)	\$ 91	90.00 X
1	Engine oil	\$ 11	18.00 X
1	Engine cover gasket	\$ 11	22.00 X
1	Rear box	\$ 677	180.00 /
1	Rear box bracket	\$ 11	100.00 X
1	Helmet	\$ 11	120.00 X
1	Coolant	\$ 11	18.00 /
1	Sticker (1 set)	\$ 11	90.00 /
		\$	752.00

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service.	\$ 35	50.00
2	To check wiring and reset headlamp focusing.	11 \$ X	80.00
3	To provide labour.	\$ 300	380.00
		\$	510.00

Grand Total \$ 5,059.10

Dollars: Five Thousand Fifty-Nine And Ten Cents Only.


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016040/Usbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4766S	Veh. Inspected	FBD 105L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006085MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	31/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA T135	c.c	135	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	5YP009222	Colour	MULTI	
Odometer	4000	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80/90-17	MICHELIN	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90/80-17	MICHELIN	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/08/2018	Inspection Date	31/08/2018	
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 105L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT COWLING INNER BRACKET	BENT	55.00	55.00
2	FRONT FORK TUBES ASSY	BENT / TWISTED	640.00	640.00
1	FRONT WHEEL RIM	DENTED / BENT	280.00	280.00
1	FORK UNDER BRACKET	BENT	185.00	185.00
1	FRONT RIM SHAFT	BENT	45.00	45.00
1	FRONT RIM BEARING	DAMAGED	38.00	38.00
1	FRONT BRAKE DISC	BENT	155.00	155.00
1	HANDLE BAR	BENT	75.00	75.00
1	HANDLE BAR END	TWISTED	28.00	28.00
1	SET HAND GRIP	TORN	45.00	45.00
1	HANDLE BAR INNER BRACKET	NOT NECESSARY	68.00	-
1	SIDE MIRROR-L/H	CUT	55.00	55.00
1	BRAKE LEVER	SERVICEABLE	32.00	-
2	FRONT SIGNALS	CRACKED	130.00	130.00
1	HEADLAMP	SCRATCHED	185.00	185.00
1	SET FAIRING ASSY	BROKEN	425.00	425.00
1	SIDE COWLING INNER GARNISH	CRACKED	90.00	90.00
1	CENTRE INNER PANEL	CRACKED	145.00	145.00
1	RADIATOR	PUNCTURE	458.00	458.00
1	RADIATOR FAN ASSY	NOT NECESSARY	90.00	-
1	ENGINE COVER-L/H	NOT NECESSARY	145.00	-
1	FRONT FOOTREST BRACKET	BENT	65.00	65.00
1	FRONT FOOTREST RUBBER-L/H	TORN	35.00	35.00
1	GEAR PEDAL	TWISTED	42.00	42.00
1	REAR FOOTREST-L/H	SERVICEABLE	40.00	-
1	REAR FOOTREST BRACKET-L/H	NOT NECESSARY	78.00	-
1	SIDE STAND	BENT	75.00	75.00
1	MAIN STAND	TO REPAIR SEE LABOUR	95.00	-
1	UNDER SEAT PANEL	NOT NECESSARY	85.00	-
1	REAR TAILLAMP	NOT NECESSARY	135.00	-

Report Ref No. CS/FCI18016040/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER	NOT NECESSARY	120.00	-
1	SIDE BOARD	CUT	80.00	80.00
	LESS 10% DISCOUNT		-421.90	-333.10
			3,797.10	2,997.90
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	BENT	28.00	20.00
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	90.00	-
1	ENGINE OIL (SN)	NOT NECESSARY	18.00	-
1	ENGINE COVER GASKET (SN)	NOT NECESSARY	22.00	-
1	REAR BOX (SN)	CUT	180.00	180.00
1	REAR BOX BRACKET (SN)	TO REPAIR SEE LABOUR	100.00	-
1	HELMET (SN)	TO REPAIR SEE LABOUR	120.00	-
1	COOLANT (SN)	NECESSARY	18.00	18.00
1	SET STICKER (SN)	NECESSARY	90.00	90.00
			752.00	308.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE.		50.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR INCLUSIVE OF THE REPAIR OF MAIN STAND, REAR BOX BRACKET AND HELMET.		380.00	300.00
			510.00	335.00
	GRAND TOTAL		5,059.10	3,640.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS/FCI18016040/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.