

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0977/2018/PH
Date : 27-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Shawn Tan Wei Liang
Address : 139 Cavenagh Road
#06-12
Singapore 229627
Telephone : HP +65 91094600
Type of Claim : Own Damage claims
Policy No. : 2100481053-01
Vehicle No : **SLF 5909 Y**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Aug-16
Engine No : CVN 016564
Chassis No : WAUZZZF48HA017692
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Aug-18
Place of Accident : Cavenagh Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 5909 Y.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1000 .	
3	To respray front bumper, lhs front fender.	\$ 1,500.00 1100 .	
4	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>4,432.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 5909 Y.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>replaced</i>	\$ 1,849.00	✓
2	FIXING PARTS FOR FRONT BUMPER <i>not seen</i>	\$ 245.00	+
3	AIR GUIDE - LH <i>not seen</i>	\$ 73.00	X
4	AIR GUIDE GRILLE - LH <i>not seen</i>	\$ 118.00	+
5	GUIDE SECTION - LH ?	\$ 31.00	?
6	FRONT FENDER - LH <i>Dented</i>	\$ 665.00	✓
7	ATTACHMENT PRTS FOR FENDER ?	\$ 45.00	?
8	CLOSING ELEMENT - LH <i>seen</i>	\$ 44.00	✓
9	BRACKET FOR FENDER - LH <i>not seen</i>	\$ 31.00	✓
10	BRACKET FOR DEFORMATION ELEMENT - LH <i>seen</i>	\$ 43.00	✓
11	BRACKET FOR FENDER <i>not seen</i>	\$ 27.00	✓
12	FENDER BRACE ?	\$ 103.00	?
13	WHEEL HOUSING LINER - LH <i>replaced</i>	\$ 215.00	✓
14	ATTACHMENT PARTS FOR WHEEL HOUSING LINER ?	\$ 78.00	?
15	WHEEL SPOILER - LH <i>replaced</i>	\$ 63.00	✓
16	SPOILER - LH ?	\$ 30.00	?
17	STONE CHIP GUARD - SATIN BLACK <i>not seen</i>	\$ 44.00	✓
18	COVER - LH ? <i>seen</i>	\$ 27.00	✓
19	COVER - LH	\$ 20.00	✓
20	LED HEADLIGHT - LH <i>not seen</i>	\$ 6,973.00	+
SUB- TOTAL SPARE PARTS :		<u>\$ 10,724.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 5909 Y .

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
21	ALUMINIUM RIM <i>ct</i>	\$ 563.00	✓
22	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		\$ 11,587.00	
TOTAL LABOUR CHARGES		\$ 4,432.00	
GRAND TOTAL		\$ 16,019.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *03/09/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 05 Days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant