

REF:

CC 1A/18016055 /A/bn2

ASS. REC. BY: Adrian King

ASSIGNMENT

From:

Date:

Veh No:

SLF5909Y.

Yr Regn: 2016 August

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Audi A4

c.c 1395

at Workshop m/s

Colour

White

A/C: Insured / Std / NI / NA

of

Sp. Reading

30988

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

2100481053

C/No:

WAU22ZF48HA017692

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

600

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F: 205/60 R16.

R: 205/60 R16.

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental.

Bal. or Market Value:

115K.

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

06

mm

R/Bal.

06

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

06

mm

L/Bal.

06

mm

Est. Repairs:

885

5

days

Res.: Yes or No

D.O.A.

26/8/18

D.O.I.

03/09/18

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Premium.

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front n/s.

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD ALG.

SLF 5909Y - X

4/9/18 Informed Jeffery C/A ex TBA

19/12/18 final fig \$5814.32 (Red 10, 204.68, 649) confirmed by email

RECEIVED 10 JAN 2019

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 5

1)

☐

: Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

2) 9/1 -typist

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

200

10

) \$ + RS. \$

) Photos

) Others

Report Format:

merimen

Lump Sum / I.B.I. (\$)

5814.32

TOTAL

210

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 19 December 2018 11:34 AM
To: Boo seng yak; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SLF5909Y - OD AIG - SURVEYED 3 SEP 18

Dear Mr Boo,

Confirm repair cost of \$5,814.32 before excess \$600 and GST @ 5 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Monday, 3 December 2018 9:11 AM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLF5909Y - OD AIG - SURVEYED 3 SEP 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$5814.32 @ 5 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 4 September 2018 12:10 PM
To: 'Claims Dept'; SUR; Admin A
Subject: RE: OD claim for SLF 5909 Y-DOA: 26/8/2018 (AIG OD)

Dear Jeffery,

Vehicle excess \$600/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 4 September 2018 11:03 AM
To: Claims Dept <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: OD claim for SLF 5909 Y-DOA: 26/8/2018 (AIG OD)

Dear Jeffery,

As instructed by our client, please proceed to repair the **insured vehicle SLF 5909Y (Excess TBA-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Monday, 3 September 2018 6:20 PM
To: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: OD claim for SLF 5909 Y

Dear all,

Adrian have surveyed the vehicle this morning.

Kindly let us have the approval for this vehicle.

Owner is leaving the car behind in the next few days he hopes that approval can be given by then so we can proceed with the repairs accordingly.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Monday, 27 August, 2018 7:11 PM
To: 'SUR' <sur@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD claim for SLF 5909 Y

Good evening all ,

Here are the GIA and estimate attachment for your kind reference .

Thank you .

Best Regards,
Phua
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8841E
Vehicle Details	
Vehicle No.:	SLF5909Y
Vehicle to be Exported:	No
Intended De-registration Date:	28 Aug 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CVN016564
Chassis No.:	WAUZZZF48HA017692
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,163.00
Original Registration Date:	31 Aug 2016
First Registration Date:	31 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$27,029.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2026
PARF Rebate Amount:	\$20,271.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,903.00
COE Rebate Amount:	\$46,353.00
Total Rebate Amount:	\$66,624.00

The information contained herein is correct as at 28 Aug 2018

OK



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Shawn Tan Wei Liang
Period of Insurance : 31 Aug 2017 To 30 Aug 2018
Engine No. : CVN016564
Chassis No. : WAUZZZF48HA017692

Vehicle No. : SLF5909Y
Policy No. : 2100481053-01
Endorsement No. :
Issued Date : 16 Aug 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Shawn Tan Wei Liang - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center, Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125260

PREMIUM LEASING -CHB
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSPUC

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondence from third party(ies) to AIG immediately.

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S7638841E**
 Name: **SHAWN TAN WEI LIANG**

Birth Date: **25 Nov 1976**
 Issue Date: **04 Aug 2004**

001268835H




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7638841E

Name: **SHAWN TAN WEI LIANG**

Race: **CHINESE**
 Date of birth: **25-11-1976** Sex: **M**
 Country of birth: **SINGAPORE**

S7638841E




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 3 Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg

PASS DATE: **24 Jun 1994**

NP 428A

License No: S7638841E



4096287

NRIC No. **S7638841E**

Date of issue: **06-09-2007**

139 CAVENAGH ROAD #06-12
SINGAPORE 229627

NRIC No: **S7638841E** Date: **30/01/2016**




Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0977/2018/PH
Date	:	27-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Shawn Tan Wei Liang
Address	:	139 Cavenagh Road #06-12 Singapore 229627
Telephone	:	HP +65 91094600
Type of Claim	:	Own Damage claims
Policy No.	:	2100481053-01
Vehicle No	:	SLF 5909 Y
Model Code	:	Audi A4 SEDAN 1.4 TFSI
Model / Year	:	Aug-16
Engine No	:	CVN 016564
Chassis No	:	WAUZZZF48HA017692
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	26-Aug-18
Place of Accident	:	Cavenagh Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 5909 Y.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1000 ✓	✓
3	To respray front bumper, lhs front fender.	\$ 1,500.00 1100 ✓	✓
4	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ <u>4,432.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 5909 Y.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>del d</i>	\$ 1,849.00 ✓	1479.20
2	FIXING PARTS FOR FRONT BUMPER <i>not new</i>	\$ 245.00 +	
3	AIR GUIDE - LH <i>not new</i>	\$ 73.00 x	
4	AIR GUIDE GRILLE - LH <i>not new</i>	\$ 118.00 +	
5	GUIDE SECTION - LH <i>not new</i>	\$ 31.00 ?	X
6	FRONT FENDER - LH <i>Del d</i>	\$ 665.00 ✓	532
7	ATTACHMENT PRTS FOR FENDER <i>not new</i>	\$ 45.00 ?	X
8	CLOSING ELEMENT - LH <i>new</i>	\$ 44.00 ✓	34.56
9	BRACKET FOR FENDER - LH <i>Del d</i>	\$ 31.00 ✓	24.16
10	BRACKET FOR DEFORMATION ELEMENT - LH <i>new</i>	\$ 43.00 ✓	34.16
11	BRACKET FOR FENDER <i>Del d</i>	\$ 27.00 ✓	21.60
12	FENDER BRACE <i>not new</i>	\$ 103.00 ?	X
13	WHEEL HOUSING LINER - LH <i>Del d</i>	\$ 215.00 ✓	171.60
14	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>Not new</i>	\$ 78.00 ?	X
15	WHEEL SPOILER - LH <i>Del d</i>	\$ 63.00 ✓	50.16
16	SPOILER - LH <i>Not new</i>	\$ 30.00 ?	X
17	STONE CHIP GUARD - SATIN BLACK <i>new</i>	\$ 44.00 ✓	34.56
18	COVER - LH <i>new</i>	\$ 27.00 ✓	21.04
19	COVER - LH <i>new</i>	\$ 20.00 ✓	15.36
20	LED HEADLIGHT - LH <i>not new</i>	\$ 6,973.00 x	
SUB- TOTAL SPARE PARTS		\$ 10,724.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 5909 Y.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
21	ALUMINIUM RIM <i>cut</i>	\$ 563.00	✓ 450
22	SUNDRIES <i>21er</i>	\$ 300.00	? 113.98
TOTAL SPARE PARTS		:	\$ 11,587.00
TOTAL LABOUR CHARGES		:	\$ 4,432.00
GRAND TOTAL		:	\$ 16,019.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 03/09/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0977/2018/PH
Date	:	27-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adriasn

5 days - ok - jb - 3 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Shawn Tan Wei Liang
Address	:	139 Cavenagh Road
	:	#06-12
	:	Singapore 229627
Telephone	:	HP +65 91094600
Type of Claim	:	Own Damage Claim
Policy No.	:	2100481053-01
Vehicle No	:	SLF 5909 Y
Model Code	:	Audi A4 1.4 TFSI
Model / Year	:	Aug-16
Engine No	:	CVN016564
Chassis No	:	WAUZZZF48HA017692
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	26-Aug-18
Place of Accident	:	Cavenagh Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 5909 Y .

S/N	Nature of Jobs	Estimated Charges	
1	To remove and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00	\$ 1,000.00
3	To respray front bumper, lhs front fender.	\$ 1,500.00	\$ 1,100.00
4	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
5	To carry out diagnostic check	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,432.00	\$ 2,932.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 5909 Y.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	FIXING PARTS FOR FRONT BUMPER	\$ 245.00	
3	AIR GUIDE - LH	\$ 73.00	
4	AIR GUIDE GRILLE - LH	\$ 118.00	
5	GUIDE SECTION - LH	\$ 31.00	
6	FRONT FENDER - LH	\$ 665.00	\$ 532.00
7	ATTACHMENT PARTS FOR FENDER	\$ 45.00	
8	CLOSING ELEMENT - LH	\$ 44.00	\$ 34.56
9	BRACKET FOR FENDER - LH	\$ 31.00	\$ 24.16
10	BRACKET FOR DEFORMATION ELEMENT - LH	\$ 43.00	\$ 34.16
11	BRACKET FOR FENDER	\$ 27.00	\$ 21.60
12	FENDER BRACE	\$ 103.00	
13	WHEEL HOUSING LINER - LH	\$ 215.00	\$ 171.60
14	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$ 78.00	
15	WHEEL SPOILER - LH	\$ 63.00	\$ 50.16
16	SPOILER - LH	\$ 30.00	
17	STONE CHIP GUARD - SATIN BLACK	\$ 44.00	\$ 34.56
18	COVER - LH	\$ 27.00	\$ 21.04
19	COVER - LH	\$ 20.00	\$ 15.36
20	LED HEADLIGHT - LH	\$ 6,973.00	
TOTAL SPARE PARTS		\$ 10,724.00	\$ 2,418.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 5909 Y.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 2,418.40
21	ALUMINIUM RIM		\$ 563.00	\$ 450.00
22	SUNDRIES		\$ 300.00	\$ 13.92
	TOTAL SPARE PARTS	:	\$ 11,587.00	\$ 2,882.32
	TOTAL LABOUR CHARGES	:	\$ 4,432.00	\$ 2,932.00
	GRAND TOTAL	:	\$ 16,019.00	\$ 5,814.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLF 5909 Y

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0977/2018/MAS

7 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLF 5909 Y Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLF 5909 Y**, claimant,
Mr. Shawn Tan Wei Liang, please find the related document per attached.

1. A copy of the Original invoice no. 85013319 – S\$5,579.32
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLF 5909 Y

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Aug 2018		03 Sep 2018 18:00 Edit Adj Rpt	S\$5,814.32 Edit Estimates	S\$5,814.32 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SHAWN TAN WEI LIANG, ID: S7638841E, Tel: +6591094600, Email: NOEMAIL								
Vehicle Reg. No.:	SLF5909Y	Date of Loss:	26/08/2018 15:00 - :59 [23 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 3648898727SG	Policy/Cover Note No.:	2100481053 (Comprehensive)						
		Excess:	S\$600.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/09/2018]								
Driver/Custodian:	SHAWN TAN WEI LIANG (41 / Male), NRIC: S7638841E, Tel: +6591094600								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (04/09/2018): SLF5909Y / OD / 26/08/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF5909Y (3648898727SG)
OD
Aug 26 2018 3:00PM
[SHAWN TAN WEI LIANG]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	04/09/18 10:38	General View		Load JPG	☒		
2	04/09/18 10:38	General View		Load JPG	☒		
3	04/09/18 10:38	General View		Load JPG	☒		
4	04/09/18 10:38	General View		Load JPG	☒		
5	04/09/18 10:38	General View		Load JPG	☒		
6	04/09/18 10:38	General View		Load JPG	☒		
7	04/09/18 10:38	General View		Load JPG	☒		
8	04/09/18 10:38	General View		Load JPG	☒		
9	04/09/18 10:38	General View		Load JPG	☒		
10	04/09/18 10:38	General View		Load JPG	☒		
11	04/09/18 10:38	General View		Load JPG	☒		
12	04/09/18 10:38	General View		Load JPG	☒		
13	04/09/18 10:38	General View		Load JPG	☒		
14	04/09/18 10:38	General View		Load JPG	☒		
15	04/09/18 10:38	General View		Load JPG	☒		
16	04/09/18 10:38	General View		Load JPG	☒		
17	04/09/18 10:38	General View		Load JPG	☒		
Documentation						1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	04/09/18 10:50	Singapore Accident Statement		Load PDF			
2	04/09/18 10:50	Certificate of Insurance		Load PDF			
3	04/09/18 10:51	Insured's Driving License		Load PDF			
4	04/09/18 10:51	MARK ESTIMATE		Load PDF			
5	11/01/19 09:32	WORKSHOP INVOICE		Load PDF			
6	11/01/19 09:32	DISCHARGE VOUCHER		Load PDF			

Linked Accident Report Documents

			View	Use Viewer
Assessment Reports		1 per page	☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	27/08/18 14:27	Accident Statement		Load HTM
Photos/Images		3 per page	☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	27/08/18 14:23	Accident Photo		Load JPG
2	27/08/18 14:23	Accident Photo		Load JPG
3	27/08/18 14:23	Accident Photo		Load JPG
4	27/08/18 14:23	Accident Photo		Load JPG
5	27/08/18 14:23	Accident Photo		Load JPG
6	27/08/18 14:23	Accident Photo		Load JPG
7	27/08/18 14:23	Accident Photo		Load JPG
8	27/08/18 14:23	Accident Photo		Load JPG
9	27/08/18 14:23	Accident Photo		Load JPG
10	27/08/18 14:23	Accident Photo		Load JPG

11	27/08/18 14:23	Accident Photo		Load JPG	
Documentation			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	27/08/18 14:18	Sketch Plan		Load JPG	
2	27/08/18 14:18	Sketch Plan #2		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18016055/AVBN2

Date: 11/01/2019

REFERENCE

Insured/Claimant: SHAWN TAN WEI LIANG Policy No: 2100481053
Date of Loss: 26/08/2018 Nature of Claim: OD Claim No: 3648898727SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF5909Y
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN016564
Reg. Date: 31/08/2016 (Man. Year: 2016) Chassis No: WAUZZZF48HA017692
Colour: White Odometer: 30988 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$115,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,587.00	2,882.32	8,704.68	75.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,432.00	2,932.00	1,500.00	33.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,019.00	5,814.32	10,204.68	63.70
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	15,419.00	5,214.32	10,204.68	66.18
+ GST 7.00/7.00% (S\$)	1,079.33	365.00	714.33	66.18
Nett Amount (S\$)	16,498.33	5,579.32	10,919.01	66.18

INSPECTION

Date of Assignment: 03/09/2018
Date Inspected: 03/09/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,849.00 FS	*1,479.20 FS
2	1	*FIXING PARTS FOR FRONT BUMPER	Not Necessary	245.00 FS	*- FS
3	1	*AIR GUIDE-LH	Not Necessary	73.00 FS	*- FS
4	1	*AIR GUIDE GRILLE-LH	Not Necessary	118.00 FS	*- FS
5	1	*GUIDE SECTION-LH	Not Necessary	31.00 FS	*- FS
6	1	*FRONT FENDER-LH	Dented	665.00 FS	*532.00 FS
7	1	*ATTACHMENT PARTS FOR FENDER	Not Necessary	45.00 FS	*- FS
8	1	*CLOSING ELEMENT-LH	Necessary	44.00 FS	*34.56 FS
9	1	*BRACKET FOR FENDER-LH	Bent	31.00 FS	*24.16 FS
10	1	*BRACKET FOR DEFORMATION ELEMENT-LH	Necessary	43.00 FS	*34.16 FS
11	1	*BRACKET FOR FENDER	Bent	27.00 FS	*21.60 FS
12	1	*FENDER BRACE	Not Necessary	103.00 FS	*- FS
13	1	*WHEEL HOUSING LINER-LH	Deformed	215.00 FS	*171.60 FS
14	1	*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	78.00 FS	*- FS
15	1	*WHEEL SPOILER-LH	Deformed	63.00 FS	*50.16 FS
16	1	*SPOILER-LH	Not Necessary	30.00 FS	*- FS
17	1	*STONE CHIP GUARD-SATIN BLACK	Necessary	44.00 FS	*34.56 FS
18	1	*COVER-LH	Necessary	27.00 FS	*21.04 FS
19	1	*COVER-LH	Necessary	20.00 FS	*15.36 FS
20	1	*LED HEADLIGHT-LH	Not Necessary	6,973.00 FS	*- FS
21	1	*ALUMINIUM RIM	Cut	563.00 FS	*450.00 FS
22	1	*SUNDRIES	Necessary	300.00 FS	*13.92 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	11,587.00	2,882.32
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER	New	1,500.00	1,100.00
4	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,432.00	2,932.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >