Menimen Wilson Irene T	an ASSIGNMENT TOR	31082018
on A Section	OD RESTEVATING TANGES	
144 Impact Valuate 254	SJZ 8398U	GBD 6332 H
JIM I KUKY BUIKIT	N-51 Automotive	6842 6051
1 dia 1 28 88 0 4 4	16 MKC	(12)
Malic of Vels Office's Record		DOX 13/0/2017
THE THE 16/10/17	10-50am Melady	HOD februaria
tens Tien: Action/potru	STEU-X"	Do Not Finalize
	Part: 23-100019	
AFTOR YEAR	11 24-10-2017	month
	Treat Tan thru Melman.	/ // / /

RECEIVED & 8 SEP 2010

"eco love is

Report Format :

Lump Sum / I.B.I: (5

PRS.

1.1

180

Catherine Chong (LKK Auto)

From:

Irene Tan <irene_tan@sg.msig-asia.com>

Sent:

Friday, 31 August, 2018 6:24 PM

To:

Veron Chen (LKKAuto); Shiau Chan (LKKAuto); Nivitha (LKK Auto); Olivia Lau

(LKKAuto)

Subject:

Please prepare paper survey report on SJZ8398U; Our claim no.: 533109/IT

Good evening Veron,

We refer to your PRI report dated 12.3.18.

Please prepare and upload your paper survey report asap.

Best Regards

Irene Tan

Senior Executive, Claims Services (Motor)

Direct line +65 6594 2541 | Direct fax +65 6225 7402 | irene_tan@sg.msig-asia.com





Insurer Claims Team of the Year 2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg







A Member of MS&AD INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitt	nd Adj Assigned	Adt R	pt.	Adj Submitted	Ins Authled	Status	
Main	16 Oct 2017		16 Oct 2017 09:50 Edit Adj Rpt	S\$0.0 Edit Estin	00	S\$0.00 View Rpt	1119 743-111 E.S.	EEF TO S	r Survey Report
	Hain	\Box	Reference		Claim t	Petails	Docum	ents	Show All
CLAIM S	UBFOLDER DET	TAILS					fCre	ated by insu	rae1
nsured: Main Clain	nant:		O WAI KHONG,			eg. No.: 28471800			,
/ehicle Re	g. No.:	so	Z8398U		Date of	Loss:	[85	13/10/2017 15:00 - :59 [85 Months and 24 Days F Reg Date (Man Yr)]	
Daim Typ	e:	TF	/ 533109		Policy/Cover Note No.:		Cove	A28880446MKC (Comprehensive) Coverage: 10/02/2017 - 09/02/2018	
/ehicl≡ Re	g. No. (Insured)	GB	D6332H		Policy N	lo. (Claimant):	03/0	0.0000000000000000000000000000000000000	
			16. 10.000000000000000000000000000000000	111111222	Excess:		5\$70	00.00	
epairer:		Tel	51 Automotive Pte 68420051	Ltd (HQ) BU	K 2 KAKI	BUKIT, #01-17/18	KAKI BUKIT AU	TOHUB, 41792	I Kaki Bukit -
fandling I	nsurer:	MS 655	IG Insurance (Sin 4 2541)	gapore) Pte.	Ltd. (H	Q) - Tel: +65 6827	7888 [Handle	ed by Irene Ta	n Gek Ing -
Adjuster:		LK! Rp	t due 04/09/201	Pte Ltd (HQ 8]	() - Tel:	5256-3561 [Han	idled by Teo Che	ng Hing Wils	on] [Final
	TED MAIL REC	20070					View A	# I Comp	se Case Mail
MSIG_S	G (31/08/2018)	Report Send	Back Alerts - SJZI	8398U (TP)					
ALL ASSO	OCIATED TASK	s			- 0	View All Search	Tasks Cr	eate New Task	Complete
Due Dat to results.		Type Ta	sk Group Subje	ect Handle	er s	ssigned By	Completed On	Created	On Done?

VISION LAW LLC

3 0 AUG 2018

Advocates & Solicitors - Notary Public - Commissioner for Ouths Agents for Trade Marks

(Incorporated with limited liability) Unique Entity Number: 200721148H

HEAD OFFICE (65) 65342811 (Hunting) TEL (65) 65356802 (General) FAX

E-MAIL: annatan@visionlawlic.com

BRANCH

TEL (65) 63580703 TEL (65) 65330668

BRANCH

foru,

D. Upload

D. WILL A Z

TEL (65) 65342811 (Hunling) : (65) 65330889 TEL

WONG KENG LEONG RAYNEY ALTEREY WONG SU-HSIEN PAUL YAP TALSAN ANJALLI DIO MUNIANDY SEGA PARAM ANG KIM NOLDIANE BAVENDRA KRISINASAMY TAY HAD BAN JANICE HAN HA LIN TAN YINGXIAN SELWYN

FRIC NO CRING BOOK

 Head Office: 133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413 Branch: 490 Toa Payon Lorong 6 #03-11 HDB Hub Singapore 310490 Branch: 133 New Bridge Road #10-03 Chinatown Point Singapore 059413

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to HEAD OFFICE for this

Our Ref Your Ref

: AKN-atv-Ins-N63-107599-18 : GBD 6332 H 533109

Date:

28 August 2018

WITHOUT PREJUDICE

BY HAND

MSIG INSURANCE (SINGAPORE) PTE LTD 4 Shenton Way

#21-01 SGX Centre 2 Singapore 068807

Attn: Motor Claims Department

CERTIFICATE OF POSTING

[For your information only]

WENG LEE ENGINEERING WORKS

9 Pandan Loop #01-136 Singapore 128227

Dear Sir.

CLAIMANT LOO WAI KHONG ACCIDENT INVOLVING SJZ 8398 U & GBD 6332 H ON 13-OCT-2017 ALONG GEYLANG ROAD TOWARDS KALLANG ROAD AT ABOUT 1515HOURS

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 13-OCT-2017 ALONG GEYLANG ROAD TOWARDS KALLANG ROAD AT ABOUT 1515HOURS involving our client's vehicle registration number SJZ 8398 U and vehicle registration number GBD 6332 H driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

01.	Cost of Repair		\$14,124.00
02.	Rental fees		\$ 1,920.00
03.	Survey report fees		\$ 991.00
04.	Towing fees		\$ 360.00
05.	GIA & LTA search / report fees		\$ 41.84
06.	Cost Contribution (at this stage)		\$ 1,605.00
07.	Disbursements (at this stage)		\$ 50,00
		TOTAL	\$19,091.84

... /2 to be continued next page

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly probabiled. If you have received this transmission in error plante contact as immediately by telephone so that we can arrange for its return.

VISION LAW LLC

Advocates & Solicitors Page 2

Our Ref

: AKN-atv-Ins-N63-107599-18

Your Ref

: GBD 6332 H

Date:

28 August 2018

MSIG INSURANCE (SINGAPORE) PTE LTD

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

Attn: Motor Claims Department

WENG LEE ENGINEERING WORKS

9 Pandan Loop #01-136 Singapore 128227

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA report lodged by driver of SJZ 8398 U;
- (b) LTANet Search;
- (c) Certificate of Insurance;
- (d) Registration Card;
- (e) Towing receipt;
- (f) Rental agreement, rental invoice & rental receipt;
- (g) Final Repair Bill;
- (h) Surveyor's report & invoice; and
- 116 coloured photographs depicting the damages to motor vehicle SJZ 8398 U.

(P.S:- Original photographs will be sent to insurance co. only)

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

(HEAD OFFICE)

Enc.

cc: client: Loo Wai Khong

As per your instruction we have submitted your claim as set out above to the third party insurance company. Please do notify us if there is any discrepancy, if any, particularly, the number of days claimed for rental charges and/or loss of use as soon as possible. Thank you.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other discommunication is strictly prohibined. If you have received this transmission in error please contact as immediately by telephone so that we can arrange for its potator.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	THE STATE OF THE S
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	53001
Vehicle No.:	SJZ8398U
Vehicle to be Exported:	No.
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	B.M.W.
Vehicle Model:	730LI AT ABS D/AB 2WD 4DR NAV HID SR
Primary Colour:	Beige
Manufacturing Year:	2010
Engine No.:	06327353N52B30AF
Chassis No.:	WBAKB22040CN74415
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$67,618.00
Original Registration Date:	19 Aug 2010
First Registration Date:	19 Aug 2010
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$67,618.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Aug 2020
PARF Rebate Amount: Intended COE Rebate Details	\$37,189.00
COE Expiry Date:	18 Aug 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$42,810.00
COE Rebate Amount:	\$8,366.00
Total Rebate Amount:	\$45,555.00

The information contained herein is correct as at 04 Sep 2018

OK



Kaki Bukit AutoHub 2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail: sales@n51.com.sg Company Reg. No.: 200616038C GST Registration No.: 200616038C

LOO WAI KHONG 29 INGGU ROAD SINGAPORE 757193

Contact: 97604813

TAX INVOICE

Date: 06/08/2018

Date in: 13/10/2017

Vehicle Num.: SJZ8398U

Make/Model: B.M.W. 730LI AT ABS D/AB 2WD 4DR NAV HID SR-2010

Chassis/Eng#: WBAKB22040CN74415/06327353N52B30AF

Accident Date: 13/10/2017 Claim No: CLM14252

Reference: OCT-35/2017

Policy No.: GA258080/1 (18/08/2018)

Amount S\$

13,200.00

LUMPSUM REPAIR BILL AS PER SURVEYOR REPORT

REF: 0438-18-N51 DATED 23/07/2018
BY PAR AUTOMOTIVE CONSULTANCY

E. & O.E.

Sub SS:

13,200.00

Add GST (7%) S\$:

924.00

Total Amount S\$:

14,124.00

for N-51 AUTOMOTIVE PTE LTD









bizsAFE,

AUTUBAY TOWING *Adio Buint Avenue 6 *U1 55 Auth8ay @ Kaki Butut Singapore 417883 CASH SALE Tel 9015 8886 (Ah Boon) (N-51) No. _ 8398 u Sold to: Date: Item Quantity Description Unit Price Amount 120 E. & O. E. Sub Total : GST Tax : Issued by: __ \$ 120 Total AUTOBAY TOWING CASH SALE #01-55 Auro⊎≘y @ Kaki Bukit Singapore 417883 Tel: 9015 8686 (Ah Boon) (N-51) Sold to: Date: Item Quantity Description Unit Price Amount E. & O. E. Sub Total : GST Tax : Total 240 Issued by: __

WINGAR RENTAL

usiness Registration Number: 53092815M

lk 2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

el: 68420051 Fax : 67410510 emnil: sales@n51.com.sg

Invoice To:

JOO WAI KHONG
19 INGGU ROAD
SINGAPORE 757193

INVOICE

Invoice No.

13-1969

Date

25/10/2017

		Hirer's Car No.	VHA No.	Terms
		SJZ8398U	71467	CASH
No. of Day	Descripti	on	Per Day	Amount (S\$)
12	Car Rental from the period of 13/10/ Vehicle no. SLL9720R	2017 to 25/10/2017.	160.00	1,920.0
's	Singapore Dollars One Thousand Nii Only	ne Hundred and Twenty		

TWINCAR RENTAL

Authorised Signature



TWINCAR RENTAL

Kaki Bukit Autohub @ 2 Kaki Bukit Ave. 2 #01-18 Singapore 417921 Tel: 6744 0510 / 6842 0051

VHA No: 71467

ROC NO. 53092815M VEHICLE RENTAL AGREEMENT

72523018M

HIRER'S PARTICULAR	Vehicle No: SLL9720 72 Replace Veh No:	
Name: (as in I/C) _ LOO WAI KHONG	Mileage Out: Mileage Out:	
NRIC/PASSPORT No: S 75853001 Address (Res): 21 INCGU ROAD	Make & Model: "10 2010 Manual Group:	
SNGAPORE 757193	OUT: Date 13/10/17 Time: 17-45 FV2	5
Name & Address of Employer:	HIRE/PERIOD EXPIRY	
Traine & Places of Engloyer.	NON-WAIVER EXCESS : \$	
Occupation: Driving Exp:		
Driving Licence No. 375 85300 D/L Type: Local / International a	CHARGES	
Issue Date: 13/10/2014 Date of Birth: 04/02/1975		
Tel; (O) (R) HP/PG 9260403	100 100 100	00
ADDITIONAL DRIVER'S PARTICULARS	Weekly @ \$ per week	L
Name: (as in I/C)	Monthly ♥ \$ per month	
NRIC/PASSPORT No:	Hours @\$ per hour	
Address (Res):	Others @ \$	
A. A	CDW @\$ per day/month	
Driving Licence No: D/L Type: Local / International	PAI @ \$ per day/month	
Issue Date: Date of Birth:	Delivery Service	-
Occupation: Driving Exp:		
VEHICLE CHECKLIST	SUB-TOTAL \$	
<i>γ</i> η	PETROL LEVEL	
5 REAR	Out E 1/4 1/2 3/4 F .	
SCHATCHES SCHATCHES	In E 1/4 1/2 3/4 F	
SCHWAR	EXTENSION	
	Collection Service	
	Misc.	
E M A A	TOTAL CHARGE \$ (920)	M
A-ACCIDENTS A-ACCIDENTS A-ACCIDENTS A-ACCIDENTS A-ACCIDENTS	Rented out by:	
A-A-CCIO	m)\	
ACCESSORIES CHECK	Hirer's Signature	
Ashtray Cig Lighter S/Tyre		
STD Tools Jack Hub Caps		
	Addition Driver's Signature	
Radio / Cass CD Cartidges		

I have read and agree to the terms & condition on both sides of this agreement. If I have presented a change/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given TWINCARD RENTAL in connection with this Agreement is true.

* IMPORTANT

- 1. ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE TAHN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- 2. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- 3. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN, AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF COW AND/OR PAI WHERE APPLICABLE.
- 4. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY, IF THERE IS BOOLLY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- 5 VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY TWINCAR RENTAL.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO TWINCAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	The same	V 6 -
£106/01/2012	10:30M25					r.
001.00.11	10.2001				SIGNATURE	OF HIRER/DRIVER

Regn No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Report No: 0438-18-N51

23 July 2018

Loo Wai Khong 29 Inggu Road Singapore 757193

INVOICE No.

0438-18-N51

Vehicle No.

SJZ8398U

S/NO. SERVICES RENDERED Amount due I Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection). \$991.00 Total amount payable \$991.00

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy

Thomson Rd Pest Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Report No: 0438-18-N51

23 July 2018

ACCIDENT VEHICLE SURVEY REPORT

Loo Wai Khong 29 Inggu Road Singapore 757193

VEHICLE INFORMATION:

Vehicle Reg No .:

SJZ8398U

Odometer:

273594km

Make & Model:

BMW 730LI

Colour:

Beige

Regn No 52986974L

Chassis number:

WBAKB22040CN74415

Date of accident:

13/10/2017

Year of Regn.:

19/08/2010

Date inspected:

16/10/2017

Repairer at:

N-51 Automotive Pte Ltd

te Ltd Date inspected (After Repair):

25/10/2017

2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub

Singapore 417921

STATIC CHECKS, where applicable;

Steering:

scrviceable

Footbrake:

serviceable

Handbrake:

serviceable

Paintwork:

Good

General condition:

Good

TIRE CONDITION:

LH / Make

RH / Make

Size

Front:

4mm/Continental

4mm/Continental

245/50R18

Rear:

4mm/Continental

4mm/Continental

245/50R18

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assesment

PARTS

TAKIS		121		
Description of part	Qty	Condition	Repairer's	
FRONT AIR DUCT	1	reuse	301.45	0.00 NN X
FRONT BONNET	1	repair	2,784.40	
FRONT BONNET 'LOGO' EMBLEM	1	reuse	66.15	
FRONT BONNET MECHANISM LOCK L/R	2	reuse	445.20	5NN 00.0
FRONT BONNET MECHANISM LOCK UPPER COVER L/R	2	reuse	193.30	The state of the s
FRONT BONNET RUBBER GUIDE STOPPER L/R	2	reuse	12.30	
FRONT BUMPER	1	squashed	1,438.15	
FRONT BUMPER AIR DUCT L/R	2	warped	100.50	
FRONT BUMPER CHROME MOULDING L/R	21	deformed -\}		12 000
FRONT BUMPER FOGLAMP L/R	1-2	fractured	- Amount	254-40 508.80 M/5 V
FRONT BUMPER INNER FRAME BRACKET L/R	2	bent	230.30	
FRONT BUMPER INNER SPONGE	1	deformed	67.75	67.75 GuT √
FRONT BUMPER LH WASHER COVER	1	distorted	45.55	
FRONT BUMPER LH WASHER PUMP	1	fractured V	174,90	174.90 SHE
FRONT BUMPER LOWER CENTER GRILLE	1	warped	67.30	67.30 CR
FRONT BUMPER LOWER COVER L/R	21	fractured L	123,40	G170123:40 CR/
FRONT BUMPER LOWER SIDE GRILLE L/R	21	warped LH	124,50	52.25 124.50-CKV
FRONT BUMPER LOWER WEATHERSTRIP	1	deformed	65.35	65.35 UTV
FRONT BUMPER PARKING SENSOR	25	shorted	1,155.50	120-101,155.50 CUT
FRONT BUMPER PARKING SENSOR 'O' RING	5	necessary	25.00	25.00 NE CV
FRONT BUMPER PARKING SENSOR HOLDER BRACKET	25	necessary	312.50	62-50 312.50 NE U
FRONT BUMPER PARKING SENSOR WIRE HARNESS	1	snapped	109.35	109.35 CuTV
FRONT BUMPER REINFORCEMENT	1	bent	775.45	775.45 RX
FRONT BUMPER REINFORCEMENT 'LOWER'	1	bent	167.40	167.40- RX
FRONT BUMPER REINFORCEMENT BRACKET L/R	2	bent	230.30	230.30 SVCX
FRONT BUMPER SIDE RETAINER L/R	2	necessary	25.50	25.50 NECV
FRONT BUMPER UPPER WEATHERSTRIP	1	deformed	77.35	77.35 OUT V
FRONT CROSS BRACE PANEL L/R	2	bent	35.90	35.90 BT √
FRONT GRILLE L/R	2	fractured	310,30	310.30 CR /
FRONT HEADLAMP BRACKET L/R	1-2	bent	250.70	135, 35250 70
FRONT HEADLAMP L/R	1-2	fractured	5,542,80 ²	98100
FRONT HORN (HIGH & LOW)	2	distortion	169.30	169.30 SVC X
FRONT LH FENDER	1	buckled	1,171.85	1,171.85
FRONT LH FENDER INNER SHIELD	1	reuse	135.35	0.00 14114
FRONT NUMBER PLATE GARNISH BRACKET	L	bent	57.35	57.35 BT V
	Subtotal	before discount	S\$ 17,388,70	S\$ 13,450.55 7675-05
Percentage discount 0% and 5%			S\$ 0.00	S\$ 672.53 383.75
		Sub-total 1	S\$ 17,388,70	S\$ 12,778.02 7291-29

FRONT BONNET INSULATOR MAT CLIPS - SET	1	necessary	100.00	100.00 SYCX
FRONT BUMPER AIR DUCT CLIPS L/R - SET	2	necessary	60.00	
FRONT BUMPER CLIPS - SET	1	necessary	50.00	
FRONT BUMPER LOWER COVER CLIPS L/R - SET	2	necessary	60.00	4.0
FRONT LH FENDER INNER SHIELD CLIPS - SET	1	necessary	50.00	94.0
FRONT NUMBER PLATE	1	bent	25.00	The state of the s
FRONT NUMBER PLATE HOLDER	1	abraded	50,00	25 50,00 BT V
	Subtotal	before discount	S\$ 395.00	S\$ 395.00-295.00
		Sub-total 2	\$\$ 395,00	S\$ 395.00 295 00
		Parts-total	SS 17,783.70	SS 13,173.02 7586-29
LABOUR				
To reset system after repair works			500.00	400,00 NJ A
To remove, reinstall electrical wiring harness, check lighting focussing and rewire for parking sensor.	g. resetting h	cadlamp		
			200.00	60,00000
To re-spray painting on the change bodyparts, repair portion, the accident.			1,300.00	35 a. 00 880.00
To provide labour, workmanship to change the above damage construct and re-align body structure, body alignments and da	ed bodyparts	repair, re-		600 X
accident.	amaged cons	istent to the	1,500.00	S 0 0 00.000.1-
To apply anti-rust chemical on repaired and replaced panel.			120.00	60.00 40 2
		Labour Total	SS 3,620.00	SS 2,400.00 1670-00
	Parts &	Labour Total	SS 21,403.70	SS 15,573.02 9256 29

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 13,200.00 and the recommended number of working days for the repairs is within 12 day(s).

B J Loi (1 Eng., MIMI, AJRTE)

Automotive Appraiser

1/5 7400/2 Repair days 7

TGUM

4/9/18

Land Transport

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

13 Oct 2017 / 17:57:53

Receipt Date/Time: 13 Oct 2017 / 17:57:53

Tax Invoice/Receipt

Receipt No.: ITNET-00000-171013-001644

Previous Receipt No. :

Field	ous Receipt No. :				
S/N			Amount	GST	Amount
	Business Transaction Reference		Before	Amount	After GST
	No.		GST (S\$)	(S\$)	(S\$)
	It of Insurance Enquiry - GBD6332H				
	13 Oct 2017/15:15:00				
	ance Co: MSIG INSURANCE (SINGA	PORE) PTE LTD			
1	Insurance Enquiry - GBD6332H				
	Enquiry Fee		5.00	0.35	5.35
	20171013175656739903				
		Sub-Total	5,00	0.35	5.35
		Total Before Rounding	5.00	0.35	5.35
		Rounding Difference			0.00
		Total Amount Payable			5.35
		Paid By			
		200000000000000002392	Credit Card:		5.35
		nnnnnnnnnnnneude	Visa/MasterCard	1	5.55
		Total			5.35
		Cash Change			0.00
		Tendered Amount			5.35
		Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

8/26/2018 Vehicle Hub

Enquire Vehicle & Owner Information (Vehicle No. GBD6332H As At 13 Oct 2017 / 15:15:00)

Search Reason:

Insurance claim in relation to traffic accident

Law Firm Case No.:

Now Rome Towns & Chief In-

Surrein Exmention of

N63-107599-18

Owner ID Type:

Business

Owner ID:

28471800M

Owner Name:

WENG LEE ENGINEERING WORKS

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 9

Registered Street Name: PANDAN LOOP

Registered Unit No.:

#01-136

Registered Building Name: -

Registered Postal Code: 128227

terror of the Contact

Vehicle No.:

GBD6332H

Make Description/Model: NISSAN / CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD



Ng Ching Boon Eric has successfully logged out. Your last login date and time was 26 Aug 2018, 17:42:19. To return to ONE.MOTORING, please click here For security reasons, please CLEAR YOUR CACHE after each session.

Session Transaction History

5/No.I <u>1</u> 1	Asset Type Vehicle	Asset ID GBD6332H	Asset Owner ID	Transaction Type 18.19 Enquire Veh Owner Info (Others) by Law Firm	Transaction Amount(SS) 7,49	Log Date/Time 26 Aug 2018 / 17:42:41
----------------------	-----------------------	----------------------	----------------	--	-----------------------------	--

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Report No: 0438-18-N51

23 July 2018

ACCIDENT VEHICLE SURVEY REPORT

Loo Wai Khong 29 Inggu Road Singapore 757193

VEHICLE INFORMATION:

Vehicle Reg No .:

SJZ8398U

Odometer:

273594km

Make & Model:

BMW 730LI

Colour:

Beige

Regn. No: 52986974L

Chassis number:

WBAKB22040CN74415

Year of Regn.:

Date of accident:

13/10/2017

19/08/2010

Date inspected:

16/10/2017

Repairer at:

N-51 Automotive Pte Ltd

Date inspected (After Repair):

25/10/2017

2 Kaki Bukit Ave 2 #01-18

Kaki Bukit Auto Hub Singapore 417921

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number

EMail Address

- 1, Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the srchiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	14/10/2017 11:12
Date Of Accident	13/10/2017 15:15
Exact Location Of Accident	GEYLANG RD TO KALLANG ROAD B4 TURNING INTO LOR 29
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJZ8398U
Insured/Policyholder	
Name Of Registered Owner	LOO WAI KHONG
NRIC No	S7585300I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97604813
Alternative Phone No	OFFICE-97604813
Vehicle Particulars	
Manufacturer	BMW
Model	740LI
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA258080
Cover Note Number	
Driver	
Name of Driver	LOO WAI KHONG
NRIC No	\$75853001
Date Of Birth	04/02/1975
Occupation	INDOOR
Date Of Driving Pass	13/10/2014
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97604813
Fax Number	

OFFICE-97604813

NOEMAIL

Address

29 INGGU ROAD

Postcode

757193

OWNER

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBD6332H

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver-
- information provided must be as <u>trushful</u> and accurate as <u>possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
 the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)


Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (auch as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Oriver's Signature (if driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

NSI AUTOMOTIVE PTE CTD

Accident Sketch Plan Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

r	W man	mo	UINLA	OP12	Fα	on Tri	a care	r Ph	HANK	LOT .	, 6	Crowl
												SUPPENCY
A	WHICH	꾠	THE	180	FROM	THE -	F 17-12.	31912	CHAME	04 0	2	VEHICUE,
Qui	P CUT	no	INTO	ma	LANG	L AND	HIT	0.410	THE	LEFT	6317	NO PORTON
OF-	my	·	erice	LE.	\$4111.E	I am	163	THE	RIGHT	0F W	ins.	As I
We:	101	TMS	TO	TW	an an	APPAR PERM	LOR	1.7	5,630	man R	ono.	
												(ABO SHAP
												, GOING
STR	ALLHI	. 0	erone	MOH	WHY 3	+ TWAN	into	Line	124 6	entrack	- Car	0.
W TH	in were	we (AUP 63	(1456	M FUNDIO	owns pur	district.	10 IT	was to	D GWOL	son.	ne so resort.
VI	171001	LA	-	57£	trus	u						
Us	471666		-	CION	6332	14						
					8							
							_					
)					
	77						1					
							/					
		-			_							
-		_	_	_	_		1		_			

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Oriver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Accident Sketch Plan Pg. 1





AXA Impurmore Pile Ltd. 2 1800 880 4888 (Within Singapore) (65) 6880 4888 (International) (65) 6880 4740

E customer.care@exa.com.ag www.asa.com.ag

Certificate of Insurance

account number 04923

Adotor Vehicles [Third-Party Risks and Compensations Act. (Chapter 199) - Motor Vehicles (Third-Party Risks and Compensation) Risks. 1960 - Rised Transport Act, 1967 (Milloysia) -Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policybaider name

Cover

NCD applicable Vehicle registration number Period of Incarance

Finance loan company

LOO WAI KHONG Comprehensive

50% BIZESSEU

from 19/09/2017 to 18/08/2018 (both dates inclusive) BNW FINANCIAL SERVICES SINGAPORE PTE LTD

Dertificate number GA258080 / 1 Chasois number WBAKB22040CN74415 Engine number 06327353N52830AF

Persons or classes of persons entitled to drive*

(b) Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the Scensing or other laws or regulations to drive the Motor Vehicle or has been acpermitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover-use for hire or neward, racing, pace-enaking, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or hire for the connection of the with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on. a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

 Limitations rendered inoperative by Section is of the Motor Vehicles (Thirs-Pairly Risks and Compensation) Act, (Chapter 189) and Section 35 of the Road Transport Act, 1997 (Malaysia), are not to be included under these headings.

EXCESS.

Basic Own Damage Excess

Windscreen Excess.

5GD 800,00 SGD 100,00

An Additional Excess is applicable as follows:

- 1. \$\$500 for unnamed Authorised Driver
- 2, 5\$500 for declared Young and Inexperienced Driver
- 3. \$\$5,000 for undeclared Young and inexperienced Drivers. This additional oxcess is reduced to \$\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

NII

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Insurance has eventure that on the sale of a mater whicke they must summeder the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has even to the destroyed a Statisticy Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Reaks and Componation Act (Cap. 156).

The Premium Warrang Clause requires the premium to be point in Yull within a specific period failing which there would be no liability under the policy, renewal certificate, and orsement etc.

1 of 3

Accident Sketch Plan Pg. 1










LETTER OF UNDERTAKING

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence of discovery of damage.	nim is handle by my/our preferred workshop,		mine.
My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltc to claim under my/our Policy or against the Third Party and if the claim to M/s AXA Insurance Singapore Pte Ltd with all relevant fi 14(fourteen) days of occurrence of discovery of damage.	My/Our Third Party claim is handle by my/our preferred workshop,	Signed and Acknowledge by:	



Accident Photo













Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Submitte	ed Ins Auth'ed	Status		
Main	16 Oct 2017		16 Oct 2017 09:50 Edit Adj Rpt	S\$7,100 Edit Esti	35 DEC	\$\$7,100.00 View Rpt		Report Cancel	for Survey	
	Main	R	eference	C	aim Deta	ils	Documen	ts	Show All	
CLAIM SU	BFOLDER DE	TAILS				[Creat	ted by insurer]			
Insured:	WENG LE	E ENGINEERING	WORKS, Co. Reg	No.: 28471	MOOB					
Main Claimant:	LOO WAI	KHONG, ID: 57	75853001							
Vehicle Reg No.:	SJZ839	ви			Date of L		13/10/2017 15:00 - :59 [85 Months and 24 Days From LTA Reg Date (Man Yr			
Claim Type	TP / 533	109			Policy/Co Note No.:		AZ8880446MKC (Comprehensive) Coverage: 10/02/2017 - 09/02/2018			
Vehicle Reg No. (Insured):	GBD6332	н			Policy No. (Claimant					
Americanies					Excess:	5\$700.	.00		* la 400	
Repairer:	N-51 Aut	omotive Pte Ltd	(HQ) BLK 2 KAKT B	UKIT, #01-1	7/18 KAK	I BUKIT AUT	OHUB, 417921 Kaki	Bukit - Tel: 68	420051	
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (HQ)	- Tel: +65	6827 7888	3 [Handled	by Irene Tan Gek	Ing - 6594 25	41)	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	[Handled	by Lim Teov	w Guan] [Final	Rpt due 04/	09/2018]	
ASSOCIA	TED MAIL RE	CEIVED					V	iew All Cor	npose Case Mail	
 MSIG_S 	G (31/08/2018); Report Send I	Back Alerts - SJZ8	398U (TP)						
ALL ASSO	DCIATED TAS	sks⊟				View All	Search Tasks	Create New Ta	sk Complete	
Due Dat	77.1	Type Task	Group Subjec	t Handi	er As	signed By	Completed On	Create	i On Done?	

Claim Documents

*SJZ8398U (533109)

[GBD6332H]

TP

LOO WAI KHONG
Oct 13 2017 3:00PM

[WENG LEE ENGINEERING WORKS]
N-51 Automotive Pte Ltd

As:	sessment Reports		1 per p	age: 🔻	~
Νo	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/10/17 10:58	Accident Statement From:SC - Reg. No. GBD6332H, Claimant: WENG LEE ENGINEERING WORKS	0	Load HTM	
Pho	otos/Images		3 per p	age 🔻	V
No:	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Anna Jackson
Į.	06/11/17 18:43	Odometer Reading	0	Load JPG	~
2	06/11/17 18:43	General View	0	Load JPG	V
3	06/11/17 18:43	Chassis Number	0	Load JPG	V
4	06/11/17 18:43	General View	0	Load JPG	V
5	06/11/17 18:43	General View	0	Load JPG	V
6	06/11/17 18:43	General View	0	Load JPG	1
7	06/11/17 18:43	General View	0	Load JPG	3
8	06/11/17 18:43	General View	0	Load JPG	4
9	06/11/17 18:43	General View	0	Load JPG	1
10	06/11/17 18:43	General View	0	Load JPG	7
11	06/11/17 18:43	General View	0	Load JPG	50
12	06/11/17 18:43	General View	0	Load JPG	1
13	06/11/17 18:43	General View	0	Load 3PG	V
14	06/11/17 18:43	General View	0	Load JPG	3
15	06/11/17 18:43	General View	0	Load JPG	V
16	06/11/17 18:43	General View	0	Load JPG	V
17	06/11/17 18:43	General View	0	Load JPG	7
18	06/11/17 18:43	General View	0	Load JPG	V
19	06/11/17 18:43	General View	0	Load JPG	V
20	06/11/17 18:43	General View	0	Load JPG	V
21	06/11/17 18:43	General View	0	Load JPG	V
22	06/11/17 18:43	General View	0	Load JPG	V
23	06/11/17 18:43	General View	0	Load JPG	1
24	06/11/17 18:43	General View	0	Load JPG	V
25	06/11/17 18:43	General View	0	Load 3PG	~
26	06/11/17 18:43	General View	0	Load JPG	V
27	06/11/17 18:43	General View	0	Load JPG	V
28	06/11/17 18:43	General View	0	Load JPG	V
29	06/11/17 18:43	General View	0	Load JPG	3
30	06/11/17 18:43	General View	0	Load JPG	1
31	06/11/17 18:43	General View	0	Load JPG	V
32	06/11/17 18:43	General View	0	Load 3PG	V
33	06/11/17 19:43	General View	0	Load JPG	N

Ass	essment Reports		1 per p	oge 🔻	~
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	-
34	06/11/17 18:43	General View	0	Load JPG	4
35	06/11/17 18:43	General View	0	Load JPG	1
16	06/11/17 18:43	General View	0	Load JPG	¥
17	06/11/17 18:43	General View	0	Load JPG	~
18	06/11/17 18:43	General View	0	Load JPG	V
39	06/11/17 18:43	General View	0	Load JPG	1
40	06/11/17 18:43	General View	0	Load JPG	4
41	06/11/17 18:43	General View	0	Load JPG	V
12	06/11/17 18:43	General View	0	Load JPG	V
43	06/11/17 18:43	General View	0	Load JPG	V
14	06/11/17 18:43	General View	0	Load JPG	V
45	06/11/17 18:43	General View	0	Load JPG	V
16	06/11/17 18:43	General View	0	Load JPG	V
17	06/11/17 18:43	General View	0	Load JPG	12
48	06/11/17 18:43	General View	0	Load JPG	V
Co			0	Load JPG	V
19	06/11/17 18:43	General View	0	Load JPG	17
50	06/11/17 18:43	General View	0	Load JPG	V
51	06/11/17 18:43	General View		The second section is a second second	2
52	06/11/17 15:43	General View	0	Load JPG	_
53	06/11/17 18:43	General View	0	Load JPG	¥
54	06/11/17 18:43	General View	0	Load JPG	150
55	06/11/17 18:43	General View	0	Load JPG	V
56	06/11/17 18:43	General View	0	Load JPG	1
57	06/11/17 18:43	General View	0	Load JPG	×
58	06/11/17 18:43	General View	0	Load JPG	V
59	06/11/17 18:43	General View	0	Load JPG	¥
50	06/11/17 18:43	General View	0	Load JPG	5
51	06/11/17 18:43	General View	0	Load JPG	-
52	06/11/17 18:43	General View	0	Load IPG	5
53	06/11/17 18:43	General View	0	Load 3PG	5
54:	06/11/17 18:43	General View	0	Load JPG	5
55	06/11/17 18:43	General View	0	Load JPG	V
56	06/11/17 18:43	General View	0	Load JPG	E
57	06/11/17 18:43	General View	0	Load JPG	5
58	06/11/17 18:43	General View	0	Load JPG	1
59	06/11/17 18:43	General View	0	Load JPG	5
70	06/11/17 18:43	General View	0	Load 3PG	1
71	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	5
		Photographs of Damaged Parts	0	Load JPG	5
72	06/11/17 18:44	Mary Mary Control of the Control of	0	Load IPG	1
73	06/11/17 18:44	Photographs of Damaged Parts	0	Load 3PG	E
74	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	5
75	06/11/17 18:44	Photographs of Damaged Parts			-
76	06/11/17 18:44	Photographs of Damaged Parts	0	Load 3PG	5
77.	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	5
78	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	5
79	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	5
80	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	5
81	06/11/17 18:44	Photographs of Damaged Parts	0	Load 3PG	5
82	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	6
83	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	6

Asse	essment Reports		1 per j	page. V	W
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Prin
84	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	V
85	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	50
86	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	V
87	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	V
88	06/11/17 18:44	Photographs of Damaged Parts	0	Load 3PG	V
89	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	V
90	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	50
91	06/11/17 18:44	Photographs of Damaged Parts	0	Load 3PG	V
92	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	121
	THE CONTRACTOR OF THE PARTY OF		0	Load JPG	V
93	06/11/17 18:44	Photographs of Damaged Parts	0		∀
94	06/11/17 18:44	Photographs of Damaged Parts		Load JPG	
95	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	V
96	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	V
97	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	56
98	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	V
99	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	4
100	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	150
101	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	~
102	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	V
103	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	3
104	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	1
105	06/11/17 18:44	Photographs of Damaged Parts	0	Load IPG	(V)
106	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	V
107	06/11/17 18:44	Photographs of Damaged Parts	0	Lond JPG	[2]
108	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	V
109	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	V
110	06/11/17 18:44	Photographs of Damaged Parts	0	Load JPG	V
111	06/11/17 18:44	Photo After Spray	0	Load JPG	3
111 7 14 7			0	Load 3PG	V
112	06/11/17 18:44	Photo After Spray	0		_
113	06/11/17 18:44	Photo After Spray		Load JPG	V
114	06/11/17 18:44	Photo After Spray	0	Load JPG	1
115	06/11/17 18:44	Photo After Spray	0	Load JPG	V
Doc	umentation		1 per	page V	7
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per	Thumbnail	_
1	16/10/17 09:45	PRI & GIA REPORT	0	Load PDF	2.4411
2	20/10/17 10:58	TP GIA Rep - 5JZ8398U From:SC - Reg. No. GBD6332H, Claimant: WENG LEE ENGINEERING WORKS	0	Load PDF	
3	31/08/18 11:49	LOD with supporting documents - 5JZ8398U	0	Load PDF	
4	31/08/18 11:49	TPD SJZ8398U - COLOUR PHOTO A	O	Load PDF	
5	31/08/18 11:49	TPD SJZ8398U - COLOUR PHOTO B	Ō	Load PDF	
6	31/08/18 11:49	TPD S3Z8398U - COLOUR PHOTO C	0	Load PDF	
7	31/08/18 18:25	instruction to LKK to prepare paper survey report	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	-	Thumbnail	Prin
1	05/09/18 14:54	COLOUR PHOTO	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Merimen e-Claims Page 4 of 4

our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
how Remarks To: Handling Insurer ote: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg. No; 199607 198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG17019802/BVBE2-1

Date:

05/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A28880446MKC

Claimant Vehicle SJZ8398U

Insured Vehicle No:

GBD6332H

No: Date of Loss:

13/10/2017

Nature of Claim:

TP

Claim No: 533109

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJZ8398U

Make & Model:

BMW 730LI, 2.0 LED NAV HUD SR (A)

Engine No:

06327353N52B30AF

Reg. Date: Colour

19/08/2010 (Man. Year: 2010)

Chassis No: Odometer:

WBAKB22040CN74415 273594 km

Engine Capacity:

2996 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

245/50 R18

Rear Tyre Size:

245/50 R18

Front Left Side: Front Right Side: Continental 3 mm Continental 3 mm Rear Left Side: Rear Right Side: Continental 2 mm Continental 2 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,783.70	7,309.30	10,474.40	58.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,620.00	1,580.00	2,040.00	56.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,403.70	8,889.30	12,514.40	58.47
Approved Total (Overridden) (S\$)		7,100.00		
(S\$)	21,403.70	7,100.00	14,303.70	66.83
+ GST 7.00/7.00% (S\$)	1,498.26	497.00	1,001.26	66.83
Nett Amount (S\$)	22,901.96	7,597.00	15,304.96	66.83

INSPECTION

Date of Assignment:

16/10/2017

Date Inspected:

16/10/2017 Inspected At:

N-51 Automotive Pte Ltd (HQ)

BLK 2 KAKI BUKIT, #01-17/18 KAKI

BUKIT AUTOHUB Singapore 417921

Estimated Period of Repair:

7.0 days

Adjuster Report Page 2 of 5

Adjuster: Lim Teow Guan Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Sep 2018)

Parts: 143 BMW 730LI 2.0 LED NAV HUD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJZ8398U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

lo. Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT AIR DUCT	Not Necessary	301.45 F	*-FL
1		*FRONT BONNET	Repair	2,784.40 F	*-FL
1		*FRONT BONNET LOGO EMBLEM	Not Necessary	66.15 F	*- FI
2		*FRONT BONNET MECHANISM LOCK L/R	Not Necessary	445.20 F	*- FL
2		*FRONT BONNET MECHANISM LOCK UPPER COVER L/R	Not Necessary	193.30 F	*-Fl
2		*FRONT BONNET RUBBER GUIDE STOPPER L/R	Not Necessary	12.30 F	*- FI
1		*FRONT BUMPER	Cracked	1,438.15F	*1,438.15 FL
2		*FRONT BUMPER AIR DUCT L/R	Serviceable	100.50 F	*- FL
11		*FRONT BUMPER CHROME MOULDING L/R	N/S Cut	87.50 F	*43.75 FL
0 1		*FRONT BUMPER FOG LAMP L/R	N/S Missing	508.80 F	*254.40 FL
1 2		*FRONT BUMPER INNER FRAME BRACKET L/R	Serviceable	230.30 F	*-FL
2 1		*FRONT BUMPER INNER SPONGE	Cut	67.75F	*67.75 FL
3 1		*FRONT BUMPER LH WASHER COVER	Cut	45.55 F	*45.55 FL
4 1		*FRONT BUMPER LH WASHER PUMP	Fractured	174.90 F	*174.90 FL
5 1		*FRONT BUMPER LOWER CENTER GRILLE	Cracked	67.30 F	*67.30 FL
6 1		*FRONT BUMPER LOWER COVER L/R	N/S Cracked	123.40 F	*61.70 FL
7 1		*FRONT BUMPER LOWER SIDE GRILLE L/R	N/S Cracked	124.50 F	*62.25 FL
B 1		*FRONT BUMPER LOWER WEATHERSTRIP	Cut	65.35 F	*65.35 FL
9 1		*FRONT BUMPER PARKING SENSOR	Cut-2PCS ONLY	1,155.50 F	*420.00 FL
0 5		*FRONT BUMPER PARKING SENSOR O RING	Necessary	25.00 F	*25.00 FL
1 1		*FRONT BUMPER PARKING SENSOR HOLDER BRACKET (5PCS)	Necessary-2PCS ONLY	312.50 F	*62.50 FL
2 1		*FRONT BUMPER PARKING SENSOR WIRE HARNESS	Cut	109.35 F	*109.35 FL
3 1		*FRONT BUMPER REINFORCEMENT	Repair	775.45 F	*-FL
4 1		*FRONT BUMPER REINFORCEMENT LOWER	Repair	167-40 F	*- FL
5 2		*FRONT BUMPER REINFORCEMENT BRACKET L/R	Serviceable	230.30 F	*-FL
6 2		*FRONT BUMPER SIDE RETAINER L/R	Necessary	25.50 F	*25.50 FL
7 1		*FRONT BUMPER UPPER WEATHERSTRIP	Cut	77.35 F	*77.35 FL
8 2		*FRONT CROSS BRACE PANEL L/R	Bent	35.90 F	*35.90 FL
9 2		*FRONT GRILLE L/R	Cracked	310.30 F	*310.30 FL
0 1		*FRONT HEADLAMP BRACKET L/R	N/S Bent	250.70 F	*125.35 FL
1 1		*FRONT HEADLAMP L/R	N/S Fractured	5,542.80 F	*2,771.40 FL
2 2		*FRONT HORN (HIGH & LOW)	Serviceable	169.30 F	*- FL
3 1		*FRONT LH FENDER	Buckled	1,171.85 F	*1,171.85 FL
4 1		*FRONT LH FENDER INNER SHIELD		135.35 F	*-FL
			the professional distribution of the second	property and a second	*57.35 FL
76 11		*F	RONT LH FENDER INNER SHIELD RONT NUMBER PLATE GARNISH BRACKET	RONT LH FENDER INNER SHIELD Not Necessary	RONT LH FENDER INNER SHIELD Not Necessary 135.35 F RONT NUMBER PLATE GARNISH BRACKET Bent 57.35 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET FRONT BONNET INSULATOR MAT CLIPS	Serviceable	100.00 FS	*-FS
37	2		*SET FRONT BUMPER AIR DUCT CLIPS L/R	Necessary	60.00 FS	*45.00 FS
38	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*40.00 FS
39	2		*SET FRONT BUMPER LOWER COVER CLIPS L/R	Necessary	60.00 FS	*45.00 FS
40	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*40.00 FS
41	1		*FRONT NUMBER PLATE	Bent	25.00 FS	*15.00 FS
42	1		*FRONT NUMBER PLATE HOLDER	Bent	50.00 FS	*25.00 FS
F=Fra	inchise	part S=5	SpcNett. L=ListflemDisc - List Item Discount on L	Sub Total (S\$) . items 0.00/5.00% (S\$)	The second second	7,682.95 373.65
				Total Parts (S\$)	17,783.70	7,309.30
			Report was unsubmitted during th	is print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	500.00	200.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSSING AN REWIRE FOR PARKING SENSOR	New ID	200.00	40.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,300.00	600.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AID DAMAGED CONSISTENT TO THE ACCIDENT	New	1,500.00	700.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	40.00
	Gross Labo	our Cost (S\$)	3,620.00	1,580.00
	Report was unsubmitted during	g this print-out.		

< END OF ESTIMATES >