

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7482

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0512/18

DATE : 27-AUG-2018

AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

S(068811)

TEL : 68804741

FAX : 68804838

ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : CAS TECHNOLOGY PTE LTD

ADDRESS : 10 UBI CRESCENT

#05-52 UBI TECHPARK

S(408564)

TELEPHONE NO : 93633191

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : A 28878165 MKC

VEHICLE NO : GBF6172S

MODEL CODE : NV200 DX 1.6 A

MODEL/YEAR : NV200

ENGINE NO : HR16074852D

CHASSIS NO : VM20100516

MILEAGE : 21769 KM

DATE IN : 27/08/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 27/08/2018

- 9045 0084 elmer@fermchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBF6172S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR BOTH RR FENDR & TRUNK FLOOR,RENEW RR END PANEL,RR BUMPER & BACK DOOR	2500.00	1250
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	2100.00	1000
3	ZZ/003	APPLY SEALANT TO TRUNK FLOOR AND END PANEL	120.00	80
4	ZZ/004	APPLY SEALANT TO BACK DOOR	120.00	80
5	ZZ/005	RENEW BOTH RR COMBINATION LAMP	48.00	/
6	ZZ/006	RENEW REVERSE SENSOR	55.00	/
7	ZZ/007	RENEW REAR WINDSCREEN GLASS	180.00	/
8	ZZ/008	RENEW REAR WINDSCREEN SOLAR FILM WITH ANTI GLARE	250.00	X
9	ZZ/009	SUPPLY LICENSE PLATE		
TOTAL LABOUR CHARGES			5373.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBF6172S

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 LH REAR COMBINATION LAMP	26555-JX53A	235.20	X	
2 RH REAR COMBINATION LAMP	26550-JX00A	235.20	CRA	
3 SUNDRIES	NPN			50.00 70
4 REAR LICENCE PLATE	RLP			60.00 SUR
5 SENSOR-REVERSE	SENSOR			250.00 DIS
6 STRIKER BACK DOOR	90570-5LA0A	31.70	X	
7 BACK DOOR LOCK	90500-5LA0A	261.00	?	
8 WEATHER STRIP BACK DOOR	90830-5LA0A	83.90	Cut	
9 BACK DOOR UPPER HINGE @ SGD \$ 51.60 EACH	90400-JX30A	103.20	?	
10 BACK DOOR LH STAY	90451-JX00A	184.60	?	
11 BACK DOOR RH STAY	90450-JX00A	184.60	?	
12 REAR W/SCREEN SEALANT	SEALANT - 4			80.00 SUR
13 BACK DOOR MOLDING	90810-JX30A	336.00	?	
14 GLASS-BACK DOOR	90300-JX00B	1240.00	EX	
15 DOOR BACK	K010M-JX0AB	1567.80	Sur	
16 PLATE-LUGGAGE REAR	84992-JX00A	63.50	?	
17 REAR END PANEL INNER	75614-JX00A	544.00	repair	
18 REAR END PANEL OUTER	75617-JX00A	108.80	PA	
19 ENERGY ABSORBER REAR BUMPER	85090-JX00A	84.00	?	
20 RH SIDE BRACKET REAR BUMPER	85228-JX00A	33.30	new	
21 LH SIDE BRACKET REAR BUMPER	85229-JX00A	33.30	X	
22 CLIP REAR BUMPER @ SGD \$ 1.20 EACH	01553-05933	7.20	new	
23 REAR BUMPER	85022-JX00A	437.30	DE	
SUB TOTAL		5774.60	0.00	440.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1154.92	0.00	0.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBF6172S

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
GRAND TOTAL			4619.68	0.00	440.00	
OVERALL TOTAL			5059.68			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBF6172S

TOTAL LABOUR CHARGES	5373.00
TOTAL SPARE PARTS CHARGES	5059.68
GRAND TOTAL	10432.68 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME : **RASUL - Hp 90010068**
SURVEYED DATE : **05/09/18 @ 1400hrs**
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00 **7 days**
LIABILITY : 0.00
REMARKS : **Resurvey by paint**

email: rasul@lkkauto.com

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: