

AUTOLUTION INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IG/EA/0512/18
DATE : 27-AUG-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

7 DAYS
SURVEYOR : RAZUL LKK AUTO

OWNER'S NAME : CAS TECHNOLOGY PTE LTD
ADDRESS : 10 UBI GRESCENT
#05-52 UBI TECHPARK
S(408564)
TELEPHONE NO : 93633191

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : A 26878165 MKC
VEHICLE NO : GBF6172S
MODEL CODE : NV200 DX 1.6 A
MODEL/YEAR : NV200
ENGINE NO : HR160748520=F01
CHASSIS NO : VM20100516
MILEAGE : 21769 KM
DATE IN : 27/08/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 27/08/2018

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBF61725

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR BOTH RR FENDR & TRUNK FLOOR,RENEW RR END PANEL,RR BUMPER & BACK DOOR	2500.00	1250.00 ✓
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	2100.00	1000.00 ✓
3	ZZ/003	APPLY SEALANT TO TRUNK FLOOR AND END PANEL	120.00	80.00 ✓
4	ZZ/004	APPLY SEALANT TO BACK DOOR	120.00	80.00 ✓
5	ZZ/005	RENEW BOTH RR COMBINATION LAMP	48.00	48.00 ✓
6	ZZ/006	RENEW REVERSE SENSOR	55.00	55.00 ✓
7	ZZ/007	RENEW REAR WINDSCREEN GLASS	180.00	180.00 ✓
8	ZZ/008	RENEW REAR WINDSCREEN SOLAR FILM WITH ANTI GLARE	250.00	.00
9	ZZ/009	SUPPLY LICENSE PLATE		
10	ZZ/10	SUPPLY BACK DOOR COMPANY STICKER	400.00	400.00
TOTAL LABOUR CHARGES			5773.00	3093.00
ADDITIONAL DISCOUNT(5.00%)				154.65
FINAL LABOUR CHARGES				2938.35

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBF61725

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	BACK DOOR UPPER HINGE @ SGD \$ 51.60 EACH	90400-JX30A	103.20		X
2	BUMPER B/DOOR	90878-JX00A	6.50	(Supplementary)	OK ✓
3	LH REAR COMBINATION LAMP	26555-JX53A	235.20		X
4	RH REAR COMBINATION LAMP	26550-JX00A	235.20		OK ✓
5	SUNDRIES	NPN			20.00 OK ✓
6	REAR LICENCE PLATE	RLP			60.00 OK ✓
7	SENSOR-REVERSE	SENSOR			250.00 OK ✓
8	STRIKER BACK DOOR	90570-5LA0A	31.70		X
9	BACK DOOR LOCK	90500-5LA0A	261.00		X
10	WEATHER STRIP BACK DOOR	90830-5LA0A	83.90		OK ✓
11	REAR END PANEL INNER	75614-JX00A	544.00		X
12	REAR END PANEL OUTER	75617-JX00A	108.80		OK ✓
13	ENERGY ABSORBER REAR BUMPER	85090-JX00A	84.00		X
14	RH SIDE BRACKET REAR BUMPER	85228-JX00A	33.30		OK ✓
15	LH SIDE BRACKET REAR BUMPER	85229-JX00A	33.30		X
16	CLIP REAR BUMPER @ SGD \$ 1.20 EACH	01553-05933	7.20		OK ✓
17	REAR BUMPER	85022-JX00A	437.30		OK ✓
18	BACK DOOR LH STAY	90451-JX00A	184.60		X
19	BACK DOOR RH STAY	90450-JX00A	184.60		X
20	REAR W/SCREEN SEALANT	SEALANT - 4			80.00 X
21	BACK DOOR MOLDING	90810-JX30A	336.00		X
22	GLASS-BACK DOOR	90300-JX00B	1240.00		X
23	DOOR BACK	K010M-JX00B	1567.80		OK ✓
24	PLATE-LUGGAGE REAR	84992-JX00A	63.50		X

AUTOLUTION INDUSTRIAL PTE. LTD

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBF61725

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
SUB TOTAL		2480.00	0.00	330.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		496.00	0.00	0.00
GRAND TOTAL		1984.00	0.00	330.00
ADDITIONAL DISCOUNT (NETT-5.00%, LIST-5.00%, S/NETT-.00%)		99.20	0.00	0.00
OVERALL TOTAL		2214.80		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO GBF61725

NETT ITEM 2480.00
LESS 20.00%) -496.00
NETT AMOUNT 1984.00
ADDITIONAL DISCOUNT(5.00%) -99.20
FINAL AMOUNT 1884.80

LIST ITEM 0.00
LESS 30.00%) 0.00
LIST AMOUNT 0.00

SPECIAL NETT ITEM 330.00
LESS .00%) 0.00
SPECIAL NETT AMOUNT 330.00

TOTAL LABOUR CHARGES 2938.35
TOTAL SPARE PARTS CHARGES 2214.80

TOTAL CHARGES 5153.15
ADD 7 % GST 360.72

GRAND TOTAL 5513.87
