

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

3-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6342 M

1 pc	Bonnet /	\$	979.00
1 pc	Bonnet lock X	\$	36.00
1 pc	Bonnet lifter X	\$	70.00
1 pc	Bonnet hinge o/s & n/s @ \$23.00 X	\$	46.00
1 pc	Bonnet weatherstrip X	\$	58.00
1 pc	Bonnet grille /	\$	385.00
1 pc	Support panel /	\$	645.00
1 pc	Front bumper /	\$	531.00
1 pc	Front bumper emblem /	\$	44.00
1 pc	Front bumper centre grille	\$	174.00
1 pc	Front bumper lower stiffer X	\$	134.00
1 pc	Front bumper tow hook cover /	\$	14.00
1 pc	Front bumper lip X	\$	52.00
1 pc	Front bumper inner sponge ?	\$	110.00
1 pc	Front bumper upper reinforcement ?	\$	40.00
1 pc	Front bumper reinforcement ?	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 ?	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 ?	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 ?	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 n/s X o/s ✓	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 X	\$	132.00
2 pcs	Front bumper o/s & n/s protector @ \$51.00 X	\$	102.00
1 pc	Air duct X	\$	210.00
1 pc	Boot lid X	\$	1,119.00
1 pc	Bootlid emblem X	\$	27.00
1 pc	Bootlid CRDi X	\$	29.00
1 pc	Boot lid rubber weatherstrip X	\$	96.00
1 pc	Boot lid lower garnish X	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 X	\$	132.00
1 pc	End panel X n/s	\$	250.00
1 pc	End panel inner garnish X	\$	74.00
1 pc	Rear o/s fender X n/s	\$	1,205.00
1 pc	Rear o/s fender inner shield X	\$	120.00
1 pc	Rear windscreen moulding X	\$	87.00
1 pc	o/s refletor /	\$	350.00
1 pc	o/s tail lamp /	\$	421.00
1 pc	Rear bumper /	\$	696.00
1 pc	Rear bumper lower cover /	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X	\$	58.00
1 pc	Rear bumper inner sponge ?	\$	114.00

3-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6342 M

1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00
		\$	12,395.00
	Less 10%	\$	1,239.50
		\$	11,155.50

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	End panel inner garnish clips	\$	30.00
1 set	Bootlid lower garnish clips	\$	60.00
1 set	Bootlid stickers	\$	100.00
1 set	Reverse sensor	\$	280.00
1 pc	Front no. plate with casing	\$	50.00
1 pc	Front bumper clips	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00	\$	6.00
1 pc	Rear o/s fender sticker	\$	60.00
1 set	Bootlid stickers	\$	100.00

LKK Auto Consultancy

Towing Fee

Sundry

To resurvey before and after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary work must be resurveyed and is subject to final approval from insurance company

Acknowledged by Rep:

Signature:

Date:

To check for wiring and to focus head lamps

To top up aircon gas

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To dismantle and refit rear windscreen

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the same etc

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, rear o/s fender, front bumper, bonnet,

To apply rustproofing on the repaired and replaced panels.

\$	50.00	✓
\$	50.00	20
\$	80.00	20
\$	120.00	50
\$	120.00	30
\$	180.00	50
\$	120.00	X
\$	1,600.00	1000
\$	1,400.00	900
\$	250.00	50
\$	15,919.50	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.