

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4
 #02-37 Premier @ Kaki Bukit
 Singapore 415875
 Tel : 94513429

ESTIMATE

WDD2120342B149942

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
 Attn: Motor Claims Department

Poh Kim

Date : 03.09.2018
 Vehicle No. : SKV 1902U
 Make/Model : M/Benz E200
 Chassis/Eng# :
 Accident Date : 01.09.2018

Parts

01) Boot lid <i>dent</i>	\$	3,500.00 2150.
02) Boot star logo	\$	120.00 ✓
03) E 200 emblem <i>2 new</i>	\$	98.00 ✓
04) 7 G-Tronic emblem	\$	158.00 ✓
05) Boot lid chrome <i>new</i>	\$	380.80 ✗
06) Boot lid lock <i>new</i>	\$	550.80 ✗
07) Boot lid lamp rh <i>cracked</i>	\$	450.80 ✓
08) Rear fender rh <i>Repair</i>	\$	2,500.00 ✗
09) Rear fender retainer rh	\$	120.00 ✗
10) Rear fender inner shield rh <i>2 new</i>	\$	180.00 ✗
11) Rear fender inner shield clips rh	\$	120.00 ✗
12) Rear bumper <i>Dislodged</i>	\$	2,850.00 1630.
13) Rear bumper bracket @\$150.00 x 2 <i>new</i>	\$	300.00 96.
14) Rear bumper reinforcement <i>Bent</i>	\$	880.90 762
15) Rear bumper reflector rh <i>new</i>	\$	3,500.00 ✗
16) Rear bumper clips <i>new</i>	\$	120.00 30
17) Rear bumper lower chrome <i>cut</i>	\$	650.00 294
18) Rear bumper sponge <i>new</i>	\$	280.50 ✗
19) Rear exhaust <i>new</i>	\$	2,650.00 ✗
20) Rear exhaust chorme <i>Bent</i>	\$	350.00 287
21) Rear Panel <i>Dent Repair</i>	\$	2,800.00 ✗
22) Rear panel garnish (black) <i>cracked</i>	\$	280.00 2
23) Tail lamp assy rh <i>cracked</i>	\$	750.80 688.
24) Tail lamp socket rh <i>new</i>	\$	280.50 ✗
25) Tail lamp lower panel rh <i>Repair</i>	\$	380.00 ✗
	\$	24,251.10
Less 10%	\$	(2,425.11)
	\$	21,825.99

7053.80

6348.42

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4
#02-37 Premier @ Kaki Bukit
Singapore 415875
Tel : 94513429

-1

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

Date : 03.09.2018
Vehicle No. : SKV 1902U
Make/Model : M/Benz E200
Chassis/Eng# :
Accident Date : 01.09.2018

S/Nett

26) Reverse sensor 6 pcs	<i>3 pieces damaged</i>	<i>750.</i>	\$	1,800.00	<i>750</i>
		<i>675</i>	\$	1,800.00	500

Labour charges

23) Towing charges(King Dolly)			\$	200.00	<i>120</i>
24) To check wiring			\$	200.00	<i>30</i>
25) To dismantle petrol tank			\$	100.00	<i>P.</i>
26) To dismantle exhaust		<i>1750.</i>	\$	200.00	<i>K.</i>
27) To knock out dents on effected areas and renew parts			\$	2,000.00	<i>800</i>
28) To putty & respray painting			\$	2,000.00	<i>800</i>
			\$	4,700.00	

Grand Total \$ 28,325.99


for JA AUTOCARE PTE LTD

Adrian Lim
P/P 03/09/18.

OT Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary: 866-70

total: 9640.12

CP/P.