



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SFM763S
Date of Accident : 01 September 2018

Mr Neo Chee Seng (Liang Zhicheng)

Date : 01 September 2018

Estimate To Repair SJV1376A - SUBARU FORESTER 2.0X AWD 4AT D/AIRBAG
Chassis No : JF1SH5KS59G020228

S/No	Quantity	Description	Amount
NETT ITEMS			
01	1 pc	tailgate lid <i>Buc</i>	\$ 1,392.00
02	1 pc	tailgate lid weatherstrip <i>deformed</i>	\$ 146.00
03	1 pc	tailgate lid lock <i>Dem</i>	\$ 220.00
04	1 pc	tailgate lid lock stricker <i>new</i>	\$ 22.00
05	1 pc	tailgate lid subaru badge <i>huc</i>	\$ 58.00
06	1 pc	tailgate lid forester badge <i>huc</i>	\$ 49.40
07	2 ps	tailgate lid side latch @ \$65.00 <i>NH</i>	\$ 130.00
08	1 pc	tailgate lid inner trim board ?	\$ 430.00
09	1 pc	tailgate lid outer garnish <i>NH</i>	\$ 560.00
10	1 pc	tailgate lid outer garnish emblem badge <i>NH</i>	\$ 58.00
11	1 pc	rear wiper motor <i>huc</i>	\$ 325.00
12	2 ps	rear licence plate lamps @ \$75.00 <i>NH</i>	\$ 150.00
13	1 pc	rear licence plate garnish <i>huc</i>	\$ 60.00
14	1 pc	rear windscreen glass weatherstrip <i>huc</i>	\$ 123.60
15	1 pc	rear end panel <i>Buc</i>	\$ 433.00
16	1 pc	rear end panel inner trim <i>SA</i>	\$ 78.40
17	1 pc	rear bumper <i>distorted</i>	\$ 720.00
18	2 ps	rear bumper reflectors @ \$33.00 ?	\$ 66.00
19	1 pc	rear bumper tow cover <i>distorted</i>	\$ 30.00
20	1 pc	rear bumper reinforcement ?	\$ 332.00
21	2 ps	rear bumper side retainer @ \$30.00 <i>SVC</i>	\$ 60.00
22	10 ps	rear bumper clips @ \$4.50 <i>huc</i>	\$ 45.00
23	2 ps	rear exhaust box @ \$998.00 <i>NH</i>	\$ 1,996.00
24	3 ps	rear exhaust box mount @ \$88.00 <i>NH</i>	\$ 264.00
25	1 pc	rear exhaust box chrome cutter <i>NH</i>	\$ 75.00
26	2 ps	rear lamps @ \$490.20 <i>NH</i>	\$ 980.40
27	4 ps	rear lamp clip holders @ \$45.00 <i>huc</i>	\$ 180.00
28	1 pc	spare tyre - well panel <i>Painted</i>	\$ 450.00
29	1 pc	spare tyre - trimboard <i>SVC</i>	\$ 552.50
30	1 pc	spare tyre - rubber grommet <i>huc</i>	\$ 55.00
31	1 pc	spare tyre - fastener clamp <i>SVC</i>	\$ 123.50
32	1 pc	tools, jack foam bowl <i>tova</i>	\$ 89.80
33	1 pc	left rear luggage floor side compartment foam <i>SVC</i>	\$ 159.60
34	1 pc	right rear luggage floor side compartment foam <i>SVC</i>	\$ 159.60
35	2 ps	rear fender inner trim @ \$175.00 <i>huc</i>	\$ 350.00
36	2 ps	rear fender inner liner @ \$78.00 <i>NH</i>	\$ 156.00
			\$ 11,079.80
Less 10 %			\$ 1,107.98
			\$ 9,971.82



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SFM763S
Date of Accident : 01 September 2018

Mr Neo Chee Seng (Liang Zhicheng)

Date : 01 September 2018

Estimate To Repair SJV1376A - SUBARU FORESTER 2.0X AWD 4AT D/AIRBAG
Chassis No : JF1SH5KS59G020228

S/No	Quantity	Description	Amount	
SPECIAL NETT ITEMS				
37	1 pc	rear licence plate NH	\$ 80.00	X
38	1 pc	rear windscreen glass sealant HCC	\$ 180.00	✓ 40/-
39	1 pc	rear windscreen glass inner sponge HCC	\$ 120.00	40/-
40	1 set	rear bumper parking sensor Dem	\$ 450.00	220/-
41	1 set	sundries and clips & NH	\$ 180.00	X
			\$ 1,010.00	
LABOUR & MISC. CHARGES				
01		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 550.00	NH
02		To rust-proofing of the affected areas.	\$ 250.00	60/-
03		To reinstall of rear bumper parking sensor.	\$ 150.00	40/-
04		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 480.00	80/-
05		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00	80/-
06		To drop rear exhaust box and renew the same.	\$ 280.00	60/-
07		To remove and refit rear windscreen glass.	\$ 180.00	120/-
08		To check electrical lighting concerned.	\$ 60.00	NH
09		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 2,200.00	1200/-
10		Putty and spray painting of the affected portion.	\$ 1,500.00	900/-
			\$ 5,500.00	
Total			\$ 16,481.82	

03/09/2018 @ 1000hrs
NH Andru
4pm 9 days.
Ryan
2KK Auto