

ASS. REC. BY:

REF: CS/FCU8016073/Ksbnz Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): MS Serene Lee of FCL Date/Time: 03092018 3:45pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 68G 5613M Insured: SH 9489Yat Workshop m/s: CP Motors Tel: 8201 8103of BK 160 Sin Ming Dr #05-05Policy No: Claim No: 218006394 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 25081018
(Client's Record)CA / REV / REP. / REV 24 HRS 'DS' 04092018 H.O.D. Endorsement:Date/Time: 03092018 4:58pm Person Contacted: Thomas Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>68G 5613M - X</u>
	<u>SH 9489Y - CS/FCU8016073/UBG1</u> <u>DUA: 15052019</u>
<u>03/09/18</u>	<u>@ 14:28 p.m. revised PA to Serene via email.</u>
<u>2019 05020-55</u>	<u>Cashmere</u>
<u>2010/1/8</u>	

0001/1/13 - wof

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From
Estimated Cost

OP (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GAG 5613M
at Workshop m/s CP Motors
of Blk 160 Sin Ming Drive #05-05
Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$54k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (DS)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

GAG 5613M Yr Regn: 08 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Dyna C.C. 2982

Colour

M. Silver A/C: Insured / Std / NI / NA

Sp. Reading

42187 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT-35 50k 208849

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F: 1P5175R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

d mm

R/Bal.

4 4 mm

L/Bal.

p mm

L/Bal.

4 4 mm

D.O.A.

25/8/18

D.O.I.

4/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

191 N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/9 File PPS to Catherine
20/09/18 Confirmed P/P \$5,020.55 @ 4 days with Kenneth
(\$821.70 Red - 14%)

RECEIVED

2018

Date/Time, File Pass to?

1) 21/09/18 Typ:4

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

140
50
50
22
262

Report Format :

Lump Sum / I.B.I. (\$ 5,020.55 P/P)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006394MFSH

Date: 05 September 2018

Our Ref: CS/FCI18016073/Ksb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBG 5613M .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/09/2018 at the premises of M/s CP Motors Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,842.25</u> .
Revised Estimate Amount	: S\$ <u>4,024.10</u> .
"Check" Items Amount	: S\$ <u>1,116.45</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the front n/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	27-08-2018	Our Ref No. D18006394MFSH
Accident Date	25-08-2018	Claim Type. Third Party
Insured Vehicle	SH9489Y	Third Party Vehicle. GBG5613M
Survey Location	160 Sin Ming Drive Sin Ming Auto City #05-05	
Contact Person.	THOMAS TAN	
Contact No.	82018103/ 82018103	Fax No. 64595357
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

13/09/2018 @ 4:58pm
 Thomas veh in
 04/09/2018

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CP MOTORS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 5 September 2018 2:28 PM
To: SERENELER@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: sur@lkkauto.com; 'Catherine Chong (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18006394MFSH/1
Attachments: GBG 5613M - Preli Advise.pdf

Dear Serene,

Enclosed herewith preliminary advice of GBG 5613M.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 3 September 2018 4:59 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18006394MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 3 September, 2018 3:45 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006394MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

CP MOTORS PTE LTD

160 Sin Ming Drive #05-05 Sin Ming Auto City
Singapore 575722

Tel No. : 64571357 Fax No. : 64595357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd
160 Sin Ming Drive #05-05
Sin Ming Auto City S 575722

Attention : Motor Claim Department

Contact : 82018103

Estimate : ES000100

Date : 03/09/2018
Vehicle Num. : GBG5613M
Make/Model : Toyota Dyna
Chassis/Eng# : JTFAT35Y50K208849
Accident Date : 25/08/2018
Claim No. : D18006394MFSH
Reference : T/P Claim Against First Cap.
Policy No. : 5093748198

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	2 pcs	Headlamp	885.64	1,771.28
2.	1 pc	Front Grille	CM	488.37
3.	1 pc	Front Grille Logo	m	84.50
4.	1 pc	Front Body Panel Logo	Bu	68.94
5.	1 pc	Front Bumper	B	755.46
6.	1 pc	Left Front Bumper Bracket	B	286.52
7.	6 pcs	Clip	Ne	8.23
8.	1 pc	Air Con Condenser	M	49.38
9.	1 pc	Left Step Panel Garnish	nd/ut	955.27
List TotalS\$:				356.62
25.00% Discount S\$:				4,816.34
				1,204.09
				3,612.25

SPECIAL NETT ITEMS :				
1.	1 pc	Body Lettering	Ne	10.00
2.	1 pc	Body Lettering Logo	m (Bill)	250.00
Special Nett Total S\$:				260.00

LABOUR :
Focus Headlamp
Remove/Refix air con condenser, pipe vacuum & top up gas

20.00
150.00

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CP MOTORS PTE LTD

160 Sin Ming Drive #05-05 Sin Ming Auto City
Singapore 575722

Tel No. : 64571357 Fax No. : 64595357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd
160 Sin Ming Drive #05-05
Sin Ming Auto City S 575722

Estimate : ES000100

Date : 03/09/2018
Vehicle Num. : GBG5613M
Make/Model : Toyota Dyna
Chassis/Eng# : JTFAT35Y50K208849
Accident Date : 25/08/2018
Claim No. : D18006394MFSH
Reference : T/P Claim Against First Cap.
Policy No. : 5093748198

Attention : Motor Claim Department

Contact : 82018103

S/N	Quantity	Particular	Unit Price	Amount S\$
		To straighten front body panel, left front door, left door pillar, left front chassis include replacement of parts.		5001 900.00
		Spray paint on front body panel, front body panel, left front door, left front door pillar & front bumper.		6801 900.00
		Labour Total S\$:		1,970.00

E. & O.E.

Total S\$: 5,842.25

=====



for CP MOTORS PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016073/Ksbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9489Y	Veh. Inspected	GBG 5613M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006394MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	03/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTFAT35Y50K208849	Colour	METALLIC SILVER	
Odometer	42187	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/75 R15	BRIDGESTONE	8 mm	
L/H Front Tyre	195/75 R15	BRIDGESTONE	8 mm	
R/H Rear Tyre	195/75 R15 (D)	BRIDGESTONE	4/4 mm	
L/H Rear Tyre	195/75 R15 (D)	BRIDGESTONE	4/4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/08/2018	Inspection Date	04/09/2018	
Survey held at	BLK 160 SIN MING DRIVE #05-05			
Repairer	CP MOTORS PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 5613M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	HEADLAMP @\$885.64	N/S CRACKED / O/S MTG CRACKED	1,771.28	1,771.28
1	FRONT GRILLE	CRACKED	488.37	488.37
1	FRONT GRILLE LOGO	NECESSARY	84.50	84.50
1	FRONT BODY PANEL LOGO	NOT NECESSARY	68.94	-
1	FRONT BUMPER	BUCKLED	755.46	755.46
1	LEFT FRONT BUMPER BRACKET	BENT	286.52	286.52
6	CLIP @\$8.23	NECESSARY	49.38	49.38
1	AIR CON CONDENSER	BENT	955.27	955.27
1	LEFT STEP PANEL GARNISH	DENTED / CUT	356.62	356.62
	LESS 25% DISCOUNT		-1,204.09	-1,186.85
			3,612.25	3,560.55
SPECIAL NETT ITEMS				
1	BODY LETTERING (SN)	NECESSARY	10.00	10.00
1	BODY LETTERING LOGO (SN)	NECESSARY	250.00	180.00
			260.00	190.00
LABOUR				
	FOCUS HEADLAMP.		20.00	20.00
	REMOVE/REFIX AIR CON CONDENSER,PIPE,VACCUM & TOP UP GAS.		150.00	100.00
	TO STRAIGHTEN FRONT BODY PANEL,LEFT FRONT DOOR,LEFT DOOR PILLAR,LEFT FRONT CHASSIS INCLUDE REPLACEMENT OF PARTS.		900.00	500.00
	SPRAY PAINT ON FRONT BODY PANEL,FRONT BODY PANEL,LEFT FRONT DOOR,LEFT FRONT DOOR PILLAR & FRONT BUMPER.		900.00	650.00
	-		-	-
	-		-	-
	-		-	-
			1,970.00	1,270.00
GRAND TOTAL			5,842.25	5,020.55

Report Ref No. CS/FCI18016073/Ksbn2



RECOMMENDED COST OF REPAIRS			5,020.55
-----------------------------	--	--	----------

Report Ref No. CS/FC18016073/Ksbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.