

ASS. REC. BY:

REF: CS/FWD18016074/ANBS

Special Instruction:

ASSIGNMENT (Office)

SUBJECT

From (Person): Merimen Josey Loh

of TWD

Date/Time: 03/09/2018 3:57pm

Estimated Cost:

Bill to:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 4719Y

Insured:

SKT 3992G

at Workshop m/s

Siang Hai Motor

Tel:

6555 7272

of

Sik N Kaki Bukit ANL 6 #02-03

Policy No:

PNPV 2018-00006939

Claim No:

12018 000 11061

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/09/2018

CA / REV / REP. / REV 24 HRS WP

04-09-2018

H.O.D. Endorsement:

Date/Time:

03/09/2018 4:40pm

Person Contacted:

Ah Huet

Vehicle

IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	FBL 4719Y - X
	SKT 3992G - X
5/9/18	Informal Josey pending workshop est via merimen
13/3/19	Adrian confirmed LS: \$4500 (Red 7329.40, 629)
14/3/19	Sand pret. revised via merimen

00/11/18 wol  
ISS. REC. BY:

REF: FWD

ASSIGNMENT

From: Date: 11/9/18  
Estimated Cost:  
OD: TP WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No: FBL 4719 Y  
at Workshop m/s: Siong Hui Motor  
of: Blk 1, Kaki Bkt Ave 6 #02-03  
Insured:  
Policy No:  
Claims No:  
Sum Insured: Excess:  
(Client's Record)  
Make of Veh:

Veh No: FBL4719 Y Yr Regn: 2016 / Oct  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Yamaha. YZF R15 c.c. 150  
Colour: Blue A/C: Insured / Std / NI / NA  
Sp. Reading: T/Radio: Insured / Std / NI / NA  
Eng/No:  
C/No: ME1KG0698142001957.  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modi: Nil / STD A/Rim / STD A/Rim or  
Tyre Size: F: 90/80 R17.  
R: 130/70 R17.  
BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Front Rear  
R/Bal. 06 mm R/Bal. 06 mm  
L/Bal. mm L/Bal. mm  
D.O.A. D.O.I. 04/09/18.  
Survey held at Siong Hui.  
Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value:  
IDAC Accident Rpt: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: days Res.: Yes or No  
Lum Sum: % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS lup  
Date: Person Contacted:  
Vehicle: IN / OUT

Date / Time Action / Instruction  
TP. FWD  
MV: 9.5K.  
PV: 5.1K  
Nett: 4.7K.

RECEIVED 14 MAR 2019

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 5  
Resurvey No. of Trip: 1

Date/Time, File Return to?  
14/3 - typist

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Survey Fee:	250
Transportation:	50
S + RS, SI	50
Photos	
Others	
	10
TOTAL	

Report Format: merimen  
Lump Sum / I.B.I.: (\$ 4500/- )

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Sep 2018 <a href="#">Edit Reg</a>		04 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>		<b>Last:IA</b> 14 Mar 2019 10:18		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	<b>CHOONG LEE CHOO</b> , ID: S2617812F		
Main Claimant:	<b>TAN JIAN YAN</b> , ID: S9722938D		
Vehicle Reg. No.:	<b>FBL4719Y</b>	Date of Loss:	02/09/2018 13:00 - :59
Claim Type:	<b>TP / 1201800011061</b>	Policy/Cover Note No.:	PNPV2018-00006939 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SKT3992G</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Siong Hai Motor &amp; Trading (HQ)</b> NO 1 KAKI BUKIT AVE 6, #02-03 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:		
Handling Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Clara Li Zi Rong</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 13/09/2018]</b>		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

<b>To:</b> FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
<b>Attn:</b> Clara Li Zi Rong	<b>Date:</b> 14 Mar 2019
<b>Preliminary Advice</b>	

Insured Vehicle No : SKT3992G			
TP Vehicle No : FBL4719Y	Accident Date	:	02/09/2018
Make : YAMAHA YZF-R15	Assignment Date	:	04/09/2018
Date of Inspection : 4/9/2018	Est. Duration of Repair	:	5
Inspection At : SIONG HAI MOTOR AND TRADING			

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,649.40
Revised Amount (estimated)	:S\$	4,500.00 (LUMP SUM)
Check Items (Estimated)	:S\$	
<b>Total</b>	<b>:S\$</b>	<b>4,500.00</b>
Lump Sum Repair	:S\$	

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

( )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
( )	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
( X )	Other comments : The above survey was conducted on a 'Without Prejudice' basis.

## View Sent Message

This mail is associated with :

**\*FBL4719Y**  
**[SKT3992G]**

TP  
TAN JIAN YAN  
Sep 2 2018 1:00PM

Siong Hai Motor & Trading

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **05/09/2018 09:54 AM.**

**To** FWD\_SG; josey.loh@fwd.com

**Subject** TP SURVEY FBL 4719Y

Dear Josey,

Please be informed that we have inspected the vehicle FBL 4719Y on 4/9/2018 .

We are pending estimate from repairer.

Best Regards,  
Veron Chen

### DOCUMENTS SUMMARY

There are no documents.

**Catherine Chong (LKK Auto)**

---

**From:** motorclaims.sg@fwd.com  
**Sent:** Monday, 3 September, 2018 3:57 PM  
**To:** assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com  
**Cc:** motorclaims.sg@fwd.com  
**Subject:** FW: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SBL4719Y [OUR REF. TCL.GCN.RO.50319.SHM] (FWD Ref: PNPV2018-00006939)  
**Importance:** High

Hi LKK team,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.


Thank you.

Kind Regards  
Josey Loh  
Executive, Claims

03092018 @ 4:40pm  
An Hui wei in

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872  
E [josey.loh@fwd.com](mailto:josey.loh@fwd.com)  
W [fwd.com.sg](http://fwd.com.sg)



---

**From:** Ruby Ong [mailto:[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)]  
**Sent:** Monday, 3 September, 2018 3:19 PM  
**To:** Motor Claims SG - SG Common  
**Cc:** Josey Loh Kah Wai - SGUser  
**Subject:** Re: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SBL4719Y [OUR REF. TCL.GCN.RO.50319.SHM] (FWD Ref: PNPV2018-00006939)  
**Importance:** High

WITHOUT PREJUDICE

URGENT

Dear Josey

We refer to your email of even date. Please note that our client's vehicle is a motorcycle.

Our client is agreeable to appoint **LKK Auto Consultants Pte Ltd** as the single joint expert to carry out the pre-repair survey for FBL 4719Y.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : Siong Hai Motor & Trading  
1 Kaki Bukit Avenue 6  
#02-03 Autobay  
Singapore 417883

Contact Person : Mr Ah Huat (H/P : 6555 7272)

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,  
Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners  
20 Upper Circular Road  
#02-10/12 The Riverwalk  
Singapore 058416  
**Tel : 6533 0212 ext 278**  
Fax : 6338 3536 / 6533 0313

[www.htapartners.com.sg](http://www.htapartners.com.sg)

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

---

**From:** [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com) <[motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com)>

**Sent:** Monday, September 3, 2018 2:26 PM

**To:** Ruby Ong

**Cc:** [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com)

**Subject:** RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SBL4719Y [OUR REF. TCL.GCN.RO.50319.SHM] (FWD Ref: PNPV2018-00006939)

**WITHOUT PREJUDICE**

Dear Ruby,

We refer to your letter dated 03 September 2018 of the PRI Notice of your client's vehicle SBL4719Y.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

***\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com). Thank you.***


Kind Regards

Josey Loh  
Executive, Claims

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872  
E [josey.loh@fwd.com](mailto:josey.loh@fwd.com)  
W [fwd.com.sg](http://fwd.com.sg)

**FWD**  
insurance



---

**From:** Ruby Ong [<mailto:ruby@htapartners.com.sg>]  
**Sent:** Monday, 3 September, 2018 12:10 PM  
**To:** Clara Li Zirong - SGUser  
**Subject:** REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SBL4719Y [OUR REF. TCL.GCN.RO.50319.SHM]

Your ref: SKT 3992G  
Our ref: TCL.GCN.ro.50319.18.shm

**WITHOUT PREJUDICE**

3 September 2018

FWD Singapore Pte Ltd  
Motor Claims Department  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

By Email Only

**VERY URGENT**

Dear Sir,

**CLAIMANT: TAN JIAN YAN**

**NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - ACCIDENT INVOLVING FBL 4719Y & SKT 3992G ALONG UPPER EAST COAST ROAD ON 02/09/2018 @ 1320HRS**

We are instructed by Tan Jian Yan to notify you of a road traffic accident on 2 September 2018 at about 1320 hrs along Upper East Coast Road involving our client's vehicle registration number FBL 4719Y and vehicle registration number SKT 3992G driven by your insured's driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

**Tel : 6533 0212 ext 278**

**Fax : 6338 3536 / 6533 0313**

[www.htapartners.com.sg](http://www.htapartners.com.sg)

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not

use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/09/2018 12:46
Date Of Accident	02/09/2018 13:20
Exact Location Of Accident	UPPER EAST COAST ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL4719Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN JIAN YAN
NRIC No	S9722938D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96451470
Alternative Phone No	OTHERS-96451470

### Vehicle Particulars

Manufacturer	YAMAHA
Model	YZF-R15-150CC (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	CN:72109190
Cover Note Number	CN:72109190

### Driver

Name of Driver	TAN JIAN YAN
NRIC No	S9722938D
Date Of Birth	10/07/1997
Occupation	INDOOR
Date Of Driving Pass	02/07/2018
Driving Experience	0 YEAR AND 2 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96451470
Fax Number	
Contact Number	OTHERS-96451470
EMail Address	NOEMAIL

Address	BLK 34 BEDOK SOUTH AVE 02 #15-371
Postcode	460034
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK NEIGHBOURHOOD POLICE POST
Police Station Address	<b>ROAD:</b> BLK 15 BEDOK SOUTH ROAD #01-117 , <b>POSTCODE:</b> 460015 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-2419999 - <b>FAX NO:</b> 64431687
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

Type Of Accident: HEAD TO SIDE. AS PER POLICE REPORT No. T/20180902/2069

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT3992G
Vehicle Make/Model/Colour	MERCEDES BENZ A180 (R17)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHOW SU RIN
NRIC/Passport Number	S9240439J
Contact Number	93387521
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	TAN JIAN YAN
Approximate Age	21
Injuries Sustain	
Injured person in which vehicle?	FBL4719Y
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 34 BEDOK SOUTH AVE 02 #15-371
Postcode	460034

## Accident Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

03 SEP 2018


  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

**IDAC KAKI BUKIT(VAC)**  
23 KAKI BUKIT AVE 4  
Reporting Centre  
Singapore 415933  
Name: \_\_\_\_\_  
Tel: 67416697  
NRIC/FIN No.: \_\_\_\_\_  
Fax: 67492305  
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Police Report Made.

The section contains a large, hand-drawn scribble or signature that spans across most of the lined area.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

03 SEP 2010  
IDAC KAKI BUKIT(VAC)  
23 KAKI BUKIT AVE 4  
Reporting Centre Singapore 415933  
Name: Tel: 67416697  
NRIC/FIN No.: Fax: 67492305  
Email: vackb@singnet.com.sg



Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180902/2069

Police Station Of Origin:  
Bedok NPP  
15 Bedok South Road #01-117 SINGAPORE  
460015  
Tel No: 1800-2419999

2 of 4

Report No. T/20180902/2069

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	TAN JIAN YAN	ID No.	S9722938D
Related Vehicle	FBL4719Y (Motorcycle)	Contact No.	96451470
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
<b>Driver</b>			
Name	CHOW SU RIN	ID No.	S9240439J
Related Vehicle	SKT3992G (Car)	Contact No.	93387521
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 02/09/2018 at about 1320hrs, I was travelling along Upper East Coast Road on my vehicle (Motorcycle, FBL4719Y) on the right lane of two lane heading towards Bedok Road. As I was approaching the Esso petrol station, one vehicle (Motorcar, SKT3992G) suddenly drove out of the petrol station into Upper East Coast Road heading towards East Coast Road. I then applied the brake however, I could not stop in time and collided onto the vehicle right front side portion of the vehicle.

Subsequently, the driver (a Chinese female) then came out the vehicle and attended to check if I was alright. We then took photos of the accident scene and exchanged our particulars. I then called for towing services as my vehicle's handle was unable to turn and we then left the scene shortly after.

I wish to state that I had landed onto the motor car's front bonnet when the accident occurred and I had sustained some abrasion on the right forearm, thigh and shoulder area of my body. I will heading to the clinic for a medical checkup later this evening as I felt some sharp pain on the right side of my body. There was a in-build camera in the female driver vehicle and she mentioned that the camera was on when the accident happened.

Common Statement Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180902/2069

Police Station Of Origin:  
Bedok NPP  
15 Bedok South Road #01-117 SINGAPORE  
460015  
Tel No: 1800-2419999

3 of 4

Report No. T/20180902/2069

CONTINUATION OF REPORT

Accident Sketch Plan Pg. 1



SINGAPORE  
POLICE FORCE



T/20180902/2069

Police Station Of Origin:  
Bedok NPP  
15 Bedok South Road #01-117 SINGAPORE  
460015  
Tel No: 1800-2419999

4 of 4

Report No. T/20180902/2069

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 TAN EDMUND NEIL 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 02/09/2018 16:24
Officer In Charge Of Case: TP / AEIT / SSI KASMAWATI BTE SAMIAN Contact No.: 65476179	Classification Of Case:
Authentication Stamp NP168 	

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2938D
Vehicle Details	
Vehicle No.:	FBL4719Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YZF-R15
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	2PB2002743
Chassis No.:	ME1KG0698H2001957
Maximum Power Output:	-
Open Market Value:	\$3,091.00
Original Registration Date:	24 Oct 2016
First Registration Date:	24 Oct 2016
Transfer Count:	2
Actual ARF Paid:	\$464.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Oct 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,354.00
COE Rebate Amount:	\$5,083.00
<b>Total Rebate Amount:</b>	<b>\$5,083.00</b>

The information contained herein is correct as at 04 Sep 2018

OK

Bike model  
Yamaha YZF-R15

Type  
Any

Price From  
Any

Price To  
Any

Class  
Any

MORE SEARCH OPTIONS ▾

Q SEARCH  VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH ▾

Yamaha YZF-R15 (/listing/usedbike/yamaha-yamaha-yzf-r15/9135/)



(/listing/usedbike/yamaha-yamaha-yzf-r15/9135/)

SGD**\$6500**

Reg : 29/04/2013

Type: Sport Bikes

150cc

49525km

Red/White Yamaha YZF-R15 Version 2 / V2 For Sale. 1st Owner. Slight blemishes on exterior (not for fussy buyer). Meet @ Hougang For Viewing. Under usage as driving to Car. Serviced/changed In ...

Posted on : 16/08/2018

★ PAID AD   ★ DIRECT SELLER

■ COMPARE   DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-YZF-R15/9135/)

Yamaha YZF-R15 (/listing/usedbike/yamaha-yamaha-yzf-r15/9280/)



(/listing/usedbike/yamaha-yamaha-yzf-r15/9280/)

SGD**\$7000**

Reg : 14/11/2013

Type: Sport Bikes

150cc

35000km

Posted on : 27/08/2018

★ DIRECT SELLER

■ COMPARE   DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-YZF-R15/9280/)

**SIONG HAI MOTOR AND TRADING**  
 Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TP FWD.  
 VERON.

04/09/2018

TEL: 65557272

Fax: 67411019

H/P: 93365311 (Ah Huat)

Vehicle No: FBL4719Y

Model: YAMAHA YZF-R15-150CC (M)

QTY	List Items	Price \$
1	Front fender <i>delivered</i>	93.00 ✓
1	Front coving <i>cracked</i>	135.00 ✓
1	Front coving inner bracket <i>dayd</i>	55.00 ✓
1	Front inner tubes <i>Best</i>	199.00 ✓
1	Front outer tubes <i>Best</i>	228.00 ✓
1	Front sport rim <i>new</i>	380.00 ✗
2	Front L/R fork (1) 770.00 <i>Best</i>	1540.00 ✓
2	Front L/R fork under bracket (1) 245.00 <i>Best</i>	490.00 <del>245.</del>
1	Front rim shaft	65.00 +
1	Front brake disc <i>new</i>	228.00 ✗
1	Front brake caliper	326.00 ✗
1	Handle bar <i>new</i>	93.00 +
2	Handle L/R bar end (1) 32.00 <i>LH Best</i>	64.00 <del>32.</del>
2	Handle L/R bar inner bracket (1) 58.00 <i>Distanted</i>	116.00 ✓
2	Front L/R side mirror (1) 85.00 <i>new</i>	170.00 ✗
2	L/R brake lever (1) 33.00 <i>RH fit</i>	66.00 <del>33.</del>
1	Beuing cover <i>new</i>	110.00 ✗
1	Top cowlings <i>cracked</i>	90.00 ✓
2	Front L/R headlamp (1) 260.00 <i>cracked</i>	520.00 ✓
2	Front L/R headlamp bracket (1) 85.00 <i>cracked</i>	170.00 ✓
2	Front L/R signals (1) 85.00 <i>LH fit</i>	170.00 <del>45.</del>
1	Meter assy <i>fit</i>	538.00 ✓
2	L/R side cowlings outer cover (1) 123.00 <i>RH cracked</i>	246.00 <del>123</del>
2	L/R side cowlings inner cover (1) 95.00	190.00 <del>95</del>
1	Center inner panel <i>new</i>	70.00 +
1	Radiator <i>new</i>	398.00 ✗
1	Front footrest bracket <i>new</i>	48.00 +
1	Front O/S footrest rubber <i>fit</i>	18.00 ✓
1	Brake pedal <i>new</i>	45.00 +
1	Front windscreen glass <i>fit</i>	127.00 ✓
1	Fuel tank <i>new</i>	480.00 ✗
1set	Engine overhaul gasket <i>new</i>	280.00 ✓
1set	Piston engine	550.00 +
1set	Con-rod engine	470.00 +
1set	Con-rod bearing engine	65.00 +
1set	Main bearing engine	70.00 ✗
1set	Valve engine	190.00 +
1pc	Engine claim shaft <i>new</i>	430.00 +
1set	Engine injector <i>new</i>	325.00 ✗
1set	Engine timing chain	286.00 ✗
1set	Engine timing gear <i>fit</i>	297.00 ✗
1set	Engine timing cover	109.00 ✓

1set	Valve bush	} new	88.00	*
1set	Valve roller		113.00	*
1set	Engine oil pump		385.00	*
			<b>\$10,646.00</b>	11326
			<b>1064.60</b>	
			<b>\$9,581.40</b>	10193.40

4991  
4491.9

**Special Nett Items**

1	Number plate	new	28.00	20.
2	Fork oils	} new	40.00	✓
2	Fork oil seals		60.00	✓
1	Steering cone (set)	new	90.00	✓
1	Front tyre (depreciation)	new	100.00	*
1	Coolant	new	20.00	✓
1	Engine oil (1 tin)	new	80.00	60.

290

**\$418.00**

**Labour**

To engine re-programming	200.00	*
To provide towing service	<del>70.00</del>	40.
To check, repair and straighten body fame to the original position	<del>350.00</del>	250.
To overhaul engine	600.00	250.
To machinery shop for engine reball	180.00	*
To provide labour charges, workmanship to dismantle above damaged parts realign body structure and damages consistent to the accident	<del>450.00</del>	300.
<b>Total</b>	<b>\$1,850.00</b>	

840

**ESTIMATE PARTS AND LABOUR GRAND TOTAL**

**\$ 11,649.40** 11,829.40

total: 562.90  
L/S: 4SK  
050mgs.

12461.40

4SK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Sep 2018 <a href="#">Edit Reg</a>		03 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	CHOONG LEE CHOO, ID: S2617812F								
Main Claimant:	TAN JIAN YAN, ID: S9722938D								
Vehicle Reg. No.:	FBL4719Y	Date of Loss: 02/09/2018 13:00 - :59 [22 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 1201800011061	Policy/Cover Note No.: PNPV2018-00006939 (Comprehensive)							
Vehicle Reg. No. (Insured):	SKT3992G	Policy No. (Claimant):							
		Excess:							
Repairer:	Siong Hai Motor & Trading (HQ) NO 1 KAKI BUKIT AVE 6, #02-03 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/09/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*FBL4719Y (1201800011061)  
[SKT3992G]  
TP  
TAN JIAN YAN  
Sep 2 2018 1:00PM  
[CHOONG LEE CHOO]  
Siong Hai Motor & Trading

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/19 10:18	<b>Adjuster Immediate Advice</b>	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
28	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
29	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
30	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
31	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
32	13/03/19 14:14	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
33	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
34	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
35	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
36	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
37	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
38	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
39	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
40	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
41	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
42	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
43	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
44	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
45	13/03/19 14:14	General View		Load JPG	<input checked="" type="checkbox"/>
46	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
47	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
48	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
49	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
50	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
51	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
52	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
53	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
54	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
55	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
56	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
57	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
58	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
59	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
60	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
61	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
62	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
63	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
64	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
65	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
66	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
67	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
68	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
69	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
70	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
71	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
72	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
73	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
74	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
75	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
76	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
77	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
78	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
79	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
80	13/03/19 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	13/03/19 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	13/03/19 14:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	05/09/18 13:45	<b>Insured GIA Report</b>	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/FWD18016074/AVBS2  
**Date:** 18/03/2019

### REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2018-00006939
<b>Claimant Vehicle No :</b>	FBL4719Y	<b>Insured Vehicle No :</b>	SKT3992G
Date of Loss:	02/09/2018	Nature of Claim:	TP
		Claim No:	1201800011061

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBL4719Y</b>	Engine No:	2PB2002743
Make & Model:	YAMAHA YZF-R15, 150cc (M)	Chassis No:	ME1KG0698H2001957
Reg. Date:	25/10/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	90/80R17	Rear Tyre Size:	130/70R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,611.40	4,781.90	5,829.50	54.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	840.00	1,010.00	54.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,461.40</b>	<b>5,621.90</b>	<b>6,839.50</b>	<b>54.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,461.40</b>	<b>4,500.00</b>	<b>7,961.40</b>	<b>63.89</b>

### INSPECTION

Date of Assignment:	03/09/2018	
Date Inspected:	04/09/2018 Inspected At:	Siong Hai Motor & Trading (HQ) NO 1 KAKI BUKIT AVE 6, #02-03 AUTOBAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	5.0 days	

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 18 Mar 2019)
<b>Parts:</b>	N/A YAMAHA YZF-R15 150cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBL4719Y)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Deformed	93.00 FL	*93.00 FL
2	1		*FRONT COWLING	Cracked	135.00 FL	*135.00 FL
3	1		*FRONT COWLING INNER BRACKET	Damaged	55.00 FL	*55.00 FL
4	1		*FRONT INNER TUBES	Bent	199.00 FL	*199.00 FL
5	1		*FRONT OUTER TUBES	Bent	228.00 FL	*228.00 FL
6	1		*FRONT SPORT RIM	Not Necessary	380.00 FL	*- FL
7	2		*FRONT L/R FORK	Bent	1,540.00 FL	*1,540.00 FL
8	2		*FRONT L/R FORK UNDER BRACKET	Bent	490.00 FL	*245.00 FL
9	1		*FRONT RIM SHAFT	Not Necessary	65.00 FL	*- FL
10	1		*FRONT BRAKE DISC	Not Necessary	228.00 FL	*- FL
11	1		*FRONT BRAKE CALIPER	Not Necessary	326.00 FL	*- FL
12	1		*HANDLE BAR	Not Necessary	93.00 FL	*- FL
13	1		*HANDLE L/R BAR END	N/s Bent	64.00 FL	*32.00 FL
14	2		*HANDLE L/R BAR INNER BRACKET	Distorted	116.00 FL	*116.00 FL
15	2		*FRONT L/R SIDE MIRROR	Not Necessary	170.00 FL	*- FL
16	1		*L/R BRAKE LEVER	O/s Cut	66.00 FL	*33.00 FL
17	1		*BEUING COVER	Not Necessary	110.00 FL	*- FL
18	1		*TOP COWLING	Cracked	90.00 FL	*90.00 FL
19	2		*FRONT L/R HEADLAMP	Cracked	520.00 FL	*520.00 FL
20	2		*FRONT L/R HEADLAMP BRACKET	Cracked	170.00 FL	*170.00 FL
21	1		*FRONT L/R SIGNALS	N/s Cut	170.00 FL	*45.00 FL
22	1		*METER ASSY	Cut	738.00 FL	*738.00 FL
23	1		*L/R SIDE COWLING OUTER COVER	O/s Cracked	246.00 FL	*123.00 FL
24	1		*L/R SIDE COWLINGS INNER COVER	O/s Cracked	190.00 FL	*95.00 FL
25	1		*CENTER INNER PANEL	Not Necessary	70.00 FL	*- FL
26	1		*RADIATOR	Not Necessary	398.00 FL	*- FL
27	1		*FRONT FOOTREST BRACKET	Not Necessary	48.00 FL	*- FL
28	1		*FRONT O/S FOOTREST RUBBER	Cut	18.00 FL	*18.00 FL
29	1		*BRAKE PEDAL	Not Necessary	45.00 FL	*- FL
30	1		*FRONT WINDSCREEN GLASS	Cut	127.00 FL	*127.00 FL
31	1		*FUEL TANK	Not Necessary	480.00 FL	*- FL
32	1		*SET ENGINE OVERHAUL GASKET	Necessary	280.00 FL	*280.00 FL
33	1		*SET PISTON ENGINE	Not Necessary	550.00 FL	*- FL
34	1		*SET CON-ROD ENGINE	Not Necessary	470.00 FL	*- FL
35	1		*SET CON-ROD BEARING ENGINE	Not Necessary	65.00 FL	*- FL
36	1		*SET MAIN BEARING ENGINE	Not Necessary	70.00 FL	*- FL
37	1		*SET VALVE ENGINE	Not Necessary	190.00 FL	*- FL
38	1		*ENGINE CLAIM SHAFT	Not Necessary	430.00 FL	*- FL
39	1		*SET ENGINE INJECTOR	Not Necessary	325.00 FL	*- FL
40	1		*SET ENGINE TIMING CHAIN	Not Necessary	286.00 FL	*- FL
41	1		*SET ENGINE TIMING GEAR	Not Necessary	297.00 FL	*- FL
42	1		*SET ENGINE TIMING COVER	Cut	109.00 FL	*109.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SET VALVE BUSH	Not Necessary	88.00 FL	*- FL
44	1		*SET VALVE ROLLER	Not Necessary	113.00 FL	*- FL
45	1		*SET ENGINE OIL PUMP	Not Necessary	385.00 FL	*- FL
46	1		*NUMBER PLATE	Necessary	28.00 FS	*20.00 FS
47	2		*FORK OILS	Necessary	40.00 FS	*40.00 FS
48	2		*FORK OIL SEALS	Necessary	60.00 FS	*60.00 FS
49	1		*SET STEERING CONE	Necessary	90.00 FS	*90.00 FS
50	1		*FRONT TYRE	Not Necessary	100.00 FS	*- FS
51	1		*COOLANT	Necessary	20.00 FS	*20.00 FS
52	1		*TIN ENGINE OIL	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,744.00</b>	<b>5,281.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,132.60	499.10
<b>Total Parts (\$\$)</b>	<b>10,611.40</b>	<b>4,781.90</b>

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO ENGINE RE-PROGRAMMING.	New	200.00	0.00
2	TO PROVIDE TOWING SERVICE.	New	70.00	40.00
3	TO CHECK, REPAIR AND STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION.	New	350.00	250.00
4	TO OVERHAUL ENGINE.	New	600.00	250.00
5	TO MACHINERY SHOP FOR ENGINE REBALL.	New	180.00	0.00
6	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS REALIGN BODY STRUCTURE AND DAMAGES CONSISTENT TO THE ACCIDENT.	New	450.00	300.00
<b>Gross Labour Cost (S\$)</b>			<b>1,850.00</b>	<b>840.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >