

INSURANCE

INS. CASE OWNER

Bennie

CC6 /AIG1801

6083, Apr 9

LKK

IDAC

Surveyor:

Adrian

DOI:

ASSIGNMENT

3/4/18

Date / Time:

12/11/18

Registered in Merimen:

4/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLW 3948H

Name of Insured:

MRN LIMB TH ARTHUR

Insured Tel No.:

HP:

20/8/18

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LMR LIMB TH ARTHUR

Driver Tel No.:

(V/I YES / NO)

Claim No.:

20757642056

Policy No.:

1800018533

Make / Model:

MAZDA

Place of Accident:

PLETMS PIONEER NORTH

OI GIA REPORT (YES / NO)

YES / NO

Insured Liability:

% Final ? Yes / No

67 2833n



INSRS:

WSP:

Tel:

Liability:

RMKS:

Eastth
Km chuee



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

6/1/18
LHT

48 1533n - 4

SLW 3948H - 7

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

2 CH 12/1/18

12/1/18 4:24pm AD rear ended TP
Request OI video from AIG

9/1/18 - OI video ✓ memo

17/1/18 - File pass to shut per to close

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Cal

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO of B 28. Ass. Lia:

Repair Cost:

SS

4547.50

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

560.00 (5 8u x 7 days)

Loss of Income (LOI):

SS

(5 s days)

LOR only

LOU only

LOR + LOU

LOR + LOU

(Tick only one)

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

1) Claim status: Non-Report/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

5109.50

Global Sum SS:

5100.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Cal

Payee 1:

SS

5100.00

Name 1:

Km chuee Auto pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

1/1/18

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 06 days Res: Yes or No
 Lum Sum: 20. % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: G22837U Yr Regn: 2006 Feb.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.C. 2494.
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 519615. T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: JTFHS02P400038930

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C
 R: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 03/09/18

Survey held at: Fastech.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
TP AIG.

CoE Expiry: 21/04/21

MV: 2010.
 GV: 112K
 Nelt: 8.81K

44 \$ 4750 (Real \$ 14067.98 / 75%)
4250.

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

11

Date/Time, File Return to?

2)

Report Format

Lump Sum / I.B.E (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

5 = 95. 54

Photos:

Others:

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18016083/Apb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 04-09-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 3948H	Veh. Inspected	GZ 2837U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	30/08/2018	Inspection Date	03/09/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

KIM CHWEE AUTO PTE LTD

page 1/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Estimate : 20536

TPA 164

Xiao Tang

JTFH5027400038930

Date : 03.09.2018

Vehicle Num : GZ 2837U

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 30.08.2018

Claim No : 0918-20536

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Rear boot cover <i>Dented</i>	877.50 \$ 1,845.50
1 pc	Rear boot cover inner lock <i>Paint</i>	\$ 356.20 223
1 pc	Rear boot lock actuator <i>new</i>	\$ 491.50
1 pc	Rear boot lock catch <i>new</i>	\$ 78.90
1 pc	Rear boot centre emblem <i>new</i>	\$ 66.70
1 pc	Rear toyota hiace sticker <i>new</i>	\$ 68.70
1 pc	Rear boot centre garnish <i>new</i>	\$ 265.50
1 pc	Rear boot inner cover <i>new</i>	\$ 547.20
1 pc	Rear boot rubber <i>new</i>	\$ 479.80 387
2 pc	Rear boot absorber @ 361.90 <i>new</i>	\$ 723.80
2 pc	Rear boot hinge @ 101.20 <i>new</i>	\$ 202.40
2 pc	Rear tail lamp @ 457.10 <i>LH cracked</i>	\$ 914.20 291
2 pc	Rear tail lamp lower garnish @ 111.20 <i>LH Dented</i>	\$ 222.40 111.20
1 pc	Taillamp panel LH <i>new</i>	\$ 292.50
1 pc	Rear end panel outer <i>Dented</i>	\$ 685.20
1 pc	Rear end panel inner <i>Repair</i>	\$ 1,012.60
1 pc	Rear end panel top garnish <i>new</i>	\$ 173.80
2 pc	Rear number plate lamp @ 85.20 <i>new</i>	\$ 170.40
1 pc	Rear bumper <i>Dented</i>	\$ 802.20 384
2 pc	Rear bumper side retainer @ 101.20 <i>new</i>	\$ 202.40
4 pc	Rear bumper lower support bracker @ 45.20 <i>Best</i>	\$ 90.40
1 pc	Rear spare tyre carrier	\$ 651.20
1 pc	Rear spare tyre lock screw	\$ 246.90
1 pc	Rear floor board panel	\$ 2,023.80
1 pc	Rear exhaust pipe	\$ 725.20
2 pc	Rear exhaust rubber @ 35.20	\$ 70.40
1 pc	Rear fender LH <i>Repair</i>	\$ 1,747.50
List Item Total :		\$ 15,157.30
Discount 25 % :		\$ 3,789.33
		\$ 11,367.98

KIM CHWEE AUTO PTE LTD

page 2/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Estimate : 20536

Date : 03.09.2018

Vehicle Num : GZ 2837U

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 30.08.2018

Claim No : 0918-20536

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>Special Nett Item :</u>		
12pc	Rear boot inner cover clips @ 5.00 <i>new</i>	\$ 60.00 <i>30</i>
8 pc	Rear bumper lower clips @ 5.00 <i>new</i>	\$ 40.00 <i>30</i>
4 pc	Rear tail lamp clips @ 5.00 <i>new</i>	\$ 20.00 <i>+</i>
1 pc	Rear number plate <i>new</i>	\$ 45.00 <i>+</i>
1 pc	Rear end panel sealant <i>new</i>	\$ 80.00 <i>60</i>
3 pc	Rear end panel top garnish clips @ 5.00 <i>new</i>	\$ 15.00 <i>+</i>
1 pc	Rear windscreen sealant <i>new</i>	\$ 80.00 <i>60</i>
1 pc	Rear boot sticker (6 pax) <i>new</i>	\$ 25.00 <i>15</i>
1 pc	Rear boot sticker (70km/h) <i>new</i>	\$ 25.00 <i>15</i>
1 pc	Rear floor board panel top insulator <i>new</i>	\$ 350.00 <i>+</i>
1 set	Rear bumper sensor <i>Damaged</i>	\$ 450.00 <i>200</i>
Special Nett Total :		\$ 1,190.00

Labour Charge :

To check wiring	\$ 180.00 <i>30</i>
Tuff kote	\$ 200.00 <i>50</i>
To cut body sticker	\$ 1,200.00 <i>45</i>
Remove and refix rear windscreen	\$ 180.00 <i>120</i>
Remove and replace reverse sensor	\$ 150.00 <i>50</i>
Remove and replace rear exhaust pipe	\$ 150.00 <i>x</i>
Remove and refix upholstery	\$ 150.00 <i>40</i>
To remove and replace spare part and panel beating	\$ 2,000.00 <i>800</i>
To spray painting and etc	\$ 2,000.00 <i>800</i>
Labour Charge Total :	\$ 6,210.00

<p>Letting the insured party hence notify</p> <p>of the following:</p> <ul style="list-style-type: none">• To resurvey before after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "without prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature _____</p> <p>Date: _____</p> <p>KIM CHWEE AUTO PTE LTD</p>	<p>E & O . E</p> <p>Total Amount : \$ 18,767.98</p> <p><i>total: 554845 5796.37</i></p> <p><i>1/c 4.7K 422000</i></p> <p><i>6 days 607</i></p>
--	---

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Company
Owner ID:	3103W
Vehicle Details	
Vehicle No.:	GZ2837U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	2KD1417537
Chassis No.:	JTFH502P400038930
Maximum Power Output:	-
Open Market Value:	\$23,810.00
Original Registration Date:	22 Feb 2006
First Registration Date:	22 Feb 2006
Transfer Count:	1
Actual ARF Paid:	\$1,191.00
Intended PARF/COE Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Feb 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,695.00
COE Rebate Amount:	\$11,212.00
Total Rebate Amount:	\$11,212.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 03 Sep 2018

OK

Net Link Partners Pte Ltd

☆ Posted: 29-Aug-2018 Tags: 2004 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota



☐ Toyota Hiace (COE till 08/2019) \$22,800 \$22,990 /yr 03-Sep-2004 2,986 cc - Van Available

Fuel Type: Diesel

Excellent Condition, New Paint, New Seats! High Loan, High Trade In, 3 Days Delivery, Call Now Before It's Sold!

Net Link Partners Pte Ltd

☆ Posted: 25-Jul-2018 Tags: 2004 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

PREMIUM AD



☐ Toyota Hiace (COE till 02/2022) \$25,000 \$7,160 /yr 14-Oct-2004 2,986 cc - Van Available

Fuel Type: Diesel

COE Left 4 Years.

☆ Posted: 20-Aug-2018 Tags: 2004 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

DIRECT CONTACT



☐ Toyota Hiace (COE till 03/2020) \$15,800 \$10,390 /yr 12-Mar-2005 2,494 cc - Bus Available

Fuel Type: Diesel

Re-furnished In 2016 (Re-spray Vehicle Exterior And Changed All Seats Cushions), Upgraded Radio Set To LCD Screen, Reverse Cam And Dash Cam Are Connect And Can Be View Via The LCD Screen. Vehicle Is W...

☆ Posted: 22-Aug-2018 Tags: 2005 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

DIRECT CONTACT



Lease a car for peace of mind

No worries over hefty repair costs and depreciation with leasing. Find the list of recommended car leasing companies now.

Find out more!



☐ Toyota Hiace (COE till 09/2020) \$18,800 \$9,370 /yr 05-Sep-2005 2,494 cc - Van Available

Fuel Type: Diesel

Cheapest In The Market! Well Maintained By Previous Owner, No Repairs Needed! Wear And Tear Replaced And Very Low Maintenance! Definitely A Workhorse For Your Company Needs. High Trade And Flexible Lo...

Tan Wei Auto Pte Ltd

☆ Posted: 13-Jul-2018 Tags: 2005 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota



☐ Toyota Hiace (COE till 02/2021) \$19,800 \$8,070 /yr 16-Feb-2006 2,494 cc - Van Available

Fuel Type: Diesel

☆ Posted: 29-Aug-2018 Tags: 2006 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota



☐ Toyota Hiace (COE till 12/2020) \$22,800 \$9,790 /yr 22-Feb-2006 2,494 cc - Van Available

Fuel Type: Diesel

Vehicle In Excellent Condition. Just Done Full Polishing. Very Fussy Previous Customer Got All Wear And Tear Replaced. Come With Double Din Radio Set. Call Us Now.

Ezy-1 Pte Ltd

☆ Posted: 22-Aug-2018 Tags: 2006 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

PREMIUM AD



☐ Toyota Hiace (COE till 03/2021) \$18,800 \$7,480 /yr 09-Mar-2006 2,494 cc - Van Available

Fuel Type: Diesel

Please Genuine Buyers Only. Good Condition Paint Works.

☆ Posted: 01-Sep-2018 Tags: 2006 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

DIRECT CONTACT



☐ Toyota Hiace (COE till 04/2021) \$23,800 \$9,200 /yr 05-Apr-2006 2,494 cc - Van Available

Fuel Type: Diesel

The Most Highly Sought After Japanese Commercial Vehicle That Cater Your Business Need. Best Economical Buy, Fuel Efficient Diesel Engine. Call Now For A Non Obligatory Discussion.

Car (S) Pte Ltd

☆ Posted: 03-Sep-2018 Tags: 2006 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

PREMIUM AD



☐ Toyota Hiace (COE till 07/2021) \$23,000 \$7,900 /yr 04-Sep-2006 2,494 cc - Bus Available

Fuel Type: Diesel

Can Convert To School Bus (CB Plate) If Available As Where It Is Condition. Do Not Miss This Opportunity Again. Make An Exclusive Appointment To View Now.

☆ Posted: 20-Aug-2018 Tags: 2006 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

DIRECT CONTACT

SHORTLISTED HISTORY

Compare [3]

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 29 November 2018 8:49 AM
To: Jason Fastech Auto (jason@fastechauto.com.sg)
Subject: RE: Your ref: GZ 2837U *Our ref: CC6/AIG18016083/Apb3 [ACCIDENT INVOLVING SLW 3948H(AIG) & GZ 2837U ON 30/08/2018]

Without Prejudice

Hi Jason,

Further to our below email,

For repair cost, we would like to propose L/sum **\$4,250.00** with **06 repair days**.

Please confirm.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 8 October 2018 2:37 PM
To: Jason Fastech Auto (jason@fastechauto.com.sg) <jason@fastechauto.com.sg>
Subject: Your ref: GZ 2837U *Our ref: CC6/AIG18016083/Apb3 [ACCIDENT INVOLVING SLW 3948H(AIG) & GZ 2837U ON 30/08/2018]

Your ref: **GZ 2837U**
Our ref: CC6/AIG18016083/Apb3

Without Prejudice

Dear Jason,

ACCIDENT INVOLVING SLW 3948H(AIG) & GZ 2837U ON 30/08/2018

We refer to the above matter.

As spoken earlier, attached is a copy of our insured video for your easy reference. There was pre-existing damage on your client's tailgate.

We would like to re-finalise the cost of repair on this matter.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Thursday, 29 November 2018 10:44 AM
To: Hsiao Tong (LKKAUTO)
Subject: RE: Your ref: GZ 2837U *Our ref: CC6/AIG18016083/Apb3 [ACCIDENT INVOLVING SLW 3948H(AIG) & GZ 2837U ON 30/08/2018]

Without Prejudice

Dear Hsiao Tong,

We are agreeable to your recommendation for COR:\$4250 L/S and 06 repair days.

Thank you.

Best Regards

Jason Tang
Kim Chwee Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Thursday, November 29, 2018 8:49 AM
To: Jason Fastech Auto (jason@fastechauto.com.sg) <jason@fastechauto.com.sg>
Subject: RE: Your ref: GZ 2837U *Our ref: CC6/AIG18016083/Apb3 [ACCIDENT INVOLVING SLW 3948H(AIG) & GZ 2837U ON 30/08/2018]

Without Prejudice

Hi Jason,

Further to our below email,

For repair cost, we would like to propose L/sum **\$4,250.00** with **06 repair days**.

Please confirm.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Date : 29.11.2018

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES : GZ 2837U / SLW 3948H ON 30.08.2018

We are the authorized repair workshop for the owner of motor vehicle no: **GZ 2837U**, which was involved in the captioned accident with your insured vehicle no: **SLW 3948H**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$ 4,547.50
2) Loss of Use (6 days + 1 Sunday X S\$100)	\$ 700.00
3) GIA Search Fee	\$ 2.00
	<u>\$ 5,249.50</u>

80 + 7 = 160

We enclosed herewith the following documents to support the claims:

- | | |
|------------------------------------|--------------------------|
| a) Final Repair Invoice | b) GIA Search Result |
| c) Letter of Authorisation, etc... | d) GIA Report |
| e) I/C & Driving Licence | f) Insurance Certificate |
| g) Vehicle Registration Log Card | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)

For KIM CHWEE AUTO PTE LTD

DATE : 03.09.2018

TO : AIG Asia Pacific Insurance Pte Ltd

RE : ACCIDENT INVOLVING VEHICLE NO. GZ2837U, SLW3948H

ALONG PSE TOLUANG CHANGAT BEHIND BAHAR EAT

ON 30/08/2018

I/We, Innotel Solution Pte Ltd

of (NRIC No./ROC No.) 200103103W

of 5014 Ang Mo Kio Avenue 5 # 04-06 Singapore 569881

owner of vehicle no. GZ 2837U in consideration of M/s KIM CHWEE AUTO PTE LTD repairing my/our vehicle GZ 2837U at my/our instruction and hereby authorise M/s KIM CHWEE AUTO PTE LTD to demand claim settlement whatever amount settled/payable by the Insurance Company and/or third party or to commence legal proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use, etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the above-mentioned claim cost which may arise therewith.

Signature of Owner :  _____

Name of Owner : _____

Hsiao Tong (LKKAuto)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Saturday, 8 December 2018 12:40 PM
To: Hsiao Tong (LKKAuto)
Subject: RE: Your ref: GZ 2837U *Our ref: CC6/AIG18016083/Apb3 [ACCIDENT INVOLVING SLW 3948H(AIG) & GZ 2837U ON 30/08/2018]

Without Prejudice

Dear Hsiao Tong,

We are pleased to accept your offer of global sum of \$5,100.00(all-in) for property claim.

Thank you.

Best Regards

Jason Tang
Kim Chwee Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Saturday, December 8, 2018 9:41 AM
To: jason@fastechauto.com.sg
Subject: RE: Your ref: GZ 2837U *Our ref: CC6/AIG18016083/Apb3 [ACCIDENT INVOLVING SLW 3948H(AIG) & GZ 2837U ON 30/08/2018]

Without Prejudice

Hi Jason,

We propose settlement at a global sum of \$5,100.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Thursday, 29 November 2018 11:21 AM

To: 'jason@fastechauto.com.sg' <jason@fastechauto.com.sg>

Subject: RE: Your ref: GZ 2837U *Our ref: CC6/AIG18016083/Apb3 [ACCIDENT INVOLVING SLW 3948H(AIG) & GZ 2837U ON 30/08/2018]

Without Prejudice

Hi Jason,

Noted with thanks.

Kindly submit your LOD and repair invoice to us for our further action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason Fastech Auto <jason@fastechauto.com.sg>

Sent: Thursday, 29 November 2018 10:44 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Your ref: GZ 2837U *Our ref: CC6/AIG18016083/Apb3 [ACCIDENT INVOLVING SLW 3948H(AIG) & GZ 2837U ON 30/08/2018]

Without Prejudice

Dear Hsiao Tong,

We are agreeable to your recommendation for COR:\$4250 L/S and 06 repair days.

Thank you.

Best Regards

Jason Tang
Kim Chwee Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]
Sent: Thursday, November 29, 2018 8:49 AM
To: Jason Fastech Auto (jason@fastechauto.com.sg) <jason@fastechauto.com.sg>
Subject: RE: Your ref: GZ 2837U *Our ref: CC6/AIG18016083/Apb3 [ACCIDENT INVOLVING SLW 3948H(AIG) & GZ 2837U ON 30/08/2018]

Without Prejudice

Hi Jason,

Further to our below email.

For repair cost, we would like to propose L/sum **\$4,250.00** with **06 repair days**.

Please confirm.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Monday, 8 October 2018 2:37 PM

To: Jason Fastech Auto (jason@fastechauto.com.sg) <jason@fastechauto.com.sg>

Subject: Your ref: GZ 2837U *Our ref: CC6/AIG18016083/Apb3 [ACCIDENT INVOLVING SLW 3948H(AIG) & GZ 2837U ON 30/08/2018]

Your ref: **GZ 2837U**

Without Prejudice

Our ref: CC6/AIG18016083/Apb3

Dear Jason,

ACCIDENT INVOLVING SLW 3948H(AIG) & GZ 2837U ON 30/08/2018

We refer to the above matter.

As spoken earlier, attached is a copy of our insured video for your easy reference. There was pre-existing damage on your client's tailgate.

We would like to re-finalise the cost of repair on this matter.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18016083/Apb3

14 SEPT 2018

MAN LIANG TA, ARTHUR (MA LIANGDA, ARTHUR)

528 JELAPANG ROAD

#16-79

SINGAPORE 670528

Dear Sir/Madam,

**ACCIDENT INVOLVING SLW 3948H & GZ 2837U ALONG/AT PIE TOWARDS
PIONEER NORTH ON 30/08/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from GZ 2837U against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG

Case Handler

DID: 6742 3197

FAX: 6741 4108

Email: chewht@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Innotel Solution Pte Ltd ("the third party claimant")
of 5014 Ang Mo Kio Avenue 5 #04-06 Singapore 569881 (address),
owner of GZ 2837U (vehicle no.) hereby authorize
Kim Chwee Auto Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. GZ 2837U that was
damaged pursuant to the accident which occurred on 30-08-2018 (date) along
PIE Towards Changi (location)
involving vehicle no/s SLN 3948H ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 07 day of 09 (month) 20 18 (year)



Signed by "the third party claimant"



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, Kim Chwee Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 5100.00 ^(Global Sum) ~~(repair costs)~~, S\$ _____ (loss of use/rental) S\$ _____ (search fees) for vehicle no. GZ 2837U that was damaged pursuant to the accident which occurred on 30.08.2018 (date) along PIE Towards Changi (location) involving vehicle no/s 2W 3948H.

This is pursuant to the inspection conducted on 03.09.2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Innotel Solution Pte Ltd ("third party claimant") of vehicle no. GZ 2837U to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GZ 2837U (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15th day of 12 (month) 20 18 (year)



LKP

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

TAX INVOICE

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn : Motor Claim Department

Tax Invoice : 20536-001

Date : 29.11.2018

Vehicle No : GZ 2837U

Make/Model : TOYOTA HIACE

Chassis/Eng# :

Accident Date : 30.08.2018

Claim No :

Reference : 0918 -20536

Policy No :

	Amount
To proceed on lump sum repair	S\$ 4250.00

E. & O. E.

Total : S\$ 4250.00

GST @ 7% : S\$ 297.50

Amount Due : **S\$ 4547.50**


for KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-134506

Date of Request: 31/08/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 31/08/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SLW3948H
Accident Date 30/08/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLW3948H	AIG Asia Pacific Insurance Pte. Ltd.	09/02/2018-08/02/2020	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-134506
Date of Request: 31/08/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 31/08/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SLW3948H
Accident Date 30/08/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Aug 2018 Edit Reg		03 Sep 2018 00:00 Edit Adj Rpt	S\$4,250.00 Edit Estimates	S\$4,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	MAN LIANG TA, ARTHUR (MA LIANGDA, ARTHUR), ID: 57932772G								
Main Claimant:	INNOCENT SOLUTION PTE LTD, Co. Reg. No.: 200103103W								
Vehicle Reg. No.:	GZ2837U	Date of Loss:	30/08/2018 17:00 - :59 (150 Months and 8 Days From LTA Reg Date (Man Yr))						
Claim Type:	TP / 3075364200SG	Policy/Cover Note No.:	1800018583 (Comprehensive) Coverage: 09/02/2018 - 08/02/2020						
Vehicle Reg. No. (Insured):	SLW3948H	Policy No. (Claimant):	GA1456044/1						
		Excess:							
Repairer:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/09/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GZ2837U (3075364200SG)**
[SLW3948H]
TP
INNOTECH SOLUTION PTE LTD
Aug 30 2018 5:00PM
[MAN LIANG TA, ARTHUR (MA LIANGDA, ARTHUR)]
Kim Chwee Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		<input type="checkbox"/>			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	04/10/18 11:54	Video - Accident From: OD - Reg. No: SLW3948H, Claimant: MAN LIANG TA, ARTHUR (MA LIANGDA, ARTHUR)													Load MP4					
Letters/Correspondences															1 per page		<input type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown													Edit					
Assessment Reports															1 per page		<input type="checkbox"/>			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	05/09/18 14:10	Accident Statement From: OD - Reg. No: SLW3948H, Claimant: MAN LIANG TA, ARTHUR (MA LIANGDA, ARTHUR)													Load HTM					
Photos/Images															3 per page		<input type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
2	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
3	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
4	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
5	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
6	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
7	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
8	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
9	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
10	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
11	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
12	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
13	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
14	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
15	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
16	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
17	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
18	12/09/18 16:17	General View													Load JPG <input checked="" type="checkbox"/>					
19	12/09/18 16:17	Reinspection Photo													Load JPG <input checked="" type="checkbox"/>					
20	12/09/18 16:17	Reinspection Photo													Load JPG <input checked="" type="checkbox"/>					
21	12/09/18 16:17	Reinspection Photo													Load JPG <input checked="" type="checkbox"/>					
22	12/09/18 16:17	Reinspection Photo													Load JPG <input checked="" type="checkbox"/>					
23	12/09/18 16:17	Reinspection Photo													Load JPG <input checked="" type="checkbox"/>					
24	12/09/18 16:17	Reinspection Photo													Load JPG <input checked="" type="checkbox"/>					
25	12/09/18 16:17	Reinspection Photo													Load JPG <input checked="" type="checkbox"/>					
26	12/09/18 16:17	Reinspection Photo													Load JPG <input checked="" type="checkbox"/>					

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
27	12/09/18 16:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/18 19:09	TP GIA REPORT	 Load PDF	
2	03/10/18 09:03	TP ESTIMATE_MARKED	 Load PDF	
3	24/12/18 11:19	WORKSHOP INVOICE	 Load PDF	
4	24/12/18 11:19	AUTHORISATION TO ACT FORM	 Load PDF	
5	24/12/18 11:19	Release Voucher	 Load PDF	
6	24/12/18 11:19	GIA SEARCH	 Load PDF	
7	24/12/18 11:19	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLW3948H (Insd veh)	Model:	TOYOTA HIACE 2.0 (M)
	GZ2837U (TP veh)		
Date of Accident:	30/08/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	20,081.73
Final Repair Cost	:	\$	5,100.00
Loss of Use	:	\$	7.00 days at \$80.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	5,100.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	:	\$ 5,100.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

24 Dec
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18016083/APB3Q2

Date: 24/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800018583
Claimant Vehicle GZ2837U **Insured Vehicle No :** SLW3948H
No :
 Date of Loss: 30/08/2018 Nature of Claim: TP Claim No: 3075364200SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GZ2837U**
 Make & Model: TOYOTA HIACE, 2.0 (M) Engine No: 2KD1417537
 Reg. Date: 22/02/2006 (Man. Year: 2006) Chassis No: JTFHS02P400038930
 Colour: Silver Odometer: 519615 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,557.97	2,950.32	9,607.65	76.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,210.00	2,340.00	3,870.00	62.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,767.97	5,290.32	13,477.65	71.81
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	18,767.97	4,250.00	14,517.97	77.36
+ GST 7.00/7.00% (S\$)	1,313.76	297.50	1,016.26	77.36
Nett Amount (S\$)	20,081.73	4,547.50	15,534.23	77.36
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,109.50		
Global Sum Settlement (S\$)		5,100.00		

INSPECTION

Date of Assignment: 03/09/2018
 Date Inspected: 03/09/2018 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)
1 Kaki Bukit Avenue 6 #01-48,
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Dented	1,845.50 FL	*877.50 FL
2	1		*REAR BOOT COVER INNER LOCK	Damaged	358.20 FL	*223.00 FL
3	1		*REAR BOOT LOCK ACTUATOR	Not Necessary	491.50 FL	*- FL
4	1		*REAR BOOT LOCK CATCH	Not Necessary	78.90 FL	*- FL
5	1		*REAR BOOT CENTRE EMBLEM	Necessary	66.70 FL	*66.70 FL
6	1		*REAR TOYOTA HIACE STICKER	Necessary	68.70 FL	*68.70 FL
7	1		*REAR BOOT CENTRE GARNISH	Not Necessary	265.50 FL	*- FL
8	1		*REAR BOOT INNER COVER	Not Necessary	547.20 FL	*- FL
9	1		*REAR BOOT RUBBER	Cut	479.80 FL	*387.00 FL
10	2		*REAR BOOT ABSORBER	Not Necessary	723.80 FL	*- FL
11	2		*REAR BOOT HINGE	Not Necessary	202.40 FL	*- FL
12	1		*REAR TAIL LAMP	N/S Cracked	914.20 FL	*291.00 FL
13	1		*REAR TAIL LAMP LOWER GARNISH	N/S Deformed	222.40 FL	*111.20 FL
14	1		*TAILLAMP PANEL LH	Not Necessary	292.50 FL	*- FL
15	1		*REAR END PANEL OUTER	Dented	685.20 FL	*685.20 FL
16	1		*REAR END PANEL INNER	Repair	1,012.60 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	173.80 FL	*- FL
18	2		*REAR NUMBER PLATE LAMP	Not Necessary	170.40 FL	*- FL
19	1		*REAR BUMPER	Deformed	802.20 FL	*384.00 FL
20	2		*REAR BUMPER SIDE RETAINER	Necessary	202.40 FL	*202.40 FL
21	4		*REAR BUMPER LOWER SUPPORT BRACKET	Bent	90.40 FL	*90.40 FL
22	1		*REAR SPARE TYRE CARRIER	Not Necessary	651.20 FL	*- FL
23	1		*REAR SPARE TYRE LOCK SCREW	Not Necessary	246.90 FL	*- FL
24	1		*REAR FLOOR BOARD PANEL	Not Necessary	2,023.80 FL	*- FL
25	1		*REAR EXHAUST PIPE	Not Necessary	725.20 FL	*- FL
26	2		*REAR EXHAUST RUBBER	Not Necessary	70.40 FL	*- FL
27	1		*REAR FENDER LH	Repair	1,747.50 FL	*- FL
28	12		*REAR BOOT INNER COVER CLIPS	Necessary	60.00 FS	*30.00 FS
29	8		*REAR BUMPER LOWER CLIPS	Necessary	40.00 FS	*30.00 FS
30	4		*REAR TAIL LAMP CLIPS	Not Necessary	20.00 FS	*- FS
31	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
32	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
33	3		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	15.00 FS	*- FS
34	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
35	6		*REAR BOOT STICKER	Necessary	25.00 FS	*15.00 FS
36	1		*REAR BOOT STICKER (70KM/H)	Necessary	25.00 FS	*15.00 FS
37	1		*REAR FLOOR BOARD PANEL TOP INSULATOR	Not Necessary	350.00 FS	*- FS
38	1		*SET REAR BUMPER SENSOR	Damaged	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,347.30	3,797.10
- List Item Discount on L Items 25.00/25.00% (S\$)	3,789.33	846.78
Total Parts (S\$)	12,557.97	2,950.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	180.00	30.00
2	TUFF KOTE	New	200.00	50.00
3	TO CUT BODY STICKER	New	1,200.00	450.00
4	REMOVE AND REFIX REAR WINDSCREEN	New	180.00	120.00
5	REMOVE AND REPLACE REVERSE SENSOR	New	150.00	50.00
6	REMOVE AND REPLACE REAR EXHAUST PIPE	New	150.00	0.00
7	REMOVE AND REFIX UPHOLTERY	New	150.00	40.00
8	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	2,000.00	800.00
9	TO SPRAY PAINTING AND ETC	New	2,000.00	800.00
Gross Labour Cost (\$\$)			6,210.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >