

KIM CHWEE AUTO PTE LTD

page 1/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Estimate : 20536

TPA LG.

Xiao Tang.

JT FHS027400038930

Date : 03.09.2018

Vehicle Num : GZ 2837U

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 30.08.2018

Claim No : 0918-20536

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

List Item :

1 pc	Rear boot cover <i>Dented</i>	\$	1,845.50 ¹⁷⁵⁵
1 pc	Rear boot cover inner lock <i>new</i>	\$	356.20 223
1 pc	Rear boot lock actuator <i>new</i>	\$	491.50
1 pc	Rear boot lock catch <i>new</i>	\$	78.90
1 pc	Rear boot centre emblem <i>new</i>	\$	66.70
1 pc	Rear toyota hiace sticker <i>new</i>	\$	68.70
1 pc	Rear boot centre garnish <i>new</i>	\$	265.50
1 pc	Rear boot inner cover <i>new</i>	\$	547.20
1 pc	Rear boot rubber <i>new</i>	\$	479.80 387
2 pc	Rear boot absorber @ 361.90 <i>new</i>	\$	723.80
2 pc	Rear boot hinge @ 101.20 <i>new</i>	\$	202.40
2 pc	Rear tail lamp @ 457.10 <i>LH cracked</i>	\$	914.20 291
2 pc	Rear tail lamp lower garnish @ 111.20 <i>LH Dented</i>	\$	222.40 111.20
1 pc	Taillamp panel LH <i>new</i>	\$	292.50
1 pc	Rear end panel outer <i>Dented</i>	\$	685.20
1 pc	Rear end panel inner <i>Repair</i>	\$	1,012.60
1 pc	Rear end panel top garnish <i>new</i>	\$	173.80
2 pc	Rear number plate lamp @ 85.20 <i>new</i>	\$	170.40
1 pc	Rear bumper <i>Dented</i>	\$	802.20 384
2 pc	Rear bumper side retainer @ 101.20 <i>new</i>	\$	202.40
4 pc	Rear bumper lower support bracker @ 45.20 <i>Best</i>	\$	90.40
1 pc	Rear spare tyre carrier	\$	651.20
1 pc	Rear spare tyre lock screw	\$	246.90
1 pc	Rear floor board panel <i>LH</i>	\$	2,023.80
1 pc	Rear exhaust pipe	\$	725.20
2 pc	Rear exhaust rubber @ 35.20	\$	70.40
1 pc	Rear fender LH <i>Repair</i>	\$	1,747.50
List Item Total :		\$	15,157.30
Discount 25 % :		\$	3,789.33
		\$	11,367.98

426460

315845

KIM CHWEE AUTO PTE LTD

page 2/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Estimate : 20536

Date : 03.09.2018

Vehicle Num : GZ 2837U

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 30.08.2018

Claim No : 0918-20536

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

Special Nett Item :

12pc	Rear boot inner cover clips @ 5.00 <i>new</i>	\$	60.00 30
8 pc	Rear bumper lower clips @ 5.00 <i>new</i>	\$	40.00 30
4 pc	Rear tail lamp clips @ 5.00 <i>new</i>	\$	20.00 +
1 pc	Rear number plate <i>new</i>	\$	45.00 +
1 pc	Rear end panel sealant <i>new</i>	\$	80.00 60
3 pc	Rear end panel top garnish clips @ 5.00 <i>new</i>	\$	15.00 +
1 pc	Rear windscreen sealant <i>new</i>	\$	80.00 60
1 pc	Rear boot sticker (6 pax) <i>2 new</i>	\$	25.00 15
1 pc	Rear boot sticker (70km/h) <i>2 new</i>	\$	25.00 15
1 pc	Rear floor board panel top insulator <i>new</i>	\$	350.00 +
1 set	Rear bumper sensor <i>Damaged</i>	\$	450.00 200
Special Nett Total :		\$	1,190.00

Labour Charge :

To check wiring	\$	180.00 30
Tuff kote	\$	200.00 50
To cut body sticker	\$	1,200.00 450
Remove and refix rear windscreen	\$	180.00 120
Remove and replace reverse sensor	\$	150.00 50
Remove and replace rear exhaust pipe	\$	150.00 x
Remove and refix upholstery	\$	150.00 40
To remove and replace spare part and panel beating	\$	2,000.00 800
To spray painting and etc	\$	2,000.00 800
Labour Charge Total :	\$	6,210.00

To spray painting and etc parts hence notify
 of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

 Signature:
 Date:

KIM CHWEE AUTO PTE LTD

Total Amount : \$ 18,767.98

total: 554845

1/s: A.7K

06 Sep.