

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

30-Aug-18

Our ref : TP/4564/18

The Hardware shop Pte Ltd

TP LCR

1chancha

JTFAT35Y501C2035

RE : estimate cost for vehicle no :GBD 4169B

1 pc	frt w/screen glass	cracked	\$	1,225.47	✓
1 pc	frt w/screen rubber	na		305.00	✓
1 pc	frt panel	cracked		1100.00	✓
1 pc	Dyna emblem	na		65.00	✓
1 pc	frt grille	cracked		550.00	481
1 pc	frt grille logo	na		75.00	✓
6 pcs	frt grille clips	na		33.00	✓
2 pcs	headlamp	cracked		2,400.00	658
1 pc	frt bumper	distorted		485.00	✓
2 pcs	frt bumper bracket	Rt Bent		150.00	75
1 pc	frt rh corner panel	distorted		285.00	✓
2 pcs	frt rh lh garnish	cut		260.00	✓
1 pc	frt centre garnish	cut		310.00	✓
1 pc	frt rh wiper garnish	na		275.00	✓
1 pc	frt rh door	distorted		1,600.00	1310
2 pcs	frt rh door hinges	Best		190.00	✓
1 pc	frt rh door lock	Damaged		286.00	✓
1 pc	frt rh door w/strip	cut		195.00	✓
1 pc	frt rh door trimboard	cracked		565.00	✓
1 pc	frt rh door regulator gear	distorted		375.00	✓
1 pc	frt rh door regulator motor	Rt new		580.00	+
1 pc	frt rh door ledge	Damaged		110.00	✓
1 pc	frt rh door outer handle	Damaged		185.00	✓
1 pc	frt rh door centre lock motor	Damaged		580.00	✓
1 pc	frt rh door outer moulding	delaminated		103.00	✓
1 pc	frt rh door door glass	shattered		225.00	525
1 pc	frt rh door channel	Damaged		220.00	✓
1 pc	frt rh door vertical rubber	Damaged		350.00	✓
1 pc	frt rh door inner handle	Damaged		45.00	✓
1 pc	frt rh door power window switch	na		249.17	+
1 pc	frt rh door speaker	na		265.90	+
1 pc	frt rh door pillart frt	Distorted		370.00	✓
1 pc	frt rh door pillar rear	Rt		449.10	+
1 p/c	D4D emblem	na		46.00	✓
1 pc	frt rh wheel arch panel	Distorted		390.20	✓
1 pc	frt frt wheel arch rubber	cut		100.00	✓
				15497.84	

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : GBD 4169B

Bal brought forward:

\$

15497.84

1 pc	frt rh step panel	3 Distal	390.20	✓
1 pc	frt rh step garnish		300.00	✓
1 pc	frt rh wheel arch garnish	Cracked	48.00	✓
1 pc	floorboard panel	Page	2,569.30	✓
1 pc	dashboard	Cracked	950.00	✓
1 pc	meter box	Cracked	865.00	✓
1 pc	air intake box	Dented	210.30	✓
1 pc	steering box	Dist	985.00	✓
1 pc	steering shaft	Dist	725.00	✓
1 pc	brake pump	2 New	1205.00	✓
1 pc	brake pump bracket	2 New	287.00	✓
1 pc	frt rh shock absorber	2 New	195.00	✓
1 pc	frt rh knuckle arm	2 New	176.60	✓
1 pc	frt rh knuckle bearing top	2 New	116.60	✓
1 pc	frt rh knuckle bearing lower	2 New	153.98	✓
1 pc	frt rh lower arm	2 New	607.00	✓
1 pc	frt rh upper arm	2 New	1,450.00	✓
1 pc	radiator	Dented	1,840.60	✓
1 pc	radiator fan clutch	2 New	779.90	✓
1 pc	radiator fan cowling	2 New	230.00	✓
1 pc	radiator fan blade	2 New	217.00	✓
1 pc	cabin bracket	2 New	456.00	✓
			30,255.41	
less 25%			7,563.85	
			22691.56	
1 pc	frt no plate	2 New	30.00	snett ✓
1 pc	ERP bracket	2 New	26.00	✓
1 pc	body sticker	2 New	10.00	✓
1 pc	frt rh door co logo	2 New	200.00	150 ✓
1 pc	frt rh tyre	2 New	200.00	150 ✓
1 pc	frt rh rim	2 New	200.00	180 ✓
Towing.			60.00	✓
Panel beating.			2800.00	1500 ✓
Spray painting.			2000.00	1400 ✓
Wiring.			30.00	✓
Remove & refit dashboard.			300.00	220 ✓
Transfer door parts.			80.00	✓
Remove & refit frt w/screen.			100.00	✓
			28827.56	

17958.35

13468.51

1637

546

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : GBD 4169B

Bal brought forward:	\$	28827.56
Repair cabin.	4290	800.00 300
Alignment.		80.00 ✓
Remove & refit undercarriage.		300.00 220
		30,007.56
Plus 7% GST		2100.53
		<u>32108.09</u>

SD : Thirty-two thousand one hundred & eight & cents nine only.

Abrian hiny,
L/c 03/09/18
14 Pays.

total: 18305.51
L/s: 14.6K. ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: