

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

**AIG Asia Pacific Insurance Pte. Ltd**  
 AIG Building  
 78 Shenton Way #08-16  
 Singapore (079120)  
 ATTN: MOTOR CLAIM DEPARTMENT  
 Tel : 6419 3000 Fax : 6835 7416

*Not Asharik  
 Uly & ?  
 Return After Pain*

**ACCIDENT REPAIR ON : SGF7189D**  
**MODEL : SUZUKI SWIFT 1.5**  
**POLICY NO : MPC18B00022401**  
**CHASSIS NO : JSAEZC21S00153881**  
**MANUFACTURING YEAR : 2006**  
**DATE / TIME OF ACCIDENT: 02/09/2018 Time: 1100Hrs ALONG OUTSIDE TAGORE AVE**  
**THIRD PARTY VEHICLE NO : GBH167L**

Date: 20/06/2018  
 Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Front Bonnet	1	463.25		<i>B1</i> 463.25 ✓
2	Front Bonnet Hinge LH	1	25.75		<i>R</i> 25.75 X
3	Front Bonnet Hinge RH	1	25.75		<i>R</i> 25.75 X
4	Front Bumper	1	628.15		<i>CM</i> 628.15 ✓
5	Front Bumper Side Retainer LH	1	28.30		<i>D1</i> 28.30 ✓
6	Front Bumper Side Retainer RH	1	28.30		<i>R</i> 28.30 X
7	Front Bumper Centre Bracket	1	38.25		<i>R</i> 38.25 X
8	Front Bumper Upper Grille	1	72.80		<i>SM</i> 72.80 X
9	Front Bumper Grille Emblem	1	20.00		<i>SM</i> 20.00 X
10	Front Bumper Lower Grille	1	73.30		<i>SM</i> 73.30 X
11	Front Bumper Lower Skirt/Spoiler	1	-		-
12	Front Bumper Diffuser LH	1	-		-
13	Front Bumper Fog Lamp Cover LH	1	15.05		<i>SM</i> 15.05 X
14	Front Bumper Sponge Lower	1	92.65		<i>SM</i> 92.65 X
15	Front Bumper Sponge Upper	1	85.35		<i>SM</i> 85.35 X
16	Front Bumper Reinforcement	1	172.75		172.75 ?
17	Front Support Panel Assy	1	535.00		<i>R</i> 535.00 X
18	Front Headlamp LH	1	259.15		<i>BU</i> 259.15 ✓
19	Front Headlamp Bracket LH	1	-		-
20	Front Fender LH	1	235.60		<i>B1</i> 235.60 ✓
21	Front Fender Shield LH	1	63.90		<i>SM</i> 63.90 X
Sub-Total:					2,863.30
Less Discount 15%					429.50
<b>Total Parts:</b>					<b>2,433.81</b>

**Special Nett Items**

1	Anti-rust coating	2	80.00		160.00 <i>60%</i>
2	Front Bonnet Insulator Clips	10	4.00		<i>NE</i> 40.00 ✓
3	Front Bumper Clips	10	4.00		<i>NA</i> 40.00 ✓
4	Front Fender Shield Clips	10	4.00		<i>NA</i> 40.00 X
<b>Total Parts:</b>					<b>280.00</b>

**Labour Charges For Front and Side Portion**

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.
- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
- 3 Provide skill labour to disconnect and check electrical wiring

500

1,250.00

600 750.00

200 30.00

2,030.00

**Total Parts & Labour:** 4,743.81

**GST 7%** 332.07

**Grand Total:** 5,075.87

**Estimate Repair Duration**

6 days

5 days

ACCIDENT VEHICLE OF : SGF7189D

Page : 2 of 2

**Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.**

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : Kenneth  
 Company : LKK  
 Date : 5/9/18  
 Time : 1pm  
 Contact No: 96910663  
 Email : \_\_\_\_\_

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: