

15/9/2019

INS. CASE OWNER:

CC 4/1111801 6096, 14 jbsz

LKK:
IDAC:

Surveyor: WAB

DOI: ASSIGNMENT
1/1/18

Date / Time: 7/9/18

Registered in Merimen: 4/9/18

Pre-assign / CCU / FTE



Insured Vehicle No.: SHL 3777J
Name of Insured: LTOL
Insured Tel No.: _____ HP: _____
Excess Sec II :SS _____ D.O.A: 1/9/18
Is driver the owner? (YES / NO) _____ Nature of Accident: _____
If NO, Driver Name / Age: KOH BEM TALK
Driver Tel No.: _____ (VL: YES / NO)

Claim No.: MUT1009009
Policy No.: MUM00005
Make / Model: MUM0000
Place of Accident: PIE HU ENROS BRIT
OI GIA REPORT: YES / NO: /
TP GIA REPORT: YES / NO: /
Insured Liability: % _____ Final ? Yes / No

SLA 2609C



INSRS: _____
WSP: World Auto
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

| Date/ Time | | STAGE | DATE / PIC |
|----------------|--|--|-------------------------------------|
| <u>11/9/18</u> | <u>SLA 2605C - X</u> | Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI: | |
| <u>20/6/19</u> | <u>liability clear via merimen</u> | Documentation Check List: Handler Typist | |
| <u>21/7/19</u> | <u>File pass to typist type report</u> | Notification ltr (if non-pickup) | <input checked="" type="checkbox"/> |
| <u>21/7/19</u> | <u>seek manda via merimen</u> | After call ltr to OI: | <input checked="" type="checkbox"/> |
| <u>21/7/19</u> | <u>manda approve via merimen</u> | Authorisation To Act: | <input checked="" type="checkbox"/> |
| <u>17/9</u> | <u>dv in file pass to cuu</u> | Release Voucher: | <input checked="" type="checkbox"/> |
| <u>17/9/19</u> | <u>File pass to LSP to close</u> | Final Repair Bill: | <input checked="" type="checkbox"/> |
| | | Car Rental Invoice: | <input checked="" type="checkbox"/> |
| | | Towing Invoice: | <input checked="" type="checkbox"/> |
| | | LTA / GIA: | <input checked="" type="checkbox"/> |
| | | Medical Bill: | <input checked="" type="checkbox"/> |
| | | PIR: | <input checked="" type="checkbox"/> |
| | | Mandate/Reject Instruction: | <input checked="" type="checkbox"/> |
| | | LOD: | <input checked="" type="checkbox"/> |
| | | Payment Breakdown Form: | <input checked="" type="checkbox"/> |
| | | Post-Repair Photos: | <input checked="" type="checkbox"/> |
| | | Others: | <input checked="" type="checkbox"/> |

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$S _____ (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with Sophia Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia: _____

Repair Cost: \$S 13202.20

Loss of Rental (LOR): \$S _____ (_____ days)

Loss of Use (LOU): \$S 8400.00 (\$ 60 x 14 days)

Loss of Income (LOI): \$S _____ (\$ _____ x _____ days)

LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIALTA Search: \$S _____

Medical: \$S _____

Disbursement: \$S _____ (e.g. Tow/Independent)

Legal Cost: \$S _____

Total: \$S 14042.20 Global Sum \$S: 14000.00

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S 14000.00 Name 1: World Auto Pte Ltd

Payee 2: (Strike if N.A.) \$S _____ Name 2: _____

Payee 3: (Strike if N.A.) \$S _____ Name 3: _____

COPY SENT 18/9/19

1) Claim status: Normal/Reject/Private Settle
2) Report Format: OT
3) Survey fee: #6001-

08/11/13 wof
ASS REC HY: NAZ

REF: III

ASSIGNMENT

From: Date: 14/11/18
Estimated Cost:
OP / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLQ 7605C
at Workshop m/s: World Auto
of: No.1 Kranji Loop
Insured:
Policy No:
Claims No:
Sum Insured: Excess:
(Client's Record)
Make of Veh:

Veh No: SLQ 7605C Yr Regn: 21 Jul 2017
Type: MCar / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: TOYOTA PR14 c.c. 1,798
Colour: WHITE A/C: Insured / Std / NI / NA
Sp. Reading: 84,790 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: JTDKB3FU503562229
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD / R/Rim or
Tyre Size: F: 195/65 R15
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 1/9/18 D.O.I. 5/9/18

Bal. or Market Value:
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 14 days Res.: Yes or No
Lum Sum: 2.82 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS 1cp
Date: Person Contacted: Vehicle: IN / OUT

Survey held at: WORLD AUTO
Des. of Damages: Frt (Rear) OIS / NIS / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|---|
| 20/11/19 | Confirm 2.82 @ 12338.50 with 14 working days III P1P (Pd = \$ 9656.00 44%) |

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

Date/Time, File Return to?

1)

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

| | |
|-----------------|-------------|
| Survey Fee: | |
| Transportation: | \$ + RS, \$ |
| Photos: | |
| Others: | |
| TOTAL | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC4/III18016096/Njb3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 04-09-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-----------|----------------|------------|
| Insured Veh. | SHC 3333J | Veh. Inspected | SLQ 7605C |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 04/09/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|--------|--------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| |
|--|
| |
|--|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 01/09/2018 | Inspection Date | 05/09/2018 |
| Survey held at | WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

Reg: 21/7/17

Chassis: J1D83FU50

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Estimate : ES000322

Date : 03/09/2018
 Vehicle Num. : SLQ 7605C(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 01/09/2018
 Claim No. :
 Reference :
 Policy No. :

Attention : Motor Claim Department
 Contact : 6223 8122

S/N Quantity Particular Unit Price Amount S\$

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|--------------|----------|---------------------------------|------------|------------|
| LIST ITEMS : | | | | |
| 1. | 1 | REAR BOOT LID | | 1,400.00 |
| 2. | 1 | REAR BOOTLID OUTER GARNISH | | 570.00 |
| 3. | 1 | REAR BOOT HYBRID EMBLEM (PRIUS) | | 89.00 |
| 4. | 1 | REAR BOOT PRIUS EMBLEM | | 89.00 |
| 5. | 1 | REAR WINDSCREEN GLASS MOULDING | | 250.00 |
| 6. | 1 | REAR WINDSCREEN LOWER MOULDING | | 180.00 |
| 7. | 1 | REAR BOOT INNER TRIM BOARD | | 350.00 |
| 8. | 1 | REAR BOOT WEATHER STRIP | | 280.00 |
| 9. | 1 | REAR BOOT LOCK ASSY | | 280.00 |
| 10. | 1 | REAR BOOT LOCK SWITCH | | 180.00 |
| 11. | 1 | REAR BOOT LOCK CATCH | | 110.00 |
| 12. | 2/LH,RH | REAR TAIL LAMP | 900.00 | 1,800.00 |
| 13. | 1 | REAR BOOT HAND GRIP COVER | | 120.00 |
| 14. | 1 | REAR BOOT ABSORBER | | 190.00 |
| 15. | 1 | REAR BOOT STOPPER | | 110.00 |
| 16. | 1 | REAR BUMPER | | 900.00 |
| 17. | 2/LH,RH | REAR BUMPER TAILLAMP | 600 | 1,200.00 |
| 18. | 1 | REAR END PANEL | 600 | 600.00 |
| 19. | 1 | REAR END PANEL TOP GARNISH | | 750.00 |
| 20. | 1 | REAR BUMPER REINFORCEMENT | | 280.00 |
| 21. | 1 | REAR FLOOR BOARD | | 350.00 |
| 22. | 2/LH,RH | REAR TAILLAMP PANEL | 300 | 600.00 |
| 23. | 2/LH,RH | REAR FENDER | | 950.00 |
| 24. | 2/LH,RH | REAR FENDER INNER TRIM BOARD | | 345.00 |
| 25. | 2/LH,RH | REAR FENDER UNDERDUST COVER | | 250.00 |
| 26. | 2/LH,RH | REAR FENDER AIR GRILLE | | 140.00 |
| 27. | 1 | REAR BUMPER WRING | 150 | 150.00 |
| 28. | 1 | REAR BUMPER TOW COVER | | 100.00 |
| 29. | 2/LH,RH | REAR BUMPER UNDERDUST COVER | | 240.00 |
| | | | | 7,668 |

CONTINUE / ...

Jay

Finalized

31/5/19

Naz

14188

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000322

Date : 03/09/2018
 Vehicle Num. : SLQ 7605C(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 01/09/2018
 Claim No. :
 Reference :
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

- 30. 1 REAR BUMPER CENTER DUST COVER
- 31. 1 REAR LOWER BUMPER
- 32. 2/LH,RH REAR BUMPER EXTENSION FILLER
- 33. 1 REAR ANTENNA SENSOR
- 34. 1 REAR BOOT SPARE TYRE PANEL
- 35. 2/LH,RH REAR BOOT TOOLKIT FOAM BOX
- 36. 2/LH,RH REAR BUMPER RETAINER

400
 230.00
 570.00
 460.00
 188.00
 60.00
 60.00
 240.00
 18,286.00
 4,571.50
 13,714.50

BT
 DD
 RHCRA CH
 DT
 BT
 LH SUC, RH ?XSUC

RH/CRA
 ? LH X SUC

12,286
 12,964.50

List Total S\$:
 25.00% Discount S\$:

- SPECIAL NETT ITEMS :
- 1. 1 REAR BOOTLID OUTER GARNISH CLIPS
 - 2. 1 REAR BOOT INNER TRIM BOARD CLIP
 - 3. 1 REAR BUMPER CLIP
 - 4. 1 REAR END PANEL TOP GARNISH CLIPS
 - 5. 2/LH,RH REAR FENDER INNER TRIM BOARD CLIPS
 - 6. 2/LH,RH REAR FENDER UNDERDUST COVER CLIPS
 - 7. 2/LH,RH REAR BUMPER UNDERDUST COVER CLIP
 - 8. 1 REAR BUMPER CENTER DUST COVER CLIP
 - 9. 1 REAR NUMBER PLATE W/CASING
 - 10. 1 REVERSE SENSOR
 - 11. 2PC REAR WINDSCREEN SEALANT

40.00
 40.00
 40.00
 40.00
 40.00
 40.00
 40.00
 40.00
 40.00
 280.00
 240.00
 1,000.00
 180.00

all
 all
 all
 all
 all
 all
 all
 all
 all
 CRA
 all
 all
 1,000
 60

Special Nett Total S\$:

LABOUR :
 TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000322

Date : 03/09/2018
 Vehicle Num. : SLQ 7605C(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 01/09/2018
 Claim No. :
 Reference :
 Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|--|------------|-------------|
| | | REMOVE & REFIT REAR WINDSCREEN GLASS (2PC WINDSCREEN GLASS) | 360.00 | 2 10 |
| | | TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS. | 200.00 | 100 |
| | | TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS. | 3,000.00 | 2,400 1,500 |
| | | TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS (PEARL WHITE) | 2,600.00 | 2,000 1,500 |
| | | TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS. | 380.00 | 240 |
| | | TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS. | 380.00 | 120 |
| | | TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS | 180.00 | 50 |
| | | Labour Total S\$: | 7,280.00 | 3,780 |

E. & O.E.

Total S\$: 21,994.50

=====

21,244.50
21,394.50

for WORLD AUTO PTE LTD

PARTS \$10,078
 LESS 25% \$7,558.50
 S/NETT \$1,000
 LABOUR \$3,780

\$12,338.50 / 12 DAYS

N/A LKK
 5/9/18 1300
 P/P
 14 DAYS
 BEFORE PAINT 11:30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD **Supplementary Estimate : ES000341**

64 CECIL ST #04-05 IOB BUILDING
049711

Attention : Motor Claim Department
Contact : 6223 8122

Date : 12/09/2018
Vehicle Num. : SLQ 7605C(LCR)
Make/Model : TOYOTA PRIUS HYBRID
Chassis/Eng# :
Accident Date : 01/09/2018
Claim No. :
Reference :
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

- | | | | | |
|----|---|-----------------------------------|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | REAR BOOT SPARE TYRE LOCKING BOLT | | |
| | | REAR BOOT TOYOTA LOGO | | |

List TotalS\$:
25.00% Discount S\$:

| | |
|--------|-----|
| 110.00 | BT |
| 90.00 | SCR |
| 200.00 | |
| 50.00 | 120 |
| 150.00 | |

E. & O.E.

Total S\$: 150.00

for WORLD AUTO PTE LTD



WORLD AUTO PTE LTD PO:
47 JALAN PEMIMPIN #01-
02/03
HALCYON 2
SINGAPORE 577200

PURCHASE ORDER

Date: 5/9/18

Supplier

| S/N | Parts name | Parts number | QTY | Unit Price | Inv No |
|-----|---------------------------------|----------------|-----|------------|------------|
| 1 | | 67005-47440 | 1 | | DL19207528 |
| 2 | Rear Tailgate Outer Garnish | 76801-47110-A0 | 1 | A340 | DL19207570 |
| 3 | () | Used | 1 | | |
| 4 | Rear Tailgate Prius Emblem | 75442-47130 | 1 | | DL19207570 |
| 5 | Rear Windscreen Glass Moulding | Used | 1 | | |
| 6 | Rear Windscreen Lower Moulding | Used | 1 | | |
| 7 | Rear Tailgate Inner Trim Board | 67750-47080 | 1 | A200 | Kranji |
| 8 | Rear Tailgate Weather Strip | 67881-47050 | 1 | " | DL19207570 |
| 9 | Rear Tailgate Hand Grip Cover | 74811-47070-C0 | 1 | | DL19207570 |
| 10 | Rear Bumper | 52159-47913 | 1 | | DL19207570 |
| 11 | Rear End Panel | 58307-47090 | 1 | | DL19207570 |
| 12 | Rear End Panel Top Garnish | 64716-47130 | 1 | | DL19207570 |
| 13 | Rear Bumper Reinforcement | 52023-47030 | 1 | | DL19207570 |
| 14 | Rear Floor Board | | 1 | | Kranji |
| 15 | Rear Fender Inner Trim Board RH | 64730-47240-C2 | 1 | 230 | DL19207570 |
| 16 | Rear Bumper Tow Cover | 52169-47020 | 1 | | DL19207570 |
| 17 | Rear Bumper Underdust Cover RH | 58348-47050 | 1 | | DL19207570 |
| 18 | Rear Bumper Underdust Cover LH | 58349-47050 | 1 | | DL19207570 |
| 19 | Rear Bumper Center Dust Cover | 66759-47010 | 1 | | DL19207570 |
| 20 | Rear Lower Bumper | 52453-47010 | 1 | | DL19207570 |

Ordered by:

Authorised by:



WORLD AUTO PTE LTD PO:
 47 JALAN PEMIMPIN #01-
 02/03
 HALCYON 2
 SINGAPORE 577200

PURCHASE ORDER

Date: 5/9/18

Supplier

Vehicle NO: SLQ 7605 C T. Prius Hybrid (TP)

| S/N | Parts name | Parts number | QTY | Unit Price | Inv No |
|-----------|---------------------------------|-----------------|-----|------------|------------|
| 1 | Rear Boot Spare Tyre Panel | 58311-47130 | 1 | | DL19207570 |
| 2 | Rear Boot Toolkit Foam Box RH | 64935-47050 | 1 | #170 | Kranji |
| 3 | Rear Boot Toolkit Foam Box LH | | 1 | #170 | Kranji |
| 4 | Rear Number Plate With Casing | | 1 | ? | |
| 5 | Reverse Sensor | TPC507-47001 23 | 1 | ... | DL19207570 |
| 6 | Rear Bumper Tail Lamp RH | 81581-47010 | 1 | #170 | Kranji |
| 7 | Rear Bumper Wring | 82183-47020 | 1 | | DL19207576 |
| 8 | Rear Bumper Extension Filler RH | 52565-47900 | 1 | | DL19207570 |
| 9 | Rear Antenna Sensor | 84997-30100 | 1 | | DL19207570 |
| 10 | Rear Fender Inner Trim Board LH | 64740-47150-02 | 1 | | DL19207600 |
| Extra) 11 | Spare Tyre Bolt | 51931-22040 | 1 | | DL19207570 |
| Extra) 12 | Rear Tailgate Emblem | 75403-48010 | 1 | | Kranji |
| 13 | | | | | |
| 14 | | | | | |
| 15 | | | | | |
| 16 | | | | | |
| 17 | | | | | |
| 18 | | | | | |
| 19 | | | | | |
| 20 | | | | | |

Ordered by:

Authorised by:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000322

Date : 03/09/2018
 Vehicle Num. : SLQ 7605C(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 01/09/2018
 Claim No. :
 Reference :
 Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|--------------|----------|---------------------------------|------------|------------|
| LIST ITEMS : | | | | |
| 1. | 1 | REAR BOOT LID | | 1,400.00 |
| 2. | 1 | REAR BOOTLID OUTER GARNISH | | 570.00 |
| 3. | 1 | REAR BOOT HYBRID EMBLEM (PRIUS) | | 89.00 |
| 4. | 1 | REAR BOOT PRIUS EMBLEM | | 89.00 |
| 5. | 1 | REAR WINDSCREEN GLASS MOULDING | | 250.00 |
| 6. | 1 | REAR WINDSCREEN LOWER MOULDING | | 180.00 |
| 7. | 1 | REAR BOOT INNER TRIM BOARD | | 350.00 |
| 8. | 1 | REAR BOOT WEATHER STRIP | | 280.00 |
| 9. | 1 | REAR BOOT LOCK ASSY | | 280.00 |
| 10. | 1 | REAR BOOT LOCK SWITCH | | 180.00 |
| 11. | 1 | REAR BOOT LOCK CATCH | | 110.00 |
| 12. | 2/LH,RH | REAR TAIL LAMP | 900.00 | 1,800.00 |
| 13. | 1 | REAR BOOT HAND GRIP COVER | | 120.00 |
| 14. | 1 | REAR BOOT ABSORBER | | 190.00 |
| 15. | 1 | REAR BOOT STOPPER | | 110.00 |
| 16. | 1 | REAR BUMPER | | 900.00 |
| 17. | 2/LH,RH | REAR BUMPER TAILLAMP | 750.00 | 1,500.00 |
| 18. | 1 | REAR END PANEL | | 750.00 |
| 19. | 1 | REAR END PANEL TOP GARNISH | | 280.00 |
| 20. | 1 | REAR BUMPER REINFORCEMENT | | 350.00 |
| 21. | 1 | REAR FLOOR BOARD | | 350.00 |
| 22. | 2/LH,RH | REAR TAILLAMP PANEL | 450.00 | 900.00 |
| 23. | 2/LH,RH | REAR FENDER | 950.00 | 1,900.00 |
| 24. | 2/LH,RH | REAR FENDER INNER TRIM BOARD | 345.00 | 690.00 |
| 25. | 2/LH,RH | REAR FENDER UNDERDUST COVER | 250.00 | 500.00 |
| 26. | 2/LH,RH | REAR FENDER AIR GRILLE | 140.00 | 280.00 |
| 27. | 1 | REAR BUMPER WRING | | 180.00 |
| 28. | 1 | REAR BUMPER TOW COVER | | 100.00 |
| 29. | 2/LH,RH | REAR BUMPER UNDERDUST COVER | 240.00 | 480.00 |

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000322

Date : 03/09/2018
 Vehicle Num. : SLQ 7605C(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 01/09/2018
 Claim No. :
 Reference :
 Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

| | | | | | |
|-----------------------|---------|-------------------------------|--------|-----------|--------------|
| 30. | 1 | REAR BUMPER CENTER DUST COVER | | 230.00 | BT |
| 31. | 1 | REAR LOWER BUMPER | | 570.00 | DD |
| 32. | 2/LH,RH | REAR BUMPER EXTENSION FILLER | 230.00 | 460.00 | RHCRA, CH? |
| 33. | 1 | REAR ANTENNA SENSOR | | 188.00 | ? |
| 34. | 1 | REAR BOOT SPARE TYRE PANEL | | 680.00 | BT |
| 35. | 2/LH,RH | REAR BOOT TOOLKIT FOAM BOX | 380.00 | 760.00 | BT |
| 36. | 2/LH,RH | REAR BUMPER RETAINER | 120.00 | 240.00 | LIT SVC, RH? |
| List TotalS\$: | | | | 18,286.00 | |
| 25.00% Discount S\$: | | | | 4,571.50 | |
| | | | | 13,714.50 | |

SPECIAL NETT ITEMS :

| | | | | | |
|-----|---------|------------------------------------|--------|--------|-----|
| 1. | 1 | REAR BOOTLID OUTER GARNISH CLIPS | | 40.00 | acc |
| 2. | 1 | REAR BOOT INNER TRIM BOARD CLIP | | 40.00 | acc |
| 3. | 1 | REAR BUMPER CLIP | | 40.00 | acc |
| 4. | 1 | REAR END PANEL TOP GARNISH CLIPS | | 40.00 | acc |
| 5. | 2/LH,RH | REAR FENDER INNER TRIM BOARD CLIPS | 40.00 | 80.00 | acc |
| 6. | 2/LH,RH | REAR FENDER UNDERDUST COVER CLIPS | 40.00 | 80.00 | acc |
| 7. | 2/LH,RH | REAR BUMPER UNDERDUST COVER CLIP | 40.00 | 80.00 | acc |
| 8. | 1 | REAR BUMPER CENTER DUST COVER CLIP | | 40.00 | acc |
| 9. | 1 | REAR NUMBER PLATE W/CASING | | 40.00 | CRA |
| 10. | 1 | REVERSE SENSOR | | 280.00 | acc |
| 11. | 2PC | REAR WINDSCREEN SEALANT | 120.00 | 240.00 | acc |

Special Nett Total S\$:

1,000.00

LABOUR :

TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES

180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000322

Date : 03/09/2018
 Vehicle Num. : SLQ 7605C(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 01/09/2018
 Claim No. :
 Reference :
 Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|--|---------------------|------------|
| | | REMOVE & REFIT REAR WINDSCREEN GLASS (2PC WINDSCREEN GLASS) | 360.00 | 210 |
| | | TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS. | 200.00 | 100 |
| | | TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS. | 3,000.00 | 2,400 |
| | | TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS (PEARL WHITE) | 2,600.00 | 2,000 |
| | | TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS. | 380.00 | 240 |
| | | TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS. | 380.00 | 120 |
| | | TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS | 180.00 | 50 |
| | | Labour Total S\$: | | 7,280.00 |

E. & O.E.

Total S\$: 21,994.50
 =====

for WORLD AUTO PTE LTD

NAR LKIC
 5/9/18 1300
 P/P
 14 DAYS
 BEFORE PAINT FIBRO

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 3 September, 2018 3:50 PM
To: ainee31@worldauto.com.sg; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: 'Daniel Tan'; Sundari Nagarajan - III
Subject: RE: Request for Third Party Motor Claim Survey (SLQ7605C) DOA: 01-09-2018

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLQ7605C and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

03092018 C 452pm
Ainee veh in.
04092018

From: ainee31@worldauto.com.sg [mailto:ainee31@worldauto.com.sg]
Sent: 03 September, 2018 2:03 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: 'Daniel Tan' <worldautopl@yahoo.com.sg>
Subject: RE: Request for Third Party Motor Claim Survey (SLQ7605C) DOA: 01-09-2018

DEAR ALL

- LKK Auto Consultants Pte Ltd

Ainee

Thanks and Rgds,

World Auto Pte Ltd

Kranji: 63621776

Fax: 63631250

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, September 3, 2018 1:59 PM
To: ainee31@worldauto.com.sg
Cc: 'Daniel Tan' <worldautopl@yahoo.com.sg>
Subject: RE: Request for Third Party Motor Claim Survey (SLQ7605C) DOA: 01-09-2018

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: [aine31@worldauto.com.sg](mailto:ainee31@worldauto.com.sg) [<mailto:ainee31@worldauto.com.sg>]

Sent: 03 September, 2018 9:55 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: 'Daniel Tan' <worldautopl@yahoo.com.sg>

Subject: Request for Third Party Motor Claim Survey (SLQ7605C) DOA: 01-09-2018

Good morning/afternoon,

We would like to request for a third party motor claim survey, details as follow;

Our Vehicle: SLQ7605C

Your Insured: SHC3333J

DOA: 01-09-2018

Our vehicle is currently in the workshop, address as follow;

World Auto Pte Ltd

No.1, Kranji Loop

Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee

Thanks and Rgds,

World Auto Pte Ltd

Kranji: 63621776

Fax: 63631250

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***SLQ7605C (MCT18090019)**
[SHC3333J]
TP
LCRF PTE LTD
Sep 1 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
World Auto Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 03/07/2019 09:22 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14042.20) - SLQ7605C - Claim Handler: Sundari Nagarajan

Approved:14042.20:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
|------|---|---------------|--|---|---|-------------|---|
| Main | 01 Sep 2018 Edit Reg | | 03 Sep 2018 00:00 Edit Adj Rpt | S\$12,338.50 Edit Estimates | S\$12,338.50 View Rpt | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

| | | | |
|-----------------------------|--|------------------------|--|
| Insured: | COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: - | | |
| Main Claimant: | LCRF PTE LTD , Co. Reg. No.: 20162497K | | |
| Vehicle Reg. No.: | SLQ7605C | Date of Loss: | 01/09/2018 00:00 - :59 [13 Months and 11 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / MCT18090019 | Policy/Cover Note No.: | MCOM0015 |
| Vehicle Reg. No. (Insured): | SHC3333J | Policy No. (Claimant): | 999995174 |
| | | Excess: | |
| Repairer: | World Auto Pte Ltd - Halcyon 2 (HQ) 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG, 577200 Bishan - Tel: 6451 3933 | | |
| Handling Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071] | | |
| Claimant's Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 13/09/2018] | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (03/07/2019): Alert - Adj Mandate Approved (S\$14042.20) - SLQ7605C - Claim Handler: Sundari Na...
- III_SG (14/09/2018): Alert - Adj Mandate Approved (S\$0.00) - SLQ7605C - Claim Handler: Sundari Nagara...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

***SLQ7605C (MCT18090019)**
[SHC3333J]
TP
LCRF PTE LTD
Sep 1 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
World Auto Pte Ltd - Halcyon 2

| Upload Documents Upload Photos Compose New Letter | | | View | View in Browser ▼ |
|---|-----------------|-----------------------------------|--|-------------------------------------|
| Photos/Images | | | 3 per page ▼ | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 06/09/18 22:58 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 13/09/18 09:12 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 13/09/18 09:12 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 13/09/18 09:12 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 13/09/18 09:12 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 13/09/18 09:12 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 13/09/18 09:12 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 13/09/18 09:12 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 13/09/18 09:12 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 13/09/18 09:12 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 13/09/18 09:12 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 13/09/18 09:12 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18016096/NGB3S2
Date: 18/09/2019

REFERENCE

| | | | |
|-----------------------|---------------------------------------|----------------------|-------------|
| Handling Insurer: | India International Insurance Pte Ltd | Policy No: | MCOM0015 |
| Claimant Vehicle No : | SLQ7605C | Insured Vehicle No : | SHC3333J |
| Date of Loss: | 01/09/2018 | Nature of Claim: | TP |
| | | Claim No: | MCT18090019 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SLQ7605C | Engine No: | HIDDEN |
| Make & Model: | TOYOTA PRIUS, 1.8 HYBRID CVT (A) | Chassis No: | JTDKB3FU503562229 |
| Reg. Date: | 21/07/2017 (Man. Year: 2017) | Odometer: | 84790 km |
| Colour: | White | | |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition: | Fair | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 195/65R15 | Rear Tyre Size: | 195/65R15 |
| Front Left Side: | Pirelli 5 mm | Rear Left Side: | Pirelli 5 mm |
| Front Right Side: | Pirelli 5 mm | Rear Right Side: | Pirelli 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------------------------|------------------|-----------------|--------------|
| Parts | 14,114.50 | 8,558.50 | 5,556.00 | 39.36 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 7,280.00 | 3,780.00 | 3,500.00 | 48.08 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 21,394.50 | 12,338.50 | 9,056.00 | 42.33 |
| + GST 7.00/7.00% (S\$) | 1,497.62 | 863.70 | 633.92 | 42.33 |
| Nett Amount (S\$) | 22,892.12 | 13,202.20 | 9,689.92 | 42.33 |
| + Loss of Use (14.0 x S\$60.00/day) (S\$) | | 840.00 | | |
| | Nett Liability (S\$) | 14,042.20 | | |
| | Global Sum Settlement (S\$) | 14,000.00 | | |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 03/09/2018 | | |
| Date Inspected: | 05/09/2018 | Inspected At: | NO.1 KRANJI LOOP Repairer: World Auto Pte Ltd |
| Estimated Period of Repair: | 14.0 days | | |

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 18 Sep 2019)**Parts:** 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLQ7605C)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|--------------------------------|-------------|--------------|
| 1 | 1 | | *REAR BOOT LID | Dented | 1,400.00 FL | *1,000.00 FL |
| 2 | 1 | | *REAR BOOTLID OUTER GARNISH | Cracked | 570.00 FL | *400.00 FL |
| 3 | 1 | | *REAR BOOT HYBRID EMBLEM (PRIUS) | Necessary | 89.00 FL | *89.00 FL |
| 4 | 1 | | *REAR BOOT PRIUS EMBLEM | Necessary | 89.00 FL | *89.00 FL |
| 5 | 1 | | *REAR WINDSCREEN GLASS MOULDING | Necessary | 250.00 FL | *250.00 FL |
| 6 | 1 | | *REAR WINDSCREEN LOWER MOULDING | Necessary | 180.00 FL | *180.00 FL |
| 7 | 1 | | *REAR BOOT INNER TRIM BOARD | Cracked | 350.00 FL | *350.00 FL |
| 8 | 1 | | *REAR BOOT WEATHERSTRIP | Distorted | 280.00 FL | *280.00 FL |
| 9 | 1 | | *REAR BOOT LOCK ASSY | Serviceable | 280.00 FL | *- FL |
| 10 | 1 | | *REAR BOOT LOCK SWITCH | Serviceable | 180.00 FL | *- FL |
| 11 | 1 | | *REAR BOOT LOCK CATCH | Serviceable | 110.00 FL | *- FL |
| 12 | 1 | | *LH,RH REAR TAIL LAMP | O/s Cracked / N/s Serviceable | 1,800.00 FL | *500.00 FL |
| 13 | 1 | | *REAR BOOT HAND GRIP COVER | Dented | 120.00 FL | *120.00 FL |
| 14 | 1 | | *REAR BOOT ABSORBER | Serviceable | 190.00 FL | *- FL |
| 15 | 1 | | *REAR BOOT STOPPER | Serviceable | 110.00 FL | *- FL |
| 16 | 1 | | *REAR BUMPER | Cracked | 900.00 FL | *600.00 FL |
| 17 | 1 | | *LH,RH REAR BUMPER TAILLAMP | O/s Cracked / N/s Serviceable | 1,500.00 FL | *600.00 FL |
| 18 | 1 | | *REAR END PANEL | Dented | 750.00 FL | *600.00 FL |
| 19 | 1 | | *REAR END PANEL TOP GARNISH | Distorted | 280.00 FL | *280.00 FL |
| 20 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 350.00 FL | *350.00 FL |
| 21 | 1 | | *REAR FLOOR BOARD | Cracked | 350.00 FL | *350.00 FL |
| 22 | 1 | | *LH,RH REAR TAILLAMP PANEL | O/s Deformed / N/s Serviceable | 900.00 FL | *300.00 FL |
| 23 | 2 | | *LH,RH REAR FENDER | Serviceable | 900.00 FL | *- FL |
| 24 | 2 | | *LH,RH REAR FENDER INNER TRIM BOARD | Distorted | 690.00 FL | *600.00 FL |
| 25 | 2 | | *LH,RH REAR FENDER UNDERDUST COVER | Serviceable | 500.00 FL | *- FL |
| 26 | 2 | | *LH,RH REAR FENDER AIR GRILLE | Serviceable | 280.00 FL | *- FL |
| 27 | 1 | | *REAR BUMPER WIRING | Torn | 180.00 FL | *150.00 FL |
| 28 | 1 | | *REAR BUMPER TOW COVER | Missing | 100.00 FL | *100.00 FL |
| 29 | 2 | | *LH,RH REAR BUMPER UNDERDUST COVER | Dented | 480.00 FL | *480.00 FL |
| 30 | 1 | | *REAR BUMPER CENTER DUST COVER | Bent | 230.00 FL | *230.00 FL |
| 31 | 1 | | *REAR LOWER BUMPER | Dented | 570.00 FL | *400.00 FL |
| 32 | 1 | | *LH,RH REAR BUMPER EXTENSION FILLER | O/s Cracked / N/s Serviceable | 460.00 FL | *230.00 FL |
| 33 | 1 | | *REAR ANTENNA SENSOR | Cracked | 188.00 FL | *150.00 FL |
| 34 | 1 | | *REAR BOOT SPARE TYRE PANEL | Dented | 680.00 FL | *680.00 FL |
| 35 | 2 | | *LH,RH REAR BOOT TOOLKIT FOAM BOX | Bent | 760.00 FL | *600.00 FL |
| 36 | 2 | | *LH,RH REAR BUMPER RETAINER | Serviceable | 240.00 FL | *- FL |
| 37 | 1 | | *REAR BOOTLID OUTER GARNISH CLIPS | Necessary | 40.00 FS | *40.00 FS |
| 38 | 1 | | *REAR BOOT INNER TRIM BOARD CLIP | Necessary | 40.00 FS | *40.00 FS |
| 39 | 1 | | *REAR BUMPER CLIP | Necessary | 40.00 FS | *40.00 FS |
| 40 | 1 | | *REAR END PANEL TOP GARNISH CLIPS | Necessary | 40.00 FS | *40.00 FS |
| 41 | 2 | | *LH,RH REAR FENDER INNER TRIM BOARD CLIPS | Necessary | 80.00 FS | *80.00 FS |
| 42 | 2 | | *LH,RH REAR FENDER UNDERDUST COVER CLIPS | Necessary | 80.00 FS | *80.00 FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|-----------|------------|------------|
| 43 | 2 | | *LH,RH REAR BUMPER UNDERDUST COVER CLIP | Necessary | 80.00 FS | *80.00 FS |
| 44 | 1 | | *REAR BUMPER CENTER DUST COVER CLIP | Necessary | 40.00 FS | *40.00 FS |
| 45 | 1 | | *REAR NUMBER PLATE W/CASING | Cracked | 40.00 FS | *40.00 FS |
| 46 | 1 | | *REVERSE SENSOR | Necessary | 280.00 FS | *280.00 FS |
| 47 | 2 | | *REAR WINDSCREEN SEALANT | Necessary | 240.00 FS | *240.00 FS |
| 48 | 1 | | *REAR BOOT SPARE TYRE LOCKING BOLT | Bent | 110.00 FL | *70.00 FL |
| 49 | 1 | | *REAR BOOT TOYOTA LOGO | Scratched | 90.00 FL | *50.00 FL |

F=Franchise part, S=SpcNett, L=ListItemDisc.

| | | |
|--|------------------|------------------|
| Sub Total (\$) | 18,486.00 | 11,078.00 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 4,371.50 | 2,519.50 |
| Total Parts (\$) | 14,114.50 | 8,558.50 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES. | New | 180.00 | 60.00 |
| 2 | REMOVE & REFIT REAR WINDSCREEN GLASS (2PC WINDSCREEN GLASS) | New | 360.00 | 210.00 |
| 3 | TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS. | New | 200.00 | 100.00 |
| 4 | TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS. | New | 3,000.00 | 1,500.00 |
| 5 | TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS (PEARL WHITE) | New | 2,600.00 | 1,500.00 |
| 6 | TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS. | New | 380.00 | 240.00 |
| 7 | TO CONDUCT A STANDARD OF OPERATING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS. | New | 380.00 | 120.00 |
| 8 | TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START / STOP UNIT CAPACITORS. | New | 180.00 | 50.00 |
| Gross Labour Cost (\$\$) | | | 7,280.00 | 3,780.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >