

Surveyor
merimen

Rasul

ASSIGNMENT (Office)

From (Person):

Crystabelle Tan

of

fcs

Date/Time:

4/9/18 @ 9:10am

Estimated Cost:

Bill to:

① TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKR 1345Z

Insured:

at Workshop no/s

Ricardo Auto

Tel:

6475 2112

of

160 Sin Ming Drive # 02-02

Policy No:

MPC18A 00079400

Claim No:

DMPC1800346H/CT

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

28/08/2018

5/9/18 @ morning

CA

REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:31am @ 4/9/18

Person Contacted:

Grace

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKR 1345Z -X
06/09/18	@ 13:42 p.m. revised IA to Crystabelle Tan via merimen.
06/09/18	@ 13:46 p.m. mandate request authorise repair to Crystabelle Tan via merimen.
06/09/18	@ 17:13 p.m. mandate approved by Janice Goh via merimen.
06/09/18	@ 17:19 p.m. revert authorise repair to Grace (repairer) via email.

Surveys

Rasul

REF:


9388B

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 To Inspect Vehicle No: SKR13452
 at Workshop m/s: RICARDO AUTO
 of: 160, SUN MINE DRIVE #02-02
 Insured: ICS
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 500
 (Client's Record) _____
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 66k
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKR13452 Yr Regn: 2015 / Jan
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: TOYOTA COROLLA ALTIS 1.6 cc 1558
 Colour: BLACK A/C: Insured / Std / NI / NA
 Sp. Reading: 80648 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRO53REH 1045 24407
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / 8 Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 28/08/18 D.O.I: 05/09/18
 Survey held at: RICARDO
 Des. of Damages: FR Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: 17/01/19 Action / Instruction: Confirmed P/P \$3,246.90 @ 5 days with Rasul
(\$ 1,215.50 Red - 27%)

21/1/2019

Date/Time, File Pass to? 08/02/19 ☐ : Preli. Report

1) Typ. st ☒ : Final Report

Date/Time, File Return to? _____

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: 250

Transportation _____

) S + RS. SI _____

) Photos _____

) Others _____

TOTAL _____

Report Format :

Lump Sum / I.B.I.: (\$ 3,246.90 P/P)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. invs (\$ _____)

☐ : Weekend (\$ _____)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CS/ICS18016104/R1sd3		
10 EUNOS ROAD 8 SINGAPORE POST CENTRE #09-04A SINGAPORE 408600		Date : 04-09-2018		
Code : ICS				
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	SKR 1345Z	
Policy No.	MPC18A00079400	Coverage (\$)	0.00	
Claim No.	DMPC1800346H/CT	Excess (\$)	500.00	
Assign From	MERIMEN (CRYSTABELLE TAN)	Assign Date	04/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/08/2018	Inspection Date	05/09/2018	
Survey held at	RICARDO AUTO CENTRE PTE LTD 160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2018 15:04 Sendback Est	03 Sep 2018 17:54 S\$4,236.80	04 Sep 2018 09:10 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CHIA CHEE ONN PHILLIP, ID: S1789388B, Tel: +6597304394, Email: smartking935@gmail.com		
Vehicle Reg. No.:	SKR1345Z	Date of Loss:	28/08/2018 08:00 - :59 [43 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1800346H/CT	Policy/Cover Note No.:	MPC18A00079400 (Comprehensive) Coverage: 20/01/2018 - 19/01/2019
Vehicle Reg. No. (TP):	SLM423C	Policy No. (TP):	
		Excess:	S\$500.00
Repairer:	Ricardo Auto Centre Pte Ltd (HQ) 160 Sin Ming Drive, #02-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64752112		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/09/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 8 February 2019 9:19 AM
To: 'Grace'
Cc: SUR
Subject: RE: SKR 1345Z OD (ECICS)

Dear Grace,

Confirmed final fig of \$ 3,246.90 (part by part) @ 5 days of repairs before excess \$500/- & GST.

Final invoice and all supporting documents sent over to ECICS LTD.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Grace [mailto:grace@ricardo.com.sg]
Sent: Friday, 1 February 2019 12:59 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Subject: FW: SKR 1345Z OD (ECICS)

Hi Shirley,

I manage to change the estimate to original amount, please check. Thanks.

Kind Regards,

Grace Tan
Ricardo Auto Centre Pte Ltd

160 Sin Ming Drive #02-02/03
Sin Ming AutoCity
Singapore 575722

T: 6475 2112 (Main)
6460 9542 (DID)
F: 6475 4666
W: www.ricardo.com.sg

Save Paper. Save the Earth. Think twice before you print.

NOTICE: This message is intended only for the use of the individual or entity to which it is addressed, and may contain information that is privileged, confidential or exempt from disclosure under applicable law. If you are not the intended recipient of this message, or the employee or agent responsible for delivering this message to the intended recipient, you are advised that any dissemination, distribution, copying or acting upon the information contained herein, may be a violation of applicable law and is strictly prohibited. Action may be taken upon any unlawful use as proscribed herein. If you have received this message in error, please notify the sender immediately by replying to this message.

From: Grace <grace@ricardo.com.sg>
Sent: Thursday, January 31, 2019 3:25 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Subject: FW: SKR 1345Z OD (ECICS)

Hi Shirley,

I asked ECICS to re-send from Marimen. What should I do now.

Kind Regards,

Grace Tan
Ricardo Auto Centre Pte Ltd

160 Sin Ming Drive #02-02/03
Sin Ming AutoCity
Singapore 575722

T: 6475 2112 (Main)
6460 9542 (DID)
F: 6475 4666
W: www.ricardo.com.sg

Save Paper. Save the Earth. Think twice before you print.

NOTICE: This message is intended only for the use of the individual or entity to which it is addressed, and may contain information that is privileged, confidential or exempt from disclosure under applicable law. If you are not the intended recipient of this message, or the employee or agent responsible for delivering this message to the intended recipient, you are advised that any dissemination, distribution, copying or acting upon the information contained herein, may be a violation of applicable law and is strictly prohibited. Action may be taken upon any unlawful use as proscribed herein. If you have received this message in error, please notify the sender immediately by replying to this message.

From: Grace <grace@ricardo.com.sg>
Sent: Friday, January 18, 2019 12:49 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Subject: RE: SKR 1345Z OD (ECICS)

Hi Shirley,

I checked all items are okay, only the brace panel pricing change to \$40 +10% = \$44
Total amount is \$3246.90.

Kind Regards,

Grace Tan
Ricardo Auto Centre Pte Ltd

160 Sin Ming Drive #02-02/03
Sin Ming AutoCity
Singapore 575722

T: 6475 2112 (Main)
6460 9542 (DID)
F: 6475 4666
W: www.ricardo.com.sg

Save Paper. Save the Earth. Think twice before you print.

NOTICE: This message is intended only for the use of the individual or entity to which it is addressed, and may contain information that is privileged, confidential or exempt from disclosure under applicable law. If you are not the intended recipient of this message, or the employee or agent responsible for delivering this message to the

intended recipient, you are advised that any dissemination, distribution, copying or acting upon the information contained herein, may be a violation of applicable law and is strictly prohibited. Action may be taken upon any unlawful use as proscribed herein. If you have received this message in error, please notify the sender immediately by replying to this message

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, January 10, 2019 4:10 PM
To: 'Grace' <grace@ricardo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SKR 1345Z OD (ECICS)

Dear Grace,

As spoken, please refer to the attachment.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Grace [<mailto:grace@ricardo.com.sg>]
Sent: Wednesday, 9 January 2019 5:22 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Subject: RE: SKR 1345Z OD (ECICS)

Hi Shirley,

Can finalise this car?

Kind Regards,

Grace Tan
Ricardo Auto Centre Pte Ltd

160 Sin Ming Drive #02-02/03
Sin Ming AutoCity
Singapore 575722

T: 6475 2112 (Main)
6460 9542 (DID)
F: 6475 4666
W: www.ricardo.com.sg

Save Paper. Save the Earth. Think twice before you print.

NOTICE: This message is intended only for the use of the individual or entity to which it is addressed, and may contain information that is privileged, confidential or exempt from disclosure under applicable law. If you are not the intended recipient of this message, or the employee or agent responsible for delivering this message to the intended recipient, you are advised that any dissemination, distribution, copying or acting upon the information contained herein, may be a violation of applicable law and is strictly prohibited. Action may be taken upon any unlawful use as proscribed herein. If you have received this message in error, please notify the sender immediately by replying to this message

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, November 29, 2018 1:57 PM
To: 'Grace' <grace@ricardo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SKR 1345Z OD (ECICS)

Dear Grace,

Please assist on the status, ECICS is asking

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Grace [<mailto:grace@ricardo.com.sg>]
Sent: Thursday, 6 September 2018 5:28 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Subject: RE: SKR 1345Z OD (ECICS)

Noted. Thanks.

Kind Regards,

Grace Tan
Ricardo Auto Centre Pte Ltd

160 Sin Ming Drive #02-02/03
Sin Ming AutoCity
Singapore 575722

T: 6475 2112 (Main)
6460 9542 (DID)
F: 6475 4666
W: www.ricardo.com.sg

Save Paper. Save the Earth. Think twice before you print.

NOTICE: This message is intended only for the use of the individual or entity to which it is addressed, and may contain information that is privileged, confidential or exempt from disclosure under applicable law. If you are not the intended recipient of this message, or the employee or agent responsible for delivering this message to the intended recipient, you are advised that any dissemination, distribution, copying or acting upon the information contained herein, may be a violation of applicable law and is strictly prohibited. Action may be taken upon any unlawful use as proscribed herein. If you have received this message in error, please notify the sender immediately by replying to this message

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, September 06, 2018 5:19 PM
To: grace@ricardo.com.sg
Cc: sur@lkkauto.com
Subject: SKR 1345Z OD (ECICS)

Dear Grace,

As instructed by our client, please proceed to repair the insured vehicle **SKR 1345Z (Excess \$ 500/-)**.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 6 September 2018 5:19 PM
To: grace@ricardo.com.sg
Cc: sur@lkkauto.com
Subject: SKR 1345Z OD (ECICS)

Dear Grace,

As instructed by our client, please proceed to repair the insured vehicle **SKR 1345Z (Excess \$ 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

**SKR1345Z (DMPC1800346H/CT)
[SLM423C]**

OD
Aug 28 2018 8:00AM
[CHIA CHEE ONN PHILLIP]
Ricardo Auto Centre Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on **01/02/2019 17:44 PM.**

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$3246.90) - SKR1345Z - Claim Handler: Crystabelle Tan

Approved:3246.90.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SKR1345Z (DMPC1800346H/CT)
[SLM423C]

OD
Aug 28 2018 8:00AM
[CHIA CHEE ONN PHILLIP]
Ricardo Auto Centre Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on **06/09/2018 17:13 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$3207.19) - SKR1345Z - Claim Handler: Crystabelle Tan

Approved:3207.19.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 01 Feb 2019

Preliminary Advice

Vehicle No	: SKR1345Z	Accident Date	: 28/08/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MPC18A00079400
Assignment Date	: 04/09/2018	Excess	: S\$500.00
Date of Inspection	: 05/09/2018	Est. Duration of Repair	: 5 days
Inspection At	Ricardo Auto Centre Pte Ltd (HQ) 160 Sin Ming Drive, #02-02, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,462.40
Revised Amount	:S\$	3,246.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,246.90

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	52,644.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,356.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 06 Sep 2018

Preliminary Advice

Vehicle No	: SKR1345Z	Accident Date	: 28/08/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MPC18A00079400
Assignment Date	: 04/09/2018	Excess	: S\$500.00
Date of Inspection	: 05/09/2018	Est. Duration of Repair	: 5 days
Inspection At	: Ricardo Auto Centre Pte Ltd (HQ) 160 Sin Ming Drive, #02-02, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,462.40
Revised Amount	:S\$	2,922.84
Check Items (Estimated)	:S\$	284.35
Total	:S\$	3,207.19

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	52,644.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,356.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/08/2018 15:47
Date Of Accident	28/08/2018 08:30
Exact Location Of Accident	LENTOR AVE TOWARDS YIO CHU KANG ROAD SLIP ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR1345Z
Insured/Policyholder	
Name Of Registered Owner	CHIA CHEE ONN PHILLIP
NRIC No	S1789388B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97304394
Alternative Phone No	OFFICE-97304394
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 L CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00079400
Cover Note Number	
Driver	
Name of Driver	CHIA CHEE ONN PHILLIP
NRIC No	S1789388B
Date Of Birth	08/02/1967
Occupation	INDOOR
Date Of Driving Pass	18/10/2007
Driving Experience	10 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97304394
Fax Number	
Contact Number	OFFICE-97304394
Email Address	NOEMAIL

Address	BLK 935 YISHUN CENTRAL 1 #03-49
Postcode	760935
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM423C
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	FRANCIS LOW KIM HUAT
NRIC/Passport Number	S7245266F
Contact Number	81007245
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When I moved off my car, the other driver's car was sudden brake out of the waiting line. Eventually, my car cannot stop in time and hit on the left side of his car's bumper. There is no injury for myself and the other ~~other~~ driver. There is no passenger for my car and also no passenger in other driver's car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 28 Aug 2018
14:45 hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: TAN KIAN ANN

NRIC/FIN No.: S1549534J

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9388B
Vehicle Details	
Vehicle No.:	SKR1345Z
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	1ZRY140148
Chassis No.:	MR053REH104524407
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,143.00
Original Registration Date:	20 Jan 2015
First Registration Date:	20 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$14,143.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jan 2025
PARF Rebate Amount:	\$10,607.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,010.00
COE Rebate Amount:	\$42,037.00
Total Rebate Amount:	\$52,644.00

The information contained herein is correct as at 06 Sep 2018

OK

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
 160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
 TEL: 6475 2112 FAX: 6475 4666
 WEBSITE: <http://www.ricardo.com.sg>



QUOTATION

M/S: ECICS LTD

10 EUNOS ROAD 8
 SINGAPORE POST CENTRE #09-04A
 SINGAPORE 408600

TEL: 63030185

ATTN: MOTOR CLAIM DEPT

NO: WQT0800867

DATE: 30 Aug 2018

A/C CODE: C010247

YOUR REF: SKR1345Z

VEH REG NO: SKR1345Z

MAKE/MODEL: TOYOTA TOYOTA
 COROLLA ALTIS 1.6L
 CVT

SALESMAN:

PAGE:1

Description	Quantity	Unit Price	%	Amount
		SS		SS
WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIR TO ABOVE MENTIONED VEHICLE.				
DOA: 28/08/2018 @0830 HRS				
INSURED: CHIA CHEE ONN PHILLIP				
POLICY NO: MPC18A00079400				
CLAIM TYPE: OD CLAIM				
1/ FRONT BUMPER	170	1 PC	187.0000 DE	187.00
2/ FRONT BUMPER REINFORCEMENT	120	1 PC	132.0000 2 Pt	132.00
3/ FRONT BUMPER SPONGE	45	1 PC	49.5000 2 DE	49.50
4/ FRONT BUMPER CLIPS	16	8 PCS	2.2000 per	17.60
5/ FRONT BUMPER SIDE RETAINER LH & RH	50	2 PCS	27.5000 per	55.00
6/ FRONT SUPPORT PANEL	240	1 PC	264.0000 repair	264.00
7/ BRACE PANEL	40 45	1 PC	PA 49.5000 X repair	49.50
8/ AIR CON CONDENSER	150	1 PC	165.0000 X repair	165.00
9/ BONNET	300	1 PC	330.0000 Pt	330.00
10/ HEADLAMP RH	620	1 PC	682.0000 CRA	682.00
11/ FRONT ENGINE UNDER COVER	70	1 PC	77.0000 X 2 DE	77.00
12/ FRONT GRILLE	140	1 PC	154.0000 CRA	154.00
13/ FRONT GRILLE COVER CLIPS	8	4 PCS	2.2000 per	8.80
14/ WIPER TANK	60	1 SVC	66.0000 X SVC	66.00
15/ FRONT NUMBER PLATE WITH HOLDER (S/NETT)		1 PC	45.0000 PA - 35	45.00
16/ TO FOCUS HEADLAMP.		1 SVC	30.0000	30.00
17/ TO SERVICE AIR-CON SYSTEM, REMOVE & REPLACE DAMAGE PARTS. TOP UP AIR-CON GAS.		1 SVC	150.0000 80	150.00
18/ TO CUT, WELD & STRAIGHTEN DAMAGE PARTS, ADJUST & REPLACE DAMAGE PARTS.		1 SVC	1,000.0000 600	1,000.00
19/ TO SPRAY PAINT ON REPAIRED AREA.		1 SVC	1,000.0000 600	1,000.00

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6475 2112 FAX: 6475 4666
WEBSITE: <http://www.ricardo.com.sg>



QUOTATION

M/S: ECICS LTD

NO: WQT0800867
DATE: 30 Aug 2018

Total	SS 4,462.40
Add GST @ 7%	312.37
Grand Total	SS 4,774.77

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SEVEN HUNDRED SEVENTY FOUR AND CENTS SEVENTY SEVEN ONLY

ECICS LTD

For RICARDO AUTO CENTRE PTE LTD

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE

Parts quoted = cost plus 10%

RASUL
HP 90010068
5 days
P/P
05/09/18 @ 1050
EXCESS = 500
REVERT
Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2018 15:04 Sendback Est	31 Jan 2019 18:38 S\$4,462.40	04 Sep 2018 09:10 Edit Adj Rpt	S\$3,246.90 Edit Estimates	S\$3,246.90 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CHIA CHEE ONN PHILLIP, ID: S17893888, Tel: +6597304394, Email: smartking935@gmail.com		
Vehicle Reg. No.:	SKR1345Z	Date of Loss:	28/08/2018 08:00 - :59 [43 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1800346H/CT	Policy/Cover Note No.:	MPC18A00079400 (Comprehensive) Coverage: 20/01/2018 - 19/01/2019
Vehicle Reg. No. (TP):	SLM423C	Policy No. (TP):	
		Excess:	S\$500.00
Repairer:	Ricardo Auto Centre Pte Ltd (HQ) 160 Sin Ming Drive, #02-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64752112		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/09/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- ECICS (01/02/2019): Alert - Adj Mandate Approved (S\$3246.90) - SKR1345Z - Claim Handler: Crystabelle...
- ECICS (06/09/2018): Alert - Adj Mandate Approved (S\$3207.19) - SKR1345Z - Claim Handler: Crystabelle...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKR1345Z (DMPC1800346H/CT)
[SLM423C]

OD

Aug 28 2018 8:00AM
[CHIA CHEE ONN PHILLIP]
Ricardo Auto Centre Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports



























































































1 per page

No	Finalized On	Ricardo Auto Centre Pte Ltd (HQ)		Thumbnail	Print
1	31/01/19 18:38	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/09/18 13:42	Adjuster Immediate Advice		Load HTM	
2	01/02/19 13:41	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/09/18 13:32	Odometer Reading		Load JPG	
2	06/09/18 13:32	Chassis Number		Load JPG	
3	06/09/18 13:32	General View		Load JPG	
4	06/09/18 13:32	General View		Load JPG	
5	06/09/18 13:32	General View		Load JPG	
6	06/09/18 13:32	General View		Load JPG	
7	06/09/18 13:32	General View		Load JPG	
8	06/09/18 13:32	General View		Load JPG	
9	06/09/18 13:32	General View		Load JPG	
10	06/09/18 13:32	General View		Load JPG	
11	06/09/18 13:32	General View		Load JPG	
12	06/09/18 13:32	General View		Load JPG	
13	06/09/18 13:32	General View		Load JPG	
14	06/09/18 13:32	General View		Load JPG	
15	06/09/18 13:32	General View		Load JPG	
16	06/09/18 13:32	General View		Load JPG	
17	06/09/18 13:32	General View		Load JPG	
18	06/09/18 13:32	General View		Load JPG	
19	06/09/18 13:32	General View		Load JPG	
20	06/09/18 13:32	General View		Load JPG	
21	06/09/18 13:32	General View		Load JPG	
22	06/09/18 13:32	General View		Load JPG	
23	06/09/18 13:32	General View		Load JPG	
24	06/09/18 13:32	General View		Load JPG	
25	06/09/18 13:32	General View		Load JPG	
26	06/09/18 13:32	General View		Load JPG	
27	06/09/18 13:32	General View		Load JPG	
28	06/09/18 13:32	General View		Load JPG	
29	06/09/18 13:32	General View		Load JPG	
30	06/09/18 13:32	General View		Load JPG	

Assessment Reports			1 per page	
No	Finalized On	Ricardo Auto Centre Pte Ltd (HQ)	Thumbnail	Print
31	06/09/18 13:32	General View	 Load JPG	
32	06/09/18 13:32	General View	 Load JPG	
33	06/09/18 13:32	General View	 Load JPG	
34	06/09/18 13:32	General View	 Load JPG	
35	06/09/18 13:32	General View	 Load JPG	
36	06/09/18 13:32	General View	 Load JPG	
37	06/09/18 13:32	General View	 Load JPG	
38	06/09/18 13:32	General View	 Load JPG	
39	06/09/18 13:32	General View	 Load JPG	
40	06/09/18 13:32	General View	 Load JPG	
41	06/09/18 13:32	General View	 Load JPG	
42	18/01/19 15:37	Reinspection Photo	 Load JPG	
43	18/01/19 15:37	Reinspection Photo	 Load JPG	
44	18/01/19 15:37	Reinspection Photo	 Load JPG	
45	18/01/19 15:37	Reinspection Photo	 Load JPG	
46	18/01/19 15:37	Reinspection Photo	 Load JPG	
47	18/01/19 15:37	Reinspection Photo	 Load JPG	
48	18/01/19 15:37	Reinspection Photo	 Load JPG	
49	18/01/19 15:37	Reinspection Photo	 Load JPG	
50	18/01/19 15:37	Reinspection Photo	 Load JPG	
51	18/01/19 15:37	Reinspection Photo	 Load JPG	
52	18/01/19 15:37	Reinspection Photo	 Load JPG	
53	18/01/19 15:37	Reinspection Photo	 Load JPG	
54	18/01/19 15:37	Reinspection Photo	 Load JPG	
55	18/01/19 15:37	Reinspection Photo	 Load JPG	
56	18/01/19 15:37	Reinspection Photo	 Load JPG	
57	18/01/19 15:37	Reinspection Photo	 Load JPG	
58	18/01/19 15:37	Reinspection Photo	 Load JPG	
59	18/01/19 15:37	Reinspection Photo	 Load JPG	
60	18/01/19 15:37	Reinspection Photo	 Load JPG	
61	18/01/19 15:37	Reinspection Photo	 Load JPG	
62	18/01/19 15:37	Reinspection Photo	 Load JPG	
63	18/01/19 15:37	Reinspection Photo	 Load JPG	
64	18/01/19 15:37	Reinspection Photo	 Load JPG	
65	18/01/19 15:37	Reinspection Photo	 Load JPG	
66	18/01/19 15:37	Reinspection Photo	 Load JPG	
67	18/01/19 15:37	Reinspection Photo	 Load JPG	
68	18/01/19 15:37	Reinspection Photo	 Load JPG	
69	18/01/19 15:37	Reinspection Photo	 Load JPG	
70	18/01/19 15:37	Reinspection Photo	 Load JPG	
71	18/01/19 15:37	Reinspection Photo	 Load JPG	
72	18/01/19 15:37	Reinspection Photo	 Load JPG	
73	18/01/19 15:37	Reinspection Photo	 Load JPG	
74	18/01/19 15:37	Reinspection Photo	 Load JPG	
75	18/01/19 15:37	Reinspection Photo	 Load JPG	
76	18/01/19 15:37	Reinspection Photo	Load JPG	
77	18/01/19 15:37	Reinspection Photo	Load JPG	

Assessment Reports			1 per page ▼	✓
No	Finalized On	Ricardo Auto Centre Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/18 13:33	ESTIMATE	1 Load PDF	
2	06/09/18 13:41	TP GIA REPORT	1 Load PDF	
3	01/02/19 13:41	ESTIMATE MARKED.pdf	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One
Singapore 038987

Our File No: CS/ICS18016104/R1SD3S2

Date: 08/02/2019

REFERENCE

Insured/Claimant:	CHIA CHEE ONN PHILLIP	Policy No:	MPC18A00079400	
Date of Loss:	28/08/2018	Nature of Claim:	OD	Claim No: DMPC1800346H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR1345Z	Engine No:	1ZRY140148
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Chassis No:	MR053REH104524407
Reg. Date:	20/01/2015 (Man. Year: 2014)	Odometer:	80648 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$66,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,237.40	1,901.90	335.50	15.00
Miscellaneous Items	45.00	35.00	10.00	22.22
Labour	2,180.00	1,310.00	870.00	39.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,462.40	3,246.90	1,215.50	27.24
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	3,962.40	2,746.90	1,215.50	30.68
+ GST 7.00/7.00% (S\$)	277.37	192.28	85.09	30.68
Nett Amount (S\$)	4,239.77	2,939.18	1,300.59	30.68

INSPECTION

Date of Assignment:	04/09/2018	
Date Inspected:	05/09/2018	Inspected At: Ricardo Auto Centre Pte Ltd (HQ) 160 Sin Ming Drive, #02-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR1345Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Deformed	170.00 F	*170.00 F
2	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	120.00 F	*120.00 F
3	1		*FRONT BUMPER SPONGE (WCP)	Deformed	45.00 F	*45.00 F
4	8		*FRONT BUMPER CLIPS (WCP)	Necessary	16.00 F	*16.00 F
5	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Necessary	25.00 F	*25.00 F
6	1		*FRONT BUMPER SIDE RETAINER RH (WCP)	Necessary	25.00 F	*25.00 F
7	1		*FRONT SUPPORT PANEL (WCP)	Repair	240.00 F	*- F
8	1		*BRACE PANEL (WCP)	Bent	45.00 F	*40.00 F
9	1		*AIR-CON CONDENSER (WCP)	Bent	150.00 F	*150.00 F
10	1		*BONNET (WCP)	Bent	300.00 F	*300.00 F
11	1		*HEADLAMP RH (WCP)	Cracked	620.00 F	*620.00 F
12	1		*FRONT ENGINE UNDER COVER (WCP)	Deformed	70.00 F	*70.00 F
13	1		*FRONT GRILLE (WCP)	Cracked	140.00 F	*140.00 F
14	4		*FRONT GRILL COVER CLIPS (WCP)	Necessary	8.00 F	*8.00 F
15	1		*WIPER TANK (WCP)	Serviceable	60.00 F	*- F

F=Franchise part.

Sub Total (S\$)	2,034.00	1,729.00
+ Margin on L,N Items 10.00/10.00% (S\$)	203.40	172.90
Total Parts (S\$)	2,237.40	1,901.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	SUPPLY & REPLACE FRONT NUMBER PLATE WITH HOLDER (BENT)	45.00	35.00
Sub Total (S\$)			45.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FOCUS HEADLAMP	New	30.00	30.00
2	TO SERVICE AIR-CON SYSTEM, REMOVE & REPLACE DAMAGE PARTS. TOP UP AIR-CON GAS.	New	150.00	80.00
3	TO CUT, WELD & STRAIGHTEN FRONT PORTION OF CAR CAUSED BY ACCIDENT, ADJUST & REPLACE DAMAGE PARTS.	New	1,000.00	600.00
4	TO SPRAY PAINT ON REPAIRED AREA.	New	1,000.00	600.00
Gross Labour Cost (S\$)			2,180.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >