

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Crystabelle Tan

Date: 01 Feb 2019

## Preliminary Advice

Vehicle No	: SKR1345Z	Accident Date	: 28/08/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MPC18A00079400
Assignment Date	: 04/09/2018	Excess	: S\$500.00
Date of Inspection	: 05/09/2018	Est. Duration of Repair	: 5 days
Inspection At	: Ricardo Auto Centre Pte Ltd (HQ) 160 Sin Ming Drive, #02-02, Sin Ming AutoCity Singapore 575722		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,462.40
Revised Amount	:S\$	3,246.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,246.90
Lump Sum Repair		:S\$

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	52,644.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,356.00

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.  
Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :