

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 06 Sep 2018

Preliminary Advice

Vehicle No	: SKR1345Z	Accident Date	: 28/08/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MPC18A00079400
Assignment Date	: 04/09/2018	Excess	: S\$500.00
Date of Inspection	: 05/09/2018	Est. Duration of Repair	: 5 days
Inspection At	: Ricardo Auto Centre Pte Ltd (HQ) 160 Sin Ming Drive, #02-02, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,462.40
Revised Amount	:S\$	2,922.84
Check Items (Estimated)	:S\$	284.35
Total	:S\$	3,207.19

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	52,644.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,356.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :