

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

03-Sep-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1161 X

1 pc	Front o/s head lamp		\$	1,531.57	SCA-
1 pc	Front bumper		\$	811.11	DE-
1 pc	Front bumper emblem		\$	27.80	MSA-
1 pc	Front bumper o/s side bracket		\$	32.51	MS-
1 pc	Front o/s fender		\$	514.02	PA-
1 pc	Front o/s fender inner shield		\$	176.72	?
1 pc	Front o/s rim		\$	246.00	SCA-
				\$	3,339.73
				\$	667.95
				\$	2,671.78

Rasul
Hp 90010068
5 days
P/P

S/NETT

1 set	Front bumper clips		\$	48.00	MS-
1 pc	Front o/s fender sticker		\$	30.00	MS-
1 set	Front o/s fender inner shield clips		\$	28.00	MS-?
				\$	30 50.00
				\$	50.00
				\$	80.00
				\$	40.00
				\$	750.00
				\$	500.00
				\$	120.00
				\$	4,367.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.