

110

22/03/2003

ASS. REC. BY:

REF:

CS/CTF/8016110/Kcd302

Special Instruction:

Survivor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Joyn Tay

of

CTF

Date/Time:

4/11/80 12:01pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No:

SKH 4807R

Insured:

GBH 3309

at Workshop m/s

SKH Motor

Tel:

6453 4730

of

160 Sin Ming Drive #07-02

Policy No:

SNM18D04228C02

Claim No:

DMCVSN1771291700

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/08/2018

CA / REV / REP. / REV 24 HRS

cup

5/11/80 Morning

H.O.D. Endorsement:

Date/Time:

2:05pm @ 4/11/8

Person Contacted:

Cynthia

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SKH 4807R - X

GBH 3309 - X

16/11 11 Lnp @ 510d email

24/11 2:58pm Doris confirmed LS \$5100f and 9 days. (Red. 3868f, 43%)

(08/11/13) wof
ASS REC. BY:

REF: **ETI**

ASSIGNMENT

From: Date: **5/9/18**

Estimated Cost:

OD / ☒ P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SKH 4807R**

at Workshop m/s: **S & H Motor**

of **160 Sin Ming Drive # 07-02**

Insured:

Policy No:

Claims No:

Sum Insured: Excess:


(Client's Record)

Morning

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: **9** days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **1 up**

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: **SKH 4807R** Yr Regn: **12 / 12**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Wagon

Make: **Chrysler Cruise LS.c** **1598**

Colour: **Mr. Grey** A/C: Insured / Std / NI / NA

Sp. Reading: **-** T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: **KL1CA 8PE 9CK 651328**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **205/60R16**

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **9** mm R/Bal. **9** mm

L/Bal. **9** mm L/Bal. **9** mm

D.O.A. **28/8 118** D.O.I. **5/9/18**

Survey held at **✓**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt O/S & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/9 File pass to Catherine, Bottom Star

RECEIVED 12 DEC 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: **TP**

Lump Sum / I.B.I. (\$) **5100**

Days Of Repair: **9**

Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

220

Transportation:

☐ S + RS, ☐ SI

Photos

Others

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18016110/Krd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 04-09-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 330G	Veh. Inspected	SKH 4807R	
Policy No.	DMCVSN1771291700	Coverage (\$)	0.00	
Claim No.	SNM18D04228C02	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	04/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/08/2018	Inspection Date	05/09/2018	
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2018 Sendback Est	03 Sep 2018 16:37 S\$8,588.00	04 Sep 2018 12:01 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SIN HONG HWA PTE LTD , Co. Reg. No.: 197701628N		
Main Claimant:	JASON PNG CHENG KHIM , ID: S8362553H		
Vehicle Reg. No.:	SKH4807R	Date of Loss:	29/08/2018 17:00 - :59 [68 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / DMCVSN1771291700	Policy/Cover Note No.:	SNM18D04228C02
Vehicle Reg. No. (Insured):	GBH330G	Policy No. (Claimant):	2017-V0102975-VAW
		Excess:	S\$0.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	Great Eastern General Insurance Limited (HQ) - Tel: +65 248 2888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/09/2018]		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY & ARRANGE FOR DIRECT SETTLEMENT.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2553H
Vehicle Details	
Vehicle No.:	SKH4807R
Vehicle to be Exported:	Yes
Intended De-registration Date:	30 Aug 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	F16D4314978KA
Chassis No.:	KL1JA69E9CK651328
Maximum Power Output:	91.0 kW (122 bhp)
Open Market Value:	\$13,104.00
Original Registration Date:	13 Dec 2012
First Registration Date:	13 Dec 2012
Transfer Count:	0
Actual ARF Paid:	\$13,104.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2022
PARF Rebate Amount:	\$9,172.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$78,523.00
COE Rebate Amount:	\$33,625.00
Total Rebate Amount:	\$42,797.00

The information contained herein is correct as at 30 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/08/2018 15:29
Date Of Accident	29/08/2018 17:45
Exact Location Of Accident	ALONG 21 BENOI PLACE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH4807R
Insured/Policyholder	
Name Of Registered Owner	JASON PNG CHENG KHIM
NRIC No	S8362553H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96478688
Alternative Phone No	OFFICE-96478688

Vehicle Particulars

Manufacturer	CHEVROLET
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2017-V0102975-VAW
Cover Note Number	

Driver

Name of Driver	JASON PNG CHENG KHIM
NRIC No	S8362553H
Date Of Birth	26/05/1983
Occupation	INDOOR
Date Of Driving Pass	15/12/2012
Driving Experience	5 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96478688
Fax Number	
Contact Number	OFFICE-96478688
EMail Address	NOEMAIL

Address	-
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH330G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RAMANI A/L VADIVELU
NRIC/Passport Number	F8348349X
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLP8559B
Vehicle Make/Model/Colour	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I had parked my vehicle SKH4807R along 21 Benoi Place. My vehicle is locked and parked in a stationary position. I had then entered 29 Benoi Place.

At approximately 17:25 to 17:45, I heard a loud crashing sound and was informed to go out to investigate what had happened. I went out to find vehicle

GBH3306 driven by Mr. Ramani A/L Vadivelu had ~~crashed~~ ^{damaged} my vehicle. My vehicle SKH4807R (Chevrolet Cruze) that was stationary parked with no

occupants had moved approximately 3-4 meters backwards, coming into contact with the side of the road curb and also in contact with a

Nissan Qashqai of vehicle plate SLP8559D parked stationary behind my vehicle. Mr. Ramani A/L Vadivelu is an employee of Sin Hong Hua Pte Ltd that was driving vehicle GBH3306.

Employees of Sin Hong Hua Pte Ltd. come out to investigate including the operations manager Mr. Michael Oon. Mr. Ramani admitted to knocking my vehicle SKH4807R ~~into~~ ^{his own reasons} citing ~~his own reasons~~. Mr. Michael Oon confessed to his employees mistake and requested me to claim the damages to his vehicle/company's insurance.

I have videographic evidence of the site ~~when I~~ ^{when I} had arrived on site as well.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

Claimant Insurer: Great Eastern General Insurance Limited

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	29/08/2018
Vehicle Reg. No.:	SKH4807R	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	JASON PNG CHENG KHIM		
Make/Model:	CHEVROLET CRUZE, 1.6 (A)	Vehicle Reg. Date:	13/12/2012
Vehicle Colour:	Metallic Grey		
Engine No:	F16D4314978KA	Chassis No:	KL1JA69E9CK651328
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14 9 days		
Description of Accident/Loss	REFER ATTACHED REPORT.		
Present Location:	S & H MOTOR PTE LTD (SIN MING)		

*Not Authorized
1-B.1
Repair B&P*

COST OF CLAIMS	Amount
Parts	5,443.00
Miscellaneous Items	0.00
Labour	3,065.00
Paintwork Labour	0.00
Towing	80.00
Gross Total (S\$)	8968.00 8,588.00
+ GST 7.00% (S\$)	601.16
Nett Amount (S\$)	9,189.16

This claim is handled by: LUM WEE KEAT

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 03 Sep 2018)

Parts: 143 **CHEVROLET CRUZE 1.6 (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: S & H Motor Pte Ltd/SKH4807R/03/09/2018 16:37

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear bumper	Bu 0.00	0.00	*750.00 F
2	1		*Rear bumper clips (1 set)	bu 0.00	0.00	*18.00 F
3	1		*Rear bumper tow cover		0.00	bu *20.00 F
4	1		*Rear bumper reinforcement	R 0.00	0.00	*230.00 F
5	4		*Rear bumper parking sensor	bu 0.00	0.00	*600.00 F
6	1		*RH Rear bumper retainer	bu 0.00	0.00	*18.00 F
7	1		*LH Rear bumper retainer	bu 0.00	0.00	*18.00 F
8	1		*Rear boot badge "Chevrolet"****	bu 0.00	0.00	*40.00 F
9	1		*Rear boot badge "Cruze LS"****	bu 0.00	0.00	*30.00 F
10	1		*Rear boot emblem	bu 0.00	0.00	*55.00 F
11	1		*Bonnet	bu 0.00	0.00	*850.00 F
12	1		*RH front fender	bu 0.00	0.00	*490.00 F
13	1		*RH front fender wheel cowling	bu 0.00	0.00	*65.00 F
14	1		*RH front fender wheel cowling clips (1 set)	bu 0.00	0.00	*28.00 F
15	1		*RH front fender top garnish	bu 0.00	0.00	*18.00 F
16	1		*RH head lamp	bu 0.00	0.00	*490.00 F
17	1		*Front bumper	bu 0.00	0.00	*680.00 F
18	1		*RH front bumper retainer	bu 0.00	0.00	*18.00 F
19	1		*RH front bumper fog lamp	bu 0.00	0.00	*180.00 F
20	1		*RH front bumper fog lamp cover	bu 0.00	0.00	*35.00 F
21	1		*Front bumper bottom dust panel	R 0.00	0.00	*65.00 F
22	1		*Front support panel	R 0.00	0.00	*480.00 F
23	1		*RH front air duct	bu 0.00	0.00	*85.00 F
24	1		*RH air con condensor aluminium pipe	bu 0.00	0.00	*180.00 F

F=Franchise part.

Total Parts (S\$) **5,443.00**

S & H Motor Pte Ltd/SKH4807R/03/09/2018 16:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

11 Lp & 510 qd

9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars		Lab.Type	Amount
<u>Labour Items</u>			
1	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	New	45.00
2	To spray paint affected front and inner damaged portion inclusive of preparatory works and material	New	950.00
3	To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet hinge panel, RH front fender and inner panel, RH head lamp inner panel, front support panel, RH front door, RH front door pillar, front chassis member and adjust body panel alignment	New	750.00
4	To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality	New	50.00
5	To spray paint affected rear and inner damaged portion inclusive of preparatory works and material	New	600.00
6	To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member and adjust rear body and boot alignment	New	550.00
7	To perform computer diagnostic on drivetrain, ABS systems, parking system, and clear fault codes	New	120.00
Gross Labour Cost (S\$)			3,065.00

S & H Motor Pte Ltd/SKH4807R/03/09/2018 16:37. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 11 Oct 2018)
Parts: 143 **CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's **(Price-denominated Standard List)**
Print Code: S & H Motor Pte Ltd/SKH4807R/11/10/2018 12:58
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front air-cleaner	0.00	0.00	CM *380.00 P
Total Parts (S\$)						380.00

F=Franchise part.

S & H Motor Pte Ltd/SKH4807R/11/10/2018 12:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Kenneth Kong (LKKAUTO)

From: Doris <doris@sh-motor.com>
Sent: Saturday, 24 November, 2018 2:58 PM
To: Kenneth Kong (LKKAUTO)
Subject: RE: vehicle no : SKH4807R-final

Dear Kenneth

Noted....Thank...lump sum cost S\$5,100.00

Thank

Doris

From: Kenneth Kong (LKKAUTO) [<mailto:KennethKong@lkkauto.com>]
Sent: Friday, 16 November 2018 8:25 AM
To: Doris
Subject: RE: vehicle no : SKH4807R-final

Attach finalised for SKH 4807R. Kenneth

From: Doris [<mailto:doris@sh-motor.com>]
Sent: Thursday, 11 October, 2018 1:12 PM
To: Kenneth Kong (LKKAUTO)
Subject: vehicle no : SKH4807R-final

Dear Kenneth

Forward vehicle no : SKH 4807 R for lump sum repair.

Front support panel no stock, we repair back & rear taillamp panel(can arrange some labour)

Thank

Doris

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2018 Sendback Est	03 Sep 2018 16:37 S\$8,588.00	04 Sep 2018 12:01 Edit Adj Rpt	S\$5,100.00 Edit Estimates	S\$5,100.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	11 Oct 2018 12:58	11 Oct 2018 12:58 S\$380.00	11 Oct 2018 12:58			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	SIN HONG HWA PTE LTD , Co. Reg. No.: 197701628N		
Main Claimant:	JASON PNG CHENG KHIM , ID: S8362553H		
Vehicle Reg. No.:	SKH4807R	Date of Loss:	29/08/2018 17:00 - :59 [68 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / DMCVSN1771291700	Policy/Cover Note No.:	SNM18D04228C02
Vehicle Reg. No. (Insured):	GBH330G	Policy No. (Claimant):	2017-V0102975-VAW
		Excess:	S\$0.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	Great Eastern General Insurance Limited (HQ) - Tel: +65 248 2888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/09/2018]		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY & ARRANGE FOR DIRECT SETTLEMENT.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

**SKH4807R (DMCVSN1771291700)
[GBH330G]**

TP

JASON PNG CHENG KHIM

Aug 29 2018 5:00PM

[SIN HONG HWA PTE LTD]

S & H Motor Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	03/09/18 16:37	Repairer Estimates		Load HTM	
2	11/10/18 12:58	Repairer Estimates Suppl. #1		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/12/18 18:36	General View		Load PDF	
2	07/12/18 18:36	Photo After Spray		Load PDF	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/12/18 09:32	Supplementary		Load PDF	

Linked Accident Report Documents

										View	View in Browser	
Assessment Reports										1 per page		
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)								Thumbnail	Print	
1	30/08/18 16:16	Accident Statement							1	Load HTM		
Photos/Images										3 per page		
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)								Thumbnail	Print	
1	30/08/18 15:51	Accident Photo							1	Load JPG		
2	30/08/18 15:51	Accident Photo							1	Load JPG		
3	30/08/18 15:51	Accident Photo							1	Load JPG		
4	30/08/18 15:51	Accident Photo							1	Load JPG		
5	30/08/18 15:51	Accident Photo							1	Load JPG		
6	30/08/18 15:51	Accident Photo							1	Load JPG		
7	30/08/18 15:51	Accident Photo							1	Load JPG		
8	30/08/18 15:51	Accident Photo							1	Load JPG		
9	30/08/18 15:51	Accident Photo							1	Load JPG		
10	30/08/18 15:51	Accident Photo							1	Load JPG		
11	30/08/18 15:51	Accident Photo							1	Load JPG		
12	30/08/18 15:51	Accident Photo							1	Load JPG		
Documentation										1 per page		
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)								Thumbnail	Print	
1	30/08/18 15:40	Sketch Plan							1	Load TIF		
2	30/08/18 15:40	Sketch Plan #2							1	Load TIF		
3	30/08/18 15:40	Sketch Plan #3							1	Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016110/KCD3E2

Date: 13/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	SNM18D04228C02
Claimant Vehicle No :	SKH4807R	Insured Vehicle No :	GBH330G
Date of Loss:	29/08/2018	Nature of Claim:	TP
		Claim No:	DMCVSN1771291700

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH4807R		
Make & Model:	CHEVROLET CRUZE, 1.6 (A)	Engine No:	F16D4314978KA
Reg. Date:	13/12/2012 (Man. Year: 2012)	Chassis No:	KL1JA69E9CK651328
Colour:	Metallic Grey	Odometer:	0 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,823.00	4,165.00	1,658.00	28.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,065.00	2,220.00	845.00	27.57
Paintwork Labour	0.00	0.00	0.00	
Towing	80.00	0.00	80.00	100.00
Calculated Gross Total (\$\$)	8,968.00	6,385.00	2,583.00	28.80
Approved Total (Overridden) (\$\$)		5,100.00		
(\$\$)	8,968.00	5,100.00	3,868.00	43.13
+ GST 7.00/7.00% (\$\$)	627.76	357.00	270.76	43.13
Nett Amount (\$\$)	9,595.76	5,457.00	4,138.76	43.13

INSPECTION

Date of Assignment:	04/09/2018 Present Location:	S & H Motor Pte Ltd (Sin Ming)
Date Inspected:	05/09/2018 Inspected At:	S & H Motor Pte Ltd (Sin Ming)
		160 Sin Ming Drive #07-02, Sin Ming
		AutoCity
		Singapore 575722

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2018)
Parts: 143	CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKH4807R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear bumper	Buckled	750.00 F	*750.00 F
2	1		*Rear bumper clips (1 set)	Necessary	18.00 F	*18.00 F
3	1		*Rear bumper tow cover	Dented	20.00 F	*20.00 F
4	1		*Rear bumper reinforcement	Repair	230.00 F	*- F
5	4		*Rear bumper parking sensor	Serviceable	600.00 F	*- F
6	1		*RH Rear bumper retainer	Serviceable	18.00 F	*- F
7	1		*LH Rear bumper retainer	Distorted	18.00 F	*18.00 F
8	1		*Rear boot badge "Chevrolet"****	Necessary	40.00 F	*40.00 F
9	1		*Rear boot badge "Cruze LS"****	Necessary	30.00 F	*30.00 F
10	1		*Rear boot emblem	Necessary	55.00 F	*55.00 F
11	1		*Bonnet	Bent	850.00 F	*850.00 F
12	1		*RH front fender	Bent	490.00 F	*490.00 F
13	1		*RH front fender wheel cowling	Distorted	65.00 F	*65.00 F
14	1		*RH front fender wheel cowling clips (1 set)	Necessary	28.00 F	*28.00 F
15	1		*RH front fender top garnish	Cracked	18.00 F	*18.00 F
16	1		*RH head lamp	Broken	490.00 F	*490.00 F
17	1		*Front bumper	Cracked	680.00 F	*680.00 F
18	1		*RH front bumper retainer	Distorted	18.00 F	*18.00 F
19	1		*RH front bumper fog lamp	Cracked	180.00 F	*180.00 F
20	1		*RH front bumper fog lamp cover	Missing	35.00 F	*35.00 F
21	1		*Front bumper bottom dust panel	Repair	65.00 F	*- F
22	1		*Front support panel	Repair	480.00 F	*- F
23	1		*RH front air duct	Serviceable	85.00 F	*- F
24	1		*RH air con condensor aluminium pipe	Serviceable	180.00 F	*- F
Supplementary #1						
25	1		*Front air-cleaner	Cracked	380.00 F	*380.00 F
F=Franchise part.						
Total Parts (\$\$)					5,823.00	4,165.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	New	45.00	20.00
2	To spray paint affected front and inner damaged portion inclusive of preparatory works and material	New	950.00	800.00
3	To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet hinge panel, RH front fender and inner panel, RH head lamp inner panel, front support panel, RH front door, RH front door pillar, front chassis member and adjust body panel alignment	New	750.00	600.00
4	To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality	New	50.00	0.00
5	To spray paint affected rear and inner damaged portion inclusive of preparatory works and material	New	600.00	400.00
6	To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member and adjust rear body and boot alignment	New	550.00	400.00
7	To perform computer diagnostic on drivetrain, ABS systems, parking system, and clear fault codes	New	120.00	0.00
Gross Labour Cost (\$\$)			3,065.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >