

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SJR 5093 K  
 TP/AXA

M/S : AXA INSURANCE (S) PTE LTD  
 8 SHENTON WAY  
 #27-02 AXA TOWER  
 SINGAPORE 068811

TEL: 63387288  
 ATTN: Motor Claim Department

FAX: 68804739

Estimate No: ES1891048/YISHUN  
 Date: 12 Sep 2018  
 Policy No: MT103789  
 Veh Reg No: SJR5093K  
 Make/Model: MAZDA MAZDA3 1.6L SDN  
 Chassis No: JM6BL10Z1A0104065  
 Engine No: Z6794430  
 Reg. Date: 26/06/2009

WS Ref: TP/AXA/YS  
 Claim Type: Third Party  
 Accident Date: 31/08/2018  
 TP Veh Reg No: SKX8558Z

*Not Notified*  
*1/1 Sep 8?*  
*Missing After Paint*

## Estimate Repair Cost to Vehicle No :SJR5093K

PAGE:1/1

| Description                                                                                                                | U/Price  | Quantity | List Price<br>S\$    | Amount<br>S\$ |
|----------------------------------------------------------------------------------------------------------------------------|----------|----------|----------------------|---------------|
| <b>List Price</b>                                                                                                          |          |          |                      |               |
| 1 REAR BUMPER                                                                                                              | 1,049.00 | 1 PC     | <i>Bu</i> 1,049.00   | <i>—</i>      |
| 2 REAR BUMPER REINFORCEMENT                                                                                                | 529.00   | 1 PC     | 529.00               | <i>?</i>      |
| 3 REAR BUMPER REFLECTORS <i>old Bro</i>                                                                                    | 59.20    | 2 PCS    | <i>na</i> 118.40     | <i>—</i>      |
| 4 REAR BUMPER CLIPS                                                                                                        | 4.50     | 4 PCS    | <i>na</i> 18.00      | <i>—</i>      |
| 5 REAR BOOT                                                                                                                | 1,161.00 | 1 PC     | <i>na</i> 1,161.00   | <i>—</i>      |
| 6 REAR BOOT LOGO                                                                                                           | 70.90    | 1 PC     | <i>na</i> 70.90      | <i>—</i>      |
| 7 REAR BOOT EMBLEM (MAZDA)                                                                                                 | 38.70    | 1 PC     | <i>na</i> 38.70      | <i>—</i>      |
| 8 REAR BOOT EMBLEM (3)                                                                                                     | 27.40    | 1 PC     | <i>na</i> 27.40      | <i>—</i>      |
| 9 REAR BOOT INNER LOCK                                                                                                     | 177.00   | 1 PC     | 177.00               | <i>?</i>      |
| 10 REAR CENTRE PANEL                                                                                                       | 409.00   | 1 PC     | 409.00               | <i>?</i>      |
| 11 REAR CENTRE PANEL INNER TOP GARNISH                                                                                     | 193.30   | 1 PC     | 193.30               | <i>?</i>      |
|                                                                                                                            |          |          | 3,791.70             |               |
|                                                                                                                            |          | Less 20% | 758.34               | 3,033.36      |
| <b>Special Net</b>                                                                                                         |          |          |                      |               |
| 12 REAR BUMPER LOWER SKIRT                                                                                                 | 480.00   | 1 PC     | <i>bu</i> 480.00     | <i>X</i>      |
| 13 REAR NUMBER PLATE                                                                                                       | 35.00    | 1 PC     | <i>na</i> 35.00      | <i>✓</i>      |
| 14 REVERSE SENSOR                                                                                                          | 200.00   | 1 SET    | 200.00               | <i>?</i>      |
|                                                                                                                            |          |          | 715.00               | 715.00        |
| <b>Labour</b>                                                                                                              |          |          |                      |               |
| 15 REMOVE & REFIX REAR BUM PER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, TO CUT, WELD & RENEW REAR PANEL & REALIGN THE SAME | 700.00   | 1 LA     | 700.00               | <i>600</i>    |
| 16 PUTTY & RESPRAY ON REAR PANEL, REAR BUMPER, REINFORCEMENT, BOOT                                                         | 800.00   | 1 LA     | 800.00               | <i>650</i>    |
| 17 RUSTPROOFING                                                                                                            | 30.00    | 1 LA     | 30.00                | <i>✓</i>      |
|                                                                                                                            |          |          | 1,530.00             | 1,530.00      |
|                                                                                                                            |          |          | Total                | S\$ 5,278.36  |
|                                                                                                                            |          |          | Add GST @ 7%         | 369.49        |
|                                                                                                                            |          |          | Total Amount Payable | S\$ 5,647.85  |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Acknowledged by Repairer

Signature:

Date: